



181 US Hwy 46  
Mine Hill, NJ 07830  
(908) 654-8068  
(800) 783-0567  
Fax 908-654-8069

## Lead-Based Paint Evaluation Report Inspection

**Performed At:**

170 Township Line Road Unit:Primary  
Primary  
Hillsborough Township, NJ 08844

**Performed For:**

Arthur Laurie  
1600 Jersey Ave  
North Brunswick, NJ 08902

**Prepared By:**

LEW Environmental Services, LLC.  
181 US Hwy 46  
Mine Hill, NJ 07803  
Phone (908) 654-8068  
Fax (908) 654-8069  
Inspection Date: 05/23/24  
Order Number: 33895

# Table Of Contents

Contact Information	3
Executive Summary	4
Components with Lead Based Paint	4
Regulatory Requirements	5
Required Disclosure	5
Required Training for Workers	5
Controlling Lead-Based Paint	5
Abatement for Lead-Based Paint Free Certification	6
Component Removal	6
Paint Stripping	6
Procedures & Methodology	6
Location Conventions	6
Paint Testing	6
X-Ray Fluorescence	6
Calibration Check Readings	7

## Appendices

Appendix A - Floor Plan

Appendix B - Lead-Based Paint Evaluation Report

# Contact Information


## Site

Street Address	170 Township Line Road Unit Primary Hillsborough Township, NJ 08844
----------------	--

## Property Owner

Name	Arthur Laurie
Street Address	1600 Jersey Ave North Brunswick, NJ 08902
Phone Number	732-266-6549

## Lead-Based Paint Risk Assessor

Name	Danny Feliciano
Certification Number	033001
Instrumentation	Viken Pb200i/e
Signature	
Date	05/27/2024

## Firm

Organization:	LEW Environmental Services, LLC.
Certification #:	NJDCA 00015
Street:	181 US Hwy 46
City, State & Zip:	Mine Hill, NJ 07803
Phone Number:	908-654-8068
Web Address:	lewenvironmental.com

## Executive Summary

For 170 Township Line Road Unit Primary  
 Hillsborough Township, NJ 08844  
 05/27/2024

On 05/23/24, Danny Feliciano of LEW Environmental Services, LLC (NJDCA 00015 E) performed a lead-based paint inspection at 170 Township Line Road Unit Primary . The lead-based paint inspection sampling protocol that was applied follows “Inspections in Single-Family Housing” Chapter 7 of the HUD Guidelines (2012 revision) and the protocol as referenced in USEPA 40 CFR Part 745.227(b). See Appendix B Lead Paint Inspection Report for the complete set of X-Ray Fluorescence data.

The tables below indicate the location of the lead-based paint found. Each positive reading applies to all similar components in the same room equivalent (room, hall, stairwell, building exterior, etc.) For a lead-based paint free certification, the lead must be stripped or the leaded component replaced and confirmation achieved. Enclosure and encapsulation are not acceptable methods for a lead-based paint free certification. If no lead-based paint was identified, the table will list “None” and the dwelling unit is considered lead-based paint free.

## Components With Lead Based Paint

Room Equivalent	Component	Substrate	Value( mg/cm <sup>2</sup> )
Foyer/Hall	Door Casing	Wood	6.4
Foyer/Hall	Door Jamb	Wood	5.4
Foyer/Hall	Room Baseboard	Wood	1.9
Foyer/Hall	Room Chair Rail	Wood	5.9
Foyer/Hall	Room Wall Trim	Wood	3
Foyer/Hall	Door	Wood	1.6
Foyer/Hall	Window Casing	Wood	6.7
Foyer/Hall	Window Sill	Wood	2.6
Living Room	Door Casing	Wood	7.8
Living Room	Door Jamb	Wood	4
Living Room	Room Baseboard	Wood	4.3
Living Room	Room Chair Rail	Wood	9.6
Living Room	Window Casing	Wood	20.5
Living Room	Window Sill	Wood	17.4
Living Room	Fire Place Mantle	Wood	1.8
Living Room	Cabinets Door	Wood	7.3
Living Room	Cabinets Door	Wood	7.1
Family Room	Fire Place Frame	Wood	7
Family Room	Fire Place Trim	Wood	4.2

Family Room	Cabinets Door	Wood	2.8
Family Room	Cabinets Door	Wood	1.7
Family Room	Window Casing	Wood	2.4
Family Room	Window Sill	Wood	2.9
Family Room	Room Chair Rail	Wood	2.5
Family Room	Door Casing	Wood	2.6
Family Room	Door Jamb	Wood	7.1
Dining Room	Window Casing	Wood	1
Dining Room	Door	Wood	2
Dining Room	Door Jamb	Wood	5
Dining Room	Door	Wood	1
Dining Room	Closet Door Casing	Wood	1.3
Rear Entry	Door Casing	Wood	1
Rear Entry	Room Wall	Wood	0.9
Rear Entry	Room Wall	Wood	0.9
Rear Entry	Room Wall	Wood	1.3
Rear Entry	Window Sill	Wood	1.9
2nd Floor Hallway	Window Casing	Wood	1.1
2nd Floor Hallway	Room Baseboard	Wood	1.2
2nd Floor Hallway	Closet Door	Wood	2.4
2nd Floor Hallway	Closet Door Casing	Wood	2.4
2nd Floor Hallway	Door	Wood	3.9
2nd Floor Hallway	Access Panel Door	Wood	1.3
Bathroom	Window Casing	Wood	1.1
Bedroom 1	Door	Wood	1.6
Bedroom 1	Door Threshold	Wood	1.2
Bedroom 2	Door	Wood	2.3
Bedroom 2	Window Casing	Wood	1.2
Basement room 1	Door	Wood	1.3

EPA 40 CFR 745.227(h) states lead-based paint is present on any surface that is tested and found to contain lead equal to or in excess of 1.0 milligrams per square centimeter or equal to or in excess of 0.5% by weight. Local thresholds may be lower than this Federal standard.

## **Regulatory Requirements**

### ***Required Disclosure***

A summary of this lead-based paint evaluation report must be provided to new lessees (tenants). A complete copy of this report must be provided to purchasers and owners of this property and it must be made available to new tenants under federal law (24 CFR PART 35 AND 40 CFR PART 745) before they become obligated under a lease or sales contract. Landlords (lessors) and sellers are also required to distribute an educational pamphlet approved by the U.S. Environmental Protection Agency and include standard warning language in their leases or sales contracts to ensure that parents have the information they need to protect their children from lead-based paint hazards.”

Should the recipient of this report receive federal subsidy they are responsible to comply with all requirements of 24 CFR Part 35 Requirements for the Notification, Evaluation and Reduction of Lead-Based Paint Hazards in Federally Owned Residential Property and Housing Receiving Federal Assistance; Final Rule which, are applicable to the type of program they are participating in and the dollar amount of subsidy being received. If this property or any of its tenants receives financial federal assistance, the results of the evaluation or hazard reduction activities must be provided by the designated party (client) to the owner of the referenced property and the occupants within 15 calendar days of the date when the designated party receives this report, or makes the presumption that lead-based paint hazards do exist.

### ***Required Training for Workers***

Should the lead-based paint and lead hazard reduction activities be part of a program which receives federal subsidy or a New Jersey multifamily building, all persons performing “Interim Controls” or “Standard Treatments” must be trained in accordance with 29 CFR 1926.59 and be supervised by an individual who successfully completed one of the following courses:

1. A lead-based paint abatement supervisors course accredited in accordance with 40 CFR 745.225
2. A lead-based paint abatement worker course accredited in accordance with 40 CFR 745.225
3. The lead-based paint Maintenance Training Program, “Work Smart, Work Wet, and Work Clean to Work Lead Safe”, prepared by the National Environmental Training Association for EPA and HUD
4. “The Remodeler’s and Renovator’s Lead-Based Paint Training Program,” prepared by HUD and the National Association of the Remodeling Industry
5. Another course approved by HUD for this purpose after consultation with EPA.

In accordance with Section 35.1340 all Lead-Based Paint and Lead Hazard reduction activities, which are not exempt (see regulations) require Lead Dust Wipe Clearance testing by a 1) certified lead inspector, 2) certified risk assessor or 3) a dust wipe sampling technician whose work is reviewed by a certified risk assessor.

If a renovation at the property is to occur, all work should comply with 40 CFR 745 Subpart E- Residential Property Renovation.

### **Controlling Lead-Based Paint**

There are different options available for controlling lead-based paint. Each option has its own associated costs and benefits both short and long term. In most cases, a combination of the options can be implemented to reduce the possibility of lead contamination. LEW Environmental Services,

LLC. strongly suggests that each option is thoroughly contemplated before beginning any activity.

Components that are found to be positive for lead-based paint should be checked for deterioration. Lead-based paint in deteriorated condition is considered a paint-lead hazard. Those components should be address as soon as possible using lead safe work practices at a minimum. However, if any components are found to test positive for lead based paint, they should be considered for future component removal or paint stripping.

### ***Abatement for Lead-Based Paint Free Certification***

#### **Component Removal**

Component removal is a permanent solution to the issue of potential exposure of lead. It requires taking the old lead-based painted component out and replacing it with a new non-lead painted component. The cost associated with this option depends mostly on the cost of the replacement component. Since labor is most often the more costly aspect of controlling lead issues, many owners choose component removal over more labor intensive methods. Components often chosen for removal are wood trim, windows, most doors, and exterior railings. Plaster and drywall ceilings and walls, fire rated doors, and wood porch components should also be considered.

#### **Paint Stripping**

Paint stripping is a permanent solution to the issue of potential exposure of lead. The paint can be removed either in-place or by an off-site processing facility. In-place removal can be mechanical or chemical. In-place paint stripping has the issue of proper disposal of the hazardous waste generated.

Mechanical stripping scrapes the paint off the substrate. Most times dry scraping is prohibited, but sanding or scraping can be done in conjunction with engineering controls to reduce airborne and settled lead dust. Power tools used to remove the paint must be equipped with a HEPA filtered shroud. Wetting a surface and hand scraping is also permitted. The components most often chosen for hand scraping are window and door jambs. Power tools are better equipped to handle lager surface areas.

Chemical stripping in-place uses strong chemicals to soften the paint for easier removal from the substrate. The chemicals are either very acidic or very basic, so proper training and protection for the worker is imperative. Generally, the chemicals must remain in- place overnight, so maintaining a secure worksite separate from occupants is mandatory.

Off site facilities use much stronger chemicals to remove the lead-based paint from the component. Components often chosen for off-site paint removal are intricate metal pieces. Sometimes this method is used for intricate wood work, but the stronger chemicals soften the wood and can drive lead into the wood while removing the paint.

#### **Procedures & Methodology**

##### ***Location Conventions***

When reviewing Appendix A "Floor Plan" and Appendix B "Lead-Based Paint Evaluation Report", you will notice that the letters A, B, C, and D or the numbers 1, 2, 3 and 4 are used to identify the location of specific components. The key to correct orientation is the location of the "A" or "1" wall. The "B" or "2" wall, "C" or "3" wall, and "D" or "4" wall run clockwise from the "A" or "1" wall. The Lead-Based Paint Evaluation Report lists this information under the "Wall" column. The "Location"

column uses numbering of replicated components starting with "1" at left and continuing sequentially to right respectively to describe the location of the component while facing the wall identified.

### ***Paint Testing***

#### **X-Ray Fluorescence**

X-Ray Fluorescence (XRF) paint testing is performed to detect the presence of lead on painted surfaces. The XRF instrument is state-of-the-art equipment. XRF testing is usually the preferred method of testing, because it is non-destructive, quantitative and can be performed on the spot with acceptable accuracy. LEW Environmental Services, LLC. 's evaluators follow the manufacturer's suggested use and the Performance Characteristic Sheet of the XRF instrument being used. The results of the XRF testing are the basis for drawing conclusions and making recommendations in the report.

All LEW Environmental Services, LLC. 's evaluators follow 40 CFR 745 and the HUD Guidelines for testing lead using an XRF instrument. All federal, state and city regulations are followed when applicable. The evaluator will test one of each and every different type of testing combination (component) in each room being surveyed. Each XRF reading is assigned an exclusive sample reference number and a measurement that is stored in the instrument. Each sample reference number location is logged on the XRF instrument for future reference, testing location, and report generation. The above described testing format is followed unless otherwise not practical or if the evaluator's judgment decides to test in a different systematic approach.

It should be noted that detected lead levels below current levels still could create lead dust or lead-contaminated soil hazards if the paint is turned into dust by abrasion, scraping, or sanding leading to possible elevated blood lead levels. Lead poisoning is a cumulative affect. Should a child or an adult inhale or ingest sufficient quantities of low concentrations of leaded paint, dust, or soil, it will accumulate in the body's systems and could eventually cumulate to an elevated blood level of concern.

**Any untested building components should be considered lead-based paint until tested.**

#### **Calibration Check Readings**

In addition to the manufacturer's recommended warm up and quality control procedures, LEW Environmental Services, LLC. collects quality control readings as recommended in the HUD Guidelines. Quality control for XRF instrumentation instruments involves readings to check calibration.

For each XRF instrument, one set of XRF calibration check readings are recommended at least every four hours. The first is a set of three nominal-time or source decay corrected time XRF calibration check readings to be taken before the inspection begins for the day. The second occurs either after the day's inspection work has been completed, or at least every four hours, whichever occurs first. LEW Environmental Services, LLC. 's XRF calibration check readings are taken on the Standard Reference Material (SRM) paint film nearest to 1.0 mg/cm<sup>2</sup> within the National Institute of Standards and Technology (NIST) SRM Used or the XRF manufacturer's factory supplied SRM film. Three readings are collected on the SRM. The average of the three readings on the SRM must be within the acceptable plus and minus tolerances for proper calibration as detailed in the Performance Characteristic Sheet (PCS). All calibration checks are taken with the SRM film positioned at least several inches away from any potential source of lead.



Three readings are taken each time calibration check readings are made. The average of the readings are compared to the known value and if the average value is within the acceptable calibration check tolerance specified in the XRF Performance Characteristic Sheet the instrument is considered in control. If the average readings are not within the calibration check tolerance the instrument is not used until the instrument is brought back into control.

Company LEW Corporation  
 XRF Make Heuresis  
 Model Pb200i  
 Serial Num. 2128  
 Lead concentration units: mg/cm2  
 Total Readings: 205  
 Action Level 1  
 Mode Action Level  
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
5231531	21166	1		TRUE	FALSE	5/23/2024	3:32 PM	Danny Feliciano	Paint	170 Township Line Rd								
5231531	21167	1		TRUE	FALSE	5/23/2024	3:32 PM	Danny Feliciano	Paint	170 Township Line Rd								
5231531	21168	1		TRUE	FALSE	5/23/2024	3:33 PM	Danny Feliciano	Paint	170 Township Line Rd								
5231531	21169	0		TRUE	FALSE	5/23/2024	3:34 PM	Danny Feliciano	Paint	170 Township Line Rd								
5231531	21170	0.1		TRUE	FALSE	5/23/2024	3:34 PM	Danny Feliciano	Paint	170 Township Line Rd								
5231531	21171	0		TRUE	FALSE	5/23/2024	3:35 PM	Danny Feliciano	Paint	170 Township Line Rd								
5231531	21172	0.2	Negative	FALSE	FALSE	5/23/2024	3:35 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Door		Metal	A	
5231531	21173	-0.9	Negative	FALSE	TRUE	5/23/2024	3:36 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Door	Casing	Wood	A	
5231531	21174	6.4	Positive	FALSE	FALSE	5/23/2024	3:36 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Door	Casing	Wood	B	
5231531	21175	5.4	Positive	FALSE	FALSE	5/23/2024	3:37 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Door	Jamb	Wood	B	
5231531	21176	1.9	Positive	FALSE	FALSE	5/23/2024	3:38 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Baseboard	Wood	B	
5231531	21177	5.9	Positive	FALSE	FALSE	5/23/2024	3:39 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Chair Rail	Wood	B	
5231531	21178	-0.8	Negative	FALSE	TRUE	5/23/2024	3:39 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Archway		Wood	C	
5231531	21179	0.3	Negative	FALSE	FALSE	5/23/2024	3:40 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Window	Casing	Wood	C	
5231531	21180	0.6	Negative	FALSE	FALSE	5/23/2024	3:40 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Window	Sill	Wood	C	
5231531	21181	-0.5	Negative	FALSE	TRUE	5/23/2024	3:41 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Floor	Wood		
5231531	21182	0	Negative	FALSE	FALSE	5/23/2024	3:44 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Wall	Plaster	D	
5231531	21183	0	Negative	FALSE	FALSE	5/23/2024	3:44 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Wall	Plaster	B	
5231531	21184	0.2	Negative	FALSE	FALSE	5/23/2024	3:45 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Wall	Plaster	A	
5231531	21185	-0.1	Negative	FALSE	FALSE	5/23/2024	3:45 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Wall	Plaster	C	
5231531	21186	0.1	Negative	FALSE	FALSE	5/23/2024	3:46 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Ceiling	Plaster		2
5231531	21187	-0.1	Negative	FALSE	FALSE	5/23/2024	3:46 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Ceiling	Drywall		1
5231531	21188	0	Negative	FALSE	FALSE	5/23/2024	3:47 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Crown Molding	Wood	D	
5231531	21189	3	Positive	FALSE	FALSE	5/23/2024	3:48 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Wall Trim	Wood	D	
5231531	21190	1.6	Positive	FALSE	FALSE	5/23/2024	3:48 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Door		Wood	A	2
5231531	21191	-0.6	Negative	FALSE	TRUE	5/23/2024	3:49 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Baseboard	Wood	D	2
5231531	21192	0.3	Negative	FALSE	FALSE	5/23/2024	3:50 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Door	Casing	Wood	A	2
5231531	21193	0.3	Negative	FALSE	FALSE	5/23/2024	3:52 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Wall	Concrete	D	2
5231531	21194	-0.5	Negative	FALSE	TRUE	5/23/2024	3:54 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Stair	Wall	Wood	A	
5231531	21195	0.5	Negative	FALSE	TRUE	5/23/2024	3:54 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Stair	Ceiling	Wood	A	
5231531	21196	-0.4	Negative	FALSE	TRUE	5/23/2024	3:56 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Stair	Wall	Wood	B	
5231531	21197	0	Negative	FALSE	FALSE	5/23/2024	3:56 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Stair	Wall	Plaster	D	
5231531	21198	6.7	Positive	FALSE	FALSE	5/23/2024	3:57 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Window	Casing	Wood	D	
5231531	21199	2.6	Positive	FALSE	FALSE	5/23/2024	3:58 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Window	Sill	Wood	D	
5231531	21200	7.8	Positive	FALSE	FALSE	5/23/2024	3:59 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Door	Casing	Wood	D	
5231531	21201	4	Positive	FALSE	FALSE	5/23/2024	3:59 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Door	Jamb	Wood	D	
5231531	21202	4.3	Positive	FALSE	FALSE	5/23/2024	3:59 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Room	Baseboard	Wood	D	
5231531	21203	9.6	Positive	FALSE	TRUE	5/23/2024	4:00 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Room	Chair Rail	Wood	D	
5231531	21204	20.5	Positive	FALSE	TRUE	5/23/2024	4:01 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Window	Casing	Wood	A	1
5231531	21205	17.4	Positive	FALSE	TRUE	5/23/2024	4:01 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Window	Sill	Wood	A	1
5231531	21206	0.2	Negative	FALSE	FALSE	5/23/2024	4:02 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Pipe	Vertical	Metal	A	1
5231531	21207	0.1	Negative	FALSE	FALSE	5/23/2024	4:03 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Radiator		Metal	A	
5231531	21208	-0.8	Negative	FALSE	TRUE	5/23/2024	4:03 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Closet	Door	Wood	B	
5231531	21209	-0.6	Negative	FALSE	TRUE	5/23/2024	4:04 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Closet	Door Casing	Wood	B	
5231531	21210	-0.3	Negative	FALSE	TRUE	5/23/2024	4:04 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Closet	Door Jamb	Wood	B	
5231531	21211	0.2	Negative	FALSE	FALSE	5/23/2024	4:05 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Closet	Wall	Wood	B	
5231531	21212	1.8	Positive	FALSE	TRUE	5/23/2024	4:05 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Fire Place	Mantle	Wood	B	

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
5231531	21213	0.7	Negative	FALSE	TRUE	5/23/2024	4:06 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Fire Place	Frame	Wood	B	
5231531	21214	0	Negative	FALSE	TRUE	5/23/2024	4:07 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Fire Place	Trim	Wood	B	
5231531	21215	0	Negative	FALSE	FALSE	5/23/2024	4:08 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Archway		Wood	C	
5231531	21216	7.3	Positive	FALSE	FALSE	5/23/2024	4:08 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Cabinets	Door	Wood	B	Upper
5231531	21217	7.1	Positive	FALSE	FALSE	5/23/2024	4:09 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Cabinets	Door	Wood	B	Lower
5231531	21218	-1	Negative	FALSE	TRUE	5/23/2024	4:10 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Cabinets	Shelf	Wood	B	Lower
5231531	21219	-0.5	Negative	FALSE	TRUE	5/23/2024	4:11 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Cabinets	Shelf Support	Wood	B	Lower
5231531	21220	0.2	Negative	FALSE	FALSE	5/23/2024	4:12 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Cabinets	Inside Wall	Plaster	B	Lower
5231531	21221	0	Negative	FALSE	FALSE	5/23/2024	4:13 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Cabinets	Inside Wall	Plaster	B	Lower
5231531	21222	0.5	Negative	FALSE	TRUE	5/23/2024	4:15 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Cabinets	Door	Wood	B	Lower
5231531	21223	0.1	Negative	FALSE	FALSE	5/23/2024	4:18 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Column		Wood	C	Lower
5231531	21224	0	Negative	FALSE	FALSE	5/23/2024	4:20 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Room	Wall	Plaster	D	
5231531	21225	0	Negative	FALSE	FALSE	5/23/2024	4:21 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Room	Wall	Plaster	C	
5231531	21226	0.2	Negative	FALSE	FALSE	5/23/2024	4:21 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Room	Wall	Concrete	B	
5231531	21227	0.3	Negative	FALSE	FALSE	5/23/2024	4:22 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Room	Wall	Drywall	A	
5231531	21228	0.2	Negative	FALSE	FALSE	5/23/2024	4:23 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Room	Wall	Plaster	A	2
5231531	21229	0	Negative	FALSE	FALSE	5/23/2024	4:24 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Room	Crown Molding	Wood	C	2
5231531	21230	-0.1	Negative	FALSE	FALSE	5/23/2024	4:25 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Room	Ceiling	Plaster		
5231531	21231	0	Negative	FALSE	FALSE	5/23/2024	4:26 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Room	Wall	Plaster	D	
5231531	21232	0.1	Negative	FALSE	FALSE	5/23/2024	4:26 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Room	Wall	Plaster	C	
5231531	21233	0.2	Negative	FALSE	FALSE	5/23/2024	4:27 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Room	Wall	Concrete	B	
5231531	21234	-0.1	Negative	FALSE	FALSE	5/23/2024	4:27 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Room	Wall	Plaster	A	
5231531	21235	0	Negative	FALSE	FALSE	5/23/2024	4:28 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Archway		Wood	A	
5231531	21236	0	Negative	FALSE	FALSE	5/23/2024	4:28 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Column		Wood	A	
5231531	21237	0.5	Negative	FALSE	FALSE	5/23/2024	4:29 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Fire Place	Mantle	Wood	B	
5231531	21238	7	Positive	FALSE	FALSE	5/23/2024	4:30 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Fire Place	Frame	Wood	B	
5231531	21239	4.2	Positive	FALSE	FALSE	5/23/2024	4:30 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Fire Place	Trim	Wood	B	
5231531	21240	2.8	Positive	FALSE	FALSE	5/23/2024	4:32 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Cabinets	Door	Wood	B	Upper
5231531	21241	1.7	Positive	FALSE	FALSE	5/23/2024	4:32 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Cabinets	Door	Wood	B	Lower
5231531	21242	-0.6	Negative	FALSE	TRUE	5/23/2024	4:34 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Closet	Door	Wood	B	
5231531	21243	-0.7	Negative	FALSE	TRUE	5/23/2024	4:35 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Closet	Door Casing	Wood	B	
5231531	21244	2.4	Positive	FALSE	FALSE	5/23/2024	4:36 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Window	Casing	Wood	C	1
5231531	21245	2.9	Positive	FALSE	TRUE	5/23/2024	4:36 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Window	Sill	Wood	C	1
5231531	21246	2.5	Positive	FALSE	FALSE	5/23/2024	4:37 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Room	Chair Rail	Wood	C	1
5231531	21247	0.6	Negative	FALSE	FALSE	5/23/2024	4:38 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Room	Baseboard	Wood	A	1
5231531	21248	2.6	Positive	FALSE	FALSE	5/23/2024	4:39 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Door	Casing	Wood	D	1
5231531	21249	7.1	Positive	FALSE	TRUE	5/23/2024	4:40 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Door	Jamb	Wood	D	1
5231531	21250	0	Negative	FALSE	FALSE	5/23/2024	4:41 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Room	Wall	Plaster	A	
5231531	21251	-0.1	Negative	FALSE	FALSE	5/23/2024	4:41 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Room	Wall	Plaster	D	
5231531	21252	0.2	Negative	FALSE	FALSE	5/23/2024	4:42 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Room	Wall	Plaster	C	
5231531	21253	0.3	Negative	FALSE	FALSE	5/23/2024	4:45 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Room	Wall	Plaster	C	
5231531	21254	0.3	Negative	FALSE	FALSE	5/23/2024	4:46 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Room	Wall	Plaster	B	
5231531	21255	0.2	Negative	FALSE	FALSE	5/23/2024	4:46 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Room	Wall	Plaster	A	
5231531	21256	0.2	Negative	FALSE	FALSE	5/23/2024	4:47 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Room	Wall	Plaster	D	
5231531	21257	1	Positive	FALSE	FALSE	5/23/2024	4:48 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Window	Casing	Wood	D	
5231531	21258	-0.1	Negative	FALSE	FALSE	5/23/2024	4:48 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Window	Sill	Wood	D	
5231531	21259	0	Negative	FALSE	FALSE	5/23/2024	4:49 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Room	Baseboard	Wood	D	
5231531	21260	0.7	Negative	FALSE	FALSE	5/23/2024	4:50 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Door	Casing	Wood	B	
5231531	21261	2	Positive	FALSE	FALSE	5/23/2024	4:51 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Door	---	Wood	B	
5231531	21262	5	Positive	FALSE	FALSE	5/23/2024	4:51 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Door	Jamb	Wood	B	
5231531	21263	1	Positive	FALSE	FALSE	5/23/2024	4:53 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Door	---	Wood	A	
5231531	21264	0.7	Negative	FALSE	FALSE	5/23/2024	4:53 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Door	Casing	Wood	A	
5231531	21265	1.3	Positive	FALSE	FALSE	5/23/2024	4:54 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Closet	Door Casing	Wood	A	
5231531	21266	-0.4	Negative	FALSE	TRUE	5/23/2024	4:55 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Closet	Door	Wood	A	
5231531	21267	0.6	Negative	FALSE	FALSE	5/23/2024	4:55 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Closet	Door	Wood		
5231531	21268	0.7	Negative	FALSE	FALSE	5/23/2024	4:56 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Closet	Door Jamb	Wood		
5231531	21269	0.6	Negative	FALSE	FALSE	5/23/2024	4:58 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Room	Floor	Wood		

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
5231531	21270	0.2	Negative	FALSE	FALSE	5/23/2024	4:59 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Room	Ceiling	Plaster		
5231531	21271	0.2	Negative	FALSE	FALSE	5/23/2024	5:03 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Room	Ceiling	Plaster		
5231531	21272	-0.8	Negative	FALSE	TRUE	5/23/2024	5:03 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Door	Casing	Wood	C	
5231531	21273	0.2	Negative	FALSE	FALSE	5/23/2024	5:04 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Room	Wall	Drywall	A	
5231531	21274	-0.1	Negative	FALSE	FALSE	5/23/2024	5:04 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Room	Wall	Drywall	D	
5231531	21275	0	Negative	FALSE	FALSE	5/23/2024	5:05 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Room	Wall	Drywall	C	
5231531	21276	-0.1	Negative	FALSE	FALSE	5/23/2024	5:05 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Room	Wall	Drywall	B	
5231531	21277	0.1	Negative	FALSE	FALSE	5/23/2024	5:06 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Room	Ceiling	Drywall		
5231531	21278	-0.6	Negative	FALSE	TRUE	5/23/2024	5:07 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Window	Casing	Wood	C	
5231531	21279	-0.7	Negative	FALSE	TRUE	5/23/2024	5:08 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Window	Sill	Wood	C	
5231531	21280	-0.8	Negative	FALSE	TRUE	5/23/2024	5:08 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Window	Casing	Wood	D	
5231531	21281	-0.8	Negative	FALSE	TRUE	5/23/2024	5:09 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Window	Sill	Wood	D	
5231531	21282	0.8	Negative	FALSE	FALSE	5/23/2024	5:09 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Window	Sash	Wood	D	
5231531	21283	-0.1	Negative	FALSE	FALSE	5/23/2024	5:10 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Room	Baseboard	Wood	C	
5231531	21284	-0.1	Negative	FALSE	FALSE	5/23/2024	5:10 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Door	Casing	Wood	C	
5231531	21285	-0.7	Negative	FALSE	TRUE	5/23/2024	5:11 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Door	Jamb	Wood	C	
5231531	21286	-0.2	Negative	FALSE	TRUE	5/23/2024	5:11 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Door	---	Metal	A	
5231531	21287	-0.7	Negative	FALSE	TRUE	5/23/2024	5:12 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Door	Casing	Wood	A	
5231531	21288	-0.4	Negative	FALSE	TRUE	5/23/2024	5:12 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Door	Outer Casing	Wood	A	
5231531	21289	-0.7	Negative	FALSE	TRUE	5/23/2024	5:13 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Door	Jamb	Wood	A	
5231531	21290	1	Positive	FALSE	FALSE	5/23/2024	5:13 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Door	Casing	Wood	C	
5231531	21291	0.4	Negative	FALSE	TRUE	5/23/2024	5:14 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Room	Wall	Wood	C	
5231531	21292	0.9	Positive	FALSE	TRUE	5/23/2024	5:15 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Room	Wall	Wood	D	
5231531	21293	0.9	Positive	FALSE	TRUE	5/23/2024	5:16 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Room	Wall	Wood	A	
5231531	21294	1.3	Positive	FALSE	TRUE	5/23/2024	5:17 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Room	Wall	Wood	B	
5231531	21295	0.7	Negative	FALSE	FALSE	5/23/2024	5:19 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Room	Ceiling	Wood		
5231531	21296	-0.1	Negative	FALSE	FALSE	5/23/2024	5:19 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Room	Ceiling	Wood		
5231531	21297	0.7	Negative	FALSE	FALSE	5/23/2024	5:20 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Window	Casing	Wood	B	
5231531	21298	1.9	Positive	FALSE	TRUE	5/23/2024	5:21 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Window	Sill	Wood	B	
5231531	21299	0.3	Negative	FALSE	TRUE	5/23/2024	5:22 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Window	Sill	Wood	D	
5231531	21300	0.8	Negative	FALSE	FALSE	5/23/2024	5:24 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Window	Sill	Wood	C	
5231531	21301	1.1	Positive	FALSE	FALSE	5/23/2024	5:25 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Window	Casing	Wood	C	
5231531	21302	1.2	Positive	FALSE	FALSE	5/23/2024	5:25 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Room	Baseboard	Wood	C	
5231531	21303	0.2	Negative	FALSE	FALSE	5/23/2024	5:26 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Room	Wall	Plaster	C	
5231531	21304	0.7	Negative	FALSE	FALSE	5/23/2024	5:27 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Room	Wall	Wood	B	
5231531	21305	0.8	Negative	FALSE	FALSE	5/23/2024	5:27 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Room	Wall	Wood	D	
5231531	21306	-0.1	Negative	FALSE	FALSE	5/23/2024	5:28 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Room	Wall	Plaster	A	
5231531	21307	2.4	Positive	FALSE	TRUE	5/23/2024	5:29 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Closet	Door	Wood	C	
5231531	21308	2.4	Positive	FALSE	TRUE	5/23/2024	5:29 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Closet	Door Casing	Wood	C	
5231531	21309	3.9	Positive	FALSE	FALSE	5/23/2024	5:30 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Door		Wood	B	1
5231531	21310	0.7	Negative	FALSE	FALSE	5/23/2024	5:30 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Door		Wood	B	2
5231531	21311	0.8	Negative	FALSE	FALSE	5/23/2024	5:31 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Door	Casing	Wood	B	2
5231531	21312	0.1	Negative	FALSE	FALSE	5/23/2024	5:33 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Door	---	Wood	A	
5231531	21313	0.8	Negative	FALSE	FALSE	5/23/2024	5:33 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Door	Casing	Wood	A	
5231531	21314	1.3	Positive	FALSE	FALSE	5/23/2024	5:34 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Access Panel	Door	Wood	D	
5231531	21315	0.8	Negative	FALSE	FALSE	5/23/2024	5:35 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Access Panel	Casing	Wood	D	
5231531	21316	0.8	Negative	FALSE	FALSE	5/23/2024	5:36 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bathroom	Door		Wood	C	
5231531	21317	-0.6	Negative	FALSE	TRUE	5/23/2024	5:37 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bathroom	Door	Casing	Wood	C	
5231531	21318	-0.4	Negative	FALSE	TRUE	5/23/2024	5:37 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bathroom	Room	Baseboard	Wood	C	
5231531	21319	-0.6	Negative	FALSE	TRUE	5/23/2024	5:37 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bathroom	Room	Chair Rail	Wood	C	
5231531	21320	0	Negative	FALSE	FALSE	5/23/2024	5:38 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bathroom	Room	Crown Molding	Wood	C	
5231531	21321	0.1	Negative	FALSE	FALSE	5/23/2024	5:39 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bathroom	Room	Ceiling	Drywall		
5231531	21322	-0.6	Negative	FALSE	TRUE	5/23/2024	5:39 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bathroom	Room	Wall	Drywall	A	
5231531	21323	-0.1	Negative	FALSE	FALSE	5/23/2024	5:40 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bathroom	Room	Wall	Drywall	D	
5231531	21324	-0.1	Negative	FALSE	FALSE	5/23/2024	5:40 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bathroom	Room	Wall	Drywall	C	
5231531	21325	-0.1	Negative	FALSE	FALSE	5/23/2024	5:40 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bathroom	Room	Wall	Drywall	B	
5231531	21326	1.1	Positive	FALSE	FALSE	5/23/2024	5:41 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bathroom	Window	Casing	Wood	A	



Company LEW Corporation  
 XRF Make Heuresis  
 Model Pb200i  
 Serial Num. 2128

Lead concentration units: mg/cm2

Total Readings: 205 Total Positives 48  
 Action Level 1  
 Mode Action Level  
 Analytic Mode Paint

Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
5231531	21174	6.4	Positive	FALSE	FALSE	5/23/2024	3:36 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Door	Casing	Wood	B	
5231531	21175	5.4	Positive	FALSE	FALSE	5/23/2024	3:37 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Door	Jamb	Wood	B	
5231531	21176	1.9	Positive	FALSE	FALSE	5/23/2024	3:38 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Baseboard	Wood	B	
5231531	21177	5.9	Positive	FALSE	FALSE	5/23/2024	3:39 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Chair Rail	Wood	B	
5231531	21189	3	Positive	FALSE	FALSE	5/23/2024	3:48 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Wall Trim	Wood	D	
5231531	21190	1.6	Positive	FALSE	FALSE	5/23/2024	3:48 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Door		Wood	A	2
5231531	21198	6.7	Positive	FALSE	FALSE	5/23/2024	3:57 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Window	Casing	Wood	D	
5231531	21199	2.6	Positive	FALSE	FALSE	5/23/2024	3:58 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Window	Sill	Wood	D	
5231531	21200	7.8	Positive	FALSE	FALSE	5/23/2024	3:59 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Door	Casing	Wood	D	
5231531	21201	4	Positive	FALSE	FALSE	5/23/2024	3:59 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Door	Jamb	Wood	D	
5231531	21202	4.3	Positive	FALSE	FALSE	5/23/2024	3:59 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Room	Baseboard	Wood	D	
5231531	21203	9.6	Positive	FALSE	TRUE	5/23/2024	4:00 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Room	Chair Rail	Wood	D	
5231531	21204	20.5	Positive	FALSE	TRUE	5/23/2024	4:01 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Window	Casing	Wood	A	1
5231531	21205	17.4	Positive	FALSE	TRUE	5/23/2024	4:01 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Window	Sill	Wood	A	1
5231531	21212	1.8	Positive	FALSE	TRUE	5/23/2024	4:05 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Fire Place	Mantle	Wood	B	
5231531	21216	7.3	Positive	FALSE	FALSE	5/23/2024	4:08 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Cabinets	Door	Wood	B	Upper
5231531	21217	7.1	Positive	FALSE	FALSE	5/23/2024	4:09 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Cabinets	Door	Wood	B	Lower
5231531	21238	7	Positive	FALSE	FALSE	5/23/2024	4:30 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Fire Place	Frame	Wood	B	
5231531	21239	4.2	Positive	FALSE	FALSE	5/23/2024	4:30 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Fire Place	Trim	Wood	B	
5231531	21240	2.8	Positive	FALSE	FALSE	5/23/2024	4:32 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Cabinets	Door	Wood	B	Upper
5231531	21241	1.7	Positive	FALSE	FALSE	5/23/2024	4:32 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Cabinets	Door	Wood	B	Lower
5231531	21244	2.4	Positive	FALSE	FALSE	5/23/2024	4:36 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Window	Casing	Wood	C	1
5231531	21245	2.9	Positive	FALSE	TRUE	5/23/2024	4:36 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Window	Sill	Wood	C	1
5231531	21246	2.5	Positive	FALSE	FALSE	5/23/2024	4:37 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Room	Chair Rail	Wood	C	1
5231531	21248	2.6	Positive	FALSE	FALSE	5/23/2024	4:39 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Door	Casing	Wood	D	1
5231531	21249	7.1	Positive	FALSE	TRUE	5/23/2024	4:40 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Door	Jamb	Wood	D	1
5231531	21257	1	Positive	FALSE	FALSE	5/23/2024	4:48 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Window	Casing	Wood	D	
5231531	21261	2	Positive	FALSE	FALSE	5/23/2024	4:51 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Door	---	Wood	B	
5231531	21262	5	Positive	FALSE	FALSE	5/23/2024	4:51 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Door	Jamb	Wood	B	
5231531	21263	1	Positive	FALSE	FALSE	5/23/2024	4:53 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Door	---	Wood	A	
5231531	21265	1.3	Positive	FALSE	FALSE	5/23/2024	4:54 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Closet	Door Casing	Wood	A	
5231531	21290	1	Positive	FALSE	FALSE	5/23/2024	5:13 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Door	Casing	Wood	C	
5231531	21292	0.9	Positive	FALSE	TRUE	5/23/2024	5:15 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Room	Wall	Wood	D	
5231531	21293	0.9	Positive	FALSE	TRUE	5/23/2024	5:16 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Room	Wall	Wood	A	
5231531	21294	1.3	Positive	FALSE	TRUE	5/23/2024	5:17 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Room	Wall	Wood	B	
5231531	21298	1.9	Positive	FALSE	TRUE	5/23/2024	5:21 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Window	Sill	Wood	B	
5231531	21301	1.1	Positive	FALSE	FALSE	5/23/2024	5:25 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Window	Casing	Wood	C	
5231531	21302	1.2	Positive	FALSE	FALSE	5/23/2024	5:25 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Room	Baseboard	Wood	C	
5231531	21307	2.4	Positive	FALSE	TRUE	5/23/2024	5:29 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Closet	Door	Wood	C	
5231531	21308	2.4	Positive	FALSE	TRUE	5/23/2024	5:29 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Closet	Door Casing	Wood	C	
5231531	21309	3.9	Positive	FALSE	FALSE	5/23/2024	5:30 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Door		Wood	B	1
5231531	21314	1.3	Positive	FALSE	FALSE	5/23/2024	5:34 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Access Panel	Door	Wood	D	
5231531	21326	1.1	Positive	FALSE	FALSE	5/23/2024	5:41 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bathroom	Window	Casing	Wood	A	
5231531	21334	1.6	Positive	FALSE	TRUE	5/23/2024	5:45 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bedroom 1	Door		Wood	B	
5231531	21336	1.2	Positive	FALSE	FALSE	5/23/2024	5:46 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bedroom 1	Door	Threshold	Wood	D	
5231531	21351	2.3	Positive	FALSE	FALSE	5/23/2024	5:54 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bedroom 2	Door		Wood	D	
5231531	21354	1.2	Positive	FALSE	FALSE	5/23/2024	5:56 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bedroom 2	Window	Casing	Wood	C	2

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
5231531	21362	1.3	Positive	FALSE	FALSE	5/23/2024	6:02 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Basement room 1	Door	---	Wood	C	

# Floor Plan(s)

Site: 170 Township Line Rd

