

## **Visual Paint Assesment Report**

For 19 Club Place Freehold Borough, NJ 07728 04/04/2024


On 03/26/24, LEW Environmental Services, LLC (NJDCA 00015 E) performed a visual paint condition assessment for the presence of deteriorated paint, chips or dust from painting activities and paint residue on floors at 19 Club Place, (the "property") in compliance with NJAC 5:28A. Only the dwelling and common area interiors were included. Exteriors were not part of the assessment. The visual assessment followed the protocols found in HUD's Visual Assessment Training course.

No deteriorated paint, chips or dust from painting activities or paint residue on floors were observed in the dwelling unit. The property is eligible for a lead-safe certificate per NJAC 5:28A. Certificate enclosed


Respectfully Submitted,

Nyire Grant EPA Dust Wipe Technician, ID#D-I-T233827-23-00185 Encl: Floor Plan, Lead-safe Certificate;

## Floor Plan(s)



Floor 1 Lew Environmental Services - 19 Club Place -Visual Inspection Prepared By: LEW Environmental Services, LLC 04/04/2024



## Floor 2

Lew Environmental Services - 19 Club Place -Visual Inspection Prepared By: LEW Environmental Services, LLC 04/04/2024

