# Lead Paint Remediation Sales Lead Form

Project Information	
Project Number	28206
Site Address	197 Hale Street, New Brunswick NJ
Client Name	Aurelio Vergara
Client Contact	Aurelio Vergara
Client Phone Number	732-259-7451
Client Email	Ladesignlic@aol.com
Inspector:	Mark Franz

To be filled out b	y mapecior										
X	No lead paint found.										
	Lead paint found but remediation NOT recommended.										
	Lead paint found and recommended remediation.										
To be filled out b	y Administration										
To be filled out b	y Administration										
Date Report	rt was Mailed:										
☐ USPS	1st Class  FedEx 2 Day  FedEx Overnight										





# LEAD-BASED PAINT EVALUATION REPORT DWELLING UNIT(S) INSPECTION

## Performed At:

197 Hale Street New Brunswick NJ

## **Performed For:**

Aurelio Vergara 67 Taylor Drive Franklin Park NJ

## Prepared By:

LEW Environmental Services, LLC. 181 US Hwy 46 Mine Hill, NJ 07803

Phone (908) 654-8068 Fax (908) 654-8069

Inspection Date: 12/14/23 Project Number: 28206

# **Table of Contents**

CONTACT INFORMATION	3
EXECUTIVE SUMMARY	4
HOUSE INTERIOR COMPONENTS WITH LEAD BASED PAINT	4
REGULATORY REQUIREMENTS	5
Required Disclosure	5
Required Training for Workers	5
CONTROLLING LEAD-BASED PAINT	5
ABATEMENT FOR LEAD-BASED PAINT FREE CERTIFICATION	6
ABATEMENT TO CONTROL LEAD-BASED PAINT HAZARDS	6
Interim Control Options	7
PROCEDURES & METHODOLOGY	7
LOCATION CONVENTIONS	7
PAINT TESTING	7

# **Appendices**

APPENDIX A FLOOR PLAN

APPENDIX B LEAD-BASED PAINT EVALUATION REPORT APPENDIX C LAB SUPPORT DOCUMENTS (IF APPLICABLE)

## **Contact Information**

## Site

Street Address	197 Hale Street, New Brunswick NJ
Year Of Construction	Pre 1978

## Client

Name	Aurelio Vergara
Contact	Aurelio Vergara
Street	67 Taylor Drive, Franklin Park NJ
Phone Number	732-259-7451

#### **Site Evaluator**

Site Evaluator	Mark Franz
Certification Number	NJDHSS 003265
Instrumentation	Viken Pb200i Serial #2823
Signature	y willes
Date	December 14, 2023

#### Firm

Organization:	LEW Environmental Services, LLC.
Certification #:	NJDCA 00015E
Street:	181 US Hwy 46
City, State & Zip:	Mine Hill, NJ 07803
Phone Number:	908-654-8068
Web Address:	www.lewcorp.com

## **Executive Summary**

On 12/14/23 Mark Franz, of LEW Environmental Services, LLC. performed a lead-based paint inspection at 197 Hale Street, New Brunswick NJ Only dwelling unit and common area interiors were inspected. Exteriors were not part of the scope of services. The lead-based paint inspection sampling protocol that was applied follows "Inspections in Single-Family Housing" Chapter 7 of the HUD Guidelines (2012 revision) and the protocol as referenced in USEPA 40 CFR Part 745.227(b). See Appendix B Lead Paint Inspection Report for the complete set of X-Ray Fluorescence data.

The house interior A-Wall pertains to the wall that is in the same plane or closest to the street address of the property.

The tables below indicate the location of the lead-based paint found. Each positive reading applies to all similar components in the same room equivalent (room, hall, stairwell, building exterior, etc.) For a lead-based paint free certification, the lead must be stripped or the leaded component replaced and confirmation achieved. Enclosure and encapsulation are not acceptable methods for a lead-based paint free certification.

### House Interior Components with Lead Based Paint

Room Equivalent	Component	Substrate	Value(mg/cm²)
	NONE		

EPA 40 CFR 745.227(h) states lead-based paint is present on any surface that is tested and found to contain lead equal to or in excess of 1.0 milligrams per square centimeter or equal to or in excess of 0.5% by weight. Local thresholds may be lower than this Federal standard.

## **Regulatory Requirements**

#### Required Disclosure

A summary of this lead-based paint evaluation report must be provided to new lessees (tenants). A complete copy of this report must be provided to purchasers and owners of this property and it must be made available to new tenants under federal law (24 CFR PART 35 AND 40 CFR PART 745) before they become obligated under a lease or sales contract. Landlords (lessors) and sellers are also required to distribute an educational pamphlet approved by the U.S. Environmental Protection Agency and include standard warning language in their leases or sales contracts to ensure that parents have the information they need to protect their children from lead-based paint hazards."

Should the recipient of this report receive federal subsidy they are responsible to comply with all requirements of 24 CFR Part 35 Requirements for the Notification, Evaluation and Reduction of Lead-Based Paint Hazards in Federally Owned Residential Property and Housing Receiving Federal Assistance; Final Rule which, are applicable to the type of program they are participating in and the dollar amount of subsidy being received. If this property or any of its tenants receives financial federal assistance, the results of the evaluation or hazard reduction activities must be provided by the designated party (client) to the owner of the referenced property and the occupants within 15 calendar days of the date when the designated party receives this report, or makes the presumption that lead-based paint hazards do exist.

#### Required Training for Workers

Should the lead-based paint and lead hazard reduction activities be part of a program which receives federal subsidy or a New Jersey multifamily building, all persons performing "Interim Controls" or "Standard Treatments" must be trained in accordance with 29 CFR 1926.59 and be supervised by an individual who successfully completed one of the following courses:

- A lead-based paint abatement supervisors course accredited in accordance with 40 CFR 745.225
- 2. A lead-based paint abatement worker course accredited in accordance with 40 CFR 745.225
- 3. The lead-based paint Maintenance Training Program, "Work Smart, Work Wet, and Work Clean to Work Lead Safe", prepared by the National Environmental Training Association for EPA and HUD
- "The Remodeler's and Renovator's Lead-Based Paint Training Program," prepared by HUD and the National Association of the Remodeling Industry
- 5. Another course approved by HUD for this purpose after consultation with EPA.

In accordance with Section 35.1340 all Lead-Based Paint and Lead Hazard reduction activities, which are not exempt (see regulations) require Lead Dust Wipe Clearance testing by a 1) certified lead inspector, 2) certified risk assessor or 3) a dust wipe sampling technician whose work is reviewed by a certified risk assessor.

If a renovation at the property is to occur, all work should comply with 40 CFR 745 Subpart E-Residential Property Renovation.

## **Controlling Lead-Based Paint**

There are different options available for controlling lead-based paint. Each option has its own associated costs and benefits both short and long term. In most cases, a combination of the options can be implemented to reduce the possibility of lead contamination. LEW Environmental Services, LLC. strongly suggests that each option is thoroughly contemplated before beginning any activity.

Components that are found to be positive for lead-based paint should be checked for deterioration. Lead-based paint in deteriorated condition is considered a paint-lead hazard. Those components should be address as soon as possible using lead safe work practices at a minimum. However, if any components are found to test positive for lead based paint, they should be considered for future component removal or paint stripping.

#### Abatement for Lead-Based Paint Free Certification

#### **Component Removal**

Component removal is a permanent solution to the issue of potential exposure of lead. It requires taking the old lead-based painted component out and replacing it with a new non-lead painted component. The cost associated with this option depends mostly on the cost of the replacement component. Since labor is most often the more costly aspect of controlling lead issues, many owners choose component removal over more labor intensive methods. Components often chosen for removal are wood trim, windows, most doors, and exterior railings. Plaster and drywall ceilings and walls, fire rated doors, and wood porch components should also be considered.

#### **Paint Stripping**

Paint stripping is a permanent solution to the issue of potential exposure of lead. The paint can be removed either inplace or by an off-site processing facility. In-place removal can be mechanical or chemical. In-place paint stripping has the issue of proper disposal of the hazardous waste generated.

Mechanical stripping scrapes the paint off the substrate. Most times dry scraping is prohibited, but sanding or scraping can be done in conjunction with engineering controls to reduce airborne and settled lead dust. Power tools used to remove the paint must be equipped with a HEPA filtered shroud. Wetting a surface and hand scraping is also permitted. The components most often chosen for hand scraping are window and door jambs. Power tools are better equipped to handle lager surface areas.

Chemical stripping in-place uses strong chemicals to soften the paint for easier removal from the substrate. The chemicals are either very acidic or very basic, so proper training and protection for the worker is imperative. Generally, the chemicals must remain in- place overnight, so maintaining a secure worksite separate from occupants is mandatory.

Off site facilities use much stronger chemicals to remove the lead-based paint from the component. Components often chosen for off-site paint removal are intricate metal pieces. Sometimes this method is used for intricate wood work, but the stronger chemicals soften the wood and can drive lead into the wood while removing the paint.

#### Abatement to Control Lead-Based Paint Hazards

#### **Enclosure**

Enclosure is the option of sealing off the lead-based painted component by sealing it in with another building material. Such materials would include, but are not limited to; sheet rock, paneling, vinyl or aluminum siding and radiator covers, etc. Enclosure is not a permanent solution; and, if the enclosure material ever becomes disturbed, the lead-based paint is exposed. Depending on the building material used for enclosure, this can be an affordable option. Depending on the enclosure option taken it is possible that no lead abatement procedures need to be followed; but, of course, consult a professional before beginning.

#### **Encapsulation**

Encapsulation is the process of using an encapsulant-type of product that is applied over the lead-painted component. There are currently many different types of encapsulants on the market, and they come in many different forms. Some encapsulants are like stucco, some are like a two-part epoxy, some are like a heavy latex paint, and some are like a cement or plaster. Different types of encapsulants have different life expectancies and some come in different colors. None of the encapsulants are guaranteed forever, although some do come with a life or 10 to 20 year guarantee. To be considered a true lead abatement method according to the American Society of Testing Materials (ASTM) the encapsulant must meet their longevity criteria of at a minimum twenty (20) years. This option is not a permanent solution; and if the encapsulant ever becomes disturbed, the lead-based paint is exposed. Encapsulation is typically the least expensive option and has currently been accepted at the federal level as a viable and affordable option for lead abatement or in-place management, assuming the encapsulant meets the ASTM requirements for encapsulants.

#### **Interim Control Options**

An In-Place Management program is an on going set of measures designed to temporarily reduce human exposure or possible exposure and accessibility to lead-based paint hazards. Such measures include specialized cleaning, repairs, maintenance, paint stabilization, painting, temporary containment, and management and resident education programs. Monitoring, conducted by owners, and reevaluations conducted by professionals, are integral elements of interim controls. Interim controls include dust removal; paint film stabilization; treatment of friction and impact surfaces; installation of soil coverings, such as grass or sod; ground covering plants so as not to allow for easy accessibility, and land-use controls

Unlike Abatement, Interim Controls are considered to be temporary repairs and are not to be used as permanent solutions to lead-based hazards. Interim controls strategies are a very effective and cost saving program to substantially reduce the potential for lead poisoning. However, interim controls programs will only work and prove effective if reevaluation is continually performed. Reevaluation is the combination of a visual assessment and collection of environmental samples by a certified risk assessor on an on-going basis to determine if a previously implemented lead-based hazard control measure is still effective and if the dwelling remains lead-safe.

LEW Environmental Services, LLC. strongly suggests that HEPA vacuuming and Lead-Specific Cleaning detergent/LEDIZOLV wash downs should continue on a routine basis and a continual visual inspection/assessment and sample collection should be performed at least every 1 to 3 years, or until the dust levels continually remain below actionable levels.

## **Procedures & Methodology**

#### **Location Conventions**

When reviewing Appendix A "Floor Plan" and Appendix B "Lead-Based Paint Evaluation Report", you will notice that the letters A, B, C, and D are used to identify the location of specific components. The key to correct orientation is the location of the "A" wall, which is depicted on the floor plan or in the Executive Summary. The "B" wall, "C" wall, and "D" wall run clockwise from the "A" wall. The Lead-Based Paint Evaluation Report lists this information under the "Wall" column. The "Location" column uses numbering of replicated components starting with "1" at left and continuing sequentially to right respectively to describe the location of the component while facing the wall identified.

## **Paint Testing**

#### X-Ray Fluorescence

X-Ray Fluorescence (XRF) paint testing is performed to detect the presence of lead on painted surfaces. The XRF instrument is state-of-the art equipment. XRF testing is usually the preferred method of testing, because it is non-destructive, quantitative and can be performed on the spot with acceptable accuracy. LEW Environmental Services, LLC. 's evaluators follow the manufacturer's suggested use and the Performance Characteristic Sheet of the XRF instrument being used. The results of the XRF testing are the basis for drawing conclusions and making recommendations in the report.

All LEW Environmental Services, LLC. 's evaluators follow 40 CFR 745 and the HUD Guidelines for testing lead using an XRF instrument. All federal, state and city regulations are followed when applicable. The evaluator will test one of each and every different type of testing combination (component) in each room being surveyed. Each XRF reading is assigned an exclusive sample reference number and a measurement that is stored in the instrument. Each sample reference number location is logged on the XRF instrument for future reference, testing location, and report generation. The above described testing format is followed unless otherwise not practical or if the evaluator's judgment decides to test in a different systematic approach.

The federal level for lead based paint testing is 1.0 <sup>mg</sup>/cm<sup>2</sup>. It should be noted that detected lead levels below current levels still could create lead dust or lead-contaminated soil hazards if the paint is turned into dust by abrasion, scraping, or sanding leading to possible elevated blood lead levels. Lead poisoning is a cumulative affect. Should a

child or an adult inhale or ingest sufficient quantities of low concentrations of leaded paint, dust, or soil, it will accumulate in the body's systems and could eventually cumulate to an elevated blood level of concern.

Any untested building components should be considered lead-based paint until tested.

#### Calibration Check Readings

In addition to the manufacturer's recommended warm up and quality control procedures, LEW Environmental Services, LLC. collects quality control readings as recommended in the HUD Guidelines. Quality control for XRF instrumentation instruments involves readings to check calibration.

For each XRF instrument, one set of XRF calibration check readings are recommended at least every four hours. The first is a set of three nominal-time or source decay corrected time XRF calibration check readings to be taken before the inspection begins for the day. The second occurs either after the day's inspection work has been completed, or at least every four hours, whichever occurs first. LEW Environmental Services, LLC. 's XRF calibration check readings are taken on the Standard Reference Material (SRM) paint film nearest to 1.0 mg/cm² within the National Institute of Standards and Technology (NIST) SRM Used or the XRF manufacturer's factory supplied SRM film. Three readings are collected on the SRM. The average of the three readings on the SRM must be within the acceptable plus and minus tolerances for proper calibration as detailed in the Performance Characteristic Sheet (PCS). All calibration checks are taken with the SRM film positioned at least several inches away from any potential source of lead.

Three readings are taken each time calibration check readings are made, The readings are taken using the nominal time that is specified in the Performance Characteristic Sheet. The average of the readings are compared to the known value and if the average value is within the acceptable calibration check tolerance specified in the XRF Performance Characteristic Sheet the instrument is considered in control. If the average readings are not within the calibration check tolerance the instrument is not used until the instrument is brought back into control.

#### **Paint Chips**

Paint chips are taken for confirmation of lead based paint, or as a solution to inconclusive measurement recorded by the use of XRF testing. Paint chips are typically not taken unless absolutely necessary. On components that are right on the XRF action level, a paint chip is the only other way to get a conclusive determination as to the level of lead in the paint and if the component should be considered as actionable or not. Paint chips, when taken, are usually taken from an inconspicuous areas and tape and/or paint is placed over the removed paint location.

When the inspector collects paint-chip samples for analysis, they are analyzed by a laboratory recognized under the EPA's National Lead Laboratory Accreditation Program (NLLAP). Paint-chip samples contain all layers of paint (not just peeled layers) and must always include the bottom layer. If results will be reported in mg/cm², including a small amount of substrate with the sample will not significantly bias results. Substrate material should not, however, be included in samples reported in weight percent. Paint from 4 square inches (25 square centimeters) should provide a sufficient quantity for laboratory analysis. Smaller surface areas may be used, if the laboratory indicates that a smaller sample is acceptable.

Current action levels for lead in paint:

ourront dottor for too for found in paint.		_
PAINT CHIP ACTION LEVELS BY PER	CENT WEIGHT 0.5% (	OR 5000 parts per million
PAINT CHIP ACTION LEVELS BY WEI	GHT PER AREA Same	as XRF action levels, may be state dependent

Appendix A


Floor Plan



"The Environmental Company"

181 Route 46 Mine Hill, NJ 07803 (908)654-8068 (800)783-0567 Fax (908)654-8069 www.lewcorp.com

Site: 197 Hale St



Appendix B Lead-Based Paint Evaluation Report

Company **LEW Corporation** XRF Make Heuresis Pb200i Model 2823 Serial Num. Lead concentration units: mg/cm2 Total Readings: 147 **Action Level** 1 **Action Level** Mode Analytic Mode Paint

# **All Readings**

Job Id	Reading #	Concentration	Recult	Calibration	n RTA Present	Date I	ime	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall Location
12141131	11096	1	Nesuit	TRUE	FALSE	12/14/2023			,	197 Hale St New Brunswick NJ	Aica	Office #	Noon	Structure	Wiellibei	Jubstrate	VVaii Location
12141131	11097	1		TRUE	FALSE			mark franz		197 Hale St New Brunswick NJ							
12141131	11098	1		TRUE	FALSE	· · ·		mark franz		197 Hale St New Brunswick NJ							
12141131	11099	0.1		TRUE	FALSE			mark franz		197 Hale St New Brunswick NJ							
12141131	11100	0		TRUE	FALSE			mark franz		197 Hale St New Brunswick NJ							
12141131	11101	-0.1		TRUE	FALSE	12/14/2023				197 Hale St New Brunswick NJ							
						, ,											
12141131	11102	0.2	Negative	FALSE	FALSE	12/14/2023	12:04 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Living Room/Dining Room	Door		Metal	A 1
12141131	11103		Negative	FALSE	FALSE			mark franz		197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Living Room/Dining Room	Door	Casing	Wood	A 1
12141131	11104		Negative	FALSE	FALSE	12/14/2023	12:05 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Living Room/Dining Room	Baseboard	N/A	Wood	A 1
12141131	11105	0.2	Negative	FALSE	FALSE	12/14/2023	12:05 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Living Room/Dining Room	Window	Casing	Wood	A 1
12141131	11106		Negative	FALSE	FALSE	12/14/2023	12:05 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Living Room/Dining Room	Window	Frame	Wood	A 1
12141131	11107	0.1	Negative	FALSE	FALSE	12/14/2023	12:05 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Living Room/Dining Room	Stair	Baseboard	Wood	B 1
12141131	11108	0.2	Negative	FALSE	FALSE	12/14/2023	12:05 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Living Room/Dining Room	Stair	Newel Post	Wood	B 1
12141131	11109	-0.2	Negative	FALSE	FALSE	12/14/2023	12:05 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Living Room/Dining Room	Stair	Rail Cap	Wood	B 1
12141131	11110	0.1	Negative	FALSE	FALSE	12/14/2023	12:05 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Living Room/Dining Room	Stair	Hand Rail	Wood	B 1
12141131	11111	0.1	Negative	FALSE	FALSE	12/14/2023	12:06 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Living Room/Dining Room		N/A	Drywall	B 1
12141131	11112	0.2	Negative	FALSE	FALSE	12/14/2023		mark franz		197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Living Room/Dining Room		N/A	Drywall	B 1
12141131	11113	0.1	Negative	FALSE	FALSE			mark franz		197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Living Room/Dining Room		N/A	Drywall	A 1
12141131	11114	0.2	Negative	FALSE	FALSE			mark franz		197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Living Room/Dining Room		N/A	Drywall	D 1
12141131	11115		Negative	FALSE	FALSE			mark franz		197 Hale St New Brunswick NJ	_	197 Hale St New Brunswick NJ	Living Room/Dining Room		N/A	Drywall	C 1
12141131	11116		Negative	FALSE	FALSE			mark franz		197 Hale St New Brunswick NJ	_	197 Hale St New Brunswick NJ	Living Room/Dining Room	Register	N/A	Metal	D 1
12141131	11117		Negative	FALSE	FALSE	12/14/2023		mark franz		197 Hale St New Brunswick NJ	_	197 Hale St New Brunswick NJ	Living Room/Dining Room	Door		Wood	A 1
12141131	11118		Negative	FALSE	FALSE			mark franz		197 Hale St New Brunswick NJ	_	197 Hale St New Brunswick NJ	Living Room/Dining Room	Door	Casing	Wood	A 1
12141131	11119		Negative	FALSE	FALSE			mark franz		197 Hale St New Brunswick NJ	_	197 Hale St New Brunswick NJ	Living Room/Dining Room	Door	Jamb	Wood	A 1
12141131	11120		Negative	FALSE	FALSE	12/14/2023				197 Hale St New Brunswick NJ	_	197 Hale St New Brunswick NJ	Living Room/Dining Room	Cabinets	Frame	Wood	B 1
12141131			Negative	FALSE	FALSE			mark franz			_		Living Room/Dining Room		Door	Wood	B 1
12141131			Negative	FALSE	FALSE			mark franz		197 Hale St New Brunswick NJ	_	197 Hale St New Brunswick NJ	Kitchen	Door		Metal	B 1
12141131	11123		Negative	FALSE	FALSE			mark franz		197 Hale St New Brunswick NJ	_	197 Hale St New Brunswick NJ	Kitchen	Door	Casing	Wood	B 1
12141131	11124		Negative	FALSE	FALSE	, ,		mark franz		197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Kitchen		N/A	Wood	B 1
12141131	11125		Negative	FALSE	FALSE	· · ·		mark franz		197 Hale St New Brunswick NJ	_	197 Hale St New Brunswick NJ	Kitchen	Window	Frame	Wood	
12141131 12141131	11126 11127		Negative	FALSE FALSE	FALSE FALSE			mark franz mark franz		197 Hale St New Brunswick NJ 197 Hale St New Brunswick NJ	_	197 Hale St New Brunswick NJ 197 Hale St New Brunswick NJ	Kitchen Kitchen	Window Cabinets	Casing Frame	Wood Wood	
12141131	11127		Negative Negative	FALSE	FALSE			mark franz		197 Hale St New Brunswick NJ	_	197 Hale St New Brunswick NJ	Kitchen		Door	Wood	
12141131	11128		Negative	FALSE	FALSE			mark franz		197 Hale St New Brunswick NJ	_	197 Hale St New Brunswick NJ	Kitchen		N/A	Drywall	
12141131	11130		Negative	FALSE	FALSE			mark franz		197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Kitchen		N/A	Drywall	$\frac{1}{\Delta}$ 1
12141131	11131		Negative	FALSE	FALSE			mark franz		197 Hale St New Brunswick NJ	_	197 Hale St New Brunswick NJ	Kitchen		N/A	Drywall	B 1
12141131	11132		Negative	FALSE	FALSE			mark franz		197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Kitchen		N/A	Metal	B 1
12141131	11133		Negative	FALSE	FALSE			mark franz		197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Bathroom 2	Door		Wood	B 1
12141131	11134		Negative	FALSE	FALSE			mark franz		197 Hale St New Brunswick NJ	_	197 Hale St New Brunswick NJ	Bathroom 2	Door	Casing	Wood	B 1
12141131	11135		Negative	FALSE	FALSE			mark franz		197 Hale St New Brunswick NJ	+	197 Hale St New Brunswick NJ	Bathroom 2	Door	Jamb	Wood	B 1
12141131	11136		Negative	FALSE	FALSE		12:11 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Bathroom 2	Baseboard	N/A	Wood	B 1
12141131	11137		Negative	FALSE	FALSE			mark franz		197 Hale St New Brunswick NJ	_	197 Hale St New Brunswick NJ	Bathroom 2	Cabinets	Frame	Wood	C 1
12141131	11138	0.2	Negative	FALSE	FALSE	12/14/2023	12:11 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Bathroom 2	Cabinets	Door	Wood	C 1
12141131	11139	0.1	Negative	FALSE	FALSE	12/14/2023	12:11 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Bathroom 2	Wall	N/A	Drywall	C 1
12141131	11140	-0.1	Negative	FALSE	FALSE	12/14/2023	12:11 PM	mark franz	Paint	197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Bathroom 2		N/A	Drywall	B 1
12141131	11141		Negative	FALSE	FALSE	12/14/2023				197 Hale St New Brunswick NJ	_	197 Hale St New Brunswick NJ	Bathroom 2		N/A	Drywall	A 1
12141131	11142		Negative	FALSE	FALSE			mark franz		197 Hale St New Brunswick NJ	_	197 Hale St New Brunswick NJ	Bathroom 2		N/A	Drywall	D 1
12141131	11143		Negative	FALSE	FALSE			mark franz		197 Hale St New Brunswick NJ	+	197 Hale St New Brunswick NJ	Bathroom 2	_	N/A	Drywall	D 1
12141131	11144		Negative	FALSE	FALSE			mark franz		197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Bathroom 2		N/A	Metal	A 1
12141131	11145		Negative	FALSE	FALSE			mark franz		197 Hale St New Brunswick NJ	_	197 Hale St New Brunswick NJ	Kitchen		N/A	Drywall	A 1
12141131	11146		Negative	FALSE	FALSE			mark franz		197 Hale St New Brunswick NJ	_	197 Hale St New Brunswick NJ	Bedroom 1	Door		Wood	B 1
12141131	11147		Negative	FALSE	FALSE			mark franz		197 Hale St New Brunswick NJ	_	197 Hale St New Brunswick NJ	Bedroom 1	Door	Casing	Wood	B
12141131			Negative	FALSE	FALSE	12/14/2023				197 Hale St New Brunswick NJ	+	197 Hale St New Brunswick NJ	Bedroom 1		Jamb	Wood	B
12141131			Negative		FALSE	12/14/2023					_	197 Hale St New Brunswick NJ	Bedroom 1		N/A	Wood	B
12141131			Negative	FALSE	FALSE			mark franz			_	197 Hale St New Brunswick NJ	Bedroom 1		Frame	Wood	1 און
12141131			Negative	FALSE	FALSE	12/14/2023							Bedroom 1	Window	Casing	Wood	1 1
12141131	11152		Negative		FALSE			mark franz		197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Bedroom 1		N/A	Metal	
12141131 12141131	11153 11154		Negative		FALSE FALSE	12/14/2023 12/14/2023					_	197 Hale St New Brunswick NJ 197 Hale St New Brunswick NJ	Bedroom 1		Door Casing	Wood Wood	
12141131			Negative Negative		FALSE			mark franz				197 Hale St New Brunswick NJ	Bedroom 1 Bedroom 1	Closet Closet	Jamb	Wood	
12141151	11122	0.1	Inckative	FALSE	FALSE	14/2023	14.14 PIV	Imark HallZ	li anit	13/ Hale St New DIVIISMICK INJ	Joint	TENT TIGIE SUIVEW DIVILISMICK INJ	Dealoom I	Cioset	וימוווט	Ivvoou	10 1

Job Id	Reading #	Concentration Result	Calibration	RTA Present	Date Time User Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	e Wall Location
12141131	11156	0.1 Negative	FALSE	FALSE	12/14/2023 12:14 PM mark franz Paint	197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Bedroom 1	Closet	Shelf	Wood	C 1
12141131	11157	0.2 Negative	FALSE	FALSE	12/14/2023 12:14 PM mark franz Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Bedroom 1	Closet	Shelf Support	Wood	C 1
12141131	11158	0.2 Negative	FALSE	FALSE	12/14/2023 12:14 PM mark franz Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Bedroom 1	Closet	Wall	Drywall	C 1
12141131	11159	0 Negative	FALSE	FALSE	12/14/2023 12:14 PM mark franz Paint	197 Hale St New Brunswick NJ	1	197 Hale St New Brunswick NJ	Bedroom 1	Wall	N/A	Drywall	C 1
12141131	11160	0.2 Negative	FALSE	FALSE	12/14/2023 12:15 PM mark franz Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Bedroom 1	Wall	N/A	Drywall	D 1
12141131	11161	0.1 Negative	FALSE	FALSE	12/14/2023 12:15 PM mark franz Paint	197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Bedroom 1	Wall	N/A	Drywall	A 1
12141131 12141131	11162 11163	0.2 Negative 0.1 Negative	FALSE FALSE	FALSE FALSE	12/14/2023 12:15 PM mark franz Paint 12/14/2023 12:15 PM mark franz Paint	197 Hale St New Brunswick NJ 197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ 197 Hale St New Brunswick NJ	Bedroom 1 Bedroom 1	Wall Ceiling	N/A N/A	Drywall Drywall	B 1
12141131	11164	-0.1 Negative	FALSE	FALSE	12/14/2023 12:13 PM   mark franz   Paint   12/14/2023   12:18 PM   mark franz   Paint	197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	2nd Floor Hallway	Door	IV/A	Wood	C 1
12141131	11165	0.2 Negative	FALSE	FALSE	12/14/2023 12:19 PM mark franz Paint	197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	2nd Floor Hallway	Door	Casing	Wood	C 1
12141131	11166	0.1 Negative	FALSE	FALSE	12/14/2023 12:19 PM mark franz Paint	197 Hale St New Brunswick NJ	-	197 Hale St New Brunswick NJ	2nd Floor Hallway	Door	Jamb	Wood	C 1
12141131	11167	0.1 Negative	FALSE	FALSE	12/14/2023 12:19 PM mark franz Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	2nd Floor Hallway	Baseboard	N/A	Wood	C 1
12141131	11168	0.1 Negative	FALSE	FALSE	12/14/2023 12:19 PM mark franz Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	2nd Floor Hallway	Knee Wall	N/A	Wood	A 1
12141131	11169	0.2 Negative	FALSE	FALSE	12/14/2023 12:20 PM mark franz Paint	197 Hale St New Brunswick NJ	-	197 Hale St New Brunswick NJ	2nd Floor Hallway	Baseboard	N/A	Wood	B 1
12141131	11170	0.2 Negative	FALSE	FALSE	12/14/2023 12:20 PM mark franz Paint	197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	2nd Floor Hallway	Ceiling	N/A	Drywall	B 1
12141131	11171	0.3 Negative	FALSE	FALSE	12/14/2023 12:20 PM mark franz Paint	197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	2nd Floor Hallway	Wall	N/A N/A	Drywall	B 1
12141131 12141131	11172 11173	0.3 Negative 0.2 Negative	FALSE FALSE	FALSE FALSE	12/14/2023 12:20 PM mark franz Paint 12/14/2023 12:21 PM mark franz Paint	197 Hale St New Brunswick NJ 197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ 197 Hale St New Brunswick NJ	2nd Floor Hallway 2nd Floor Hallway	Wall Wall	N/A	Drywall Drywall	D 1
12141131	11174	0.1 Negative	FALSE	FALSE	12/14/2023 12:21 PM mark franz Paint	197 Hale St New Brunswick NJ	-	197 Hale St New Brunswick NJ	2nd Floor Hallway	Wall	N/A	Drywall	A 1
12141131	11175	0.3 Negative	FALSE	FALSE	12/14/2023 12:21 PM mark franz Paint	197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	2nd Floor Hallway	Access	Door	Wood	A 1
12141131	11176	0.1 Negative	FALSE	FALSE	12/14/2023 12:21 PM mark franz Paint	197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	2nd Floor Hallway	Access	Trim	Wood	A 1
12141131	11177	0 Negative	FALSE	FALSE	12/14/2023 12:21 PM mark franz Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	2nd Floor Hallway	Radiator	N/A	Metal	B 1
12141131	11178	0.1 Negative	FALSE	FALSE	12/14/2023 12:24 PM mark franz Paint	197 Hale St New Brunswick NJ	-	197 Hale St New Brunswick NJ	Bedroom 2	Door		Wood	A 1
12141131	11179	0.1 Negative	FALSE	FALSE	12/14/2023 12:25 PM mark franz Paint	197 Hale St New Brunswick NJ			Bedroom 2	Door	Casing	Wood	A 1
12141131	11180	0.2 Negative	FALSE	FALSE	12/14/2023 12:25 PM mark franz Paint	197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Bedroom 2	Door	Jamb	Wood	$\begin{vmatrix} A & 1 \\ A & 1 \end{vmatrix}$
12141131 12141131	11181 11182	0 Negative 0 Negative	FALSE FALSE	FALSE FALSE	12/14/2023 12:25 PM mark franz Paint 12/14/2023 12:25 PM mark franz Paint	197 Hale St New Brunswick NJ 197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ 197 Hale St New Brunswick NJ	Bedroom 2 Bedroom 2	Baseboard Closet	N/A Door	Wood Wood	$\begin{vmatrix} A & 1 \\ B & 1 \end{vmatrix}$
12141131	11183	0 Negative	FALSE	FALSE	12/14/2023 12:25 PM mark franz Paint	197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Bedroom 2	Closet	Casing	Wood	B 1
12141131	11184	0.2 Negative	FALSE	FALSE	12/14/2023 12:25 PM mark franz Paint	197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Bedroom 2	Closet	Jamb	Wood	B 1
12141131	11185	0.1 Negative		FALSE	12/14/2023 12:25 PM mark franz Paint	197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Bedroom 2		Shelf	Wood	B 1
12141131	11186	-0.1 Negative	FALSE	FALSE	12/14/2023 12:26 PM mark franz Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Bedroom 2	Closet	Shelf Support	Wood	B 1
12141131	11187	0.1 Negative	FALSE	FALSE	12/14/2023 12:26 PM mark franz Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Bedroom 2	Closet	Wall	Drywall	B 1
12141131	11188	0.1 Negative	FALSE	FALSE	12/14/2023 12:26 PM mark franz Paint	197 Hale St New Brunswick NJ	-	197 Hale St New Brunswick NJ	Bedroom 2		Sash	Wood	C 1
12141131	11189	0.2 Negative	FALSE	FALSE	12/14/2023 12:26 PM mark franz Paint	197 Hale St New Brunswick NJ	-	197 Hale St New Brunswick NJ	Bedroom 2	Wall	N/A	Drywall	C 1
12141131	11190	0 Negative	FALSE	FALSE	12/14/2023 12:27 PM mark franz Paint	197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Bedroom 2	Wall	N/A	Drywall	D 1
12141131 12141131	11191 11192	0 Negative	FALSE FALSE	FALSE FALSE	12/14/2023 12:27 PM mark franz Paint 12/14/2023 12:27 PM mark franz Paint	197 Hale St New Brunswick NJ 197 Hale St New Brunswick NJ	-	197 Hale St New Brunswick NJ 197 Hale St New Brunswick NJ	Bedroom 2 Bedroom 2	Wall Wall	N/A N/A	Drywall Drywall	A 1
12141131	11192	0.1 Negative 0 Negative	FALSE	FALSE	12/14/2023 12:27 PM mark franz Paint	197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Bedroom 2	Ceiling	N/A	Drywall	B 1
12141131	11194	0 Negative	FALSE	FALSE	12/14/2023 12:27 PM mark franz Paint	197 Hale St New Brunswick NJ	-	197 Hale St New Brunswick NJ	Bedroom 2	Register	N/A	Metal	B 1
12141131	11195	0.1 Negative	FALSE	FALSE	12/14/2023 12:28 PM mark franz Paint	197 Hale St New Brunswick NJ	-	197 Hale St New Brunswick NJ	Bedroom 3	Door		Wood	A 1
12141131	11196	0.2 Negative	FALSE	FALSE	12/14/2023 12:28 PM mark franz Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Bedroom 3	Door	Casing	Wood	A 1
12141131	11197	0.2 Negative	FALSE	FALSE	12/14/2023 12:28 PM mark franz Paint	197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Bedroom 3	Door	Jamb	Wood	A 1
12141131	11198	0 Negative	FALSE	FALSE	12/14/2023 12:28 PM mark franz Paint	197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Bedroom 3	Baseboard	N/A	Wood	A 1
12141131	11199	0 Negative	FALSE	FALSE	12/14/2023 12:28 PM mark franz Paint	197 Hale St New Brunswick NJ	-	197 Hale St New Brunswick NJ	Bedroom 3	Closet	Door	Wood	B 1
12141131 12141131	11200 11201	0.1 Negative 0.1 Negative	FALSE FALSE	FALSE FALSE	12/14/2023 12:28 PM mark franz Paint 12/14/2023 12:29 PM mark franz Paint	197 Hale St New Brunswick NJ 197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ 197 Hale St New Brunswick NJ	Bedroom 3 Bedroom 3	Closet Closet	Casing Jamb	Wood Wood	B 1
12141131	11201	0.1 Negative	FALSE	FALSE	12/14/2023 12:29 PM mark franz Paint	197 Hale St New Brunswick NJ	-	197 Hale St New Brunswick NJ	Bedroom 3	Closet	Shelf	Wood	B 1
12141131	11203	0.1 Negative	FALSE	FALSE	12/14/2023 12:29 PM mark franz Paint	197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Bedroom 3	Closet		Wood	B 1
12141131	11204	0.1 Negative	FALSE	FALSE	12/14/2023 12:29 PM mark franz Paint	197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Bedroom 3	Closet	Wall	Drywall	B 1
12141131	11205	0.1 Negative	FALSE	FALSE	12/14/2023 12:29 PM mark franz Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Bedroom 3	Wall	N/A	Drywall	B 1
12141131	11206	0.1 Negative	FALSE	FALSE	12/14/2023 12:29 PM mark franz Paint	197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Bedroom 3	Wall	N/A	Drywall	C 1
12141131	11207	0.1 Negative	FALSE	FALSE	12/14/2023 12:30 PM mark franz Paint	197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Bedroom 3	Wall	N/A	Drywall	$D \qquad 1$
12141131	11208	0.1 Negative		FALSE	12/14/2023 12:30 PM mark franz Paint	197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Bedroom 3	Wall	N/A	Drywall	$A \rightarrow 1$
12141131 12141131	11209 11210	0.1 Negative 0.1 Negative		FALSE FALSE	12/14/2023 12:31 PM mark franz Paint 12/14/2023 12:31 PM mark franz Paint	197 Hale St New Brunswick NJ 197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Bedroom 3 Bedroom 3	Ceiling Register	N/A N/A	Drywall Metal	$\frac{ A }{ D }$
12141131	11211	0.1 Negative		FALSE	12/14/2023 12:31 PM mark franz Paint			197 Hale St New Brunswick NJ	Bathroom 2	Door		Metal	B 1
12141131	11212	0.3 Negative		FALSE	12/14/2023 12:32 PM mark franz Paint		-	197 Hale St New Brunswick NJ	Bathroom 2	Door	Casing	Metal	B 1
12141131	11213	0.1 Negative		FALSE	12/14/2023 12:32 PM mark franz Paint			197 Hale St New Brunswick NJ		Door	Jamb	Metal	B 1
12141131		0.1 Negative		FALSE	· · ·			197 Hale St New Brunswick NJ	Bathroom 2	Baseboard	N/A	Wood	A 1
12141131	11215	-0.1 Negative		FALSE	12/14/2023 12:32 PM mark franz Paint			197 Hale St New Brunswick NJ	Bathroom 2	Cabinets	Frame	Wood	C 1
12141131	11216	0 Negative		FALSE	12/14/2023 12:32 PM mark franz Paint	197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Bathroom 2	Cabinets	Door	Wood	$\frac{ C }{ C }$
12141131 12141131	11217	0.2 Negative		FALSE FALSE	12/14/2023 12:33 PM mark franz Paint			197 Hale St New Brunswick NJ	Bathroom 2	Register Ceiling	N/A N/A	Metal	B
12141131	11218 11219	0.1 Negative 0.1 Negative		FALSE	12/14/2023 12:33 PM mark franz Paint 12/14/2023 12:33 PM mark franz Paint	197 Hale St New Brunswick NJ 197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ 197 Hale St New Brunswick NJ	Bathroom 2 Bathroom 2	Wall	N/A N/A	Drywall Drywall	D
12141131	11219	0.1 Negative		FALSE	<del>                                     </del>			197 Hale St New Brunswick NJ	Bathroom 2	Wall	N/A	Drywall	$\frac{1}{C}$
12141131	11221	0.1 Negative		FALSE		197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Bathroom 2	Wall		Drywall	A 1
12141131	11222	-0.1 Negative		FALSE	12/14/2023 12:33 PM mark franz Paint	197 Hale St New Brunswick NJ		197 Hale St New Brunswick NJ	Bedroom 4	Door		Wood	C 1
12141131	11223	0.2 Negative	FALSE	FALSE	12/14/2023 12:34 PM mark franz Paint		<b>!</b>	197 Hale St New Brunswick NJ	Bedroom 4	Door	Casing	Wood	C 1
12141131	11224	0.2 Negative		FALSE	···			197 Hale St New Brunswick NJ	Bedroom 4	Door	Jamb	Wood	C 1
12141131	11225	0.1 Negative	i	FALSE	12/14/2023 12:34 PM mark franz Paint		_		Bedroom 4	Baseboard	N/A	Wood	$\frac{ C }{ C }$
12141131	11226	0 Negative	FALSE	FALSE	12/14/2023   12:34 PM   mark franz   Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Bedroom 4	Closet	Casing	Wood	<u> B   1</u>

Job Id	Reading #	Concentration R	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
12141131	11227	0 N	legative	FALSE	FALSE	12/14/2023	12:34 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Bedroom 4	Closet	Jamb	Wood	В	1
12141131	11228	0.1 N	legative	FALSE	FALSE	12/14/2023	12:34 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Bedroom 4	Closet	Shelf	Wood	В	1
12141131	11229	0 N	legative	FALSE	FALSE	12/14/2023	12:34 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Bedroom 4	Closet	Shelf Support	Wood	В	1
12141131	11230	0.1 N	legative	FALSE	FALSE	12/14/2023	12:34 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Bedroom 4	Closet	Wall	Drywall	В	1
12141131	11231	0.2 N	legative	FALSE	FALSE	12/14/2023	12:35 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Bedroom 4		N/A	Drywall	В	1
12141131	11232	0.2 N	legative	FALSE	FALSE	12/14/2023	12:35 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Bedroom 4	Wall	N/A	Drywall	Α	1
12141131	11233	0.1 N	legative	FALSE	FALSE	12/14/2023	12:35 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Bedroom 4	Wall	N/A	Drywall	D	1
12141131	11234	0.2 N	legative	FALSE	FALSE	12/14/2023	12:35 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Bedroom 4	Wall	N/A	Drywall	C	1
12141131	11235	0.1 N	legative	FALSE	FALSE	12/14/2023	12:35 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Bedroom 4	Ceiling	N/A	Drywall	С	1
12141131	11236	0.2 N	legative	FALSE	FALSE	12/14/2023	12:35 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Bedroom 4	Register	N/A	Metal	С	1
12141131	11237	0.2 N	legative	FALSE	FALSE	12/14/2023	12:36 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Basement	Door		Wood	С	1
12141131	11238	0.2 N	legative	FALSE	FALSE	12/14/2023	12:36 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Basement	Door	Jamb	Wood	С	1
12141131	11239	0.2 N	legative	FALSE	FALSE	12/14/2023	12:37 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Basement	Wall	Upper	Drywall	С	1
12141131	11240	0 N	legative	FALSE	FALSE	12/14/2023	12:37 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Basement	Wall	Upper	Drywall	В	1
12141131	11241	0.2 N	legative	FALSE	FALSE	12/14/2023	12:37 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Basement	Wall	Upper	Drywall	Α	1
12141131	11242	0 N	legative	FALSE	FALSE	12/14/2023	12:37 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Basement	Wall	Upper	Drywall	D	1
12141131	11243	0.1 N	legative	FALSE	FALSE	12/14/2023	12:37 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Basement	Ceiling	N/A	Drywall	D	1
12141131	11244	0.5 N	legative	FALSE	FALSE	12/14/2023	12:38 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Basement	Wall	Lower	Concrete	В	1
12141131	11245	0.1 N	legative	FALSE	FALSE	12/14/2023	12:38 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Basement	Wall	Lower	Concrete	Α	1
12141131	11246	0.1 N	legative	FALSE	FALSE	12/14/2023	12:38 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Basement	Wall	Lower	Concrete	D	1
12141131	11247	0.5 N	legative	FALSE	FALSE	12/14/2023	12:39 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Basement	Wall	Lower	Concrete	С	1
12141131	11248	0 N	legative	FALSE	FALSE	12/14/2023	12:39 PM	mark franz	Paint	197 Hale St New Brunswick NJ	Unit	197 Hale St New Brunswick NJ	Basement	Ceiling Beam	N/A	Wood	С	1
12141131	11249	1		TRUE	FALSE	12/14/2023		mark franz		197 Hale St New Brunswick NJ							$\Box$	
12141131	11250	1		TRUE	FALSE	12/14/2023		mark franz		197 Hale St New Brunswick NJ							$\Box$	
12141131	11251	1		TRUE	FALSE	12/14/2023		mark franz		197 Hale St New Brunswick NJ								
12141131	11252	0		TRUE	FALSE	12/14/2023		mark franz		197 Hale St New Brunswick NJ							$\Box$	
12141131	11253	-0.1		TRUE	FALSE	12/14/2023		mark franz		197 Hale St New Brunswick NJ							$\Box$	
12141131	11254	0		TRUE	FALSE	12/14/2023	1:29 PM	mark franz	Paint	197 Hale St New Brunswick NJ								

Company LEW Corporation
XRF Make Heuresis
Model Pb200i
Serial Num. 2823
Lead concentration units: mg/cm2

concentration units: mg/cm2 Actionables

0

Total Readings: 147 Total Positives
Action Level 1

Mode Action Level Analytic Mode Paint

Job Id	Reading #	Concentration Re	esult Cali	libration R	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area Unit #	Room	Structure	Member	Substrate Wall Location
	No Actionables														

Appendix C Lab Support Documents (if applicable)