

## **Visual Paint Assesment Report**

For 626 Hillside Avenue Boonton Town, NJ 07005 06/09/2024

On 06/07/24, LEW Environmental Services, LLC (NJDCA 00015 E) performed a visual paint condition assessment for the presence of deteriorated paint, chips or dust from painting activities and paint residue on floors at 626 Hillside Avenue, (the "property") in compliance with NJAC 5:28A. Only the dwelling and common area interiors were included. Exteriors were not part of the assessment. The visual assessment followed the protocols found in HUD's Visual Assessment Training course.

Deteriorated paint, chips or dust from painting activities and paint residue on floors were observed on the following components/surfaces.

Room	Component	Hazard
Bedroom 1	Window Track	Deteriorated Paint
Living Room	Door	Deteriorated Paint
Basement	Steps	Deteriorated Paint
Basement	Steps	Dust

Identified hazards shall be remediated using either abatement (permanent) or interim controls (temporary). Abatement is permanent but has a higher cost, as Interim controls are temporary but can be much more affordable. Abatement shall be performed by a NJ Licensed lead abatement firm using licensed lead abatement supervisors and workers. You can find the list of NJ licensed lead abatement contractors at https://www.nj.gov/dca/divisions/codes/publications/pdf\_lead/ld\_abat\_c.pdf. Interim control work shall be performed by EPA RRP certified firms using an EPA certified RRP Renovator. You can find certified EPA RRP contractors at


https://cdxappstest.epacdx.net/ocspp-oppt-leadhub/firm-location-search. Select RRP Contractor, then NJ, then enter your zip code to search for contractors. After completion of interim control work, a lead-based paint post-remediation with dust wipes will be required. After completion of abatement work, a lead-based paint abatement clearance will be required.

Respectfully Submitted,

Oric Hashington


Gloria Washington NJDOH Risk Assessor, ID#040601 Encl: Floor Plan, Photographs;

## Floor Plan(s)



Floor 1

Lew Environmental Services - 626 Hillside Avenue -Visual Inspection Prepared By: LEW Environmental Services, LLC 06/09/2024





Lew Environmental Services - 626 Hillside Avenue -Visual Inspection Prepared By: LEW Environmental Services, LLC 06/09/2024

## **Hazard Photos**



Hazard: Bedroom 1 | Window Track | Deteriorated Paint



Hazard: Basement | Steps | Deteriorated Paint



Hazard: Living Room | Door | Deteriorated Paint



Hazard: Basement | Steps | Dust



Hazard: ||

Lew Environmental Services - 626 Hillside Avenue -Visual Inspection Prepared By: LEW Environmental Services, LLC 06/09/2024