



## **Lead Dust Wipe Report**

For 753-755 Jackson Ave Unit:2 Elizabeth City, NJ 07067 11/26/2024

On 11/12/2024, LEW Environmental Services, LLC (NJDCA 00015 E) performed a dust wipe sampling for the presence of lead at 753-755 Jackson Ave Unit:2, (the "property") in compliance with NJAC 5:28A. We conducted our inspection in accordance with all federal, state, and municipal regulations. The regulations and inspection standards require that we plan and perform the inspection to obtain a reasonable assurance about whether or not the property is at risk from lead dust.

The maintenance and the environmental conditions of the property are the responsibility of the property's management, principals, or owners. If the property, program, or any of its tenants receive financial federal assistance, the results of this evaluation must be provided by the designated party (client) to the owner of the referenced property and the occupants within 15 calendar days of the date when the designated party receives this report or makes the presumption that lead-based paint hazards exist, per the Department of Housing and Urban Development 24 CFR Part 35.125.

The following surfaces are considered actionable for the lead dust.

Room	Component
Bedroom 3	Floors

Identified dust hazards shall be remediated by lead dust cleaning. Cleaning shall be performed by EPA RRP certified firms using an EPA certified RRP Renovator. You can find certified EPA RRP contractors at https://cdxapps.epa.gov/ocspp-oppt-lead/firm-location-search. Select RRP Contractor, then NJ, then enter your zip code to search for contractors. After completion of interim control work, a lead-based paint post-remediation with dust wipes will be required.

### **Lead Dust Hazard Standards**

Floors (Bare and Carpeted)......< 10 ug/ft2 Window Sill...... < 100 ug/ft2

Respectfully Submitted,

Pale 1/il

Pablo Viera

Risk Assesor, ID#D-I-T226395-24-00064 Encl: Laboratory Results, Floor Plan;



7469 Whitepine Rd North Chesterfield, VA 23237 Telephone: 800.347.4010

## Lead Dust Wipe Analysis Report

**Report Number:** 24-11-02839

**Received Date:** 11/15/2024 **Analyzed Date:** 11/20/2024

**Reported Date:** 11/20/2024

Client: LEW Corp

181 US Hwy 46 Mine Hill, NJ 07803

Project/Test Address: 122322; Josef Pirog; 753 Jackson Ave. Unit 2; Elizabeth, NJ

Collection Date: 11/12/2024

Client Number: 201327 Laboratory Results Fax Number: Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft²)	Concentration (ug/ft²)	Narrative ID
24-11-02839- 001	53-1	SUNROOM		<5.00	1.00	<5.00	
24-11-02839- 002	53-2	KITCHEN CC	FL	<5.00	1.00	<5.00	
24-11-02839- 003	53-3	LIVING ROOM CC	FL	<5.00	1.00	<5.00	
24-11-02839- 004	53-4	BEDROOM 2 CC	FL	<5.00	1.00	<5.00	
24-11-02839- 005	53-5	BEDROOM 3 BC	FL	<5.00	1.00	<5.00	
24-11-02839- 006	53-6	KITCHEN D1	SL	11.2	0.252	44.6	
24-11-02839- 007	53-7	LIVING ROOM A2	SL	<5.00	0.352	<14.3	
24-11-02839- 008	53-8	BEDROOM 2	SL	<5.00	0.247	<20.3	
24-11-02839- 009	53-9	BEDROOM 3	SL	30.1	0.252	119	

## Environmental Hazards Services, L.L.C

**Client Number:** 201327 **Report Number:** 24-11-02839

Project/Test Address: 122322; Josef Pirog; 753 Jackson Ave. Unit 2;

Elizabeth, NJ

Lab Sample Client Sample Collection Location Surface Total Pb Wipe Area Concentration Narrative Number (ug) (ft²) (ug/ft²) ID

**Method:** ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory:

Tasha Eaddy

Jaha Faddy

QA/QC Clerk

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft2 are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accrediitation through AIHA LAP, LLC (100420), NY ELAP #11714.

Legend ug = microgram  $ug/ft^2 = micrograms$  per square foot Pb = lead mL = milliliter  $ft^2 = square$  foot



# **ENVIRONMENTAL SERVICES**

LEW Environmental Services P: (800) 783-0567 A Mainline Company

F: (908) 654-8069

## 


## Chain-of-Custody

			·····	 7
AE	(Wednesday)	11/20/2024	Due Date:	24-11-02839
				8

Project Number: City, State: \_ Address:\_ Project Name: Elizaseth, NJ Unit 2 753 Jackson Ave Josef Piras 122322 Dust wipe
Paint chip
Soil
TCLP Sample Type ☐ 1 Week ☐ 1 Day ☐ Same Day Turn Around Time (JAT) 2 Weeks ☐ Weekend ☐3 Day Signature: fless seems Name: Pasio Viere \* All wipe: Sampler Information

ACTIVIDATE OF THE PROPERTY OF	200	87 87	Date/Time:	Signature: 48		Received by:
2	6130 pm		Date/Time: 11-12-24	Signature: Pour Vier		Relinquished by: Rylo Wera
			×			
			×			
			×			(
			29 × 11/4	Bedwar 3 Sill		1 4
			18/1 × 2/182	Bedram 2 Sill		8
			401/2 × 11/4	Living Boom Sill AZ		+
			29 × 1%	1		7
			×	Ged rown 3 Floor BG		5
			×	Bed Room 2 Floor CC		h-1
			×	Living Rown Floor CC		ال
			×	Kitchen Floor CC		2-
			12 × 12	SUN Poon	11-12-24	\$3-(
% wt	PPM	mg/cm²	(inches)	(Ex: Fl, Kitchen, AC)	ממים כטוומכינמט	
alysis	Paint Chip Analysis	Pain	Area	Sample Location	Data Collected	Sample #

## Floor Plan(s)



Floor 1

Lew Environmental Services - 753-755 Jackson Ave Unit:2 -Visual Inspection Prepared By: LEW Environmental Services, LLC 11/26/2024