



Lead Dust Wipe Report

For 101 Bullman Street Unit:2 FL Phillipsburg Town, NJ 08865 11/25/2024

On 11/11/2024, LEW Environmental Services, LLC (NJDCA 00015 E) performed a dust wipe sampling for the presence of lead at 101 Bullman Street Unit:2 FL, (the "property") in compliance with NJAC 5:28A. We conducted our inspection in accordance with all federal, state, and municipal regulations. The regulations and inspection standards require that we plan and perform the inspection to obtain a reasonable assurance about whether or not the property is at risk from lead dust.

The maintenance and the environmental conditions of the property are the responsibility of the property's management, principals, or owners. If the property, program, or any of its tenants receive financial federal assistance, the results of this evaluation must be provided by the designated party (client) to the owner of the referenced property and the occupants within 15 calendar days of the date when the designated party receives this report or makes the presumption that lead-based paint hazards exist, per the Department of Housing and Urban Development 24 CFR Part 35.125.

The following surfaces are considered actionable for the lead dust.

Room	Component				
Bedroom 1	Window Sills				

Identified dust hazards shall be remediated by lead dust cleaning. Cleaning shall be performed by EPA RRP certified firms using an EPA certified RRP Renovator. You can find certified EPA RRP contractors at https://cdxapps.epa.gov/ocspp-oppt-lead/firm-location-search. Select RRP Contractor, then NJ, then enter your zip code to search for contractors. After completion of interim control work, a lead-based paint post-remediation with dust wipes will be required.

Lead Dust Hazard Standards

Floors (Bare and Carpeted)......< 10 ug/ft2 Window Sill...... < 100 ug/ft2

Respectfully Submitted,

Yerani Heredia De Rosado

Gerani Heredia

NJDOH Risk Assessor, ID#R001913

Encl: Laboratory Results, Floor Plan;



7469 Whitepine Rd North Chesterfield, VA 23237 Telephone: 800.347.4010

Lead Dust Wipe Analysis Report

Report Number: 24-11-02334

Received Date: 11/13/2024

Analyzed Date: 11/15/2024 **Reported Date:** 11/18/2024

Client: LEW Corp

181 US Hwy 46 Mine Hill, NJ 07803

Project/Test Address: 83805; Lead Dust Sampling; 101 Bullman St 2nd Floor; Phillipsburg, NJ

Collection Date: 11/11/2024

Client Number: 201327 Laboratory Results Fax Number: Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft²)	Concentration (ug/ft²)	Narrative ID
24-11-02334- 001	1	SUNROOM AC	FL	<5.00	1.00	<5.00	
24-11-02334- 002	2	DINING ROOM AC	FL	<5.00	1.00	<5.00	
24-11-02334- 003	3	BATHROOM AC	FL	<5.00	1.00	<5.00	
24-11-02334- 004	4	LIVING ROOM AC	FL	<5.00	1.00	<5.00	
24-11-02334- 005	5	BEDROOM 1 AC	FL	<5.00	1.00	<5.00	
24-11-02334- 006	6	LIVING ROOM BC	SL	<5.00	0.646	<7.74	
24-11-02334- 007	7	BATHROOM DC	SL	<5.00	0.700	<7.15	
24-11-02334- 008	8	DINING ROOM BC	SL	<5.00	0.700	<7.15	
24-11-02334- 009	9	BEDROOM 1 AR	SL	192	0.700	274	

Environmental Hazards Services, L.L.C

Client Number: 201327 **Report Number:** 24-11-02334

Project/Test Address: 83805; Lead Dust Sampling; 101 Bullman St 2nd

Floor; Phillipsburg, NJ

Lab Sample Client Sample Collection Location Surface Total Pb Wipe Area Concentration Narrative Number (ug) (ft²) (ug/ft²) ID

Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory:

Melissa Kanode

Milisoa Kanode

QA/QC Clerk

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft2 are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accrediitation through AIHA LAP, LLC (100420), NY ELAP #11714.

Legend ug = microgram $ug/ft^2 = micrograms per square foot$ Pb = lead mL = milliliter $ft^2 = square foot$



ENVIRONMENTAL SERVICES

A Mainline Company
LEW Environmental Services P: (800) 783-0567

F: (908) 654-8069

Project Name: Lead Dust Smaling Address: 101 Bullman St. Zud

City, State: Phillips Lug

Sample Type

Dust wipe
Saint chip

Same Day

1 Day

Turn Around Time (TAT)

* All wipe \$

Æ

3 Day

Name:

Sampler Information

Weekend


Lead

Chain-of-Custody

(Monday)	11/18/2024	Due Date:	Γ, 24-11-02334
			MANAGERIA

Received by:	Relinquished by: Vol. Com			((5)		,	6	- ~	4	· W	2			Sample #	Project Number:
Signa	Aludia Signature:				+								+2-11-11		Date Collected	Drda 83805
Signature:	ture: /lam.				١٠ ١١ - ١	11 /2 · W	W-3500	W-Sin ((lar	The second	flow	that !	floor S			Soil
	: How dia				1 moone of 1	Way Diving Rom	Wall Bathrown	W-SIN GUING ROOM	Bldrom (Living Rom	Bathron	Diving Rom	Sun Rom	(Ex: Fl, Kitchen, AC)	Sample Location	1 Week
	9				AR	m 3 (d	₩ ^	A C	A AC	AC	a AC	40			2 Weeks
Date/Time: \\\\\\?\\\]	Date/Time: //-11-74	×	×	×	31 × 3/4	31 × 3/4	31 × 31/4	W/×	21 x21	21 × 2l	21 × 21	17 × 12	21 × 72 /	(inches)	Area	Signature:
5														mg/cm ²	Paint (
ر چ ر	8-9 an						-							PPM	Paint Chip Analysis	
	کر							eries de construir						% wt	sis	

Floor Plan(s)



Floor 1

Lew Environmental Services - 101 Bullman Street Unit:2 FL -Visual Inspection Prepared By: LEW Environmental Services, LLC 11/25/2024