

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 1831
 Lead concentration units: mg/cm2
 Total Readings: 222
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
11221216	14052	0.9		TRUE	FALSE	11/22/2024	12:17 PM	Paint	1126 North Ave								
11221216	14053	0.9		TRUE	FALSE	11/22/2024	12:17 PM	Paint	1126 North Ave								
11221216	14054	0.9		TRUE	FALSE	11/22/2024	12:17 PM	Paint	1126 North Ave								
11221216	14055	-0.2		TRUE	FALSE	11/22/2024	12:17 PM	Paint	1126 North Ave								
11221216	14056	-0.1		TRUE	FALSE	11/22/2024	12:17 PM	Paint	1126 North Ave								
11221216	14057	-0.1		TRUE	FALSE	11/22/2024	12:18 PM	Paint	1126 North Ave								
11221216	14058	0	Negative	FALSE	FALSE	11/22/2024	12:19 PM	Paint	1126 North Ave	Commons		Enclosed Porch	Door	---	Metal	A	1
11221216	14059	0	Negative	FALSE	FALSE	11/22/2024	12:20 PM	Paint	1126 North Ave	Commons		Enclosed Porch	Door	Sidelight	Metal	A	1
11221216	14060	-0.1	Negative	FALSE	FALSE	11/22/2024	12:20 PM	Paint	1126 North Ave	Commons		Enclosed Porch	Door	Casing	Wood	A	1
11221216	14061	-0.2	Negative	FALSE	FALSE	11/22/2024	12:20 PM	Paint	1126 North Ave	Commons		Enclosed Porch	Window	Sash	Wood	D	1
11221216	14062	-0.1	Negative	FALSE	FALSE	11/22/2024	12:20 PM	Paint	1126 North Ave	Commons		Enclosed Porch	Window	Jamb	Wood	D	1
11221216	14063	0	Negative	FALSE	FALSE	11/22/2024	12:21 PM	Paint	1126 North Ave	Commons		Enclosed Porch	Window	Casing	Wood	D	1
11221216	14064	-0.1	Negative	FALSE	FALSE	11/22/2024	12:21 PM	Paint	1126 North Ave	Commons		Enclosed Porch	Window	Sill	Wood	D	1
11221216	14065	0.1	Negative	FALSE	FALSE	11/22/2024	12:21 PM	Paint	1126 North Ave	Commons		Enclosed Porch	Door	---	Wood	C	1
11221216	14066	-0.1	Negative	FALSE	FALSE	11/22/2024	12:21 PM	Paint	1126 North Ave	Commons		Enclosed Porch	Door	Jamb	Wood	C	1
11221216	14067	-0.2	Negative	FALSE	FALSE	11/22/2024	12:21 PM	Paint	1126 North Ave	Commons		Enclosed Porch	Door	Casing	Wood	C	1
11221216	14068	0	Negative	FALSE	FALSE	11/22/2024	12:21 PM	Paint	1126 North Ave	Commons		Enclosed Porch	Door	Threshold	Wood	C	1
11221216	14069	1.1	Positive	FALSE	FALSE	11/22/2024	12:23 PM	Paint	1126 North Ave	Commons		Enclosed Porch	Room	Floor	Wood	B	1
11221216	14070	-0.2	Negative	FALSE	FALSE	11/22/2024	12:23 PM	Paint	1126 North Ave	Commons		Enclosed Porch	Room	Baseboard	Wood	B	1
11221216	14071	0.1	Negative	FALSE	FALSE	11/22/2024	12:24 PM	Paint	1126 North Ave	Commons		Enclosed Porch	Room	Wall	Wood	A	1
11221216	14072	0	Negative	FALSE	FALSE	11/22/2024	12:24 PM	Paint	1126 North Ave	Commons		Enclosed Porch	Room	Wall	Wood	B	1
11221216	14073	4.6	Positive	FALSE	FALSE	11/22/2024	12:24 PM	Paint	1126 North Ave	Commons		Enclosed Porch	Room	Wall	Wood	C	1
11221216	14074	0.1	Negative	FALSE	FALSE	11/22/2024	12:25 PM	Paint	1126 North Ave	Commons		Enclosed Porch	Room	Wall	Wood	D	1
11221216	14075	-0.1	Negative	FALSE	FALSE	11/22/2024	12:25 PM	Paint	1126 North Ave	Commons		Enclosed Porch	Room	Ceiling	Drywall	D	1
11221216	14076	-0.1	Negative	FALSE	FALSE	11/22/2024	12:27 PM	Paint	1126 North Ave	Commons		Foyer	Room	Ceiling	Drywall	A	1
11221216	14077	-0.2	Negative	FALSE	FALSE	11/22/2024	12:27 PM	Paint	1126 North Ave	Commons		Foyer	Room	Crown Molding	Wood	A	1
11221216	14078	-0.3	Negative	FALSE	FALSE	11/22/2024	12:28 PM	Paint	1126 North Ave	Commons		Foyer	Room	Baseboard	Wood	A	1
11221216	14079	-0.1	Negative	FALSE	FALSE	11/22/2024	12:28 PM	Paint	1126 North Ave	Commons		Foyer	Room	Wall	Wood	A	Lower
11221216	14080	-0.5	Negative	FALSE	FALSE	11/22/2024	12:28 PM	Paint	1126 North Ave	Commons		Foyer	Room	Wall	Drywall	A	Upper
11221216	14081	0.1	Negative	FALSE	FALSE	11/22/2024	12:28 PM	Paint	1126 North Ave	Commons		Foyer	Room	Wall	Drywall	B	Upper
11221216	14082	0	Negative	FALSE	FALSE	11/22/2024	12:29 PM	Paint	1126 North Ave	Commons		Foyer	Room	Wall	Wood	B	Lower
11221216	14083	-0.2	Negative	FALSE	FALSE	11/22/2024	12:29 PM	Paint	1126 North Ave	Commons		Foyer	Room	Wall	Wood	C	Lower
11221216	14084	-0.1	Negative	FALSE	FALSE	11/22/2024	12:29 PM	Paint	1126 North Ave	Commons		Foyer	Room	Wall	Drywall	C	Upper
11221216	14085	0	Negative	FALSE	FALSE	11/22/2024	12:30 PM	Paint	1126 North Ave	Commons		Foyer	Room	Wall	Drywall	D	Upper
11221216	14086	0	Negative	FALSE	FALSE	11/22/2024	12:30 PM	Paint	1126 North Ave	Commons		Foyer	Room	Wall	Wood	D	Lower
11221216	14087	-0.1	Negative	FALSE	FALSE	11/22/2024	12:30 PM	Paint	1126 North Ave	Commons		Foyer	Door	---	Wood	A	1
11221216	14088	-0.1	Negative	FALSE	FALSE	11/22/2024	12:30 PM	Paint	1126 North Ave	Commons		Foyer	Door	Casing	Wood	A	1
11221216	14089	-0.1	Negative	FALSE	FALSE	11/22/2024	12:31 PM	Paint	1126 North Ave	Commons		Foyer	Door	Casing	Wood	B	1
11221216	14090	0	Negative	FALSE	FALSE	11/22/2024	12:31 PM	Paint	1126 North Ave	Commons		Foyer	Door	Jamb	Wood	B	1
11221216	14091	-0.1	Negative	FALSE	FALSE	11/22/2024	12:31 PM	Paint	1126 North Ave	Commons		Foyer	Door	---	Wood	B	1
11221216	14092	-0.1	Negative	FALSE	FALSE	11/22/2024	12:31 PM	Paint	1126 North Ave	Commons		Foyer	Door	---	Wood	C	1
11221216	14093	-0.1	Negative	FALSE	FALSE	11/22/2024	12:31 PM	Paint	1126 North Ave	Commons		Foyer	Door	---	Wood	D	1
11221216	14094	0.1	Negative	FALSE	FALSE	11/22/2024	12:32 PM	Paint	1126 North Ave	Commons		Foyer	Closet	Bi-Fold Door	Wood	D	1
11221216	14095	0	Negative	FALSE	FALSE	11/22/2024	12:32 PM	Paint	1126 North Ave	Commons		Foyer	Closet	Door Jamb	Wood	D	1

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 1831

Lead concentration units: mg/cm2

Total Readings: 222 Total Positives 27

Action Level 1

Mode Action Level

Analytic Mode Paint

Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
11221216	14069	1.1	Positive	FALSE	FALSE	11/22/2024	12:23 PM	Paint	1126 North Ave	Commons		Enclosed Porch	Room	Floor	Wood	B	1
11221216	14073	4.6	Positive	FALSE	FALSE	11/22/2024	12:24 PM	Paint	1126 North Ave	Commons		Enclosed Porch	Room	Wall	Wood	C	1
11221216	14118	12.9	Positive	FALSE	FALSE	11/22/2024	12:40 PM	Paint	1126 North Ave	Commons		Basement Stairwell	Stair	Risers	Wood	C	1
11221216	14119	17.1	Positive	FALSE	FALSE	11/22/2024	12:41 PM	Paint	1126 North Ave	Commons		Basement Stairwell	Stair	Stringer	Wood	C	1
11221216	14120	9	Positive	FALSE	FALSE	11/22/2024	12:41 PM	Paint	1126 North Ave	Commons		Basement Stairwell	Stair	Newel Post	Wood	C	1
11221216	14121	10.5	Positive	FALSE	FALSE	11/22/2024	12:41 PM	Paint	1126 North Ave	Commons		Basement Stairwell	Stair	Balusters	Wood	C	1
11221216	14122	13.7	Positive	FALSE	FALSE	11/22/2024	12:42 PM	Paint	1126 North Ave	Commons		Basement Stairwell	Stair	Underside	Drywall	C	1
11221216	14125	1.9	Positive	FALSE	FALSE	11/22/2024	12:43 PM	Paint	1126 North Ave	Commons		Basement Stairwell	Room	Wall	Wood	A	1
11221216	14126	3.6	Positive	FALSE	FALSE	11/22/2024	12:44 PM	Paint	1126 North Ave	Commons		Basement Stairwell	Room	Wall	Wood	B	1
11221216	14131	16	Positive	FALSE	FALSE	11/22/2024	12:46 PM	Paint	1126 North Ave	Commons		Basement Stairwell	Stair	Stringer	Wood	A	Lower
11221216	14133	8.9	Positive	FALSE	FALSE	11/22/2024	12:46 PM	Paint	1126 North Ave	Commons		Basement Stairwell	Stair	Railing	Wood	A	Lower
11221216	14134	21.2	Positive	FALSE	FALSE	11/22/2024	12:47 PM	Paint	1126 North Ave	Commons		Basement Stairwell	Stair	Support column	Wood	A	Lower
11221216	14139	6.3	Positive	FALSE	FALSE	11/22/2024	12:49 PM	Paint	1126 North Ave	Commons		Basement	Window	Casing	Brick	D	1
11221216	14140	1.8	Positive	FALSE	FALSE	11/22/2024	12:50 PM	Paint	1126 North Ave	Commons		Basement	Pipe	Vertical	Metal	D	1
11221216	14142	13.6	Positive	FALSE	FALSE	11/22/2024	12:51 PM	Paint	1126 North Ave	Commons		Basement	Support Column		Metal	C	1
11221216	14143	1.5	Positive	FALSE	FALSE	11/22/2024	12:52 PM	Paint	1126 North Ave	Commons		Basement	Support Column		Wood	C	1
11221216	14247	1.3	Positive	FALSE	FALSE	11/22/2024	1:26 PM	Paint	1126 North Ave	Unit	2	Bathroom	Closet	Shelf Support	Wood	C	1
11221216	14250	1.7	Positive	FALSE	FALSE	11/22/2024	1:27 PM	Paint	1126 North Ave	Unit	2	Bathroom	Window	Casing	Wood	D	1
11221216	14253	15.2	Positive	FALSE	FALSE	11/22/2024	1:28 PM	Paint	1126 North Ave	Unit	2	Bathroom	Room	Wall	Drywall	B	1
11221216	14254	18.6	Positive	FALSE	FALSE	11/22/2024	1:28 PM	Paint	1126 North Ave	Unit	2	Bathroom	Room	Wall	Drywall	D	1
11221216	14265	1.3	Positive	FALSE	FALSE	11/22/2024	1:33 PM	Paint	1126 North Ave	Unit	2	Attic	Window	Jamb	Wood	A	1
11221216	14267	1.2	Positive	FALSE	FALSE	11/22/2024	1:33 PM	Paint	1126 North Ave	Unit	2	Attic	Window	Sill	Wood	A	1
11221216	14274	3.3	Positive	FALSE	FALSE	11/22/2024	1:36 PM	Paint	1126 North Ave	Unit	2	Attic	Stair	Stringer	Wood	D	1
11221216	14275	2.8	Positive	FALSE	FALSE	11/22/2024	1:37 PM	Paint	1126 North Ave	Unit	2	Attic	Stair	Risers	Wood	D	1
11221216	14276	9.5	Positive	FALSE	FALSE	11/22/2024	1:37 PM	Paint	1126 North Ave	Unit	2	Attic	Stair	Treads	Wood	D	1
11221216	14278	4.1	Positive	FALSE	FALSE	11/22/2024	1:37 PM	Paint	1126 North Ave	Unit	2	Attic	Door	Jamb	Wood	B	1
11221216	14279	4.1	Positive	FALSE	FALSE	11/22/2024	1:38 PM	Paint	1126 North Ave	Unit	2	Attic	Door	Casing	Wood	B	1