

Company LEW Corporation  
 XRF Make Heuresis  
 Model Pb200i  
 Serial Num. 1832  
 Lead concentration units: mg/cm2  
 Total Readings: 50  
 Action Level 1  
 Mode Action Level  
 Analytic Mode Paint

**All Readings**

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location	Condition	Cause
11251057	3982	1.1		TRUE	FALSE	11/25/2024	10:57 AM	Saheed Alex Adeyeri	Paint											
11251057	3983	1		TRUE	FALSE	11/25/2024	10:57 AM	Saheed Alex Adeyeri	Paint											
11251057	3984	1		TRUE	FALSE	11/25/2024	10:58 AM	Saheed Alex Adeyeri	Paint											
11251057	3985	0		TRUE	FALSE	11/25/2024	10:58 AM	Saheed Alex Adeyeri	Paint											
11251057	3986	-0.1		TRUE	FALSE	11/25/2024	10:58 AM	Saheed Alex Adeyeri	Paint											
11251057	3987	0		TRUE	FALSE	11/25/2024	10:58 AM	Saheed Alex Adeyeri	Paint											
11251057	3988	0	Negative	FALSE	FALSE	11/25/2024	10:59 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Living Room/Kitchen	Room	Wall	Drywall	A		Intact	
11251057	3989	-0.1	Negative	FALSE	FALSE	11/25/2024	11:00 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Living Room/Kitchen	Room	Wall	Drywall	B		Intact	
11251057	3990	0	Negative	FALSE	FALSE	11/25/2024	11:00 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Living Room/Kitchen	Room	Wall	Drywall	C		Intact	
11251057	3991	0.1	Negative	FALSE	FALSE	11/25/2024	11:00 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Living Room/Kitchen	Room	Wall	Drywall	D		Intact	
11251057	3992	-0.1	Negative	FALSE	FALSE	11/25/2024	11:01 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Living Room/Kitchen	Room	Ceiling	Drywall	D		Intact	
11251057	3993	0.1	Negative	FALSE	FALSE	11/25/2024	11:02 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Living Room/Kitchen	Door	Casing	Wood	A		Intact	
11251057	3994	0.1	Negative	FALSE	FALSE	11/25/2024	11:03 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Living Room/Kitchen	Door	Jamb	Wood	A		Intact	
11251057	3995	0.1	Negative	FALSE	FALSE	11/25/2024	11:03 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Living Room/Kitchen	Door	---	Wood	A		Intact	
11251057	3996	-0.3	Negative	FALSE	FALSE	11/25/2024	11:04 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bedroom 1	Room	Wall	Drywall	A		Intact	
11251057	3997	-0.1	Negative	FALSE	FALSE	11/25/2024	11:05 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bedroom 1	Room	Wall	Drywall	B		Intact	
11251057	3998	0.1	Negative	FALSE	FALSE	11/25/2024	11:05 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bedroom 1	Room	Wall	Drywall	C		Intact	
11251057	3999	0.1	Negative	FALSE	FALSE	11/25/2024	11:05 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bedroom 1	Room	Wall	Drywall	D		Intact	
11251057	4000	0	Negative	FALSE	FALSE	11/25/2024	11:06 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bedroom 1	Window	Casing	Drywall	C		Intact	
11251057	4001	-0.1	Negative	FALSE	FALSE	11/25/2024	11:06 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bedroom 1	Window	Jamb	Drywall	C		Intact	
11251057	4002	0	Negative	FALSE	FALSE	11/25/2024	11:06 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bedroom 1	Window	Sill	Drywall	C		Intact	
11251057	4003	0	Negative	FALSE	FALSE	11/25/2024	11:07 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bedroom 1	Door	Casing	Wood	D		Intact	
11251057	4004	0	Negative	FALSE	FALSE	11/25/2024	11:07 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bedroom 1	Door	Jamb	Wood	D		Intact	
11251057	4005	0	Negative	FALSE	FALSE	11/25/2024	11:07 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bedroom 1	Door	---	Wood	D		Intact	
11251057	4006	0.2	Negative	FALSE	FALSE	11/25/2024	11:09 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bathroom 1	Room	Wall	Drywall	A		Intact	
11251057	4007	0.1	Negative	FALSE	FALSE	11/25/2024	11:09 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bathroom 1	Room	Wall	Drywall	B		Intact	
11251057	4008	0.2	Negative	FALSE	FALSE	11/25/2024	11:09 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bathroom 1	Room	Wall	Drywall	C		Intact	
11251057	4009	0.1	Negative	FALSE	FALSE	11/25/2024	11:09 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bathroom 1	Room	Wall	Drywall	D		Intact	
11251057	4010	0.1	Negative	FALSE	FALSE	11/25/2024	11:10 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bathroom 1	Room	Ceiling	Drywall	D		Intact	
11251057	4011	-0.1	Negative	FALSE	FALSE	11/25/2024	11:10 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bedroom 2	Room	Wall	Drywall	A		Intact	
11251057	4012	0.1	Negative	FALSE	FALSE	11/25/2024	11:10 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bedroom 2	Room	Wall	Drywall	B		Intact	
11251057	4013	0.1	Negative	FALSE	FALSE	11/25/2024	11:11 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bedroom 2	Room	Wall	Drywall	C		Intact	
11251057	4014	-0.1	Negative	FALSE	FALSE	11/25/2024	11:11 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bedroom 2	Room	Wall	Drywall	D		Intact	
11251057	4015	-0.1	Negative	FALSE	FALSE	11/25/2024	11:11 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bedroom 2	Room	Ceiling	Drywall	D		Intact	
11251057	4016	0	Negative	FALSE	FALSE	11/25/2024	11:12 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bedroom 2	Door	Casing	Wood	A		Intact	
11251057	4017	-0.1	Negative	FALSE	FALSE	11/25/2024	11:12 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bedroom 2	Door	Jamb	Wood	A		Intact	
11251057	4018	-0.1	Negative	FALSE	FALSE	11/25/2024	11:12 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bedroom 2	Door	---	Wood	A		Intact	
11251057	4019	0	Negative	FALSE	FALSE	11/25/2024	11:13 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bedroom 2	Window	Casing	Wood	C		Intact	
11251057	4020	0	Negative	FALSE	FALSE	11/25/2024	11:13 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bedroom 2	Window	Jamb	Wood	C		Intact	
11251057	4021	-0.1	Negative	FALSE	FALSE	11/25/2024	11:13 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bedroom 2	Window	Sill	Wood	C		Intact	
11251057	4022	0.1	Negative	FALSE	FALSE	11/25/2024	11:14 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bathroom 2	Room	Wall	Drywall	A		Intact	
11251057	4023	0.1	Negative	FALSE	FALSE	11/25/2024	11:14 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bathroom 2	Room	Wall	Drywall	B		Intact	
11251057	4024	0	Negative	FALSE	FALSE	11/25/2024	11:14 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bathroom 2	Room	Wall	Drywall	C		Intact	
11251057	4025	-0.2	Negative	FALSE	FALSE	11/25/2024	11:14 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bathroom 2	Room	Wall	Drywall	D		Intact	
11251057	4026	-0.1	Negative	FALSE	FALSE	11/25/2024	11:15 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bathroom 2	Door	Casing	Drywall	B		Intact	
11251057	4027	0	Negative	FALSE	FALSE	11/25/2024	11:16 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bathroom 2	Door	Casing	Wood	B		Intact	
11251057	4028	0.1	Negative	FALSE	FALSE	11/25/2024	11:16 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bathroom 2	Door	Jamb	Wood	B		Intact	
11251057	4029	0	Negative	FALSE	FALSE	11/25/2024	11:16 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Bathroom 2	Door	---	Wood	B		Intact	
11251057	4030	-0.1	Negative	FALSE	FALSE	11/25/2024	11:17 AM	Saheed Alex Adeyeri	Paint	238 Harrison Ave	Unit	2R	Foyer	Room	Wall	Drywall	B		Intact	



Company LEW Corporation  
XRF Make Heuresis  
Model Pb200i  
Serial Num. 1832

Lead concentration units: mg/cm2

Total Readings: 50 Total Positives 0

Action Level 1

Mode Action Level

Analytic Mode Paint

**Actionables**

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location	Condition	Cause
No Actionables																				

Company LEW Corporation  
XRF Make Heuresis  
Model Pb200i  
Serial Num. 1832

Lead concentration units: mg/cm2

Total Readings: 50 Total Hazards 0

Action Level 1

Mode Action Level

Analytic Mode Paint

**Hazards**

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location	Condition	Cause
No Hazards																				