

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 2819
 Lead concentration units: mg/cm2
 Total Readings: 156
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location	Condition	Cause
8211107	53007	1		TRUE	FALSE	8/21/2024	11:08 AM	Yerani Heredia	Paint	428 Northern Pkwy										
8211107	53008	1.1		TRUE	FALSE	8/21/2024	11:08 AM	Yerani Heredia	Paint	428 Northern Pkwy										
8211107	53009	1.1		TRUE	FALSE	8/21/2024	11:09 AM	Yerani Heredia	Paint	428 Northern Pkwy										
8211107	53010	0		TRUE	FALSE	8/21/2024	11:10 AM	Yerani Heredia	Paint	428 Northern Pkwy										
8211107	53011	0		TRUE	FALSE	8/21/2024	11:10 AM	Yerani Heredia	Paint	428 Northern Pkwy										
8211107	53012	0		TRUE	FALSE	8/21/2024	11:11 AM	Yerani Heredia	Paint	428 Northern Pkwy										
8211107	53013	0.1	Negative	FALSE	FALSE	8/21/2024	11:11 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Door	---	Wood	A	1	Intact	
8211107	53014	0	Negative	FALSE	FALSE	8/21/2024	11:12 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Door	Jamb	Wood	A	1	Intact	
8211107	53015	0.1	Negative	FALSE	FALSE	8/21/2024	11:12 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Door	Casing	Wood	A	1	Intact	
8211107	53016	-0.1	Negative	FALSE	FALSE	8/21/2024	11:13 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Room	Wall	Plaster	A	1	Intact	
8211107	53017	0.2	Negative	FALSE	FALSE	8/21/2024	11:13 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Room	Wall	Plaster	B	1	Intact	
8211107	53018	0	Negative	FALSE	FALSE	8/21/2024	11:14 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Room	Wall	Plaster	C	1	Intact	
8211107	53019	0.1	Negative	FALSE	FALSE	8/21/2024	11:14 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Room	Wall	Plaster	D	1	Intact	
8211107	53020	0	Negative	FALSE	FALSE	8/21/2024	11:15 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Room	Baseboard	Wood	D	1	Intact	
8211107	53021	0.1	Negative	FALSE	FALSE	8/21/2024	11:15 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Closet	Door	Wood	D	1	Intact	
8211107	53022	16.5	Positive	FALSE	FALSE	8/21/2024	11:17 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Closet	Door Jamb	Wood	D	1	Intact	
8211107	53023	0.1	Negative	FALSE	FALSE	8/21/2024	11:17 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Closet	Door Casing	Wood	D	1	Intact	
8211107	53024	3.2	Positive	FALSE	FALSE	8/21/2024	11:18 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Closet	Door Stop	Wood	D	1	Intact	
8211107	53025	0.1	Negative	FALSE	FALSE	8/21/2024	11:19 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Closet	Wall	Plaster	D	1	Intact	
8211107	53026	0.2	Negative	FALSE	FALSE	8/21/2024	11:20 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Closet	Shelf Support	Wood	D	1	Intact	
8211107	53027	0.1	Negative	FALSE	FALSE	8/21/2024	11:24 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Closet	Baseboard	Wood	D	1	Intact	
8211107	53028	0.2	Negative	FALSE	FALSE	8/21/2024	11:24 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Window	Sash	Wood	B	1	Intact	
8211107	53029	0.1	Negative	FALSE	FALSE	8/21/2024	11:25 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Window	Jamb	Metal	B	1	Intact	
8211107	53030	0	Negative	FALSE	FALSE	8/21/2024	11:25 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Window	Casing	Metal	B	1	Intact	
8211107	53031	0	Negative	FALSE	FALSE	8/21/2024	11:26 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Window	Sill	Metal	B	1	Intact	
8211107	53032	0	Negative	FALSE	FALSE	8/21/2024	11:26 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Window	Apron	Metal	B	1	Intact	
8211107	53033	0.3	Negative	FALSE	FALSE	8/21/2024	11:27 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Stair	Stringer	Wood	B	1	Intact	
8211107	53034	0.1	Negative	FALSE	FALSE	8/21/2024	11:28 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Stair	Railing	Wood	B	1	Intact	
8211107	53035	0.1	Negative	FALSE	FALSE	8/21/2024	11:28 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Stair	Newel Post	Wood	B	1	Intact	
8211107	53036	0.1	Negative	FALSE	FALSE	8/21/2024	11:29 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Stair	Balusters	Wood	B	1	Intact	
8211107	53037	0.1	Negative	FALSE	FALSE	8/21/2024	11:30 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Living Room	Room	Wall	Plaster	A	1	Intact	
8211107	53038	0.1	Negative	FALSE	FALSE	8/21/2024	11:30 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Living Room	Room	Wall	Plaster	B	1	Intact	
8211107	53039	-0.3	Negative	FALSE	FALSE	8/21/2024	11:31 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Living Room	Room	Wall	Plaster	C	1	Intact	
8211107	53040	0.1	Negative	FALSE	FALSE	8/21/2024	11:31 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Living Room	Room	Wall	Plaster	D	1	Intact	
8211107	53041	-0.2	Negative	FALSE	FALSE	8/21/2024	11:32 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Living Room	Room	Baseboard	Wood	D	1	Intact	
8211107	53042	-0.1	Negative	FALSE	FALSE	8/21/2024	11:33 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Living Room	Radiator	Baseboard	Metal	D	1	Intact	
8211107	53043	-0.1	Negative	FALSE	FALSE	8/21/2024	11:33 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Living Room	Window	Sash	Wood	D	1	Intact	
8211107	53044	0.5	Negative	FALSE	FALSE	8/21/2024	11:34 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Living Room	Window	Jamb	Wood	D	1	Intact	
8211107	53045	0.2	Negative	FALSE	FALSE	8/21/2024	11:34 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Living Room	Window	Casing	Wood	D	1	Intact	
8211107	53046	0.1	Negative	FALSE	FALSE	8/21/2024	11:35 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Living Room	Window	Sill	Wood	D	1	Intact	
8211107	53047	14.3	Positive	FALSE	FALSE	8/21/2024	11:36 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Kitchen	Door	---	Wood	C	1	Deteriorated	Friction
8211107	53048	6	Positive	FALSE	FALSE	8/21/2024	11:37 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Kitchen	Door	Jamb	Wood	C	1	Deteriorated	Friction
8211107	53049	0.1	Negative	FALSE	FALSE	8/21/2024	11:37 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Kitchen	Door	Casing	Wood	C	1	Deteriorated	Impact
8211107	53050	0.1	Negative	FALSE	FALSE	8/21/2024	11:38 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Kitchen	Room	Wall	Plaster	A	1	Intact	
8211107	53051	0.1	Negative	FALSE	FALSE	8/21/2024	11:38 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Kitchen	Room	Wall	Plaster	B	1	Intact	
8211107	53052	0.1	Negative	FALSE	FALSE	8/21/2024	11:39 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Kitchen	Room	Wall	Plaster	C	1	Intact	
8211107	53053	0.1	Negative	FALSE	FALSE	8/21/2024	11:40 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Kitchen	Room	Wall	Plaster	D	1	Intact	
8211107	53054	0	Negative	FALSE	FALSE	8/21/2024	11:40 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Kitchen	Room	Baseboard	Wood	D	1	Intact	
8211107	53055	0.2	Negative	FALSE	FALSE	8/21/2024	11:41 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Kitchen	Window	Sash	Wood	D	1	Intact	
8211107	53056	0	Negative	FALSE	FALSE	8/21/2024	11:41 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Kitchen	Window	Jamb	Wood	D	1	Intact	

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location	Condition	Cause
8211107	53057	0.1	Negative	FALSE	FALSE	8/21/2024	11:42 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Kitchen	Window	Casing	Wood	D	1	Intact	
8211107	53058	0.1	Negative	FALSE	FALSE	8/21/2024	11:42 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Kitchen	Window	Sill	Wood	D	1	Intact	
8211107	53059	0.1	Negative	FALSE	FALSE	8/21/2024	11:43 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Kitchen	Cabinets	Frame	Wood	D	1	Intact	
8211107	53060	0	Negative	FALSE	FALSE	8/21/2024	11:44 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Kitchen	Radiator	Baseboard	Metal	B	1	Intact	
8211107	53061	7.5	Positive	FALSE	FALSE	8/21/2024	11:45 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Rear Entry	Door	---	Wood	B	1	Intact	
8211107	53062	0.2	Negative	FALSE	FALSE	8/21/2024	11:45 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Rear Entry	Door	Jamb	Wood	B	1	Deteriorated	Friction
8211107	53063	15.4	Positive	FALSE	FALSE	8/21/2024	11:46 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Rear Entry	Door	Casing	Wood	B	1	Intact	
8211107	53064	7.1	Positive	FALSE	FALSE	8/21/2024	11:47 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Rear Entry	Room	Wall	Wood	A	1	Intact	
8211107	53065	1	Positive	FALSE	FALSE	8/21/2024	11:47 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Rear Entry	Room	Wall	Wood	B	1	Intact	
8211107	53066	0.5	Negative	FALSE	FALSE	8/21/2024	11:48 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Rear Entry	Room	Wall	Wood	C	1	Intact	
8211107	53067	1	Positive	FALSE	FALSE	8/21/2024	11:49 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Rear Entry	Room	Wall	Wood	D	1	Intact	
8211107	53068	1	Positive	FALSE	FALSE	8/21/2024	11:50 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Rear Entry	Room	Baseboard	Wood	D	1	Intact	
8211107	53069	0.4	Negative	FALSE	FALSE	8/21/2024	11:51 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Rear Entry	Room	Ceiling	Wood	D	1	Intact	
8211107	53070	3	Positive	FALSE	FALSE	8/21/2024	11:52 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Rear Entry	Window	Sash	Wood	D	1	Intact	
8211107	53071	0.8	Negative	FALSE	FALSE	8/21/2024	11:52 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Rear Entry	Window	Casing	Wood	D	1	Intact	
8211107	53072	10.6	Positive	FALSE	FALSE	8/21/2024	11:53 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Rear Entry	Window	Sill	Wood	D	1	Intact	
8211107	53073	8.5	Positive	FALSE	FALSE	8/21/2024	11:54 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Rear Entry	Shelf	---	Wood	C	1	Intact	
8211107	53074	19	Positive	FALSE	FALSE	8/21/2024	11:54 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Rear Entry	Shelf Support		Wood	C	1	Intact	
8211107	53075	0.1	Negative	FALSE	FALSE	8/21/2024	11:56 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	2nd Floor Hallway	Room	Wall	Plaster	A	1	Intact	
8211107	53076	0.1	Negative	FALSE	FALSE	8/21/2024	11:57 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	2nd Floor Hallway	Room	Wall	Plaster	B	1	Intact	
8211107	53077	0.2	Negative	FALSE	FALSE	8/21/2024	11:57 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	2nd Floor Hallway	Room	Wall	Plaster	C	1	Intact	
8211107	53078	0.1	Negative	FALSE	FALSE	8/21/2024	11:58 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	2nd Floor Hallway	Room	Wall	Plaster	D	1	Intact	
8211107	53079	0.1	Negative	FALSE	FALSE	8/21/2024	11:58 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	2nd Floor Hallway	Room	Baseboard	Wood	D	1	Intact	
8211107	53080	5.8	Positive	FALSE	FALSE	8/21/2024	11:59 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 1	Door	---	Wood	A	1	Intact	
8211107	53081	10.3	Positive	FALSE	FALSE	8/21/2024	12:00 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 1	Door	Jamb	Wood	A	1	Intact	
8211107	53082	0.2	Negative	FALSE	FALSE	8/21/2024	12:00 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 1	Door	Casing	Wood	A	1	Intact	
8211107	53083	0.1	Negative	FALSE	FALSE	8/21/2024	12:01 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 1	Room	Wall	Plaster	A	1	Intact	
8211107	53084	0.1	Negative	FALSE	FALSE	8/21/2024	12:02 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 1	Room	Wall	Plaster	B	1	Intact	
8211107	53085	0.1	Negative	FALSE	FALSE	8/21/2024	12:02 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 1	Room	Wall	Plaster	C	1	Intact	
8211107	53086	0.1	Negative	FALSE	FALSE	8/21/2024	12:03 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 1	Room	Wall	Plaster	D	1	Intact	
8211107	53087	-0.1	Negative	FALSE	FALSE	8/21/2024	12:03 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 1	Room	Baseboard	Wood	D	1	Intact	
8211107	53088	0.1	Negative	FALSE	FALSE	8/21/2024	12:04 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 1	Window	Sash	Wood	B	1	Intact	
8211107	53089	0.1	Negative	FALSE	FALSE	8/21/2024	12:05 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 1	Window	Jamb	Wood	B	1	Intact	
8211107	53090	0	Negative	FALSE	FALSE	8/21/2024	12:05 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 1	Window	Casing	Wood	B	1	Intact	
8211107	53091	-0.2	Negative	FALSE	FALSE	8/21/2024	12:06 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 1	Window	Sill	Wood	B	1	Intact	
8211107	53092	14.3	Positive	FALSE	FALSE	8/21/2024	12:06 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 1	Closet	Door	Wood	A	1	Intact	
8211107	53093	12.5	Positive	FALSE	FALSE	8/21/2024	12:07 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 1	Closet	Door Jamb	Wood	A	1	Intact	
8211107	53094	-0.1	Negative	FALSE	FALSE	8/21/2024	12:07 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 1	Closet	Door Casing	Wood	A	1	Intact	
8211107	53095	12.6	Positive	FALSE	FALSE	8/21/2024	12:08 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 1	Closet	Shelf Support	Wood	A	1	Intact	
8211107	53096	0.1	Negative	FALSE	FALSE	8/21/2024	12:09 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 1	Closet	Wall	Plaster	A	1	Intact	
8211107	53097	0.1	Negative	FALSE	FALSE	8/21/2024	12:09 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 1	Closet	Baseboard	Wood	A	1	Intact	
8211107	53098	13.2	Positive	FALSE	FALSE	8/21/2024	12:10 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 2	Door	---	Wood	A	1	Intact	
8211107	53099	9	Positive	FALSE	FALSE	8/21/2024	12:10 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 2	Door	Jamb	Wood	A	1	Intact	
8211107	53100	-0.1	Negative	FALSE	FALSE	8/21/2024	12:11 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 2	Door	Casing	Wood	A	1	Intact	
8211107	53101	0.1	Negative	FALSE	FALSE	8/21/2024	12:12 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 2	Room	Wall	Plaster	A	1	Intact	
8211107	53102	0.1	Negative	FALSE	FALSE	8/21/2024	12:12 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 2	Room	Wall	Plaster	B	1	Intact	
8211107	53103	0.1	Negative	FALSE	FALSE	8/21/2024	12:13 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 2	Room	Wall	Plaster	C	1	Intact	
8211107	53104	0.2	Negative	FALSE	FALSE	8/21/2024	12:13 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 2	Room	Wall	Plaster	D	1	Intact	
8211107	53105	0	Negative	FALSE	FALSE	8/21/2024	12:14 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 2	Room	Baseboard	Plaster	D	1	Intact	
8211107	53106	0.1	Negative	FALSE	FALSE	8/21/2024	12:15 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 2	Window	Sash	Wood	C	1	Intact	
8211107	53107	0.1	Negative	FALSE	FALSE	8/21/2024	12:15 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 2	Window	Jamb	Wood	C	1	Intact	
8211107	53108	-0.1	Negative	FALSE	FALSE	8/21/2024	12:16 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 2	Window	Casing	Wood	C	1	Intact	
8211107	53109	0	Negative	FALSE	FALSE	8/21/2024	12:17 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 2	Window	Sill	Wood	C	1	Intact	
8211107	53110	24.5	Positive	FALSE	FALSE	8/21/2024	12:17 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 2	Closet	Door	Wood	A	1	Intact	
8211107	53111	9.6	Positive	FALSE	FALSE	8/21/2024	12:18 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 2	Closet	Door Jamb	Wood	A	1	Intact	
8211107	53112	0	Negative	FALSE	FALSE	8/21/2024	12:18 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 2	Closet	Door Casing	Wood	A	1	Intact	
8211107	53113	0.1	Negative	FALSE	FALSE	8/21/2024	12:19 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 2	Closet	Wall	Plaster	A	1	Intact	
8211107	53114	-0.1	Negative	FALSE	FALSE	8/21/2024	12:20 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 2	Closet	Baseboard	Wood	A	1	Intact	
8211107	53115	0.2	Negative	FALSE	FALSE	8/21/2024	12:21 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 2	Radiator	Baseboard	Metal	C	1	Intact	
8211107	53116	0	Negative	FALSE	FALSE	8/21/2024	12:21 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 1	Radiator	Baseboard	Metal	C	1	Intact	
8211107	53117	0.1	Negative	FALSE	FALSE	8/21/2024	12:22 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 3	Radiator	Baseboard	Metal	C	1	Intact	

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 2819

Lead concentration units: mg/cm2

Total Readings: 156 Total Positives 34

Action Level 1

Mode Action Level

Analytic Mode Paint

Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location	Condition	Cause
8211107	53022	16.5	Positive	FALSE	FALSE	8/21/2024	11:17 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Closet	Door Jamb	Wood	D	1	Intact	
8211107	53024	3.2	Positive	FALSE	FALSE	8/21/2024	11:18 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Foyer	Closet	Door Stop	Wood	D	1	Intact	
8211107	53047	14.3	Positive	FALSE	FALSE	8/21/2024	11:36 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Kitchen	Door	---	Wood	C	1	Deteriorated	Friction
8211107	53048	6	Positive	FALSE	FALSE	8/21/2024	11:37 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Kitchen	Door	Jamb	Wood	C	1	Deteriorated	Friction
8211107	53061	7.5	Positive	FALSE	FALSE	8/21/2024	11:45 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Rear Entry	Door	---	Wood	B	1	Intact	
8211107	53063	15.4	Positive	FALSE	FALSE	8/21/2024	11:46 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Rear Entry	Door	Casing	Wood	B	1	Intact	
8211107	53064	7.1	Positive	FALSE	FALSE	8/21/2024	11:47 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Rear Entry	Room	Wall	Wood	A	1	Intact	
8211107	53065	1	Positive	FALSE	FALSE	8/21/2024	11:47 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Rear Entry	Room	Wall	Wood	B	1	Intact	
8211107	53067	1	Positive	FALSE	FALSE	8/21/2024	11:49 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Rear Entry	Room	Wall	Wood	D	1	Intact	
8211107	53068	1	Positive	FALSE	FALSE	8/21/2024	11:50 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Rear Entry	Room	Baseboard	Wood	D	1	Intact	
8211107	53070	3	Positive	FALSE	FALSE	8/21/2024	11:52 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Rear Entry	Window	Sash	Wood	D	1	Intact	
8211107	53072	10.6	Positive	FALSE	FALSE	8/21/2024	11:53 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Rear Entry	Window	Sill	Wood	D	1	Intact	
8211107	53073	8.5	Positive	FALSE	FALSE	8/21/2024	11:54 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Rear Entry	Shelf	---	Wood	C	1	Intact	
8211107	53074	19	Positive	FALSE	FALSE	8/21/2024	11:54 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Rear Entry	Shelf Support		Wood	C	1	Intact	
8211107	53080	5.8	Positive	FALSE	FALSE	8/21/2024	11:59 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 1	Door	---	Wood	A	1	Intact	
8211107	53081	10.3	Positive	FALSE	FALSE	8/21/2024	12:00 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 1	Door	Jamb	Wood	A	1	Intact	
8211107	53092	14.3	Positive	FALSE	FALSE	8/21/2024	12:06 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 1	Closet	Door	Wood	A	1	Intact	
8211107	53093	12.5	Positive	FALSE	FALSE	8/21/2024	12:07 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 1	Closet	Door Jamb	Wood	A	1	Intact	
8211107	53095	12.6	Positive	FALSE	FALSE	8/21/2024	12:08 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 1	Closet	Shelf Support	Wood	A	1	Intact	
8211107	53098	13.2	Positive	FALSE	FALSE	8/21/2024	12:10 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 2	Door	---	Wood	A	1	Intact	
8211107	53099	9	Positive	FALSE	FALSE	8/21/2024	12:10 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 2	Door	Jamb	Wood	A	1	Intact	
8211107	53110	24.5	Positive	FALSE	FALSE	8/21/2024	12:17 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 2	Closet	Door	Wood	A	1	Intact	
8211107	53111	9.6	Positive	FALSE	FALSE	8/21/2024	12:18 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 2	Closet	Door Jamb	Wood	A	1	Intact	
8211107	53118	8.5	Positive	FALSE	FALSE	8/21/2024	12:23 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 3	Door	---	Wood	C	1	Intact	
8211107	53119	1.8	Positive	FALSE	FALSE	8/21/2024	12:23 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 3	Door	Jamb	Wood	C	1	Intact	
8211107	53121	9.8	Positive	FALSE	FALSE	8/21/2024	12:24 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 3	Closet	Door	Wood	B	1	Deteriorated	Friction
8211107	53122	14.6	Positive	FALSE	FALSE	8/21/2024	12:25 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 3	Closet	Door Jamb	Wood	B	1	Deteriorated	Friction
8211107	53135	26.4	Positive	FALSE	FALSE	8/21/2024	12:34 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bathroom	Door	---	Wood	C	1	Intact	
8211107	53136	9.6	Positive	FALSE	FALSE	8/21/2024	12:34 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bathroom	Door	Jamb	Wood	C	1	Intact	
8211107	53158	26.4	Positive	FALSE	FALSE	8/21/2024	12:49 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Basement room 1	Door	---	Wood	C	1	Deteriorated	Impact
8211107	53159	12.3	Positive	FALSE	FALSE	8/21/2024	12:49 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Basement room 1	Door	Jamb	Wood	C	1	Intact	
8211107	53161	4.3	Positive	FALSE	FALSE	8/21/2024	12:50 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Basement room 1	Window	Sash	Wood	B	1	Intact	
8211107	53166	2	Positive	FALSE	FALSE	8/21/2024	12:53 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Basement room 1	Stair	Risers	Wood	D	1	Intact	
8211107	53168	3.3	Positive	FALSE	FALSE	8/21/2024	12:54 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Basement room 1	Window	Casing	Wood	B	1	Intact	

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 2819

Lead concentration units: mg/cm2

Total Readings: 156 Total Hazards 5

Action Level 1

Mode Action Level

Analytic Mode Paint

Hazards

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location	Condition	Cause
8211107	53047	14.3	Positive	FALSE	FALSE	8/21/2024	11:36 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Kitchen	Door	---	Wood	C	1	Deteriorated	Friction
8211107	53048	6	Positive	FALSE	FALSE	8/21/2024	11:37 AM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Kitchen	Door	Jamb	Wood	C	1	Deteriorated	Friction
8211107	53121	9.8	Positive	FALSE	FALSE	8/21/2024	12:24 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 3	Closet	Door	Wood	B	1	Deteriorated	Friction
8211107	53122	14.6	Positive	FALSE	FALSE	8/21/2024	12:25 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Bedroom 3	Closet	Door Jamb	Wood	B	1	Deteriorated	Friction
8211107	53158	26.4	Positive	FALSE	FALSE	8/21/2024	12:49 PM	Yerani Heredia	Paint	428 Northern Pkwy	Unit	1	Basement room 1	Door	---	Wood	C	1	Deteriorated	Impact