

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 2819

Lead concentration units: mg/cm2

Total Readings: 91
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location	Condition	Cause
8211304	53175	1.1		TRUE	FALSE	8/21/2024	1:06 PM	Yerani Heredia	Paint	431 Northern Pkwy										
8211304	53176	1.1		TRUE	FALSE	8/21/2024	1:07 PM	Yerani Heredia	Paint	431 Northern Pkwy										
8211304	53177	1.2		TRUE	FALSE	8/21/2024	1:07 PM	Yerani Heredia	Paint	431 Northern Pkwy										
8211304	53178	0		TRUE	FALSE	8/21/2024	1:08 PM	Yerani Heredia	Paint	431 Northern Pkwy										
8211304	53179	0		TRUE	FALSE	8/21/2024	1:08 PM	Yerani Heredia	Paint	431 Northern Pkwy										
8211304	53180	0		TRUE	FALSE	8/21/2024	1:09 PM	Yerani Heredia	Paint	431 Northern Pkwy										
8211304	53181	0.1	Negative	FALSE	FALSE	8/21/2024	1:09 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Living Room	Door	---	Wood	A	1	Intact	
8211304	53182	4.3	Positive	FALSE	FALSE	8/21/2024	1:10 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Living Room	Door	Jamb	Wood	A	1	Intact	
8211304	53183	0.2	Negative	FALSE	FALSE	8/21/2024	1:11 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Living Room	Door	Casing	Wood	A	1	Intact	
8211304	53184	0	Negative	FALSE	FALSE	8/21/2024	1:11 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Living Room	Window	Casing	Wood	A	1	Intact	
8211304	53185	-0.2	Negative	FALSE	FALSE	8/21/2024	1:12 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Living Room	Window	Sill	Wood	A	1	Intact	
8211304	53186	0.1	Negative	FALSE	FALSE	8/21/2024	1:12 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Living Room	Window	Apron	Wood	A	1	Intact	
8211304	53187	0.2	Negative	FALSE	FALSE	8/21/2024	1:13 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Living Room	Room	Wall	Plaster	A	1	Intact	
8211304	53188	0.1	Negative	FALSE	FALSE	8/21/2024	1:14 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Living Room	Room	Wall	Plaster	B	1	Intact	
8211304	53189	0.1	Negative	FALSE	FALSE	8/21/2024	1:14 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Living Room	Room	Wall	Plaster	C	1	Intact	
8211304	53190	0.1	Negative	FALSE	FALSE	8/21/2024	1:15 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Living Room	Room	Wall	Plaster	D	1	Intact	
8211304	53191	0.2	Negative	FALSE	FALSE	8/21/2024	1:16 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Living Room	Radiator	---	Metal	D	1	Intact	
8211304	53192	-0.1	Negative	FALSE	FALSE	8/21/2024	1:16 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Living Room	Room	Baseboard	Wood	D	1	Intact	
8211304	53193	0.6	Negative	FALSE	FALSE	8/21/2024	1:17 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Living Room	Room	Ceiling	Drywall	D	1	Intact	
8211304	53194	5.3	Positive	FALSE	FALSE	8/21/2024	1:18 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Living Room	Stair	Stringer	Wood	D	1	Intact	
8211304	53195	0.8	Negative	FALSE	FALSE	8/21/2024	1:19 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Living Room	Stair	Balusters	Wood	D	1	Intact	
8211304	53196	0	Negative	FALSE	FALSE	8/21/2024	1:20 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Living Room	Stair	Newel Post	Wood	D	1	Intact	
8211304	53197	0.4	Negative	FALSE	FALSE	8/21/2024	1:20 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Living Room	Stair	Railing	Wood	D	1	Intact	
8211304	53198	0.3	Negative	FALSE	FALSE	8/21/2024	1:21 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Living Room	Stair	Treads	Wood	D	1	Intact	
8211304	53199	6.4	Positive	FALSE	FALSE	8/21/2024	1:23 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Living Room	Stair	Risers	Wood	D	1	Intact	
8211304	53200	-0.2	Negative	FALSE	FALSE	8/21/2024	1:25 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Hallway	Room	Wall	Plaster	B	2	Intact	
8211304	53201	0.1	Negative	FALSE	FALSE	8/21/2024	1:25 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Hallway	Room	Wall	Plaster	C	2	Intact	
8211304	53202	0.1	Negative	FALSE	FALSE	8/21/2024	1:26 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Hallway	Room	Wall	Plaster	D	2	Intact	
8211304	53203	-0.1	Negative	FALSE	FALSE	8/21/2024	1:27 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Kitchen	Door	---	Wood	C	1	Intact	
8211304	53204	0	Negative	FALSE	FALSE	8/21/2024	1:27 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Kitchen	Door	Jamb	Wood	C	1	Intact	
8211304	53205	0.1	Negative	FALSE	FALSE	8/21/2024	1:28 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Kitchen	Door	Casing	Wood	C	1	Intact	
8211304	53206	0.3	Negative	FALSE	FALSE	8/21/2024	1:29 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Kitchen	Room	Wall	Plaster	A	1	Intact	
8211304	53207	0.2	Negative	FALSE	FALSE	8/21/2024	1:29 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Kitchen	Room	Wall	Plaster	B	1	Intact	
8211304	53208	0.2	Negative	FALSE	FALSE	8/21/2024	1:30 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Kitchen	Room	Wall	Plaster	C	1	Intact	
8211304	53209	0	Negative	FALSE	FALSE	8/21/2024	1:32 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Kitchen	Room	Wall	Plaster	D	1	Intact	
8211304	53210	0.2	Negative	FALSE	FALSE	8/21/2024	1:32 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Kitchen	Door	Casing	Wood	D	1	Intact	
8211304	53211	-0.1	Negative	FALSE	FALSE	8/21/2024	1:33 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Kitchen	Window	Casing	Wood	B	1	Intact	
8211304	53212	0	Negative	FALSE	FALSE	8/21/2024	1:34 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Kitchen	Window	Sash	Wood	B	1	Intact	
8211304	53213	-0.1	Negative	FALSE	FALSE	8/21/2024	1:34 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Kitchen	Window	Sill	Wood	B	1	Intact	
8211304	53214	-0.4	Negative	FALSE	FALSE	8/21/2024	1:35 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Kitchen	Radiator	Cover	Metal	A	1	Intact	
8211304	53215	-0.1	Negative	FALSE	FALSE	8/21/2024	1:36 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Kitchen	Room	Ceiling	Drywall	A	1	Intact	
8211304	53216	0.2	Negative	FALSE	FALSE	8/21/2024	1:37 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Bedroom 1	Door	---	Wood	A	1	Intact	
8211304	53217	0.1	Negative	FALSE	FALSE	8/21/2024	1:37 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Bedroom 1	Door	Jamb	Wood	A	1	Intact	
8211304	53218	0.3	Negative	FALSE	FALSE	8/21/2024	1:38 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Bedroom 1	Door	Casing	Wood	A	1	Intact	
8211304	53219	0	Negative	FALSE	FALSE	8/21/2024	1:39 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Bedroom 1	Room	Wall	Plaster	A	1	Intact	
8211304	53220	-0.1	Negative	FALSE	FALSE	8/21/2024	1:39 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Bedroom 1	Room	Wall	Plaster	B	1	Intact	

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 2819

Lead concentration units: mg/cm2

Total Readings: 91 Total Positives 6

Action Level 1

Mode Action Level

Analytic Mode Paint

Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location	Condition	Cause
8211304	53182	4.3	Positive	FALSE	FALSE	8/21/2024	1:10 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Living Room	Door	Jamb	Wood	A	1	Intact	
8211304	53194	5.3	Positive	FALSE	FALSE	8/21/2024	1:18 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Living Room	Stair	Stringer	Wood	D	1	Intact	
8211304	53199	6.4	Positive	FALSE	FALSE	8/21/2024	1:23 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Living Room	Stair	Risers	Wood	D	1	Intact	
8211304	53255	1.2	Positive	FALSE	FALSE	8/21/2024	2:04 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Bedroom 2	Window	Casing	Wood	A	1	Intact	
8211304	53256	3.9	Positive	FALSE	FALSE	8/21/2024	2:04 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Bedroom 2	Window	Sill	Wood	A	1	Intact	
8211304	53257	3	Positive	FALSE	FALSE	8/21/2024	2:05 PM	Yerani Heredia	Paint	431 Northern Pkwy	Unit	1	Bedroom 2	Window	Apron	Wood	A	1	Intact	

Company LEW Corporation
XRF Make Heuresis
Model Pb200i
Serial Num. 2819

Lead concentration units: mg/cm2

Total Readings: 91 Total Hazards 0

Action Level 1

Mode Action Level

Analytic Mode Paint

Hazards

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location	Condition	Cause
No Hazards																				