

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 2128
 Lead concentration units: mg/cm2
 Total Readings: 76
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
6051553	22229	1.1		TRUE	FALSE	6/5/2024	3:54 PM	Danny Feliciano	Paint	58 Roosevelt								
6051553	22230	1		TRUE	FALSE	6/5/2024	3:55 PM	Danny Feliciano	Paint	58 Roosevelt								
6051553	22231	1		TRUE	FALSE	6/5/2024	3:55 PM	Danny Feliciano	Paint	58 Roosevelt								
6051553	22232	0		TRUE	FALSE	6/5/2024	3:56 PM	Danny Feliciano	Paint	58 Roosevelt								
6051553	22233	0		TRUE	FALSE	6/5/2024	3:56 PM	Danny Feliciano	Paint	58 Roosevelt								
6051553	22234	0		TRUE	FALSE	6/5/2024	3:57 PM	Danny Feliciano	Paint	58 Roosevelt								
6051553	22235	-0.1	Negative	FALSE	TRUE	6/5/2024	3:58 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Living Room	Door	---	Metal	A	
6051553	22236	0.1	Negative	FALSE	FALSE	6/5/2024	3:58 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Living Room	Door	Casing	Wood	A	
6051553	22237	0.4	Negative	FALSE	FALSE	6/5/2024	3:59 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Living Room	Room	Wall	Drywall	A	
6051553	22238	0.3	Negative	FALSE	FALSE	6/5/2024	3:59 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Living Room	Room	Wall	Drywall	D	
6051553	22239	0.4	Negative	FALSE	FALSE	6/5/2024	4:00 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Living Room	Room	Wall	Drywall	C	
6051553	22240	0.2	Negative	FALSE	FALSE	6/5/2024	4:00 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Living Room	Room	Wall	Drywall	B	
6051553	22241	0.2	Negative	FALSE	FALSE	6/5/2024	4:01 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Living Room	Window	Casing	Wood	B	
6051553	22242	0.3	Negative	FALSE	FALSE	6/5/2024	4:02 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Living Room	Window	Sill	Wood	B	
6051553	22243	0.2	Negative	FALSE	FALSE	6/5/2024	4:02 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Living Room	Door	Casing	Wood	C	
6051553	22244	0.2	Negative	FALSE	FALSE	6/5/2024	4:03 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Living Room	Door	Jamb	Wood	C	
6051553	22245	0.2	Negative	FALSE	FALSE	6/5/2024	4:03 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Living Room	Room	Baseboard	Wood	C	
6051553	22246	0.1	Negative	FALSE	FALSE	6/5/2024	4:04 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Living Room	Room	Wall	Drywall	C	
6051553	22247	0.3	Negative	FALSE	FALSE	6/5/2024	4:04 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Living Room	Room	Wall	Drywall	B	
6051553	22248	0.4	Negative	FALSE	FALSE	6/5/2024	4:05 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Living Room	Room	Wall	Drywall	A	
6051553	22249	0.2	Negative	FALSE	FALSE	6/5/2024	4:05 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Living Room	Room	Wall	Drywall	D	
6051553	22250	-1	Negative	FALSE	TRUE	6/5/2024	4:06 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Living Room	Closet	Door	Wood	D	
6051553	22251	0.1	Negative	FALSE	FALSE	6/5/2024	4:06 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Living Room	Closet	Door Jamb	Wood	D	
6051553	22252	0.3	Negative	FALSE	FALSE	6/5/2024	4:07 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Living Room	Closet	Door Casing	Wood	D	
6051553	22253	-0.1	Negative	FALSE	FALSE	6/5/2024	4:08 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Living Room	Closet	Floor	Concrete		
6051553	22254	0.3	Negative	FALSE	FALSE	6/5/2024	4:09 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Living Room	Closet	Access door	Wood	A	
6051553	22255	0.3	Negative	FALSE	FALSE	6/5/2024	4:10 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Foyer/Hall	Room	Wall	Drywall	C	
6051553	22256	0.4	Negative	FALSE	FALSE	6/5/2024	4:10 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Foyer/Hall	Room	Wall	Drywall	A	
6051553	22257	0.4	Negative	FALSE	FALSE	6/5/2024	4:11 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Foyer/Hall	Room	Wall	Drywall	D	
6051553	22258	-0.4	Negative	FALSE	TRUE	6/5/2024	4:11 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Foyer/Hall	Door		Wood	D	
6051553	22259	0.1	Negative	FALSE	FALSE	6/5/2024	4:12 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Foyer/Hall	Door	Casing	Wood	D	
6051553	22260	0.1	Negative	FALSE	FALSE	6/5/2024	4:12 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Foyer/Hall	Door	Jamb	Wood	D	
6051553	22261	0.2	Negative	FALSE	FALSE	6/5/2024	4:13 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Foyer/Hall	Closet	Door	Wood	A	1
6051553	22262	-0.1	Negative	FALSE	FALSE	6/5/2024	4:13 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Foyer/Hall	Closet	Door Casing	Wood	A	1
6051553	22263	0	Negative	FALSE	FALSE	6/5/2024	4:13 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Foyer/Hall	Closet	Door Jamb	Wood	A	1
6051553	22264	0	Negative	FALSE	FALSE	6/5/2024	4:14 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Foyer/Hall	Closet	Door Jamb	Wood	A	2
6051553	22265	-0.4	Negative	FALSE	TRUE	6/5/2024	4:15 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Foyer/Hall	Closet	Door Casing	Wood	A	2
6051553	22266	-0.6	Negative	FALSE	TRUE	6/5/2024	4:15 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Foyer/Hall	Closet	Door	Wood	A	2
6051553	22267	-0.4	Negative	FALSE	TRUE	6/5/2024	4:15 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Foyer/Hall	Closet	Shelf Support	Wood	A	2
6051553	22268	0.2	Negative	FALSE	FALSE	6/5/2024	4:16 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Foyer/Hall	Room	Ceiling	Drywall		
6051553	22269	0.3	Negative	FALSE	FALSE	6/5/2024	4:17 PM	Danny Feliciano	Paint	58 Roosevelt	Unit		Bedroom 1	Room	Ceiling	Drywall		

Company LEW Corporation
XRF Make Heuresis
Model Pb200i
Serial Num. 2128

Lead concentration units: mg/cm2

Total Readings: 76 Total Positives 0
Action Level 1
Mode Action Level
Analytic Mode Paint

Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
No Actionables																		