

181 US Hwy 46 Mine Hill, NJ 07803 (908) 654-8068 (800) 783-0567 Fax 908-654-8069

## Lead Dust Wipe Report

For: 33 High Street, Apt. 5, Orange, NJ 07050 July 6, 2024

On 06/18/2024, Yerani Heredia of LEW Environmental Services, LLC (NJDCA 00015 E) performed dust wipe sampling for the presence of lead at 33 High Street, Apt. 5 Orange, NJ 07050 (the "property") in compliance with NJAC 5:28A. Nine (9) dust wipe (s) were taken for dust level determination. We conducted our inspection in accordance with all federal, state, and municipal regulations. The regulations and inspection standards require that we plan and perform the inspection to obtain a reasonable assurance about whether or not the property is at risk from lead dust.

The maintenance and the environmental conditions of the property are the responsibility of the property's management, principals, or owners. If the property, program, or any of its tenants receive financial federal assistance, the results of this evaluation must be provided by the designated party (client) to the owner of the referenced property and the occupants within 15 calendar days of the date when the designated party receives this report or makes the presumption that lead-based paint hazards exist, per the Department of Housing and Urban Development 24 CFR Part 35.125.

All dust wipes tested are not considered actionable for lead dust. The property may still contain lead painted components and lead dust re-accumulation is possible.

Lead Dust Hazard Standards

Floors (Bare and Carpeted)	$< 10 \text{ ug/ft}^2$
Window Sill<	

Respectfully submitted,

Gerani Heredia

Yerani Heredia Risk Assessor, NJDOH ID# R001913 Order# 45764

Encl: Laboratory Results, Floor Plan, Lead-safe Certificate

«Company» - «Address\_OneLineShip» -Dust Wipes



## Laboratory Results

«Company» - «Address\_OneLineShip» -Dust Wipes Prepared By: LEW Environmental Services, LLC C:\Users\yheredia\Desktop\Harper Management\_\_151 S. Munn Ave, Unit 10, East Orange, NJ, 07017\_Lead NJ Law Dust Wipe Only Report\_20240706.docx 7/6/24 2 of 6

7469 Whitepine Rd North Chesterfield, VA 23237 Telephone: 800.347.4010

Client: LEW Corp 181 US Hwy 46 Mine Hill, NJ 07803

#### Project/Test Address: 45764; Dust Wipe; 33 High St Unit 5 Collection Date: 06/08/2024

**Client Number:** 

201327

# Laboratory Results

# Lead Dust Wipe Analysis Report

Report Number: 24-06-03345

 Received Date:
 06/20/2024

 Analyzed Date:
 06/24/2024

 Reported Date:
 06/25/2024

Fax Number: Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft²)	Concentration (ug/ft <sup>2</sup> )	Narrative ID
24-06-03345- 001	1	LIVING ROOM AC	FL	<5.00	1.00	<5.00	
24-06-03345- 002	2	SUNROOM AC	FL	<5.00	1.00	<5.00	
24-06-03345- 003	3	KITCHEN CC	FL	<5.00	1.00	<5.00	
24-06-03345- 004	4	BEDROOM 1 AC	FL	<5.00	1.00	<5.00	
24-06-03345- 005	5	BEDROOM 3 DC	FL	<5.00	1.00	<5.00	
24-06-03345- 006	6	BEDROOM 3 CC	SL	<5.00	0.851	<5.88	
24-06-03345- 007	7	LIVING ROOM AR	SL	<5.00	0.851	<5.88	
24-06-03345- 008	8	KITCHEN CC	SL	<5.00	0.215	<23.3	
24-06-03345- 009	9	BEDROOM 1 AC	SL	<5.00	0.729	<6.86	

### Environmental Hazards Services, L.L.C

Client Number: 201327 Project/Test Address: 45764; Dust Wipe; 33 High St Unit 5

Lab Sample Client Sample Collection Location Surface Total Pb	Wipe Area	Concentration	Narrative
Number Number (ug)	(ft²)	(ug/ft <sup>2</sup> )	ID

#### Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory: Milisoa Kanode

Melissa Kanode

QA/QC Clerk

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft2 are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accrediitation through AIHA LAP, LLC (100420), NY ELAP #11714.

Legend	ug = microgram	ug/ft <sup>2</sup> = micrograms per square foot	Pb = lead
	mL = milliliter	ft <sup>2</sup> = square foot	

**Report Number:** 24-06-03345


				Ę	1 B																	P171	1	
Received by: MOGMUC	Relinquished by: Whans He				(9)	8	t	6	5	4	$\sim$	2		Sample #		Project Number:	City, State: Order # 45	Address: 33 Kgh St	Project Name: Duff wife	F: (908)	A Maini LEW Environmental Services P: (800)	ENVIRONMENTAL SER	R	
Sig	redia				4								22-80-90				h9t-Sh#	uwit 5	<b>0</b>	F: (908) 654-8069	A Mainline Company <b>P: (800) 783-0567</b>	SERVICES		
Signature:	Signature: Y gan				work B	w-54 14.	w-5:1 4	in-Sil Re	Floor B	floor B	floor k	FLOGE S.	floor (in	(Ex	Si		Paint chip		Sample Type		Chain-o	•	<b>-</b>	
	Hereha	*			edron, 1	ferren co	Who Room	from w	Chom 3	Long 1	itchen c	Sur Loom	windform A	(Ex: Fl, Kitchen, AC)	Sample Location	1 Week		Same Day	Turn Around Time (TAT)		Chain-ot-Custoo		Lead	
Date	Date,				AC		AR	3	SC I	ACC		K (	1			2 Weeks	end		me (TAT)	*	X			
Date/lime:	Date/Time: 06-0-27	×	×	×	75-×3.	3/× /	35× 31/2	35 × 31/2	2 × 12	21 × 7	21 × 2	Z X 7	21 x 2	(inches)	Area			Name:	Sampler li	* All wipe	(Tr	06//		24-
10301	10N													mg/cm <sup>2</sup> PPM	Paint Chip Analysis				Sampler Information		(Tuesday) AF	06/25/2024		24-06-03345
	29/2													% wt	lysis									



«Company» - «Address\_OneLineShip» -Dust Wipes Prepared By: LEW Environmental Services, LLC C:\Users\yheredia\Desktop\Harper Management\_\_151 S. Munn Ave, Unit 10, East Orange, NJ, 07017\_Lead NJ Law Dust Wipe Only Report\_20240706.docx 7/6/24 3 of 6



## <u>Floor Plan</u>



«Company» - «Address\_OneLineShip» -Dust Wipes Prepared By: LEW Environmental Services, LLC C:\Users\yheredia\Desktop\Harper Management\_\_151 S. Munn Ave, Unit 10, East Orange, NJ, 07017\_Lead NJ Law Dust Wipe Only Report\_20240706.docx 7/6/24 4 of 6



«Company» - «Address\_OneLineShip» -Dust Wipes Prepared By: LEW Environmental Services, LLC C:\Users\yheredia\Desktop\Harper Management\_\_151 S. Munn Ave, Unit 10, East Orange, NJ, 07017\_Lead NJ Law Dust Wipe Only Report\_20240706.docx 7/6/24 5 of 6



## Lead - SAFE CERTIFICATE

It is hereby certified that a lead based paint visual inspection and/or dust wipe sampling has been performed in accordance with the protocols referenced in N.J.A.C. 5:17, and the results of which indicate that no lead-based paint hazards have been found in the dwelling unit listed below. It shall be the owner's responsibility to perform any required on-going evaluation and maintenance to ensure that the dwelling unit remain in a *Lead - Safe* condition. PURSUANT TO P.L.2003, c.311 (C.52:27D-437.1 et. seq.)

#### This certificate is VALID FOR TWO YEARS.

33 High Street, Orange, NJ 07050	2201	22	
Site Address	Block	Lot	

Applicable Dwelling Unit: <u>Apt. 5</u> (CERTIFICATE IS VALID FOR A DWELLING UNIT AND SHALL BE AFFIXED TO LEASE)

Insp/RA Name Yerani Heredia

Evaluation Contractor #: 00015-E Phone 908-654-8068

Contractor Name: LEW Environmental Services, LLC

**R001913** *NJDOH ID #* 

Contractor Address: <u>181 US Hwy 46</u>

Mine Hill, NJ 07830

7/6/2024 Date Issued (mm / dd / yyyy)