

181 US Hwy 46 Mine Hill, NJ 07830 (908) 654-8068 (800) 783-0567 Fax 908-654-8069

## Lead Dust Wipe Report

For 1019-23 E 7th St Unit:2 Plainfield City, NJ 07060 09/06/2024

On 09/03/2024, LEW Environmental Services, LLC (NJDCA 00015 E) performed a dust wipe sampling for the presence of lead at 1019-23 E 7th St Unit:2, (the "property") in compliance with NJAC 5:28A. We conducted our inspection in accordance with all federal, state, and municipal regulations. The regulations and inspection standards require that we plan and perform the inspection to obtain a reasonable assurance about whether or not the property is at risk from lead dust.

The maintenance and the environmental conditions of the property are the responsibility of the property's management, principals, or owners. If the property, program, or any of its tenants receive financial federal assistance, the results of this evaluation must be provided by the designated party (client) to the owner of the referenced property and the occupants within 15 calendar days of the date when the designated party receives this report or makes the presumption that lead-based paint hazards exist, per the Department of Housing and Urban Development 24 CFR Part 35.125.

All dust wipes tested are not considered actionable for lead dust. The property may still contain lead painted components and lead dust re-accumulation is possible.

Respectfully Submitted,

5

Saheed Alex Adeyeri NJDOH Risk Assessor, NJDOH ID#0404655 Encl: Laboratory Results, Floor Plan, Lead-safe Certificate



LEW Corp

## Lead Dust Wipe Analysis Report

**Report Number:** 24-09-00410

 Received Date:
 09/04/2024

 Analyzed Date:
 09/05/2024

 Reported Date:
 09/05/2024

**Project/Test Address:** 86680; Susan Walcott; 1025 E 7th Street; Plainfield, NJ **Collection Date:** 09/03/2024

Client Number: 201327

# Laboratory Results

Fax Number: Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft <sup>2</sup> )	Concentration (ug/ft <sup>2</sup> )	Narrative ID
24-09-00410- 001	1025-1	BR 2 C1	SL	<5.00	0.753	<6.65	
24-09-00410- 002	1025-2	LR A2	SL	<5.00	0.802	<6.24	
24-09-00410- 003	1025-3	SUN ROOM CC	FL	<5.00	1.00	<5.00	

#### Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory: Milisoa Kanode

Melissa Kanode

QA/QC Clerk

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft2 are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accrediitation through AIHA LAP, LLC (100420), NY ELAP #11714.

Legend	ug = microgram	ug/ft <sup>2</sup> = micrograms per square foot	Pb = lead		
	mL = milliliter	ft <sup>2</sup> = square foot			

Page 1 of 1


181 US Hwy 46 Mine Hill, NJ 07803

Client:

										13	8							
Received by: Mound	Relinquished by: (alred) May	-										K	2	1-5201	· · · ·	Sample #	ENVIRONMENTAL SERVICES         AMainline Company         LEW Environmental Services       P: (800) 783-0567         F: (908) 654-8069         Project Name:       Su San Wal cott         Address:       1025 E 7 th Street         City, State:       Plawnfizld         Project Number:       \$6680	7
-	Aduyen											<		9/3/24		Date Collected	- SERVICES AMainline Company P: (800) 783-0567 F: (908) 654-8069 F: (908) 654-8069 Wal Coff Wal Coff Mal Coff Mal Coff Mal Coff Mal Coff Street	
Signature:	Signature:											Sur	LR	BR			Sample Type	
	journal .											iun norm Ficc	LRWSA2	BRZWSCI	(Ex: Fl, Kitchen, AC)	Sample Location	Sample Type       Turn Around Time (TAT)         A Dust wipe       Same Day         Paint chip       Same Day         soil       1 Day         TCLP       1 Week	Lead
Date/Time: 942	Date/Time: 9/3/24		×	Х	X	×	×	×	X	×	×	12 × 12	33 × 31/2	31 × 31/2	(inches)	Area	* All wipes successions and Name: Sector All All wipes succession and the sector of th	
4 1145 m	mdro.s														mg/cm <sup>2</sup> PPM	Paint Chip Analysis	09/05/2024 (Thursday) AE Sampler Information	Z4-09-00410
2	n C														% wt	/sis		

1  $\bigcirc$ 

## Floor Plan(s)



#### Floor 1

Lew Environmental Services - 1019-23 E 7th St Unit:2 -Visual Inspection Prepared By: LEW Environmental Services, LLC 09/06/2024



It is hereby certified that a lead based paint visual inspection and/or dust wipe sampling has been performed in accordance with the protocols referenced in N.J.A.C. 5:17, and the results of which indicate that no lead-based paint hazards have been found in the dwelling unit listed below. It shall be the owner's responsibility to perform any required on-going evaluation and maintenance to ensure that the dwelling unit remain in a Lead - Safe condition. PURSUANT TO P.L.2003, c.311 (C.52:27D-437.1 et. seq.)

### This certificate is **Valid For Two Years**

1019-23 E 7th St Unit:2 Plainfield City, NJ	07060			622	12					
Site Adddress				Block	Lot					
Applicable Dwelling Unit: <b>1019-23 E 7th St Unit:2</b>										
(CERTIFICATE IS VALID FOR A DWELLING UNIT AND SHALL BE AFFIXED TO LEASE)										
Insp/RA Name: Saheed Alex Adeyer	Phone: 908-654	4-8068								
5		<b>Contractor Name:</b>	tal Services, LLC							
		<b>Contractor Address:</b>	181 US Hwy 46							
& deren			Mine Hill, NJ 07830							
Alt	0404655	Date Issued:	09/03/2024							
Signature	ID#		(mm/dd/yyyy )							