



## **Lead Dust Wipe Report**

For 14 Ford Avenue Unit:Primary Freehold Borough, NJ 07728 07/01/2024

On 06/18/2024, LEW Environmental Services, LLC (NJDCA 00015 E) performed a dust wipe sampling for the presence of lead at 14 Ford Avenue Unit:Primary, (the "property") in compliance with NJAC 5:28A. We conducted our inspection in accordance with all federal, state, and municipal regulations. The regulations and inspection standards require that we plan and perform the inspection to obtain a reasonable assurance about whether or not the property is at risk from lead dust.

The maintenance and the environmental conditions of the property are the responsibility of the property's management, principals, or owners. If the property, program, or any of its tenants receive financial federal assistance, the results of this evaluation must be provided by the designated party (client) to the owner of the referenced property and the occupants within 15 calendar days of the date when the designated party receives this report or makes the presumption that lead-based paint hazards exist, per the Department of Housing and Urban Development 24 CFR Part 35.125.

All dust wipes tested are not considered actionable for lead dust. The property may still contain lead painted components and lead dust re-accumulation is possible.

Respectfully Submitted,

Nyire Grant

NJDOH Risk Assessor, NJDOH ID#021517

Encl: Laboratory Results, Floor Plan, Lead-safe Certificate



7469 Whitepine Rd North Chesterfield, VA 23237 Telephone: 800.347.4010

## **Lead Dust Wipe Analysis Report**

**Report Number:** 24-06-03065

Received Date:

06/19/2024

**Analyzed Date: Reported Date:**  06/24/2024 06/24/2024

Client: **LEW Corp** 

> 181 US Hwy 46 Mine Hill, NJ 07803

Project/Test Address: 49518; 14 Ford Ave; Freehold, NJ

**Collection Date:** 06/18/2024

**Client Number:** 

201327

Laboratory Results

Fax Number: Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft²)	Concentration (ug/ft²)	Narrative ID
24-06-03065- 001	1	BED 2	FL	<5.00	1.00	<5.00	
24-06-03065- 002	2	BED 2	SL	20.4	0.729	27.9	
24-06-03065- 003	3	SUNROOM	FL	<5.00	1.00	<5.00	

Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory: Melisoa Kanode

Melissa Kanode

QA/QC Clerk

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft2 are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accrediitation through AIHA LAP, LLC (100420), NY ELAP #11714.

Legend	ug = microgram	ug/ft² = micrograms per square foot	Pb = lead	
	mL = milliliter	ft <sup>2</sup> = square foot		

# **ENVIRONMENTAL SERVICES**

LEW Environmental Services P: (800) 783-0567

A Mainline Company

F: (908) 654-8069

## Lead

Lab

24-06-03065

## Chain-of-Custody

06/24/2024


Due Date:

(Monday) AE

Paint Chip Analysis	Area	Sample Location	10	Date Collected	Sample #
		Parameter S.			
with theres!	Signature:	☐ 1 Week ☐ 2 Weeks	I I I		Project Number: 495/8
The second second	- What	☐ 1 Day ☐ Weekend	Soil all cape		City, State: (10000)
Crario /	Name: /\////	luniplemad = =	Daint chin		
A francisco de la constantina della constantina		Same Dav 3 Dav	☐ Dust wipe		Address: 14 Ford Ave
Sampler Information	Sample	Turn Around Time (TAT)	Sample Type	14 Ford Ave	Project Name: 44518 - 14 Ford Ave
)   	* All wipes st				


Sample #	Date Collected	Sample Location	Area	Paint Chip Analysis	
		(Ex: Fl, Kitchen, AC)	(inches)	mg/cm <sup>2</sup> PPM %	% wt
	10 / N/ 34	R-12 fl	1 × 6		
2	78/24	Red 2 Ws	25 × 20		
3	6/18/24	SUN(OOM +)	12 × 12		
			×		
			×		
			×		
			×		
			×		
			×		
			×		
			×		
			×		
Relinquished by:		Signature: Mahari Charles	Date/Time: / //♡_/ つ	Tonia de la constanta de la co	
Received by:				こしている	

## Floor Plan(s)



Floor 1

Lew Environmental Services - 14 Ford Avenue Unit:Primary -Visual Inspection Prepared By: LEW Environmental Services, LLC 07/01/2024



Lew Environmental Services - 14 Ford Avenue Unit:Primary -Visual Inspection Prepared By: LEW Environmental Services, LLC 07/01/2024



## **Lead Safe Certificate**

It is hereby certified that a lead based paint visual inspection and/or dust wipe sampling has been performed in accordance with the protocols referenced in N.J.A.C. 5:17, and the results of which indicate that no lead-based paint hazards have been found in the dwelling unit listed below. It shall be the owner's responsibility to perform any required on-going evaluation and maintenance to ensure that the dwelling unit remain in a Lead - Safe condition. PURSUANT TO P.L.2003, c.311 (C.52:27D-437.1 et. seq.)

### This certificate is Valid For Two Years

14 Ford Avenue Unit:Primary Freehold Borough, NJ 07728	77	30
Site Adddress	Block	Lot

Applicable Dwelling Unit: 14 Ford Avenue Unit:Primary

(CERTIFICATE IS VALID FOR A DWELLING UNIT AND SHALL BE AFFIXED TO LEASE)

Insp/RA Name: Nyire Grant

Contractor #: 00015-E

Phone: 908-654-8068

Contractor Name:

Lew Environmental Services, LLC

181 US Hwy 46

Mine Hill, NJ 07830

06/18/2024

(mm/dd/yyyy)