



181 US Hwy 46
Mine Hill, NJ 07830
(908) 654-8068
(800) 783-0567
Fax 908-654-8069

Visual Paint Assessment Report

For 206 9th Avenue Unit: Belmar Borough, NJ 07719
09/27/2024

On 09/27/24, LEW Environmental Services, LLC (NJDCA 00015 E) performed a visual paint condition assessment for the presence of deteriorated paint, chips or dust from painting activities and paint residue on floors at 206 9th Avenue Unit: , (the "property") in compliance with NJAC 5:28A. Only the dwelling and common area interiors were included. Exteriors were not part of the assessment. The visual assessment followed the protocols found in HUD's Visual Assessment Training course.

No deteriorated paint, chips or dust from painting activities or paint residue on floors were observed in the dwelling unit. The property is eligible for a lead-safe certificate per NJAC 5:28A. Certificate enclosed

Respectfully Submitted,

5
A handwritten signature in black ink that reads 'Saheed Alex Adeyeri'. The signature is written in a cursive style with a vertical line through the middle of the name.


Saheed Alex Adeyeri
NJDOH Risk Assessor, ID#0404655
Encl: Floor Plan, Lead-safe Certificate;

Floor Plan(s)




181 US Hwy 46
Mine Hill, NJ 07803
(908) 654-8068
(800) 783-0567
Fax (908) 654-8069
www.lewenvironmental.com

Site: 206 9th Avenue



Floor 1

Lew Environmental Services - 206 9th Avenue Unit: -Visual Inspection
Prepared By: LEW Environmental Services, LLC
09/27/2024



Lead Safe Certificate

It is hereby certified that a lead based paint visual inspection and/or dust wipe sampling has been performed in accordance with the protocols referenced in N.J.A.C. 5:17, and the results of which indicate that no lead-based paint hazards have been found in the dwelling unit listed below. It shall be the owner's responsibility to perform any required on-going evaluation and maintenance to ensure that the dwelling unit remain in a Lead - Safe condition. PURSUANT TO P.L.2003, c.311 (C.52:27D-437.1 et. seq.)

This certificate is **Valid For Two Years**

206 9th Avenue Unit: Belmar Borough, NJ 07719

81

17

Site Address

Block

Lot

Applicable Dwelling Unit: **206 9th Avenue Unit:**

(CERTIFICATE IS VALID FOR A DWELLING UNIT AND SHALL BE AFFIXED TO LEASE)

Insp/RA Name: Saheed Alex Adeyeri

Evaluation Contractor #: 00015-E

Phone: 908-654-8068

5
Saheed Alex Adeyeri

Contractor Name:

Lew Environmental Services, LLC

Contractor Address:

181 US Hwy 46

Mine Hill, NJ 07830

Date Issued:

09/27/24

(mm/dd/yyyy)

0404655

Signature

ID#