

181 US Hwy 46 Mine Hill, NJ 07830 (908) 654-8068 (800) 783-0567 Fax 908-654-8069

### Lead Dust Wipe Report

For 26 Delafield St Unit:Primary New Brunswick City, NJ 08901 09/05/2024

On 08/29/2024, LEW Environmental Services, LLC (NJDCA 00015 E) performed a dust wipe sampling for the presence of lead at 26 Delafield St Unit:Primary, (the "property") in compliance with NJAC 5:28A. We conducted our inspection in accordance with all federal, state, and municipal regulations. The regulations and inspection standards require that we plan and perform the inspection to obtain a reasonable assurance about whether or not the property is at risk from lead dust.

The maintenance and the environmental conditions of the property are the responsibility of the property's management, principals, or owners. If the property, program, or any of its tenants receive financial federal assistance, the results of this evaluation must be provided by the designated party (client) to the owner of the referenced property and the occupants within 15 calendar days of the date when the designated party receives this report or makes the presumption that lead-based paint hazards exist, per the Department of Housing and Urban Development 24 CFR Part 35.125.

All dust wipes tested are not considered actionable for lead dust. The property may still contain lead painted components and lead dust re-accumulation is possible.

Respectfully Submitted,

Alex Salvador NJDOH Risk Assessor, NJDOH ID#022779 Encl: Laboratory Results, Floor Plan, Lead-safe Certificate



LEW Corp

181 US Hwy 46

Mine Hill, NJ 07803

## Lead Dust Wipe Analysis Report

**Report Number:** 24-08-05551

 Received Date:
 08/30/2024

 Analyzed Date:
 09/04/2024

 Reported Date:
 09/04/2024

Fax Number:

Ext 18 Melissa

Project/Test Address: 82782; Wing Poon; 26 Delafield Street; New Brunswick, NJ Collection Date: 08/29/2024

Client Number: 201327

Client:

# Laboratory Results

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft²)	Concentration (ug/ft <sup>2</sup> )	Narrative ID
24-08-05551- 001	26-1	DINING ROOM C2	SL	9.68	0.484	20.0	
24-08-05551- 002	26-2	SUNROOM BC	FL	<5.00	1.00	<5.00	

Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory: Milisoa Kanode

Melissa Kanode

QA/QC Clerk

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft2 are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accrediitation through AIHA LAP, LLC (100420), NY ELAP #11714.

Legend	ug = microgram	ug/ft <sup>2</sup> = micrograms per square foot	Pb = lead
	mL = milliliter	ft <sup>2</sup> = square foot	

Page 1 of 1

		40	)	
Relinquished by: A & X		4	Sample #	Lew Corporation       P: (908) 6         Project Name:       Image: Company         Address:       Image: Company         City, State:       Number: Company
AWGdZ Signature:		*	Date Collected	ATION mpanysm P: (800) 783-0567 F: (908) 654-8069 Ing Do a file 1d Shut $Je le he ld Shut Je le he ld Shut$
ure:		Smucom 1 pros	Sample Location (Ex: Fl, Kitchen, AC)	<b>Chain-of-Custo</b> Sample Type Sample Type Dust wipe Soil TCLP Same Day 1 Day 1 Week
Date/Time:		5C	i w	Time (TAT) Weekend 2 Weeks Signature:
8 29 24	× × × ×	× × × × ×	s) mgm	
30Spm			Paint Chip Analysis       /cm²     PPM     % wt	Due Date: 09/05/2024 (Thursday) AE

## Floor Plan(s)

	53838_	1000211162.jpg (77	1×1029)	
	IVICES	1000	·	181 US Ney Marcial RI O'B (Yol) 664 Bar (Ney 184 Bar Far (YOL) 654 Bar Far (YOL) 654 Bar
	she 26 Dela	field stree	et	
[::::	C.		<u>.</u>	7
	ĸ	D.		
	5	LR		
Buel				D well
	6		1	
		. <u>6.</u> K.I		
		C.C.		
	S			
	Stre	iet		-
		44.00		

Floor 1

Lew Environmental Services - 26 Delafield St Unit:Primary -Visual Inspection Prepared By: LEW Environmental Services, LLC 09/05/2024



It is hereby certified that a lead based paint visual inspection and/or dust wipe sampling has been performed in accordance with the protocols referenced in N.J.A.C. 5:17, and the results of which indicate that no lead-based paint hazards have been found in the dwelling unit listed below. It shall be the owner's responsibility to perform any required on-going evaluation and maintenance to ensure that the dwelling unit remain in a Lead - Safe condition. PURSUANT TO P.L.2003, c.311 (C.52:27D-437.1 et. seq.)

#### This certificate is **Valid For Two Years**

26 Delafield St Unit:Primary New Bruns	wick City, NJ 08901			65	37
Site Adddress				Block	Lot
	Applicable	Dwelling Unit: 26 Delafield S	t Unit:Primary		
(CERTIFIC	CATE IS VALID F	FOR A DWELLING UNIT AND S	SHALL BE AFFIXED TO LEA	SE)	
Insp/RA Name: Alex Salvador	Ev	valuation Contractor #: 00015-H	E Phone:	908-654-8068	3
		<b>Contractor Name:</b>	Lew Environmental Serv	ices, LLC	
(00, 00)		<b>Contractor Address:</b>	181 US Hwy 46		
VIIIZU	022779		Mine Hill, NJ 07830		
Signature	<u>022//5</u> ID#	Date Issued:	08/29/2024		
5			(mm/dd/yyyy)		