



181 US Hwy 46
Mine Hill, NJ 07803
(908) 654-8068
(800) 783-0567
Fax 908-654-8069

Lead Dust Wipe Report

For: 79 4th Street Unit 2 – South Orange, NJ 07079
March 5, 2024

On 02/28/24, LEW Environmental Services, LLC (NJDC 00015 E) performed dust wipe sampling for the presence of lead at 79 4th Street Unit 2 – South Orange, NJ 07079, (the “property”) in compliance with NJAC 5:28A. Eight (8) dust wipe (s) along with one control sample were taken for dust level determination. We conducted our inspection in accordance with all federal, state, and municipal regulations. The regulations and inspection standards require that we plan and perform the inspection to obtain a reasonable assurance about whether or not the property is at risk from lead dust.

The maintenance and the environmental conditions of the property are the responsibility of the property’s management, principals, or owners. If the property, program, or any of its tenants receive financial federal assistance, the results of this evaluation must be provided by the designated party (client) to the owner of the referenced property and the occupants within 15 calendar days of the date when the designated party receives this report or makes the presumption that lead-based paint hazards exist, per the Department of Housing and Urban Development 24 CFR Part 35.125.

All dust wipes tested are not considered actionable for lead dust. The property may still contain lead painted components and lead dust re-accumulation is possible.

Lead Dust Hazard Standards

Floors (Bare and Carpeted)..... < 10 ug/ft²
Window Sill..... < 100 ug/ft²

Respectfully submitted,

Danny Feliciano

Danny Feliciano
Risk Assessor, NJDOH ID#033001

Encl: Laboratory Results, Floor Plan, Lead-safe Certificate



Laboratory Results



Floor Plan



Lead - SAFE CERTIFICATE

It is hereby certified that a lead based paint visual inspection and/or dust wipe sampling has been performed in accordance with the protocols referenced in N.J.A.C. 5:17, and the results of which indicate that no lead-based paint hazards have been found in the dwelling unit listed below. It shall be the owner's responsibility to perform any required on-going evaluation and maintenance to ensure that the dwelling unit remain in a *Lead - Safe* condition. PURSUANT TO P.L.2003, c.311 (C.52:27D-437.1 et. seq.)

This certificate is VALID FOR TWO YEARS.

79 4th Street 2nd floor – South Orange, NJ 07079

2003

25

Site Address

Block

Lot

Applicable Dwelling Unit: 2nd floor Rental Unit (CERTIFICATE IS VALID FOR A DWELLING UNIT AND SHALL BE AFFIXED TO LEASE)

Insp/RA Name Danny Feliciano

Evaluation Contractor #: 00015-E Phone 908-654-8068

Danny Feliciano

Signature

License ID # 033001

NJDOH ID #

Contractor Name: LEW Environmental Services, LLC

Contractor Address: 181 US Hwy 46

Mine Hill, NJ 07830

OR

Name of Municipal Inspector

Signature

3/5/2024
Date Issued (mm / dd / yyyy)