

181 US Hwy 46 Mine Hill, NJ 07803 (908) 654-8068 (800) 783-0567 Fax 908-654-8069

### **Visual Paint Assessment Report**

For: 170 Grove Avenue, Apt. A, Verona, NJ 07044 March 19, 2024

On March 19, 2024, LEW Environmental Services, LLC (NJDCA 00015 E) performed a visual paint condition assessment for the presence of deteriorated paint, chips or dust from painting activities and paint residue on floors at 170 Grove Avenue, Apt. A, Verona, NJ 07044, (the "property") in compliance with NJAC 5:28A. Only the dwelling and common area interiors were included. Exteriors were not part of the assessment. The visual assessment followed the protocols found in HUD's Visual Assessment Training course.

Deteriorated paint, chips or dust from painting activities and paint residue on floors were observed on the following components/surfaces.

Room	Component	Hazard	Treatment
Foyer	Stair Treads	Deteriorated Paint	Stabilized the
	(Wood)		paint (Repaint)
Kitchen	Door Casing in	<b>Deteriorated Paint</b>	Stabilized the
	Wall A		paint (Repaint)
Bedroom 1	Door Jamb and	Deteriorated Paint	Stabilized the
	Casing in Wall D		paint (Repaint)
Bedroom 1	Closet Door Jamb	Deteriorated Paint	Stabilized the
	and Casing in Wall		paint (Repaint)
	C (Wood)		
Bedroom 3	Door Jamb and	Deteriorated Paint	Stabilized the
	Casing in Wall B		paint (Repaint)
	(Wood)		
Hall 1 (2 <sup>nd</sup> Floor)	Baseboards	Deteriorated Paint	Stabilized the
			Paint (Repaint)
Hall 1 (2 <sup>nd</sup> Floor)	Door Casing	Deteriorated Paint	Stabilized the
	(Attic Door)		Paint (Repaint)

Identified hazards shall be remediated using either abatement (permanent) or interim controls (temporary). Abatement shall be performed by a NJ Licensed lead abatement firm using licensed lead abatement supervisors and workers. Interim control work shall be performed by EPA RRP certified firms using an EPA certified RRP Renovator. After completion of interim control work, a lead-based paint post-remediation with dust wipes will be required. After completion of abatement work, a lead-based paint abatement clearance will be required.

Respectfully submitted,

Gerani Heredia

Yerani Heredia Risk Assessor, NJDOH ID# R001913

Encl: Photographs, Floor Plan Order# 29877



# Photographs



Foyer Stair Treads






# Bedroom 1 Door Jamb



Bedroom 1 Closet Door Jamb and Casing





Bedroom 1 Closet Door Jamb






Hall 1 Door Casing Wall B (Attic Door)

Bedroom 3 Door Jamb



## <u>Floor Plan</u>







PHILIP D. MURPHY

Governor LOCATION 101 S BROAD ST TRENTON NJ 08608 STATE OF NEW JERSEY DEPARTMENT OF COMMUNITY AFFAIRS DIVISION OF CODES AND STANDARDS LEAD HAZARD UNIT LT. GOVERNOR SHEILA Y. OLIVER

Commissioner

MAILING ADDRESS 101 S BROAD ST TRENTON NJ 08618

#### Certificate - Lead Evaluation Contractor

#### RECERTIFIED

This is to certify that the Department of Community Affairs has certified

LEW ENVIRONMENTAL SERVICES,LLC 181 US HIGHWAY 46 MINE HILL NJ 07803

To act as a Lead Evaluation Contractor on the following Projects

Residential Public Buildings Comm/Steel Structure

Cert #:00015-EEffective Date:4/1/2023Expiration Date:3/31/2025Certificate Type:2 YEAR





PHILIP D. MURPHY

Governor LOCATION 101 S BROAD ST TRENTON NJ 08608 STATE OF NEW JERSEY DEPARTMENT OF COMMUNITY AFFAIRS DIVISION OF CODES AND STANDARDS LEAD HAZARD UNIT LT. GOVERNOR SHEILA Y, OLIVER

Commissioner

MAILING ADDRESS 101 S BROAD ST TRENTON NJ 08618

3/23/2023

00015-E

LEW ENVIRONMENTAL SERVICES,LLC 181 US HIGHWAY 46 MINE HILL NJ 07803

Dear LEE E. WASSERMAN

Enclosed is the certification necessary for your firm to work as a Lead Evaluation Contractor in New Jersey. If you have any questions or need additional information, please call at (609) 633-6224.

Sincerely,

O. Tex Falajiki Supervisor of Certification Lead Hazard Unit

