

181 US Hwy 46 Mine Hill, NJ 07830 (908) 654-8068 (800) 783-0567 Fax 908-654-8069

Lead Dust Wipe Report

For 341-43 Sumner Ave Unit:2 Plainfield City, NJ 07062 09/27/2024

On 09/12/2024, LEW Environmental Services, LLC (NJDCA 00015 E) performed a dust wipe sampling for the presence of lead at 341-43 Sumner Ave Unit:2, (the "property") in compliance with NJAC 5:28A. We conducted our inspection in accordance with all federal, state, and municipal regulations. The regulations and inspection standards require that we plan and perform the inspection to obtain a reasonable assurance about whether or not the property is at risk from lead dust.

The maintenance and the environmental conditions of the property are the responsibility of the property's management, principals, or owners. If the property, program, or any of its tenants receive financial federal assistance, the results of this evaluation must be provided by the designated party (client) to the owner of the referenced property and the occupants within 15 calendar days of the date when the designated party receives this report or makes the presumption that lead-based paint hazards exist, per the Department of Housing and Urban Development 24 CFR Part 35.125.

All dust wipes tested are not considered actionable for lead dust. The property may still contain lead painted components and lead dust re-accumulation is possible.

Respectfully Submitted,

Gerani Heredia

Yerani Heredia De Rosado NJDOH Risk Assessor, NJDOH ID#R001913 Encl: Laboratory Results, Floor Plan, Lead-safe Certificate



LEW Corp

181 US Hwy 46

Mine Hill, NJ 07803

Lead Dust Wipe Analysis Report

Report Number: 24-09-02565

 Received Date:
 09/16/2024

 Analyzed Date:
 09/19/2024

 Reported Date:
 09/19/2024

Project/Test Address: 64511; Dust Wipe Sampling; 341-43 Sumner Ave Unit 2; Plainfield, NJ **Collection Date:** 09/12/2024

Client Number: 201327

Client:

Laboratory Results

<u>Fax Number:</u> Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft²)	Concentration (ug/ft²)	Narrative ID
24-09-02565- 001	1	SUNROOM AC	FL	<5.00	1.00	<5.00	
24-09-02565- 002	2	KITCHEN AC	FL	<5.00	1.00	<5.00	
24-09-02565- 003	3	BATHROOM AC	FL	<5.00	1.00	<5.00	
24-09-02565- 004	4	BEDROOM 1 AC	FL	<5.00	1.00	<5.00	
24-09-02565- 005	5	BEDROOM 2 AC	FL	<5.00	1.00	<5.00	
24-09-02565- 006	6	KITCHEN CC	SL	<5.00	0.594	<8.42	
24-09-02565- 007	7	BATHROOM DC	SL	<5.00	0.323	<15.5	
24-09-02565- 008	8	BEDROOM 1 BC	SL	<5.00	0.753	<6.65	
24-09-02565- 009	9	BEDROOM 2 BC	SL	<5.00	0.753	<6.65	

64511; Dust Wipe Sampling; 341-43 Sumner Ave Unit	
2; Plainfield, NJ	

Lab SampleClient SampleCollection LocationSurfaceTotal PbWipe AreaConcentrationNaNumberNumber(ug)(ft²)(ug/ft²)		· · · · · ·	Collection Location	Surface		•		Narrative ID
--	--	-------------	---------------------	---------	--	---	--	-----------------

Environmental Hazards Services, L.L.C

Method: ASTM E-1979-17/EPA SW846 7000B

201327

Accreditation #:

Client Number:

Project/Test Address:

Reviewed By Authorized Signatory:

Candace Mason

QA Chemist

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft2 are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accrediitation through AIHA LAP, LLC (100420), NY ELAP #11714.

Legend	ug = microgram	ug/ft ² = micrograms per square foot	Pb = lead
	mL = milliliter	ft ² = square foot	


Report Number: 24-09-02565

Relinquished by: Urani				~	8	X	9	S	7		2			Sample #	Project Number:	 	Dut 0	Fi	AI LEW Environmental Services P:	ENVIRONMENTAL S	
Hendia Signa				(h2-21-30		Date Collected	Order # 64511	MARC A	18	55	A Mainline Company P: (800) 783-0567	SERVICES	
Signature: Mari Herebia				W-Sill Bedroom 2 BC	W-Sill Bedroom 1 BC	W-Jill Bethron DC	WSill Kitchen CC	FLOUR Bedroom 2 AC	floor Aldroom 1 Ac	floor Dathrow Ac		Floor Sur Room Ac	(Ex: Fl, Kitchen, AC)	Sample Location	- Soil I Day Weekend - TCLP I Week 2 Weeks	Day R	_ Sample Type Turn Around Time (TAT)		Chain-of-Custody		Lead
Date/Time: 09 - 12 - 24 Date/Time: 9/16/24 130pm	×	×	×	31 × 31/2	2/× 3/2	151/2 × 3	28 Ex 3	12 × 12	12 × 12	21 ×21	21 × 21	2) × 21	(inches) mg/cm ²	Area Paint	ks Signature:	Name:	Sampler Information	* All wipes submitted in the second s	(Thursday) AE	09/19/2024	La Due Date:
10. july		-		· · · · · · · · · · · · · · · · · · ·									PPM % wt	Paint Chip Analysis			ion		(VE	024	e:

Floor Plan(s)



181 US Hwy 46 Mine Hill, NJ 07803 (908) 654-8068 (800) 783-0567 Fax (908) 654-8069 usaw levensyonmerful com



Floor 1

Lew Environmental Services - 341-43 Sumner Ave Unit:2 -Visual Inspection Prepared By: LEW Environmental Services, LLC 09/27/2024



It is hereby certified that a lead based paint visual inspection and/or dust wipe sampling has been performed in accordance with the protocols referenced in N.J.A.C. 5:17, and the results of which indicate that no lead-based paint hazards have been found in the dwelling unit listed below. It shall be the owner's responsibility to perform any required on-going evaluation and maintenance to ensure that the dwelling unit remain in a Lead - Safe condition. PURSUANT TO P.L.2003, c.311 (C.52:27D-437.1 et. seq.)

This certificate is **Valid For Two Years**

341-43 Sumner Ave Unit:2 Plainfield City	y, NJ 07062			414	33		
Site Adddress				Block	Lot		
	Applicable	Dwelling Unit: <u>341-43 Sumn</u>	er Ave Unit:2				
(CERTIFIC	CATE IS VALID FC	OR A DWELLING UNIT AND S	HALL BE AFFIXED	TO LEASE)			
Insp/RA Name: Yerani Heredia D	e Rosado	Evaluation Contractor	#: 00015-E	Phone: 908-65	54-8068		
		Contractor Name:	Lew Environme	ntal Services, LLC			
Gerani Heredia		Contractor Address:					
1	R001913		Mine Hill, NJ 07830 09/12/2024				
Signature	ID#	Date Issued:					
			(mm/dd/yyyy)				