

181 US Hwy 46 Mine Hill, NJ 07830 (908) 654-8068 (800) 783-0567 Fax 908-654-8069

## Lead Dust Wipe Report

For 358 Queens Court Ridgewood Village, NJ 07450 09/27/2024

On 09/13/2024, LEW Environmental Services, LLC (NJDCA 00015 E) performed a dust wipe sampling for the presence of lead at 358 Queens Court, (the "property") in compliance with NJAC 5:28A. We conducted our inspection in accordance with all federal, state, and municipal regulations. The regulations and inspection standards require that we plan and perform the inspection to obtain a reasonable assurance about whether or not the property is at risk from lead dust.

The maintenance and the environmental conditions of the property are the responsibility of the property's management, principals, or owners. If the property, program, or any of its tenants receive financial federal assistance, the results of this evaluation must be provided by the designated party (client) to the owner of the referenced property and the occupants within 15 calendar days of the date when the designated party receives this report or makes the presumption that lead-based paint hazards exist, per the Department of Housing and Urban Development 24 CFR Part 35.125.

All dust wipes tested are not considered actionable for lead dust. The property may still contain lead painted components and lead dust re-accumulation is possible.

Respectfully Submitted,

Oric Hashington

Gloria Washington NJDOH Risk Assessor, NJDOH ID#040601 Encl: Laboratory Results, Floor Plan, Lead-safe Certificate



LEW Corp

181 US Hwy 46

Mine Hill, NJ 07803

## Lead Dust Wipe **Analysis Report**

**Report Number:** 24-09-03406

**Received Date:** 09/19/2024 Analyzed Date: 09/24/2024 **Reported Date:** 09/24/2024

Project/Test Address: 93849; Walter Li; 358 Queens Ct; Ridgewood, NJ **Collection Date:** 09/13/2024

**Client Number:** 201327

Client:

# Laboratory Results

Fax Number: Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft²)	Concentration (ug/ft <sup>2</sup> )	Narrative ID
24-09-03406- 001	358-1	BSMT D	SL	<5.00	0.521	<9.60	
24-09-03406- 002	358-2	OFFICE ACC	FL	<5.00	1.00	<5.00	
24-09-03406- 003	358-3	SUNROOM AD	FL	<5.00	1.00	<5.00	

#### Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory: Milisoa Kanode

Melissa Kanode

QA/QC Clerk

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft2 are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accrediitation through AIHA LAP, LLC (100420), NY ELAP #11714.


Legend	ug = microgram	ug/ft <sup>2</sup> = micrograms per square foot	Pb = lead	
	mL = milliliter	ft <sup>2</sup> = square foot		

1 of 1 Page

Received by:	Relinquished by: Glora Mu												دو	358-1		Sample #	ENVIRONMENTAL SERVICES AMainline Company LEW Environmental Services P: (800) 783-0567 F: (908) 654-8069 Project Name: Walter Li Address: 358 (Queens Ct City, State: Magewood M Project Number: 92
rent Sig	ashundren Sig											<ul> <li>*</li></ul>		9-13-24		Date Collected	- SERVICES A Mainline Company P: (800) 783-0567 F: (908) 654-8069 F: (908) 654-8069
Signature: John	Signature:	MA A										SunroomFLAD	Office FLACE	BSMTWSD	(Ex: Fl, Kitchen, AC)	Sample Location	Sample Type       Turn Around Time (TAT)         Paint chip       Same Day         Soil       1 Day         TCLP       1 Week
Date/Time: 9/19/24 12:49 AM	Date/Time: 9/14/24.10:00		×	×	X	×	×	X	X	X	×	12×12	12×12	20 × 21/2	(inches) mg/cm <sup>2</sup> PPM % wt	Area Paint Chip Analysis	24-09-03406 Due Date: 09/24/2024 (Tuesday) AE Name: Olyna Mashington Signature: All w


SWW

## Floor Plan(s)




Floor 1

Lew Environmental Services - 358 Queens Court -Visual Inspection Prepared By: LEW Environmental Services, LLC 09/27/2024



Floor 2

Lew Environmental Services - 358 Queens Court -Visual Inspection Prepared By: LEW Environmental Services, LLC 09/27/2024



Floor 3

Lew Environmental Services - 358 Queens Court -Visual Inspection Prepared By: LEW Environmental Services, LLC 09/27/2024



It is hereby certified that a lead based paint visual inspection and/or dust wipe sampling has been performed in accordance with the protocols referenced in N.J.A.C. 5:17, and the results of which indicate that no lead-based paint hazards have been found in the dwelling unit listed below. It shall be the owner's responsibility to perform any required on-going evaluation and maintenance to ensure that the dwelling unit remain in a Lead - Safe condition. PURSUANT TO P.L.2003, c.311 (C.52:27D-437.1 et. seq.)

### This certificate is **Valid For Two Years**

358 Queens Court Ridgewood Village, NJ 07	450			4710	9	
Site Adddress				Block	Lot	
	Appl	icable Dwelling Unit: 358 Que	<u>ens Court</u>			
(CERTIFICAT	E IS VALID	FOR A DWELLING UNIT AND	SHALL BE AFFIXE	ED TO LEASE)		
Insp/RA Name: Gloria Washington	Phone: 908-654-	8068				
		<b>Contractor Name:</b>	Lew Environm	ental Services, LLC		
Rorie Hashington		<b>Contractor Address:</b>	181 US Hwy 40	6		
Junic = rushingen	040601		Mine Hill, NJ 0	7830		
Signature	 ID#	Date Issued:	09/13/2024			
			(mm/dd/yyyy )			