



Visual Paint Assesment Report

For 46 Martin Luther King Ave Unit:1 Morristown Town, NJ 07960 07/04/2024

On 07/03/24, LEW Environmental Services, LLC (NJDCA 00015 E) performed a visual paint condition assessment for the presence of deteriorated paint, chips or dust from painting activities and paint residue on floors at 46 Martin Luther King Ave Unit:1, (the "property") in compliance with NJAC 5:28A. Only the dwelling and common area interiors were included. Exteriors were not part of the assessment. The visual assessment followed the protocols found in HUD's Visual Assessment Training course.

No deteriorated paint, chips or dust from painting activities or paint residue on floors were observed in the dwelling unit. The property is eligible for a lead-safe certificate per NJAC 5:28A. Certificate enclosed

Respectfully Submitted,

Yerani Heredia De Rosado

Gerani Heredia

NJDOH Risk Assessor, ID#R001913


Encl: Floor Plan, Lead-safe Certificate;

Floor Plan(s)



181 Route 46 Mine Hill, NJ 07803 (908)654-8068 (800)783-0567 Fax (908)654-8069 www.lewcorp.com

Site: 46 Martin Wher King Ave. Unit 1, Moniston, NJ



Floor 1

Lew Environmental Services - 46 Martin Luther King Ave Unit:1 -Visual Inspection Prepared By: LEW Environmental Services, LLC 07/04/2024



Lead Safe Certificate

It is hereby certified that a lead based paint visual inspection and/or dust wipe sampling has been performed in accordance with the protocols referenced in N.J.A.C. 5:17, and the results of which indicate that no lead-based paint hazards have been found in the dwelling unit listed below. It shall be the owner's responsibility to perform any required on-going evaluation and maintenance to ensure that the dwelling unit remain in a Lead - Safe condition. PURSUANT TO P.L.2003, c.311 (C.52:27D-437.1 et. seq.)

This certificate is Valid For Two Years

46 Martin Luther King Ave Unit:1 Morristown Town, NJ 07960	2401	3
Site Adddress	Block	Lot

Applicable Dwelling Unit: 46 Martin Luther King Ave Unit:1

(CERTIFICATE IS VALID FOR A DWELLING UNIT AND SHALL BE AFFIXED TO LEASE)

Insp/RA Name: Yerani Heredia De Rosado		Evaluation Contractor #: 00015-E		Phone: 908-654-8068
		Contractor Name: Lew Environmental Services, LLC		ental Services, LLC
Gerani Heredia		Contractor Address:	181 US Hwy 46	
	R001913		Mine Hill, NJ 0	7830
Signature	ID#	Date Issued:	07/03/24	
			(mm/dd/yyyyy)	