

181 US Hwy 46 Mine Hill, NJ 07830 (908) 654-8068 (800) 783-0567 Fax 908-654-8069

Visual Paint Assesment Report

For 52 Allen St Unit:A Netcong Borough, NJ 07857 07/04/2024

On 07/03/24, LEW Environmental Services, LLC (NJDCA 00015 E) performed a visual paint condition assessment for the presence of deteriorated paint, chips or dust from painting activities and paint residue on floors at 52 Allen St Unit:A, (the "property") in compliance with NJAC 5:28A. Only the dwelling and common area interiors were included. Exteriors were not part of the assessment. The visual assessment followed the protocols found in HUD's Visual Assessment Training course.


No deteriorated paint, chips or dust from painting activities or paint residue on floors were observed in the dwelling unit. The property is eligible for a lead-safe certificate per NJAC 5:28A. Certificate enclosed

Respectfully Submitted,

Jamy Tel

Danny Feliciano NJDOH Risk Assessor, ID#033001 Encl: Floor Plan, Lead-safe Certificate;

Floor Plan(s)



Floor 1

Lew Environmental Services - 52 Allen St Unit: A -Visual Inspection Prepared By: LEW Environmental Services, LLC 07/04/2024



It is hereby certified that a lead based paint visual inspection and/or dust wipe sampling has been performed in accordance with the protocols referenced in N.J.A.C. 5:17, and the results of which indicate that no lead-based paint hazards have been found in the dwelling unit listed below. It shall be the owner's responsibility to perform any required on-going evaluation and maintenance to ensure that the dwelling unit remain in a Lead - Safe condition. PURSUANT TO P.L.2003, c.311 (C.52:27D-437.1 et. seq.)

This certificate is **Valid For Two Years**

52 Allen St Unit:A Netcong Borough, NJ 07857				5	3
Site Adddress				Block	Lot
	App	licable Dwelling Unit: <u>52 Allen</u>	<u>St Unit:A</u>		
(CERTIFICATE IS	S VALID	FOR A DWELLING UNIT AND S	HALL BE AFFIXED T	ΓΟ LEASE)	
Insp/RA Name: Danny Feliciano		Evaluation Contractor #: 00015-E Ph		Phone: 908-654-80)68
\frown		Contractor Name:	Lew Environmental Services, LLC		
Dany Tel		Contractor Address:	181 US Hwy 46		
	033001 ID#	Date Issued:	Mine Hill, NJ 07830		
· · · · · · · · · · · · · · · · · · ·			07/03/24		
			(mm/dd/yyyy)		