



## **Lead Dust Wipe Report**

For 544 W Front St Unit:4 Plainfield City, NJ 07060 11/26/2024

On 11/20/2024, LEW Environmental Services, LLC (NJDCA 00015 E) performed a dust wipe sampling for the presence of lead at 544 W Front St Unit:4, (the "property") in compliance with NJAC 5:28A. We conducted our inspection in accordance with all federal, state, and municipal regulations. The regulations and inspection standards require that we plan and perform the inspection to obtain a reasonable assurance about whether or not the property is at risk from lead dust.

The maintenance and the environmental conditions of the property are the responsibility of the property's management, principals, or owners. If the property, program, or any of its tenants receive financial federal assistance, the results of this evaluation must be provided by the designated party (client) to the owner of the referenced property and the occupants within 15 calendar days of the date when the designated party receives this report or makes the presumption that lead-based paint hazards exist, per the Department of Housing and Urban Development 24 CFR Part 35.125.

**All dust wipes tested are not considered actionable for lead dust.** Attached you will find the NJ Lead Safe Certificate. On 9/12/24, Governor Murphy signed bill S-3368 that extends the validity of the lead safe certificate to three years. The property may still contain lead painted components and lead dust re-accumulation is possible.

Respectfully Submitted,

Tale Vie

Pablo Viera

Risk Assesor, NJDOH ID#D-I-T226395-24-00064

Encl: Laboratory Results, Floor Plan, Lead-safe Certificate



7469 Whitepine Rd North Chesterfield, VA 23237 Telephone: 800.347.4010

## Lead Dust Wipe Analysis Report

**Report Number:** 24-11-04494

Client: LEW Corp

181 US Hwy 46 Mine Hill, NJ 07803 **Received Date:** 11/25/2024 **Analyzed Date:** 11/25/2024

**Reported Date:** 11/25/2024

Project/Test Address: 121977; Monica Russell; 544 W Front St Unit 4; Plainfield, NJ

Collection Date: 11/20/2024

Client Number:
201327

Laboratory Results

Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft²)	Concentration (ug/ft²)	Narrative ID
24-11-04494- 001	54-1	SUN ROOM		<5.00	1.00	<5.00	
24-11-04494- 002	54-2	BEDROOM 1 CC	FL	<5.00	1.00	<5.00	

Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory:

Candace Mason

**QA Chemist** 

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft2 are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accrediitation through AIHA LAP, LLC (100420), NY ELAP #11714.

Legend	ug = microgram	ug/ft² = micrograms per square foot	Pb = lead
	mL = milliliter	ft <sup>2</sup> = square foot	



# **ENVIRONMENTAL SERVICES**

LEW Environmental Services P: (800) 783-0567 A Mainline Company

F: (908) 654-8069

## 

## Chain-of-Custody

	Paint Chip Analysis	Area	Sample Location	Sar	Date Collected	Sample #
	Sampler Information  (O U; & C	Sampler Information Name: RSCO Uitora Signature: Racya	Turn Around Time (TAT)  Same Day  1 Day  2 Weekend  2 Weeks	Sample Type Dust wipe Paint chip Soil TCLP	11 (a. Russell W Frant St Ud , NJ UNITY (21977	Project Name: MONICA (WSJ&L) Address: SYY W FRATST  City, State: Plainticli, NJ UNITY  Project Number: (21977
L		* All wipes			F: (908) 654-8069	

TO THE POST OF THE				
Sample #	Date Collected	Sample Location	Area	Paint Chip Analysis
		(Ex: Fl, Kitchen, AC)	(inches)	mg/cm² PPM % wt
54-1	11-20-24	Sur laur	12 × 12	
54-2	11-20-24	Bediann 1 Floor CC	12 × 12	
			X	
D. Marille			×	
			×	
			×	
			×	
			×	
			×	
			×	
			×	
			×	
Relinquished by: Pasion R		Signature: Perentui	Date/Time: 11-20-24	24 4:50pm
Received by:		Signature:	Date/Time:	とくころう
		The second second	200	The second second

Ţ. ] 24-11-04494 Due Date:


11/25/2024

(Monday) AE

## Floor Plan(s)



181 US 19ay 46 Mine Hill, NJ 07803 (908) 654-8068 (800) 783-0567 Fax (908) 654-8069 www.levenvironmental.com



Floor 1

Lew Environmental Services - 544 W Front St Unit:4 -Visual Inspection Prepared By: LEW Environmental Services, LLC 11/26/2024



It is hereby certified that a lead based paint visual inspection and/or dust wipe sampling has been performed in accordance with the protocols referenced in N.J.A.C. 5:17, and the results of which indicate that no lead-based paint hazards have been found in the dwelling unit listed below. It shall be the owner's responsibility to perform any required on-going evaluation and maintenance to ensure that the dwelling unit remain in a Lead - Safe condition. PURSUANT TO P.L.2003, c.311 (C.52:27D-437.1 et. seq.)

### This certificate is Valid For Two Years

544 W Front St Unit:4 Plainfield City, NJ 07060	234	10
Site Adddress	Block	Lot

Applicable Dwelling Unit: 544 W Front St Unit:4

(CERTIFICATE IS VALID FOR A DWELLING UNIT AND SHALL BE AFFIXED TO LEASE)

Insp/RA Name: Greg Krueger Evaluation Contractor #: 00015-E Phone: 908-654-8068

013865

Signature ID#

**Contractor Name:** 

Lew Environmental Services, LLC

**Contractor Address:** 

181 US Hwy 46

Mine Hill, NJ 07830

**Date Issued:** 

11/20/2024

(mm/dd/yyyy)

Pablo Viera I

D-I-T226395-24-00064

Technician Signature

Technician Name ID#