

Lead Dust Wipe Report


For 702 Sewall Avenue Unit:2 Asbury Park City, NJ 07712
11/26/2024

On 11/14/2024, LEW Environmental Services, LLC (NJDC 00015 E) performed a dust wipe sampling for the presence of lead at 702 Sewall Avenue Unit:2, (the "property") in compliance with NJAC 5:28A. We conducted our inspection in accordance with all federal, state, and municipal regulations. The regulations and inspection standards require that we plan and perform the inspection to obtain a reasonable assurance about whether or not the property is at risk from lead dust.

The maintenance and the environmental conditions of the property are the responsibility of the property's management, principals, or owners. If the property, program, or any of its tenants receive financial federal assistance, the results of this evaluation must be provided by the designated party (client) to the owner of the referenced property and the occupants within 15 calendar days of the date when the designated party receives this report or makes the presumption that lead-based paint hazards exist, per the Department of Housing and Urban Development 24 CFR Part 35.125.

All dust wipes tested are not considered actionable for lead dust. Attached you will find the NJ Lead Safe Certificate. On 9/12/24, Governor Murphy signed bill S-3368 that extends the validity of the lead safe certificate to three years. The property may still contain lead painted components and lead dust re-accumulation is possible.

Respectfully Submitted,



Treyson Atchley
Risk Assessor, NJDOH ID#D-I-T226395-24-00076
Encl: Laboratory Results, Floor Plan, Lead-safe Certificate



7469 Whitepine Rd
 North Chesterfield, VA 23237
 Telephone: 800.347.4010

Lead Dust Wipe Analysis Report

Report Number: 24-11-03848

Client: LEW Corp
 181 US Hwy 46
 Mine Hill, NJ 07803

Received Date: 11/20/2024
Analyzed Date: 11/25/2024
Reported Date: 11/25/2024

Project/Test Address: 111811; Treyson Atchley; 702 Sewall Unit 2; Asbury Park, NJ
Collection Date: 11/14/2024

Client Number:
 201327

Laboratory Results

Fax Number:
 Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
24-11-03848-001	702-1	CA CC	FL	<5.00	1.00	<5.00	
24-11-03848-002	702-2	BATHROOM CC	FL	<5.00	1.00	<5.00	
24-11-03848-003	702-3	K CC	FL	<5.00	1.00	<5.00	
24-11-03848-004	702-4	BR 1 CC	FL	<5.00	1.00	<5.00	
24-11-03848-005	702-5	SUNROOM CC	FL	<5.00	1.00	<5.00	
24-11-03848-006	702-6	CA D	SL	<5.00	0.333	<15.1	
24-11-03848-007	702-7	BATHROOM C	SL	<5.00	0.333	<15.1	
24-11-03848-008	702-8	K B	SL	<5.00	0.333	<15.1	
24-11-03848-009	702-9	BR 1 C	SL	<5.00	0.333	<15.1	

Environmental Hazards Services, L.L.C

Client Number: 201327
Project/Test Address: 111811; Treyson Atchley; 702 Sewall Unit 2; Asbury Park, NJ

Report Number: 24-11-03848

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
-------------------	----------------------	---------------------	---------	---------------	------------------------------	-------------------------------------	--------------

Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory:



Amanda Lowery

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft² are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accreditation through AIHA LAP, LLC (100420), NY ELAP #11714.

Legend

ug = microgram
mL = milliliter

ug/ft² = micrograms per square foot
ft² = square foot

Pb = lead



ENVIRONMENTAL SERVICES

LEW Environmental Services P: (800) 783-0567 F: (908) 654-8069

Lead

Chain-of-Custody



24-11-03848

Due Date: 11/25/2024 (Monday)

* All in 5/1 AE

Project Name: Treyson Atchley
Address: 702 Sewan Court
City, State: Ashbury Park NJ
Project Number: 111811

Sample Type: Dust wipe, Paint chip, Soil, TSP
Turn Around Time (TAT): Same Day, 3 Day, 1 Day, 1 Week, 2 Weeks, Weekend

Sampler Information: Name: Treyson Atchley, Signature: Treyson Atchley

Sample #	Date Collected	Sample Location (Ex: Fl, Kitchen, AC)	Area (Inches)	Paint Chip Analysis		
				mg/cm ²	ppm	% wt
702-1	11/14/2024	CA Fl CC	12 x 12			
-2		Bathroom Fl CC	12 x 12			
-3		Lc Fl CC	12 x 12			
-4		BRA Fl CC	12 x 12			
-5		Sun Room Fl CC	12 x 12			
-6		CA WS B	24 x 2			
-7		Bath Room WS C	24 x 2			
-8		K WS B	24 x 2			
-9		BRA WS C	24 x 2			


Relinquished by: Treyson Atchley, Signature: Treyson Atchley, Date/Time: 11/14/2024 4:44 PM
Received by: Bobb, Signature: Bobb, Date/Time: 11/20/24 3:24 PM

2/5

Floor Plan(s)

Floor 1

Lew Environmental Services - 702 Sewall Avenue Unit:2 -Visual Inspection
Prepared By: LEW Environmental Services, LLC
11/26/2024



Lead Safe Certificate

It is hereby certified that a lead based paint visual inspection and/or dust wipe sampling has been performed in accordance with the protocols referenced in N.J.A.C. 5:17, and the results of which indicate that no lead-based paint hazards have been found in the dwelling unit listed below. It shall be the owner's responsibility to perform any required on-going evaluation and maintenance to ensure that the dwelling unit remain in a Lead - Safe condition. PURSUANT TO P.L.2003, c.311 (C.52:27D-437.1 et. seq.)

This certificate is **Valid For Two Years**

702 Sewall Avenue Unit:2 Asbury Park City, NJ 07712
Site Address

2608 4
Block Lot

Applicable Dwelling Unit: **702 Sewall Avenue Unit:2**

(CERTIFICATE IS VALID FOR A DWELLING UNIT AND SHALL BE AFFIXED TO LEASE)

Insp/RA Name: Greg Krueger

Evaluation Contractor #: 00015-E

Phone: 908-654-8068

013865

Signature

ID#

Contractor Name: Lew Environmental Services, LLC

Contractor Address: 181 US Hwy 46

Mine Hill, NJ 07830

Date Issued: 11/14/2024

(mm/dd/yyyy)

Treyson Atchley

D-I-T226395-24-00076

Technician Signature

Technician Name

ID#