



181 US Hwy 46
Mine Hill, NJ 07830
(908) 654-8068
(800) 783-0567
Fax 908-654-8069

Lead Dust Wipe Report

For 726 PEARL ST Elizabeth City, NJ
11/26/2024

On 11/13/2024, LEW Environmental Services, LLC (NJDC 00015 E) performed a dust wipe sampling for the presence of lead at 726 PEARL ST, (the "property") in compliance with NJAC 5:28A. We conducted our inspection in accordance with all federal, state, and municipal regulations. The regulations and inspection standards require that we plan and perform the inspection to obtain a reasonable assurance about whether or not the property is at risk from lead dust.

The maintenance and the environmental conditions of the property are the responsibility of the property's management, principals, or owners. If the property, program, or any of its tenants receive financial federal assistance, the results of this evaluation must be provided by the designated party (client) to the owner of the referenced property and the occupants within 15 calendar days of the date when the designated party receives this report or makes the presumption that lead-based paint hazards exist, per the Department of Housing and Urban Development 24 CFR Part 35.125.

All dust wipes tested are not considered actionable for lead dust. Attached you will find the NJ Lead Safe Certificate. On 9/12/24, Governor Murphy signed bill S-3368 that extends the validity of the lead safe certificate to three years. The property may still contain lead painted components and lead dust re-accumulation is possible.

Respectfully Submitted,

A handwritten signature in black ink, appearing to read 'Pablo Viera', is written in a cursive style.

Pablo Viera
Risk Assesor, NJDOH ID#D-I-T226395-24-00064
Encl: Laboratory Results, Floor Plan, Lead-safe Certificate



7469 Whitepine Rd
 North Chesterfield, VA 23237
 Telephone: 800.347.4010

Lead Dust Wipe Analysis Report

Report Number: 24-11-03255

Client: LEW Corp
 181 US Hwy 46
 Mine Hill, NJ 07803

Received Date: 11/18/2024
 Analyzed Date: 11/20/2024
 Reported Date: 11/21/2024

Project/Test Address: 114547; Mark Rappisi; 726 Pearl St; Elizabeth, NJ
 Collection Date: 11/13/2024

Client Number:
 201327

Laboratory Results

Fax Number:
 Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
24-11-03255-001	72-1	SUNROOM	FL	<5.00	1.00	<5.00	
24-11-03255-002	72-2	LIVING ROOM AC	FL	<5.00	1.00	<5.00	
24-11-03255-003	72-3	KITCHEN CC	FL	<5.00	1.00	<5.00	
24-11-03255-004	72-4	BEDROOM 1 DC	FL	<5.00	1.00	<5.00	
24-11-03255-005	72-5	BEDROOM 3 CC	FL	<5.00	1.00	<5.00	
24-11-03255-006	72-6	KITCHEN C1	SL	<5.00	0.621	<8.06	
24-11-03255-007	72-7	LIVING ROOM A1	SL	<5.00	0.766	<6.54	
24-11-03255-008	72-8	BEDROOM 1	SL	<5.00	0.688	<7.27	
24-11-03255-009	72-9	BEDROOM 3	SL	18.9	1.11	17.0	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 24-11-03255

Project/Test Address: 114547; Mark Rappisi; 726 Pearl St; Elizabeth, NJ

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
-------------------	----------------------	---------------------	---------	---------------	------------------------------	-------------------------------------	--------------

Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode

QA/QC Clerk

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft² are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accreditation through AIHA LAP, LLC (100420), NY ELAP #11714.

Legend	ug = microgram	ug/ft ² = micrograms per square foot	Pb = lead
	mL = milliliter	ft ² = square foot	



ENVIRONMENTAL SERVICES

A Mainline Company

LEW Environmental Services P: (800) 783-0567

F: (908) 654-8069

Lead

Chain-of-Custody

Lab Use C



24-1-03255

Due Date:

11/21/2024

(Thursday)

AE

* All wipes submitted

10x

Project Name: Mark Rappisi
 Address: 726 Pearl St
 City, State: Elizabeth NJ
 Project Number: 114547

Sample Type
 Dust wipe
 Paint chip
 Soil
 TCLP

Turn Around Time (TAT)
 Same Day
 1 Day
 1 Week
 3 Day
 Weekend
 2 Weeks

Sampler Information
 Name: Pasio Viora
 Signature: Pasio Viora

Sample #	Date Collected	Sample Location (Ex: Fl, Kitchen, AC)	Area (inches)	Paint Chip Analysis		
				mg/cm ²	PPM	% wt
72-1	11-13-24	Sun Room	12 x 12			
-2		Living Room Floor AC	X			
-3		Kitchen Floor CC	X			
-4		Bedroom 4 Floor DC	X			
-5		Bedroom 3 Floor CC	X			
-6		Kitchen Sill C1	27 1/2 x 3 1/4			
-7		Living Room Sill A1	31 1/2 x 3 1/2			
-8		Bedroom Sill	30 1/2 x 3 1/4			
-9		Bedroom 3 Sill	30 1/2 x 5 1/4			
			X			
			X			
			X			


Relinquished by: Pasio Viora Signature: Pasio Viora Date/Time: 11-13-24 6:40 pm
 Received by: HH Humphrey Signature: HH Humphrey Date/Time: 11/18/24 4:30p

Floor Plan(s)




181 US Hwy 46
Mine Hill, NJ 07803
(908) 654-8068
(800) 783-0567
Fax (908) 654-8069
www.lewenvironmental.com

Site: 726 Pearl St, Elizabeth



Floor 1

Lew Environmental Services - 726 PEARL ST - Visual Inspection
Prepared By: LEW Environmental Services, LLC
11/26/2024



Lead Safe Certificate

It is hereby certified that a lead based paint visual inspection and/or dust wipe sampling has been performed in accordance with the protocols referenced in N.J.A.C. 5:17, and the results of which indicate that no lead-based paint hazards have been found in the dwelling unit listed below. It shall be the owner's responsibility to perform any required on-going evaluation and maintenance to ensure that the dwelling unit remain in a Lead - Safe condition. PURSUANT TO P.L.2003, c.311 (C.52:27D-437.1 et. seq.)

This certificate is **Valid For Two Years**

726 PEARL ST Elizabeth City, NJ
Site Address

448
Block

50
Lot

Applicable Dwelling Unit: **726 PEARL ST**

(CERTIFICATE IS VALID FOR A DWELLING UNIT AND SHALL BE AFFIXED TO LEASE)

Insp/RA Name: Greg Krueger

Evaluation Contractor #: 00015-E

Phone: 908-654-8068

013865

Signature

ID#

Contractor Name:

Lew Environmental Services, LLC

Contractor Address:

181 US Hwy 46

Mine Hill, NJ 07830

Date Issued:

11/13/2024

(mm/dd/yyyy)

Pablo Viera

D-I-T226395-24-00064

Technician Signature

Technician Name ID#