

181 US Hwy 46 Mine Hill, NJ 07830 (908) 654-8068 (800) 783-0567 Fax 908-654-8069

Lead Dust Wipe Report

For 93 Morris St Unit:B Phillipsburg Town, NJ 08865 07/02/2024

On 06/21/2024, LEW Environmental Services, LLC (NJDCA 00015 E) performed a dust wipe sampling for the presence of lead at 93 Morris St Unit:B, (the "property") in compliance with NJAC 5:28A. We conducted our inspection in accordance with all federal, state, and municipal regulations. The regulations and inspection standards require that we plan and perform the inspection to obtain a reasonable assurance about whether or not the property is at risk from lead dust.

The maintenance and the environmental conditions of the property are the responsibility of the property's management, principals, or owners. If the property, program, or any of its tenants receive financial federal assistance, the results of this evaluation must be provided by the designated party (client) to the owner of the referenced property and the occupants within 15 calendar days of the date when the designated party receives this report or makes the presumption that lead-based paint hazards exist, per the Department of Housing and Urban Development 24 CFR Part 35.125.

All dust wipes tested are not considered actionable for lead dust. The property may still contain lead painted components and lead dust re-accumulation is possible.

Respectfully Submitted,

Nyire Grant NJDOH Risk Assessor, NJDOH ID#021517 Encl: Laboratory Results, Floor Plan, Lead-safe Certificate



Lead Dust Wipe Analysis Report

Report Number: 24-06-04093

 Received Date:
 06/26/2024

 Analyzed Date:
 06/28/2024

 Reported Date:
 07/01/2024

LEW Corp 181 US Hwy 46 Mine Hill, NJ 07803

Project/Test Address: 36223; 93 B Morris St; Phillipsburg, NJ Collection Date: 06/21/2024

Client Number: 201327

Client:

Laboratory Results

Fax Number: Ext 18 Melissa

| | <u> </u> | | • • | | | | |
|----------------------|-------------------------|---------------------|---------|------------------|--------------------|----------------------------------------|-----------------|
| Lab Sample Number | Client Sample Number | Collection Location | Surface | Total Pb (ug) | Wipe Area (ft²) | Concentration (ug/ft ²) | Narrative ID |
| 24-06-04093- 001 | 1 | LIVING | FL | <5.00 | 1.00 | <5.00 | |
| 24-06-04093- 002 | 2 | LIVING | SL | <5.00 | 0.653 | <7.66 | |
| 24-06-04093- 003 | 3 | DEN | FL | 10.1 | 1.00 | 10.1 | |
| 24-06-04093- 004 | 4 | DEN | SL | <5.00 | 2.09 | <2.40 | |
| 24-06-04093- 005 | 5 | 1 BED | FL | <5.00 | 1.00 | <5.00 | |
| 24-06-04093- 006 | 6 | 1 BED | SL | <5.00 | 0.538 | <9.30 | |
| 24-06-04093- 007 | 7 | 2 BED | FL | <5.00 | 1.00 | <5.00 | |
| 24-06-04093- 008 | 8 | 2 BED | SL | <5.00 | 0.646 | <7.74 | |
| 24-06-04093- 009 | 9 | SUNROOM | FL | <5.00 | 1.00 | <5.00 | |

Environmental Hazards Services, L.L.C

Client Number: 201327 Project/Test Address: 36223; 93 B Morris St; Phillipsburg, NJ

Report Number: 24-06-04093

| Lab Sample Number | Client Sample Number | Collection Location | Surface | Total Pb (ug) | Wipe Area (ft²) | Concentration (ug/ft ²) | Narrative ID |
|----------------------|-------------------------|---------------------|---------|------------------|--------------------|----------------------------------------|-----------------|
| | | | | | | | |

Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory: Milisoa Kanode

Melissa Kanode

QA/QC Clerk

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft2 are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.


ELLAP Accrediitation through AIHA LAP, LLC (100420), NY ELAP #11714.

| Legend | ug = microgram | ug/ft ² = micrograms per square foot | Pb = lead |
|--------|-----------------|-------------------------------------------------|-----------|
| | mL = milliliter | ft ² = square foot | |

2 of 2 Page

| ICES Chain-of-Custody *All wps wasses States Sample Type Turn Around Time (TAT) *All wps *All wps States Sample Type Turn Around Time (TAT) *All wps *All wps States Sample Type Turn Around Time (TAT) *All wps *All wps States Sample Type Turn Around Time (TAT) *All wps *All wps States Sample Type Sample Type *All wps *All wps States Sample Type Sample Type *All wps *All wps States Sample Type Sample Type *All wps *All wps States Sample tocation Name: Wasses Wasses *All wps Date Collected Issert, Kitchen, AC) IS X 12 Paint Chip Analysis mg/cm ² PpM % 121/24 IBed FI ISSERt ISS |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| * All wipes * All wipes Sampler Info Name: Nume: Nume: Nume: Signature: Nume: Nume: Nume: 12 X 12 mg 12 X 12 mg 12 X 12 mg 12 X 12 X 12 X X X X X X X X X X X Date/Time: 6/24/24 6/24/24 |
| |

Floor Plan(s)



Floor 1

Lew Environmental Services - 93 Morris St Unit:B -Visual Inspection Prepared By: LEW Environmental Services, LLC 07/02/2024



It is hereby certified that a lead based paint visual inspection and/or dust wipe sampling has been performed in accordance with the protocols referenced in N.J.A.C. 5:17, and the results of which indicate that no lead-based paint hazards have been found in the dwelling unit listed below. It shall be the owner's responsibility to perform any required on-going evaluation and maintenance to ensure that the dwelling unit remain in a Lead - Safe condition. PURSUANT TO P.L.2003, c.311 (C.52:27D-437.1 et. seq.)

This certificate is **Valid For Two Years**

| 93 Morris St Unit:B Phillipsburg Town, N | J 08865 | | | 303 | 6 |
|--------------------------------------------------------------------------|---------------|----------------------------------------|---------------------------------|-------------|-----|
| Site Adddress | | | | Block | Lot |
| | Appl | icable Dwelling Unit: <u>93 Morris</u> | <u>St Unit:B</u> | | |
| (CERTIFIC | ATE IS VALID | FOR A DWELLING UNIT AND S | HALL BE AFFIXED TO LEA | SE) | |
| Insp/RA Name: Nyire Grant Evaluation Contractor #: 00015-E F | | | Phone: 9 | 908-654-806 | 58 |
| | | Contractor Name: | Lew Environmental Services, LLC | | |
| Mynul Sury | | Contractor Address: | 181 US Hwy 46 | | |
| | 021517 | | Mine Hill, NJ 07830 | | |
| Signature | 021317 ID# | Date Issued: | 06/21/2024 | | |
| orgination of | | | (mm/dd/yyyy) | | |