



7469 Whitepine Rd  
 North Chesterfield, VA 23237  
 Telephone: 800.347.4010

# Lead Dust Wipe Analysis Report

**Report Number:** 24-11-03229

**Client:** LEW Corp  
 181 US Hwy 46  
 Mine Hill, NJ 07803

**Received Date:** 11/18/2024  
**Analyzed Date:** 11/20/2024  
**Reported Date:** 11/21/2024

**Project/Test Address:** 120684; 1125 Princess Ave; Camden, NJ

**Collection Date:** 11/08/2024

**Client Number:**  
 201327

## Laboratory Results

**Fax Number:**  
 Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft <sup>2</sup> )	Concentration (ug/ft <sup>2</sup> )	Narrative ID
24-11-03229-001	1	LIVING	FL	<5.00	1.00	<5.00	
24-11-03229-002	2	LIVING	SL	<5.00	0.778	<6.43	
24-11-03229-003	3	BED 1	FL	<5.00	1.00	<5.00	
24-11-03229-004	4	BED 1	SL	<5.00	0.503	<9.95	
24-11-03229-005	5	BED 2	FL	<5.00	1.00	<5.00	
24-11-03229-006	6	BED 2	SL	40.8	0.694	58.8	
24-11-03229-007	7	BED 3	FL	<5.00	1.00	<5.00	
24-11-03229-008	8	BED 3	SL	<5.00	0.938	<5.34	
24-11-03229-009	9	SUNROOM	FL	<5.00	1.00	<5.00	

# Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 24-11-03229

Project/Test Address: 120684; 1125 Princess Ave; Camden, NJ

---

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft <sup>2</sup> )	Concentration (ug/ft <sup>2</sup> )	Narrative ID
-------------------	----------------------	---------------------	---------	---------------	------------------------------	-------------------------------------	--------------

---

Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode

QA/QC Clerk

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft<sup>2</sup> are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accreditation through AIHA LAP, LLC (100420), NY ELAP #11714.

---

Legend	ug = microgram	ug/ft <sup>2</sup> = micrograms per square foot	Pb = lead
	mL = milliliter	ft <sup>2</sup> = square foot	

---



# ENVIRONMENTAL SERVICES

A Mohline Company

LEW Environmental Services P: (800) 783-0567

F: (908) 654-8069

## Lead

### Chain-of-Custody

24-11-03229



Due Date: 11/21/2024 (Thursday)

AE

\* All wipes

SN

Project Name: 120684 - 1125 Princess  
 Address: 1125 Princess Ave  
 City/State: Canden, NJ  
 Project Number: 120684

**Sample Type**

Dust wipe  
 Paint chip  
 Soil  
 TCLP

**Turn Around Time (TAT)**

Same Day  
 1 Day  
 1 Week  
 3 Day  
 Weekend  
 2 Weeks

**Sampler Information**

Name: Nyire Grant  
 Signature: [Signature]

Sample #	Date Collected	Sample Location (Ex: Fl, Kitchen, AC)	Area (inches)	Paint Chip Analysis		
				mg/cm <sup>2</sup>	PPM	% wt
1	11/8/24	Living Fl	12 x 12			
2		Living WS	4 x 28			
3		Bed 1 fl	12 x 12			
4		Bed 1 WS	2.5 x 29			
5		Bed 2 fl	12 x 12			
6		Bed 2 WS	4 x 25			
7		Bed 3 fl	12 x 12			
8		Bed 3 WS	5 x 27			
9		SUNROOM fl	12 x 12			

Relinquished by: Nyire Grant Signature: [Signature] Date/Time: 11/8/24

Received by: [Signature] Signature: [Signature] Date/Time: 11/8/24 4:02pm

h2/b/11 01