



7469 Whitepine Rd
 North Chesterfield, VA 23237
 Telephone: 800.347.4010

Lead Dust Wipe Analysis Report

Report Number: 24-11-03771

Client: LEW Corp
 181 US Hwy 46
 Mine Hill, NJ 07803

Received Date: 11/20/2024
Analyzed Date: 11/25/2024
Reported Date: 11/25/2024

Project/Test Address: 121949; Clelia Esposito; 104 Summit Ave Unit 1; North Plainfield, NJ

Collection Date: 11/11/2024

Client Number:
 201327

Laboratory Results

Fax Number:
 Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
24-11-03771-001	104-1	BR 1 CC	FL	<5.00	1.00	<5.00	
24-11-03771-002	104-2	BR 2 CC	FL	<5.00	1.00	<5.00	
24-11-03771-003	104-3	B CC	FL	<5.00	1.00	<5.00	
24-11-03771-004	104-4	K CC	FL	<5.00	1.00	<5.00	
24-11-03771-005	104-5	SUNROOM CC	FL	<5.00	1.00	<5.00	
24-11-03771-006	104-6	BR 1 C	SL	<5.00	0.361	<13.9	
24-11-03771-007	104-7	BR 2 A	SL	<5.00	0.361	<13.9	
24-11-03771-008	104-8	B C	SL	<5.00	0.361	<13.9	
24-11-03771-009	104-9	K C	SL	<5.00	0.361	<13.9	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 24-11-03771

Project/Test Address: 121949; Clelia Esposito; 104 Summit Ave Unit 1;
North Plainfield, NJ

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
-------------------	----------------------	---------------------	---------	---------------	------------------------------	-------------------------------------	--------------

Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory: Candace Mason

Candace Mason

QA Chemist

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft² are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accreditation through AIHA LAP, LLC (100420), NY ELAP #11714.

Legend	ug = microgram	ug/ft ² = micrograms per square foot	Pb = lead
	mL = milliliter	ft ² = square foot	



ENVIRONMENTAL SERVICES

LEW Environmental Services P: (800) 783-0567 F: (908) 654-8069

Lead

Chain-of-Custody

24-11-03771



Due Date:
11/25/2024
(Monday)
AE

* All wipes submitted meet ASTM E1792 requirements

Project Name: Clelia Espinoza
Address: 104 Summit Ave Unit 1
City, State: North Plainfield NJ
Project Number: 121999

Sample Type
 Dust wipe
 Paint chip
 Soil
 TSP

Turn Around Time (TAT)
 Same Day
 1 Day
 1 Week
 3 Day
 Weekend
 2 Weeks

Sampler Information
Name: Treyson Atchley
Signature: Treyson Atchley

Sample #	Date Collected	Sample Location (Ex: Fl, Kitchen, AC)	Area (inches)	Paint Chip Analysis		
				mg/cm ²	ppm	% wt
104 -1	4/11/2024	BR 1 Fl cc	12 x 12			
-2		BR 2 Fl cc	12 x 12			
-3		B Fl cc	12 x 12			
-4		K Fl cc	12 x 12			
-5		Sunroom Fl cc	12 x 12			
-6		BR 1 WS c	26 x 2			
-7		BR 2 WS A	26 x 2			
-8		B WS c	26 x 2			
-9		K WS c	26 x 2			

Relinquished by: Treyson Atchley Signature: Treyson Atchley Date/Time: 4/14/2024
Received by: Melishnik Signature: Melishnik Date/Time: 4/14/2024