



7469 Whitepine Rd
 North Chesterfield, VA 23237
 Telephone: 800.347.4010

Lead Dust Wipe Analysis Report

Report Number: 24-11-02852

Client: LEW Corp
 181 US Hwy 46
 Mine Hill, NJ 07803

Received Date: 11/15/2024
Analyzed Date: 11/20/2024
Reported Date: 11/20/2024

Project/Test Address: 122023; Joseph Augugliaro; 529 Jersey Ave Unit 2; Elizabeth, NJ

Collection Date: 11/12/2024

Client Number:
 201327

Laboratory Results

Fax Number:
 Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
24-11-02852-001	52-1	SUN ROOM		<5.00	1.00	<5.00	
24-11-02852-002	52-2	KITCHEN BC	FL	<5.00	1.00	<5.00	
24-11-02852-003	52-3	LIVING ROOM BC	FL	<5.00	1.00	<5.00	
24-11-02852-004	52-4	BEDROOM 1 CC	FL	<5.00	1.00	<5.00	
24-11-02852-005	52-5	BEDROOM 2 DC	FL	<5.00	1.00	<5.00	
24-11-02852-006	52-6	KITCHEN B1	SL	<5.00	0.563	<8.89	
24-11-02852-007	52-7	LIVING ROOM B1	SL	<5.00	0.604	<8.28	
24-11-02852-008	52-8	BEDROOM 1 C2	SL	<5.00	0.677	<7.39	
24-11-02852-009	52-9	BEDROOM 2 D2	SL	<5.00	0.729	<6.86	

Environmental Hazards Services, L.L.C

Client Number: 201327
Project/Test Address: 122023; Joseph Augugliaro; 529 Jersey Ave Unit 2;
Elizabeth, NJ

Report Number: 24-11-02852

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
-------------------	----------------------	---------------------	---------	---------------	------------------------------	-------------------------------------	--------------

Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory:



Tasha Eaddy

QA/QC Clerk

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft² are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accreditation through AIHA LAP, LLC (100420), NY ELAP #11714.

Legend	ug = microgram	ug/ft ² = micrograms per square foot	Pb = lead
	mL = milliliter	ft ² = square foot	



ENVIRONMENTAL SERVICES

A Mainline Company

LEW Environmental Services P: (800) 783-0567

F: (908) 654-8069

Lead

Chain-of-Custody

24-11-02852



Due Date:

11/20/2024

(Wednesday)

AE

* All wipes

51

Project Name: Joseph Augugliere
 Address: 529 Jersey Ave
 City, State: Elizabeth, NJ Unit 2
 Project Number: 122023

Sample Type: Dust wipe Paint chip Soil TCLP

Turn Around Time (TAT): Same Day 1 Day 1 Week 3 Day Weekend 2 Weeks

Name: Pablo Viera
 Signature: Pablo Viera

Sampler Information

Sample #	Date Collected	Sample Location (Ex: Fl, Kitchen, AC)	Area (inches)	Paint Chip Analysis		
				mg/cm ²	PPM	% wt
52 -1	11-12-24	Sw Room	12 X 12			
-2	11-12-24	Kitchen Floor BC	X			
-3		Living Room Floor BC	X			
-4		Bedroom 4 Floor CC	X			
-5		Bedroom 2 Floor DC	X			
-6		Kitchen Sill D1	X	29 1/2	23 1/4	
-7		Living Room Sill B1	X	29	3	
-8		Bedroom 1 Sill C2	X	30	3 1/4	
-9		Bedroom 2 Sill D2	X	30	3 1/2	
				X		

Relinquished by: Pablo Viera Signature: Pablo Viera Date/Time: 11-12-24 6:10 pm

Received by: Pablo Viera Signature: Pablo Viera Date/Time: 11/20/24 2:09 pm