



7469 Whitepine Rd
 North Chesterfield, VA 23237
 Telephone: 800.347.4010

Lead Dust Wipe Analysis Report

Report Number: 24-11-02833

Client: LEW Corp
 181 US Hwy 46
 Mine Hill, NJ 07803

Received Date: 11/15/2024
Analyzed Date: 11/19/2024
Reported Date: 11/19/2024

Project/Test Address: 122580; Mohamed Ramadan; 328 South 7th St Unit 1; Elizabeth, NJ

Collection Date: 11/12/2024

Client Number:
 201327

Laboratory Results

Fax Number:
 Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
24-11-02833-001	32-1	SUNROOM	FL	<5.00	1.00	<5.00	
24-11-02833-002	32-2	KITCHEN BC	FL	<5.00	1.00	<5.00	
24-11-02833-003	32-3	LIVING ROOM DC	FL	22.5	1.00	22.5	
24-11-02833-004	32-4	PLAY ROOM CC	FL	<5.00	1.00	<5.00	
24-11-02833-005	32-5	BEDROOM AC	FL	<5.00	1.00	<5.00	
24-11-02833-006	32-6	KITCHEN	SL	<5.00	0.792	<6.32	
24-11-02833-007	32-7	BEDROOM A2	SL	99.0	1.49	66.5	
24-11-02833-008	32-8	PLAYROOM C1	SL	<5.00	0.594	<8.42	

Environmental Hazards Services, L.L.C

Client Number: 201327
Project/Test Address: 122580; Mohamed Ramadan; 328 South 7th St Unit
1; Elizabeth, NJ

Report Number: 24-11-02833

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
-------------------	----------------------	---------------------	---------	---------------	------------------------------	-------------------------------------	--------------

Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory: Candace Mason

Candace Mason

QA Chemist

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft² are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accreditation through AIHA LAP, LLC (100420), NY ELAP #11714.

Legend

ug = microgram

ug/ft² = micrograms per square foot

Pb = lead

mL = milliliter

ft² = square foot



ENVIRONMENTAL SERVICES

A Mainline Company

LEW Environmental Services P: (800) 783-0567

F: (908) 654-8069

Lead

Chain-of-Custody

24-11-02833



Due Date:
11/20/2024
(Wednesday)
AE

* All wipes

51

Project Name: Mohamed Ramadan

Address: 328 South 7th St

City, State: Elizabeth, NJ Unit 1

Project Number: 122580

Sample Type: Dust wipe Paint chip Soil TCIP

Turn Around Time (TAT): Same Day 1 Day 1 Week 3 Day Weekend 2 Weeks

Name: Pasiv Viera

Signature: Pasiv Viera

Sampler Information

Sample #	Date Collected	Sample Location (Ex: Fl, Kitchen, AC)	Area (Inches)	Paint Chip Analysis		
				mg/cm ²	PPM	% wt
32-1	11-12-24	SUN ROOM	12 x 12			
-2		Kitchen Floor BC	X			
-3		Living Room Floor DC	X			
-4		Play Room Floor CC	X			
-5		Bedroom Floor AC	X			
-6		Kitchen Sill	28 1/2	X	4	
-7	Bedroom Sill A2	34 1/4	X	6 1/4		
-8	Playroom Sill C1	28 1/2	X	3		
			X			
			X			
			X			
			X			

Relinquished by: Pasiv Viera Signature: Pasiv Viera Date/Time: 11-12-24 6:40pm

Received by: Mohamed Signature: Mohamed Date/Time: 11/15/24 1:22pm

VB