

Company LEW Corporation  
 XRF Make Heuresis  
 Model Pb200i  
 Serial Num. 1834  
 Lead concentration units: mg/cm2  
 Total Readings: 128  
 Action Level 1  
 Mode Action Level  
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
6040832	39274	0.9		TRUE	FALSE	6/4/2024	8:32 AM	Paint	610 New Brunswick Ave								
6040832	39275	0.9		TRUE	FALSE	6/4/2024	8:33 AM	Paint	610 New Brunswick Ave								
6040832	39276	0.9		TRUE	FALSE	6/4/2024	8:34 AM	Paint	610 New Brunswick Ave								
6040832	39277	0		TRUE	FALSE	6/4/2024	8:34 AM	Paint	610 New Brunswick Ave								
6040832	39278	-0.1		TRUE	FALSE	6/4/2024	8:35 AM	Paint	610 New Brunswick Ave								
6040832	39279	0		TRUE	FALSE	6/4/2024	8:35 AM	Paint	610 New Brunswick Ave								
6040832	39280	-0.2	Negative	FALSE	FALSE	6/4/2024	8:36 AM	Paint	610 New Brunswick Ave	Unit		Living Room	Door	---	Wood	A	1
6040832	39281	-0.3	Negative	FALSE	FALSE	6/4/2024	8:37 AM	Paint	610 New Brunswick Ave	Unit		Living Room	Door	Casing	Wood	A	1
6040832	39282	-0.1	Negative	FALSE	FALSE	6/4/2024	8:37 AM	Paint	610 New Brunswick Ave	Unit		Living Room	Window	Jamb	Wood	A	1
6040832	39283	-0.3	Negative	FALSE	FALSE	6/4/2024	8:37 AM	Paint	610 New Brunswick Ave	Unit		Living Room	Window	Casing	Wood	A	1
6040832	39284	-0.1	Negative	FALSE	FALSE	6/4/2024	8:38 AM	Paint	610 New Brunswick Ave	Unit		Living Room	Window	Sill	Wood	A	1
6040832	39285	-0.2	Negative	FALSE	FALSE	6/4/2024	8:39 AM	Paint	610 New Brunswick Ave	Unit		Living Room	Closet	Door	Wood	B	1
6040832	39286	-0.3	Negative	FALSE	FALSE	6/4/2024	8:39 AM	Paint	610 New Brunswick Ave	Unit		Living Room	Closet	Door Casing	Wood	B	1
6040832	39287	-0.4	Negative	FALSE	FALSE	6/4/2024	8:40 AM	Paint	610 New Brunswick Ave	Unit		Living Room	Closet	Door Jamb	Wood	B	1
6040832	39288	-0.3	Negative	FALSE	FALSE	6/4/2024	8:40 AM	Paint	610 New Brunswick Ave	Unit		Living Room	Closet	Shelf Support	Wood	B	1
6040832	39289	0	Negative	FALSE	FALSE	6/4/2024	8:40 AM	Paint	610 New Brunswick Ave	Unit		Living Room	Closet	Shelf	Wood	B	1
6040832	39290	-0.1	Negative	FALSE	FALSE	6/4/2024	8:41 AM	Paint	610 New Brunswick Ave	Unit		Living Room	Closet	Wall	Plaster	B	1
6040832	39291	0.1	Negative	FALSE	FALSE	6/4/2024	8:42 AM	Paint	610 New Brunswick Ave	Unit		Living Room	Room	Wall	Plaster	A	1
6040832	39292	0.3	Negative	FALSE	FALSE	6/4/2024	8:42 AM	Paint	610 New Brunswick Ave	Unit		Living Room	Room	Wall	Plaster	B	1
6040832	39293	0.1	Negative	FALSE	FALSE	6/4/2024	8:43 AM	Paint	610 New Brunswick Ave	Unit		Living Room	Room	Wall	Plaster	C	1
6040832	39294	0.2	Negative	FALSE	FALSE	6/4/2024	8:43 AM	Paint	610 New Brunswick Ave	Unit		Living Room	Room	Wall	Plaster	D	1
6040832	39295	0.1	Negative	FALSE	FALSE	6/4/2024	8:44 AM	Paint	610 New Brunswick Ave	Unit		Living Room	Room	Ceiling	Plaster	D	1
6040832	39296	0	Negative	FALSE	FALSE	6/4/2024	8:44 AM	Paint	610 New Brunswick Ave	Unit		Living Room	Room	Floor	Wood	B	1
6040832	39297	-0.3	Negative	FALSE	FALSE	6/4/2024	8:45 AM	Paint	610 New Brunswick Ave	Unit		Living Room	Room	Baseboard	Wood	B	1
6040832	39298	-0.2	Negative	FALSE	FALSE	6/4/2024	8:45 AM	Paint	610 New Brunswick Ave	Unit		Kitchen	Room	Baseboard	Wood	B	1
6040832	39299	0	Negative	FALSE	FALSE	6/4/2024	8:46 AM	Paint	610 New Brunswick Ave	Unit		Kitchen	Room	Ceiling	Drywall	A	1
6040832	39300	0	Negative	FALSE	FALSE	6/4/2024	8:46 AM	Paint	610 New Brunswick Ave	Unit		Kitchen	Room	Wall	Drywall	A	1
6040832	39301	0	Negative	FALSE	FALSE	6/4/2024	8:47 AM	Paint	610 New Brunswick Ave	Unit		Kitchen	Room	Wall	Drywall	B	1
6040832	39302	0	Negative	FALSE	FALSE	6/4/2024	8:47 AM	Paint	610 New Brunswick Ave	Unit		Kitchen	Room	Wall	Drywall	C	1
6040832	39303	0.3	Negative	FALSE	FALSE	6/4/2024	8:48 AM	Paint	610 New Brunswick Ave	Unit		Kitchen	Room	Wall	Drywall	D	1
6040832	39304	-0.2	Negative	FALSE	FALSE	6/4/2024	8:49 AM	Paint	610 New Brunswick Ave	Unit		Kitchen	Cabinets	Door	Wood	C	1
6040832	39305	-0.1	Negative	FALSE	FALSE	6/4/2024	8:49 AM	Paint	610 New Brunswick Ave	Unit		Kitchen	Cabinets	Frame	Wood	C	1
6040832	39306	-0.3	Negative	FALSE	FALSE	6/4/2024	8:50 AM	Paint	610 New Brunswick Ave	Unit		Kitchen	Window	Jamb	Wood	C	1
6040832	39307	-0.2	Negative	FALSE	FALSE	6/4/2024	8:51 AM	Paint	610 New Brunswick Ave	Unit		Kitchen	Window	Sill	Wood	C	1
6040832	39308	-0.3	Negative	FALSE	FALSE	6/4/2024	8:51 AM	Paint	610 New Brunswick Ave	Unit		Kitchen	Stair	Risers	Wood	C	1
6040832	39309	-0.1	Negative	FALSE	FALSE	6/4/2024	8:52 AM	Paint	610 New Brunswick Ave	Unit		Kitchen	Stair	Treads	Wood	C	1
6040832	39310	0.1	Negative	FALSE	FALSE	6/4/2024	8:53 AM	Paint	610 New Brunswick Ave	Unit		Mud Room	Door	---	Metal	B	1
6040832	39311	-0.2	Negative	FALSE	FALSE	6/4/2024	8:53 AM	Paint	610 New Brunswick Ave	Unit		Mud Room	Door	Jamb	Wood	B	1
6040832	39312	-0.1	Negative	FALSE	FALSE	6/4/2024	8:54 AM	Paint	610 New Brunswick Ave	Unit		Mud Room	Door	Casing	Wood	B	1
6040832	39313	0	Negative	FALSE	FALSE	6/4/2024	8:54 AM	Paint	610 New Brunswick Ave	Unit		Mud Room	Room	Wall	Drywall	A	1
6040832	39314	-0.1	Negative	FALSE	FALSE	6/4/2024	8:55 AM	Paint	610 New Brunswick Ave	Unit		Mud Room	Room	Wall	Drywall	B	1

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
6040832	39315	-0.1	Negative	FALSE	FALSE	6/4/2024	8:55 AM	Paint	610 New Brunswick Ave	Unit		Mud Room	Room	Wall	Drywall	C	1
6040832	39316	0	Negative	FALSE	FALSE	6/4/2024	8:56 AM	Paint	610 New Brunswick Ave	Unit		Mud Room	Room	Wall	Drywall	D	1
6040832	39317	0	Negative	FALSE	FALSE	6/4/2024	8:56 AM	Paint	610 New Brunswick Ave	Unit		Mud Room	Room	Ceiling	Drywall	D	1
6040832	39318	0	Negative	FALSE	FALSE	6/4/2024	8:57 AM	Paint	610 New Brunswick Ave	Unit		Mud Room	Room	Baseboard	Wood	D	1
6040832	39319	0.1	Negative	FALSE	FALSE	6/4/2024	8:58 AM	Paint	610 New Brunswick Ave	Unit		Hall	Room	Wall	Drywall	A	1
6040832	39320	0.1	Negative	FALSE	FALSE	6/4/2024	8:58 AM	Paint	610 New Brunswick Ave	Unit		Hall	Room	Wall	Drywall	B	1
6040832	39321	0.1	Negative	FALSE	FALSE	6/4/2024	8:59 AM	Paint	610 New Brunswick Ave	Unit		Hall	Room	Wall	Drywall	C	1
6040832	39322	0.2	Negative	FALSE	FALSE	6/4/2024	8:59 AM	Paint	610 New Brunswick Ave	Unit		Hall	Room	Wall	Drywall	D	1
6040832	39323	0.1	Negative	FALSE	FALSE	6/4/2024	9:00 AM	Paint	610 New Brunswick Ave	Unit		Hall	Room	Ceiling	Drywall	D	1
6040832	39324	-0.3	Negative	FALSE	FALSE	6/4/2024	9:00 AM	Paint	610 New Brunswick Ave	Unit		Hall	Room	Baseboard	Wood	A	1
6040832	39325	0.1	Negative	FALSE	FALSE	6/4/2024	9:01 AM	Paint	610 New Brunswick Ave	Unit		Hall	Room	Floor	Wood	A	1
6040832	39326	-0.1	Negative	FALSE	FALSE	6/4/2024	9:01 AM	Paint	610 New Brunswick Ave	Unit		Hall	Door	---	Wood	A	1
6040832	39327	-0.1	Negative	FALSE	FALSE	6/4/2024	9:02 AM	Paint	610 New Brunswick Ave	Unit		Hall	Door	Jamb	Wood	A	1
6040832	39328	0	Negative	FALSE	FALSE	6/4/2024	9:02 AM	Paint	610 New Brunswick Ave	Unit		Hall	Door	Casing	Wood	A	1
6040832	39329	-0.1	Negative	FALSE	FALSE	6/4/2024	9:03 AM	Paint	610 New Brunswick Ave	Unit		Hall	Closet	Door	Wood	A	1
6040832	39330	-0.1	Negative	FALSE	FALSE	6/4/2024	9:03 AM	Paint	610 New Brunswick Ave	Unit		Hall	Closet	Door Jamb	Wood	C	1
6040832	39331	-0.3	Negative	FALSE	FALSE	6/4/2024	9:04 AM	Paint	610 New Brunswick Ave	Unit		Hall	Closet	Door Casing	Wood	C	1
6040832	39332	-0.1	Negative	FALSE	FALSE	6/4/2024	9:04 AM	Paint	610 New Brunswick Ave	Unit		Hall	Closet	Shelf Support	Wood	C	1
6040832	39333	-0.1	Negative	FALSE	FALSE	6/4/2024	9:04 AM	Paint	610 New Brunswick Ave	Unit		Hall	Closet	Shelf	Wood	C	1
6040832	39334	0.1	Negative	FALSE	FALSE	6/4/2024	9:05 AM	Paint	610 New Brunswick Ave	Unit		Hall	Closet	Wall	Drywall	C	1
6040832	39335	-0.1	Negative	FALSE	FALSE	6/4/2024	9:06 AM	Paint	610 New Brunswick Ave	Unit		Hall	Access Panel	Door	Wood	C	1
6040832	39336	-0.2	Negative	FALSE	FALSE	6/4/2024	9:06 AM	Paint	610 New Brunswick Ave	Unit		Hall	Access Panel	Casing	Wood	C	1
6040832	39337	0	Negative	FALSE	FALSE	6/4/2024	9:07 AM	Paint	610 New Brunswick Ave	Unit		Hall	Room	Ceiling	Drywall	C	1
6040832	39338	-0.3	Negative	FALSE	FALSE	6/4/2024	9:08 AM	Paint	610 New Brunswick Ave	Unit		Bathroom	Door	---	Wood	A	1
6040832	39339	0	Negative	FALSE	FALSE	6/4/2024	9:08 AM	Paint	610 New Brunswick Ave	Unit		Bathroom	Door	Jamb	Wood	A	1
6040832	39340	-0.1	Negative	FALSE	FALSE	6/4/2024	9:09 AM	Paint	610 New Brunswick Ave	Unit		Bathroom	Door	Casing	Wood	A	1
6040832	39341	0.1	Negative	FALSE	FALSE	6/4/2024	9:09 AM	Paint	610 New Brunswick Ave	Unit		Bathroom	Cabinets	Door	Wood	B	1
6040832	39342	0	Negative	FALSE	FALSE	6/4/2024	9:10 AM	Paint	610 New Brunswick Ave	Unit		Bathroom	Cabinets	Frame	Wood	B	1
6040832	39343	0.1	Negative	FALSE	FALSE	6/4/2024	9:10 AM	Paint	610 New Brunswick Ave	Unit		Bathroom	Window	Jamb	Wood	C	1
6040832	39344	-0.1	Negative	FALSE	FALSE	6/4/2024	9:11 AM	Paint	610 New Brunswick Ave	Unit		Bathroom	Window	Casing	Wood	C	1
6040832	39345	0	Negative	FALSE	FALSE	6/4/2024	9:11 AM	Paint	610 New Brunswick Ave	Unit		Bathroom	Window	Sill	Wood	C	1
6040832	39346	-0.1	Negative	FALSE	FALSE	6/4/2024	9:12 AM	Paint	610 New Brunswick Ave	Unit		Bathroom	Closet	Door	Wood	D	1
6040832	39347	-0.1	Negative	FALSE	FALSE	6/4/2024	9:12 AM	Paint	610 New Brunswick Ave	Unit		Bathroom	Closet	Door Casing	Wood	D	1
6040832	39348	-0.2	Negative	FALSE	FALSE	6/4/2024	9:13 AM	Paint	610 New Brunswick Ave	Unit		Bathroom	Closet	Door Jamb	Wood	D	1
6040832	39349	0	Negative	FALSE	FALSE	6/4/2024	9:13 AM	Paint	610 New Brunswick Ave	Unit		Bathroom	Closet	Wall	Drywall	D	1
6040832	39350	0.1	Negative	FALSE	FALSE	6/4/2024	9:14 AM	Paint	610 New Brunswick Ave	Unit		Bathroom	Room	Ceiling	Drywall	A	1
6040832	39351	-0.1	Negative	FALSE	FALSE	6/4/2024	9:14 AM	Paint	610 New Brunswick Ave	Unit		Bathroom	Room	Crown Molding	Wood	A	1
6040832	39352	0	Negative	FALSE	FALSE	6/4/2024	9:15 AM	Paint	610 New Brunswick Ave	Unit		Bedroom 1	Room	Ceiling	Drywall	A	1
6040832	39353	0.2	Negative	FALSE	FALSE	6/4/2024	9:16 AM	Paint	610 New Brunswick Ave	Unit		Bedroom 1	Room	Wall	Drywall	A	1
6040832	39354	0.1	Negative	FALSE	FALSE	6/4/2024	9:16 AM	Paint	610 New Brunswick Ave	Unit		Bedroom 1	Room	Wall	Drywall	B	1
6040832	39355	0	Negative	FALSE	FALSE	6/4/2024	9:16 AM	Paint	610 New Brunswick Ave	Unit		Bedroom 1	Room	Wall	Drywall	C	1
6040832	39356	0.1	Negative	FALSE	FALSE	6/4/2024	9:17 AM	Paint	610 New Brunswick Ave	Unit		Bedroom 1	Room	Wall	Drywall	D	1
6040832	39357	0.1	Negative	FALSE	FALSE	6/4/2024	9:17 AM	Paint	610 New Brunswick Ave	Unit		Bedroom 1	Room	Floor	Wood	D	1
6040832	39358	-0.3	Negative	FALSE	FALSE	6/4/2024	9:18 AM	Paint	610 New Brunswick Ave	Unit		Bedroom 1	Room	Baseboard	Wood	D	1
6040832	39359	-0.2	Negative	FALSE	FALSE	6/4/2024	9:18 AM	Paint	610 New Brunswick Ave	Unit		Bedroom 1	Window	Casing	Wood	A	1
6040832	39360	-0.1	Negative	FALSE	FALSE	6/4/2024	9:19 AM	Paint	610 New Brunswick Ave	Unit		Bedroom 1	Window	Jamb	Wood	A	1
6040832	39361	-0.3	Negative	FALSE	FALSE	6/4/2024	9:19 AM	Paint	610 New Brunswick Ave	Unit		Bedroom 1	Window	Sill	Wood	A	1
6040832	39362	-0.2	Negative	FALSE	FALSE	6/4/2024	9:20 AM	Paint	610 New Brunswick Ave	Unit		Bedroom 1	Closet	Door	Wood	D	1
6040832	39363	-0.2	Negative	FALSE	FALSE	6/4/2024	9:20 AM	Paint	610 New Brunswick Ave	Unit		Bedroom 1	Closet	Door Casing	Wood	D	1
6040832	39364	-0.1	Negative	FALSE	FALSE	6/4/2024	9:21 AM	Paint	610 New Brunswick Ave	Unit		Bedroom 1	Closet	Door Jamb	Wood	D	1
6040832	39365	-0.7	Negative	FALSE	FALSE	6/4/2024	9:21 AM	Paint	610 New Brunswick Ave	Unit		Bedroom 1	Closet	Shelf Support	Wood	D	1



Company LEW Corporation  
XRF Make Heuresis  
Model Pb200i  
Serial Num. 1834

Lead concentration units: mg/cm2

Total Readings: 128 Total Positives 0

Action Level 1

Mode Action Level

Analytic Mode Paint

### Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
No Actionables																	