



7469 Whitepine Rd
 North Chesterfield, VA 23237
 Telephone: 800.347.4010

Lead Dust Wipe Analysis Report

Report Number: 24-05-03265

Client: LEW Corp
 181 US Hwy 46
 Mine Hill, NJ 07803

Received Date: 05/20/2024
Analyzed Date: 05/22/2024
Reported Date: 05/23/2024

Project/Test Address: 32846; Norberto Fedullo; 107 W Clinton St Unit 1; Dover, NJ

Collection Date: 05/17/2024

Client Number:
 201327

Laboratory Results

Fax Number:
 Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
24-05-03265-001	107-1-1	BR 1 AC	FL	<5.00	1.00	<5.00	
24-05-03265-002	107-1-2	BR 2 DC	FL	<5.00	1.00	<5.00	
24-05-03265-003	107-1-3	BR 3 BC	FL	<5.00	1.00	<5.00	
24-05-03265-004	107-1-4	BR 4 AC	FL	<5.00	1.00	<5.00	
24-05-03265-005	107-1-5	SUNROOM AC	FL	<5.00	1.00	<5.00	
24-05-03265-006	107-1-6	BR 1 A2	SL	<5.00	0.521	<9.60	
24-05-03265-007	107-1-7	BR 2 B1	SL	<5.00	0.705	<7.10	
24-05-03265-008	107-1-8	BR 3 C	SL	<5.00	0.611	<8.19	
24-05-03265-009	107-1-9	BR 4 C	SL	<5.00	0.667	<7.50	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 24-05-03265

Project/Test Address: 32846; Norberto Fedullo; 107 W Clinton St Unit 1;
Dover, NJ

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
-------------------	----------------------	---------------------	---------	---------------	------------------------------	-------------------------------------	--------------

Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode

QA/QC Clerk

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft² are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accreditation through AIHA LAP, LLC (100420), NY ELAP #11714.

Legend	ug = microgram	ug/ft ² = micrograms per square foot	Pb = lead
	mL = milliliter	ft ² = square foot	



ENVIRONMENTAL SERVICES

A Mainline Company

LEW Environmental Services P: (800) 783-0567

F: (908) 654-8069

Lead

Chain-of-Custody

24-05-03265



Due Date:

05/23/2024

(Thursday)

AE

* All wt

107

nts.

Project Name: Norberto Fedullo

Address: 107 W. Clinton St Unit 1

City, State: Dover, NS

Project Number: 32246

Sample Type: Dust wipe Paint chip Soil TCLP

Turn Around Time (TAT): Same Day 1 Day 1 Week 3 Day Weekend 2 Weeks

Name: Danny Feliciano

Signature: Dg 22

Sample #	Date Collected	Sample Location (Ex: Fl, Kitchen, AC)	Area (Inches)	Paint Chip Analysis		
				mg/cm ²	PPM	% wt
107-1-1	5/17/24	BR1 Fl, AC	12x12			
2	}	BR2 Fl, DC	12x12			
3		BR3 Fl, BC	12x12			
4		BR4 Fl, AC	12x12			
5		Sen room fl, AC	12x12			
6		BR1 WS, AA	30x22			
7		BR2 WS, B1	29x31			
8		BR3 WS, C	32x23			
9		BR4 WS, C	32x3			

Relinquished by: Danny Feliciano Signature: Dg 22 Date/Time: 5/17/24 5:00pm

Received by: Humphrey Signature: H Date/Time: 5/20/24 3:44pm