

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 2096

Lead concentration units: mg/cm2
 Total Readings: 201
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
5230924	43295	1		TRUE	FALSE	5/23/2024	9:24 AM	Gloria Washington	Paint	9 Central Ave Montcll								
5230924	43296	1		TRUE	FALSE	5/23/2024	9:25 AM	Gloria Washington	Paint	9 Central Ave Montcll								
5230924	43297	1		TRUE	FALSE	5/23/2024	9:25 AM	Gloria Washington	Paint	9 Central Ave Montcll								
5230924	43298	-0.1		TRUE	FALSE	5/23/2024	9:26 AM	Gloria Washington	Paint	9 Central Ave Montcll								
5230924	43299	-0.1		TRUE	FALSE	5/23/2024	9:26 AM	Gloria Washington	Paint	9 Central Ave Montcll								
5230924	43300	-0.1		TRUE	FALSE	5/23/2024	9:27 AM	Gloria Washington	Paint	9 Central Ave Montcll								
5230924	43301	0	Negative	FALSE	FALSE	5/23/2024	9:31 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Foyer/Hall	Door		Other		A
5230924	43302	0.1	Negative	FALSE	FALSE	5/23/2024	9:32 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Foyer/Hall	Room	Wall	Drywall		D
5230924	43303	0.1	Negative	FALSE	FALSE	5/23/2024	9:33 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Foyer/Hall	Room	Wall	Drywall		C
5230924	43304	0.1	Negative	FALSE	FALSE	5/23/2024	9:33 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Foyer/Hall	Room	Wall	Drywall		B
5230924	43305	-0.1	Negative	FALSE	FALSE	5/23/2024	9:34 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Foyer/Hall	Door	Casing	Wood		A
5230924	43306	-0.1	Negative	FALSE	FALSE	5/23/2024	9:35 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Foyer/Hall	Room	Chair Rail	Wood		B
5230924	43307	0.2	Negative	FALSE	FALSE	5/23/2024	9:36 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Foyer/Hall	Room	Wall Trim	Wood		B
5230924	43308	0	Negative	FALSE	FALSE	5/23/2024	9:36 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Foyer/Hall	Room	Baseboard	Wood		B
5230924	43309	0.2	Negative	FALSE	FALSE	5/23/2024	9:38 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Foyer/Hall	Room	shoe moulding	Wood		B
5230924	43310	-0.3	Negative	FALSE	FALSE	5/23/2024	9:41 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Foyer/Hall	Door	Casing	Wood		C
5230924	43311	0	Negative	FALSE	FALSE	5/23/2024	9:42 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Foyer/Hall	Door	Jamb	Wood		D
5230924	43312	0	Negative	FALSE	FALSE	5/23/2024	9:44 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Foyer	Door	Casing	Wood		A
5230924	43313	0	Negative	FALSE	FALSE	5/23/2024	9:45 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Foyer	Door	Casing	Wood		D
5230924	43314	-0.2	Negative	FALSE	FALSE	5/23/2024	9:46 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Foyer	Door	Jamb	Wood		A
5230924	43315	0	Negative	FALSE	FALSE	5/23/2024	9:47 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement Stairwell	Door		Wood		C
5230924	43316	-0.1	Negative	FALSE	FALSE	5/23/2024	9:48 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement Stairwell	Door	Casing	Wood		C
5230924	43317	-0.1	Negative	FALSE	FALSE	5/23/2024	9:52 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement Stairwell	Door	Jamb	Wood		B
5230924	43318	-0.2	Negative	FALSE	FALSE	5/23/2024	9:53 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement Stairwell	Door	Stop	Wood		B
5230924	43319	0	Negative	FALSE	FALSE	5/23/2024	9:54 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Powder Room	Door		Wood		C
5230924	43320	0	Negative	FALSE	FALSE	5/23/2024	9:55 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Powder Room	Door	Casing	Wood		C
5230924	43321	-0.1	Negative	FALSE	FALSE	5/23/2024	9:56 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Powder Room	Door	Jamb	Wood		B
5230924	43322	-0.1	Negative	FALSE	FALSE	5/23/2024	9:56 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Powder Room	Door	Stop	Wood		B
5230924	43323	0.1	Negative	FALSE	FALSE	5/23/2024	9:58 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Powder Room	Room	Wall	Drywall		B
5230924	43324	-0.1	Negative	FALSE	FALSE	5/23/2024	9:59 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Powder Room	Room	Wall	Drywall		A
5230924	43325	-0.1	Negative	FALSE	FALSE	5/23/2024	10:00 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Powder Room	Room	Wall	Drywall		D
5230924	43326	-0.1	Negative	FALSE	FALSE	5/23/2024	10:01 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Powder Room	Room	Wall	Drywall		C
5230924	43327	-0.1	Negative	FALSE	FALSE	5/23/2024	10:02 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Powder Room	Room	Baseboard	Wood		B
5230924	43328	0.1	Negative	FALSE	FALSE	5/23/2024	10:03 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Powder Room	Room	shoe moulding	Wood		B
5230924	43329	0	Negative	FALSE	FALSE	5/23/2024	10:04 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Powder Room	Cabinets		Wood		A
5230924	43330	0.1	Negative	FALSE	FALSE	5/23/2024	10:06 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Foyer/Hall	Room	Ceiling	Drywall		A
5230924	43331	-0.1	Negative	FALSE	FALSE	5/23/2024	10:07 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Foyer/Hall	Room	Crown Molding	Wood		B
5230924	43332	-0.3	Negative	FALSE	FALSE	5/23/2024	10:09 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Foyer	Room	Ceiling	Drywall		
5230924	43333	0	Negative	FALSE	FALSE	5/23/2024	10:10 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Foyer	Room	Crown Molding	Wood		A
5230924	43334	-0.1	Negative	FALSE	FALSE	5/23/2024	10:11 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Living Room	Room	Crown Molding	Wood		B
5230924	43335	0	Negative	FALSE	FALSE	5/23/2024	10:12 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Living Room	Room	Ceiling	Wood		
5230924	43336	0.1	Negative	FALSE	FALSE	5/23/2024	10:13 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Living Room	Room	Ceiling	Wood		
5230924	43337	0	Negative	FALSE	FALSE	5/23/2024	10:14 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Living Room	Room	Wall	Drywall		A
5230924	43338	0.1	Negative	FALSE	FALSE	5/23/2024	10:15 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Living Room	Room	Wall	Drywall		B
5230924	43339	0.2	Negative	FALSE	FALSE	5/23/2024	10:16 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Living Room	Room	Wall	Drywall		C
5230924	43340	0	Negative	FALSE	FALSE	5/23/2024	10:16 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Living Room	Room	Wall	Drywall		D
5230924	43341	0	Negative	FALSE	FALSE	5/23/2024	10:18 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Living Room	Room	Wall Trim	Wood		A

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
5230924	43342	0.2	Negative	FALSE	FALSE	5/23/2024	10:20 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Living Room	Room	Chair Rail	Wood	A	
5230924	43343	-0.1	Negative	FALSE	FALSE	5/23/2024	10:21 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Living Room	Window	Sill	Wood	A	3
5230924	43344	-0.1	Negative	FALSE	FALSE	5/23/2024	10:22 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Living Room	Window	Casing	Wood	A	3
5230924	43345	-0.1	Negative	FALSE	FALSE	5/23/2024	10:22 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Living Room	Window	Jamb	Wood	A	3
5230924	43346	0	Negative	FALSE	FALSE	5/23/2024	10:23 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Living Room	Window	Apron	Wood	A	3
5230924	43347	0	Negative	FALSE	FALSE	5/23/2024	10:25 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Living Room	Room	Baseboard	Wood	A	
5230924	43348	0	Negative	FALSE	FALSE	5/23/2024	10:26 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Living Room	Room	shoe moulding	Wood	A	
5230924	43349	-0.1	Negative	FALSE	FALSE	5/23/2024	10:29 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Dining Room	Window	Sill	Wood	D	3
5230924	43350	0.1	Negative	FALSE	FALSE	5/23/2024	10:30 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Dining Room	Window	Casing	Wood	D	
5230924	43351	0	Negative	FALSE	FALSE	5/23/2024	10:31 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Dining Room	Window	Jamb	Wood	D	
5230924	43352	0	Negative	FALSE	FALSE	5/23/2024	10:31 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Dining Room	Window	Exterior Jamb	Wood	D	
5230924	43353	-0.1	Negative	FALSE	FALSE	5/23/2024	10:32 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Dining Room	Window	Apron	Wood	D	
5230924	43354	0.1	Negative	FALSE	FALSE	5/23/2024	10:34 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Hallway 1	Room	Wall	Drywall	A	
5230924	43355	0	Negative	FALSE	FALSE	5/23/2024	10:35 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Hallway 1	Room	Wall	Drywall	B	
5230924	43356	0	Negative	FALSE	FALSE	5/23/2024	10:35 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Hallway 1	Room	Wall	Drywall	D	
5230924	43357	0.2	Negative	FALSE	FALSE	5/23/2024	10:38 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Hallway 1	Room	Wall	Drywall	C	
5230924	43358	0	Negative	FALSE	FALSE	5/23/2024	10:40 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bedroom 1	Door		Wood		
5230924	43359	-0.1	Negative	FALSE	FALSE	5/23/2024	10:41 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bedroom 1	Door	Casing	Wood	B	
5230924	43360	0	Negative	FALSE	FALSE	5/23/2024	10:42 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bedroom 1	Door	Jamb	Wood	B	
5230924	43361	-0.1	Negative	FALSE	FALSE	5/23/2024	10:43 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bedroom 1	Door	Stop	Wood		
5230924	43362	0.1	Negative	FALSE	FALSE	5/23/2024	10:44 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bedroom 1	Room	Wall	Drywall	C	
5230924	43363	-0.1	Negative	FALSE	FALSE	5/23/2024	10:45 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bedroom 1	Room	Wall	Drywall	B	
5230924	43364	0	Negative	FALSE	FALSE	5/23/2024	10:45 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bedroom 1	Room	Wall	Drywall	A	
5230924	43365	0.1	Negative	FALSE	FALSE	5/23/2024	10:47 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bedroom 1	Room	Wall	Drywall	B	
5230924	43366	-0.2	Negative	FALSE	FALSE	5/23/2024	10:47 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bedroom 1	Room	Wall	Drywall	D	
5230924	43367	0	Negative	FALSE	FALSE	5/23/2024	10:49 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bedroom 1	Closet	Wall	Drywall	D	
5230924	43368	0.1	Negative	FALSE	FALSE	5/23/2024	10:50 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bedroom 1	Closet	Wall	Drywall	C	
5230924	43369	0.2	Negative	FALSE	FALSE	5/23/2024	10:51 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bedroom 1	Closet	Wall	Drywall	B	
5230924	43370	0	Negative	FALSE	FALSE	5/23/2024	10:52 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bedroom 1	Closet	Wall	Drywall	A	
5230924	43371	-0.2	Negative	FALSE	FALSE	5/23/2024	10:54 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bedroom 1	Room	Baseboard	Wood	C	
5230924	43372	-0.5	Negative	FALSE	FALSE	5/23/2024	10:55 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bedroom 1	Room	shoe moulding	Wood	C	
5230924	43373	0.1	Negative	FALSE	FALSE	5/23/2024	10:56 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bedroom 1	Window	Sill	Wood	B	
5230924	43374	-0.1	Negative	FALSE	FALSE	5/23/2024	10:57 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bedroom 1	Window	Jamb	Wood	B	
5230924	43375	-0.2	Negative	FALSE	FALSE	5/23/2024	10:57 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bedroom 1	Window	Casing	Wood	B	
5230924	43376	-0.1	Negative	FALSE	FALSE	5/23/2024	10:58 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bedroom 1	Window	Apron	Wood	B	
5230924	43377	0	Negative	FALSE	FALSE	5/23/2024	11:00 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bedroom 1	Door	Inner Casing	Wood	D	
5230924	43378	0.1	Negative	FALSE	FALSE	5/23/2024	11:02 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bedroom 1	Room	Ceiling	Drywall		
5230924	43379	-0.2	Negative	FALSE	FALSE	5/23/2024	11:02 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bedroom 1	Room	Crown Molding	Drywall		
5230924	43380	0	Negative	FALSE	FALSE	5/23/2024	11:06 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bathroom	Door	Casing	Wood	D	
5230924	43381	0	Negative	FALSE	FALSE	5/23/2024	11:07 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bathroom	Door	Jamb	Wood	A	
5230924	43382	-0.1	Negative	FALSE	FALSE	5/23/2024	11:08 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bathroom	Door	Stop	Wood	A	
5230924	43383	0	Negative	FALSE	FALSE	5/23/2024	11:09 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bathroom	Door	Inner Casing	Wood	A	
5230924	43384	0	Negative	FALSE	FALSE	5/23/2024	11:10 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bathroom	Door		Wood	D	
5230924	43385	0.1	Negative	FALSE	FALSE	5/23/2024	11:11 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bathroom	Linen Closet	Door	Wood	D	
5230924	43386	0	Negative	FALSE	FALSE	5/23/2024	11:12 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bathroom	Linen Closet	Door Casing	Wood	D	
5230924	43387	-0.4	Negative	FALSE	FALSE	5/23/2024	11:13 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bathroom	Linen Closet	Door Jamb	Wood	D	
5230924	43388	-0.2	Negative	FALSE	FALSE	5/23/2024	11:13 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bathroom	Linen Closet	Door Stop	Wood	D	
5230924	43389	0.1	Negative	FALSE	FALSE	5/23/2024	11:26 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bathroom	Linen Closet	Wall	Drywall	D	
5230924	43390	0	Negative	FALSE	FALSE	5/23/2024	11:26 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bathroom	Linen Closet	Wall	Drywall	C	
5230924	43391	0.1	Negative	FALSE	FALSE	5/23/2024	11:27 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bathroom	Linen Closet	Wall	Drywall	B	
5230924	43392	0.1	Negative	FALSE	FALSE	5/23/2024	11:28 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bathroom	Room	Wall	Drywall	D	
5230924	43393	0	Negative	FALSE	FALSE	5/23/2024	11:29 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bathroom	Room	Wall	Drywall	A	
5230924	43394	-0.4	Negative	FALSE	FALSE	5/23/2024	11:29 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bathroom	Room	Wall	Drywall	B	
5230924	43395	-0.1	Negative	FALSE	FALSE	5/23/2024	11:30 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bathroom	Room	Wall	Drywall	C	
5230924	43396	0	Negative	FALSE	FALSE	5/23/2024	11:31 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bathroom	Room	Baseboard	Wood	D	
5230924	43397	0.2	Negative	FALSE	FALSE	5/23/2024	11:33 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bathroom	Room	shoe moulding	Wood	D	
5230924	43398	-0.2	Negative	FALSE	FALSE	5/23/2024	11:35 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bathroom	Room	Ceiling	Drywall		
5230924	43399	-0.1	Negative	FALSE	FALSE	5/23/2024	11:36 AM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Bathroom	Room	Crown Molding	Wood	C	

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
5230924	43458	-0.1		TRUE	FALSE	5/23/2024	12:40 PM	Gloria Washington	Paint	9 Central Ave Montcll								
5231257	43459	0.1	Negative	FALSE	FALSE	5/23/2024	12:59 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement room 1	Room	Wall	Drywall	A	
5231257	43460	0.2	Negative	FALSE	FALSE	5/23/2024	1:00 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement room 1	Room	Wall	Drywall	D	
5231257	43461	-0.1	Negative	FALSE	FALSE	5/23/2024	1:01 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement room 1	Room	Wall	Drywall	C	
5231257	43462	0.2	Negative	FALSE	FALSE	5/23/2024	1:01 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement room 1	Room	Wall	Drywall	B	
5231257	43463	0	Negative	FALSE	FALSE	5/23/2024	1:04 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Stairwell 1	Room	Wall	Wood	D	
5231257	43464	0	Negative	FALSE	FALSE	5/23/2024	1:06 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement Stairwell	Stair	Stringer	Wood	B	
5231257	43465	-0.1	Negative	FALSE	FALSE	5/23/2024	1:06 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement Stairwell	Stair	Stringer	Wood	D	
5231257	43466	-0.1	Negative	FALSE	FALSE	5/23/2024	1:07 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement Stairwell	Stair	Stringer	Wood	D	Upper
5231257	43467	0.1	Negative	FALSE	FALSE	5/23/2024	1:09 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement Bathroom	Room	Wall	Drywall	A	Upper
5231257	43468	0	Negative	FALSE	FALSE	5/23/2024	1:09 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement Bathroom	Room	Wall	Drywall	C	
5231257	43469	0.1	Negative	FALSE	FALSE	5/23/2024	1:10 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement Bathroom	Room	Wall	Drywall	B	
5231257	43470	0.1	Negative	FALSE	FALSE	5/23/2024	1:11 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement Bathroom	Door		Wood	B	
5231257	43471	-0.1	Negative	FALSE	FALSE	5/23/2024	1:12 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement Bathroom	Door	Casing	Wood	B	
5231257	43472	-0.3	Negative	FALSE	FALSE	5/23/2024	1:12 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement Bathroom	Door	Jamb	Wood	B	
5231257	43473	0	Negative	FALSE	FALSE	5/23/2024	1:13 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement Bathroom	Door	Stop	Wood	B	
5231257	43474	0	Negative	FALSE	FALSE	5/23/2024	1:14 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement Bathroom	Room	Ceiling	Drywall		
5231257	43475	0.1	Negative	FALSE	FALSE	5/23/2024	1:15 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement Bathroom	Cabinets		Wood		
5231257	43476	-0.1	Negative	FALSE	FALSE	5/23/2024	1:16 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement Bathroom	Room	Baseboard	Wood		
5231257	43477	0	Negative	FALSE	FALSE	5/23/2024	1:17 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement Bathroom	Window	Casing	Wood	D	2
5231257	43478	0	Negative	FALSE	FALSE	5/23/2024	1:18 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement Bathroom	Window	Jamb	Wood	D	2
5231257	43479	0.7	Negative	FALSE	FALSE	5/23/2024	1:20 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement room 1	Closet	Wall	Concrete	D	
5231257	43480	0.6	Negative	FALSE	FALSE	5/23/2024	1:21 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement room 1	Closet	Wall	Concrete	A	
5231257	43481	0	Negative	FALSE	FALSE	5/23/2024	1:23 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement room 1	Closet	wallboard	Concrete	D	
5231257	43482	0.1	Negative	FALSE	FALSE	5/23/2024	1:25 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement room 1	Room	Ceiling	Drywall		
5231257	43483	0.1	Negative	FALSE	FALSE	5/23/2024	1:27 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement room 1	Closet	Door	Wood	B	1
5231257	43484	0.1	Negative	FALSE	FALSE	5/23/2024	1:28 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement room 1	Closet	Door	Wood	B	2
5231257	43485	0.2	Negative	FALSE	FALSE	5/23/2024	1:31 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		bsmt office	Room	Wall	Drywall	B	
5231257	43486	0.1	Negative	FALSE	FALSE	5/23/2024	1:32 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		bsmt office	Room	Wall	Drywall	C	
5231257	43487	0.1	Negative	FALSE	FALSE	5/23/2024	1:32 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		bsmt office	Room	Wall	Drywall	C	
5231257	43488	0.1	Negative	FALSE	FALSE	5/23/2024	1:33 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		bsmt office	Room	Wall	Drywall	D	
5231257	43489	0.2	Negative	FALSE	FALSE	5/23/2024	1:33 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		bsmt office	Room	Wall	Drywall	A	
5231257	43490	0	Negative	FALSE	FALSE	5/23/2024	1:34 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		bsmt office	Room	Baseboard	Wood	A	
5231257	43491	0.1	Negative	FALSE	FALSE	5/23/2024	1:36 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		bsmt office	Window	Jamb	Drywall	D	
5231257	43492	-0.1	Negative	FALSE	FALSE	5/23/2024	1:37 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		bsmt office	Window	Casing	Drywall	D	
5231257	43493	0	Negative	FALSE	FALSE	5/23/2024	1:38 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		bsmt office	Column		Wood	A	2
5231257	43494	-0.4	Negative	FALSE	FALSE	5/23/2024	1:39 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		bsmt office	Column	Base	Wood	A	2
5231257	43495	-0.4	Negative	FALSE	FALSE	5/23/2024	1:39 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		bsmt office	Column	Capital	Wood	A	2
5231257	43496	0	Negative	FALSE	FALSE	5/23/2024	1:40 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		bsmt office	Room	Ceiling	Drywall	A	
5231257	43497	0.2	Negative	FALSE	FALSE	5/23/2024	1:44 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		laundry	Room	Wall	Drywall	A	
5231257	43498	0.2	Negative	FALSE	FALSE	5/23/2024	1:45 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		laundry	Room	Wall	Drywall	B	
5231257	43499	0.2	Negative	FALSE	FALSE	5/23/2024	1:46 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Utility Closet	Room	Wall	Concrete	C	
5231257	43500	0.2	Negative	FALSE	FALSE	5/23/2024	1:47 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Utility Closet	Room	Wall	Concrete	B	
5231257	43501	0	Negative	FALSE	FALSE	5/23/2024	1:48 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Utility Closet	Room	Wall	Drywall	A	
5231257	43502	0	Negative	FALSE	FALSE	5/23/2024	1:50 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Boiler Room	Room	Wall	Drywall	A	
5231257	43503	0.1	Negative	FALSE	FALSE	5/23/2024	1:50 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Boiler Room	Room	Wall	Drywall	B	
5231257	43504	0.1	Negative	FALSE	FALSE	5/23/2024	1:56 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit		Basement backdoor	Door		Metal	C	
5231257	43505	0.1	Negative	FALSE	FALSE	5/23/2024	2:02 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit			Door	Casing	Wood	B	
5231257	43506	0.7	Negative	FALSE	FALSE	5/23/2024	2:15 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit			Door	Casing	Wood	B	
5231257	43507	0.7	Negative	FALSE	FALSE	5/23/2024	2:16 PM	Gloria Washington	Paint	9 Central Ave Montcll	Unit			Door	Casing	Wood	B	

Company LEW Corporation
XRF Make Heuresis
Model Pb200i
Serial Num. 2096

Lead concentration units: mg/cm2

Total Readings: 201 Total Positives 0

Action Level 1

Mode Action Level

Analytic Mode Paint

Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
No Actionables																		