



7469 Whitepine Rd  
 North Chesterfield, VA 23237  
 Telephone: 800.347.4010

# Lead Dust Wipe Analysis Report

**Report Number:** 24-05-03171

**Client:** LEW Corp  
 181 US Hwy 46  
 Mine Hill, NJ 07803

**Received Date:** 05/20/2024  
**Analyzed Date:** 05/22/2024  
**Reported Date:** 05/23/2024

**Project/Test Address:** 33617; Andy Aiken; 250 Highland Road; South Orange, NJ

**Collection Date:** 05/15/2024

**Client Number:**  
 201327

## Laboratory Results

**Fax Number:**  
 Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft <sup>2</sup> )	Concentration (ug/ft <sup>2</sup> )	Narrative ID
24-05-03171-001	250-1	DRCB	FL	<5.00	1.00	<5.00	
24-05-03171-002	250-2	FRB	FL	<5.00	1.00	<5.00	
24-05-03171-003	250-3	BR2C	FL	<5.00	1.00	<5.00	
24-05-03171-004	250-4	BR3BCC	FL	<5.00	1.00	<5.00	
24-05-03171-005	250-5	SUNROOM AD	FL	<5.00	1.00	<5.00	
24-05-03171-006	250-6	DRA2	SL	10.1	1.10	9.22	
24-05-03171-007	250-7	FAMILY ROOM A	SL	<5.00	0.407	<12.3	
24-05-03171-008	250-8	BR2C	SL	<5.00	0.802	<6.24	
24-05-03171-009	250-9	BR3B	SL	<5.00	0.812	<6.16	

# Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 24-05-03171

Project/Test Address: 33617; Andy Aiken; 250 Highland Road; South Orange, NJ

---

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft <sup>2</sup> )	Concentration (ug/ft <sup>2</sup> )	Narrative ID
-------------------	----------------------	---------------------	---------	---------------	------------------------------	-------------------------------------	--------------

---

Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory: Candace Mason

Candace Mason

QA Chemist

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft<sup>2</sup> are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accreditation through AIHA LAP, LLC (100420), NY ELAP #11714.

---

Legend

ug = microgram

ug/ft<sup>2</sup> = micrograms per square foot

Pb = lead

mL = milliliter

ft<sup>2</sup> = square foot

---



# ENVIRONMENTAL SERVICES

A Mainline Company

LEW Environmental Services P: (800) 783-0567  
F: (908) 654-8069

## Lead

### Chain-of-Custody

24-05-03171



Due Date:

05/23/2024

(Thursday)

AE

AP

\* All wipes

35

Project Name: Andy Aiken  
Address: 250 Highland Road  
City, State: South Orange, NJ  
Project Number: 33617

**Sample Type**

Dust wipe  
 Paint chip  
 Soil  
 TCLP

**Turn Around Time (TAT)**

Same Day  
 1 Day  
 1 Week  
 2 Weeks  
 3 Day  
 Weekend

**Sampler Information**

Name: Glenn Washington  
 Signature: Glenn Washington

Sample #	Date Collected	Sample Location (Ex: Fl, Kitchen, AC)	Area (inches)	Paint Chip Analysis		
				mg/cm <sup>2</sup>	PPM	% wt
250-1	5.15.2024	DRFLCB	12 x 12			
2	/	FRFLB	12 x 12			
3	/	BR2FLC	12 x 12			
4	/	BR3FLBCC	12 x 12			
5	/	Sunroom FLAD	12 x 12			
6	/	DRWSA2	53 x 3			
7	/	Family Room WSA	33 1/2 x 13 1/4			
8	/	BR2WSC	38 1/2 x 3			
9	↓	BR3WSB	39 x 3			
				X		
				X		
				X		

Relinquished by: Glenn Washington Signature: Glenn Washington Date/Time: 5.15.2024/7pm

Received by: ECTPA STARS Signature: ECTPA STARS Date/Time: 5/20/24 12:31 PM