



7469 Whitepine Rd  
 North Chesterfield, VA 23237  
 Telephone: 800.347.4010

# Lead Dust Wipe Analysis Report

**Report Number:** 24-06-00615

**Client:** LEW Corp  
 181 US Hwy 46  
 Mine Hill, NJ 07803

**Received Date:** 06/05/2024

**Analyzed Date:** 06/07/2024

**Reported Date:** 06/10/2024

**Project/Test Address:** 33671; 266 Sitgreaves; Phillipsburg, NJ

**Collection Date:** 05/28/2024

**Client Number:**  
 201327

## Laboratory Results

**Fax Number:**  
 Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft <sup>2</sup> )	Concentration (ug/ft <sup>2</sup> )	Narrative ID
24-06-00615-001	1	BED 1	FL	<5.00	1.00	<5.00	
24-06-00615-002	2	BED 1	SL	<5.00	0.427	<11.8	
24-06-00615-003	3	BED 2	FL	<5.00	1.00	<5.00	
24-06-00615-004	4	BED 2	SL	16.3	0.538	30.2	
24-06-00615-005	5	BED 3	FL	<5.00	1.00	<5.00	
24-06-00615-006	6	BED 3	SL	18.5	0.538	34.3	
24-06-00615-007	7	BED 4	FL	<5.00	1.00	<5.00	
24-06-00615-008	8	BED 4	SL	78.4	0.538	146	
24-06-00615-009	9	SUNROOM	FL	<5.00	1.00	<5.00	

# Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 24-06-00615

Project/Test Address: 33671; 266 Sitgreaves; Phillipsburg, NJ

---

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft <sup>2</sup> )	Concentration (ug/ft <sup>2</sup> )	Narrative ID
-------------------	----------------------	---------------------	---------	---------------	------------------------------	-------------------------------------	--------------

---

Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode

QA/QC Clerk

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft<sup>2</sup> are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accreditation through AIHA LAP, LLC (100420), NY ELAP #11714.

---

Legend

ug = microgram

ug/ft<sup>2</sup> = micrograms per square foot

Pb = lead

mL = milliliter

ft<sup>2</sup> = square foot

---



# ENVIRONMENTAL SERVICES

A Mainline Company

LEW Environmental Services P: (800) 783-0567

F: (908) 654-8069

## Lead

### Chain-of-Custody

24-06-00615



Due Date:

06/10/2024

(Monday)

AE

\* All wipes st

Project Name: 266 Sidgreaves - 33671  
 Address: 266 Sidgreaves  
 City, State: Phillipsburg, NJ  
 Project Number: 33671

Sample Type:  Dust wipe  Paint chip  Soil  TCIP

Turn Around Time (TAT):  Same Day  3 Day  1 Day  Weekend  1 Week  2 Weeks

Sampler Information: Name: Nyire Grant Signature: Nyire Grant

Sample #	Date Collected	Sample Location (Ex: Fl, Kitchen, AC)	Area (inches)	Paint Chip Analysis		
				mg/cm <sup>2</sup>	PPM	% wt
1	5/28/24	Bed 1 fl	12 x 12			
2	5/28/24	Bed 1 ws	3 x 26 1/2			
3	5/28/24	Bed 2 fl	12 x 12			
4	5/28/24	Bed 2 ws	2 1/2 x 31			
5	5/28/24	Bed 3 fl	12 x 12			
6	5/28/24	Bed 3 ws	2 1/2 x 31			
7	5/28/24	Bed 4 fl	12 x 12			
8	5/28/24	Bed 4 ws	2 1/2 x 31			
9	5/28/24	Sunroom fl	12 x 12			

Relinquished by: Nyire Grant Signature: Nyire Grant Date/Time: 6/4/24

Received by: Debra Signature: Debra Date/Time: 6/5/24 4:30pm

SS 6/6/24