

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 2128
 Lead concentration units: mg/cm2
 Total Readings: 112
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
5212005	20377	1		TRUE	FALSE	5/21/2024	8:05 PM	Danny Feliciano	Paint	109 Joyce Kilmer								
5212005	20378	1		TRUE	FALSE	5/21/2024	8:06 PM	Danny Feliciano	Paint	109 Joyce Kilmer								
5212005	20379	1		TRUE	FALSE	5/21/2024	8:06 PM	Danny Feliciano	Paint	109 Joyce Kilmer								
5212005	20380	0		TRUE	FALSE	5/21/2024	8:07 PM	Danny Feliciano	Paint	109 Joyce Kilmer								
5212005	20381	0		TRUE	FALSE	5/21/2024	8:07 PM	Danny Feliciano	Paint	109 Joyce Kilmer								
5212005	20382	0		TRUE	FALSE	5/21/2024	8:08 PM	Danny Feliciano	Paint	109 Joyce Kilmer								
5212005	20383	0	Negative	FALSE	FALSE	5/21/2024	8:10 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Foyer/Hall	Door	---	Metal	A	
5212005	20384	-0.6	Negative	FALSE	TRUE	5/21/2024	8:11 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Foyer/Hall	Door	Casing	Wood	A	
5212005	20385	-0.7	Negative	FALSE	TRUE	5/21/2024	8:11 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Foyer/Hall	Room	Baseboard	Wood	B	
5212005	20386	-0.7	Negative	FALSE	TRUE	5/21/2024	8:12 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Foyer/Hall	Window	Casing	Wood	D	
5212005	20387	-0.6	Negative	FALSE	TRUE	5/21/2024	8:13 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Foyer/Hall	Window	Sill	Wood	D	
5212005	20388	0	Negative	FALSE	FALSE	5/21/2024	8:13 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Foyer/Hall	Room	Wall	Drywall	B	
5212005	20389	-0.1	Negative	FALSE	FALSE	5/21/2024	8:14 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Foyer/Hall	Room	Wall	Drywall	D	
5212005	20390	0	Negative	FALSE	FALSE	5/21/2024	8:14 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Foyer/Hall	Room	Wall	Drywall	C	
5212005	20391	0	Negative	FALSE	FALSE	5/21/2024	8:14 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Foyer/Hall	Room	Wall	Drywall	A	
5212005	20392	0.1	Negative	FALSE	FALSE	5/21/2024	8:16 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Foyer/Hall	Room	Wall	Drywall	A	
5212005	20393	-0.6	Negative	FALSE	TRUE	5/21/2024	8:16 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Foyer/Hall	Stair	Stringer	Wood	D	
5212005	20394	-0.5	Negative	FALSE	TRUE	5/21/2024	8:17 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Foyer/Hall	Stair	Railing	Wood	D	
5212005	20395	-0.1	Negative	FALSE	FALSE	5/21/2024	8:18 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Living Room/Dining Room	Room	Wall	Drywall	A	
5212005	20396	-0.1	Negative	FALSE	FALSE	5/21/2024	8:18 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Living Room/Dining Room	Room	Wall	Drywall	D	
5212005	20397	-0.1	Negative	FALSE	FALSE	5/21/2024	8:19 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Living Room/Dining Room	Room	Wall	Drywall	C	
5212005	20398	-0.1	Negative	FALSE	FALSE	5/21/2024	8:20 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Living Room/Dining Room	Room	Wall	Drywall	B	
5212005	20399	-0.6	Negative	FALSE	TRUE	5/21/2024	8:20 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Living Room/Dining Room	Window	Casing	Wood	B	
5212005	20400	-0.6	Negative	FALSE	TRUE	5/21/2024	8:21 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Living Room/Dining Room	Window	Sill	Wood	B	
5212005	20401	-0.6	Negative	FALSE	TRUE	5/21/2024	8:21 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Living Room/Dining Room	Room	Baseboard	Wood	C	
5212005	20402	-0.1	Negative	FALSE	FALSE	5/21/2024	8:22 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Living Room/Dining Room	Room	Wall	Drywall	C	
5212005	20403	-0.1	Negative	FALSE	FALSE	5/21/2024	8:22 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Living Room/Dining Room	Room	Wall	Drywall	D	
5212005	20404	-0.2	Negative	FALSE	FALSE	5/21/2024	8:23 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Living Room/Dining Room	Room	Wall	Drywall	A	
5212005	20405	-0.1	Negative	FALSE	FALSE	5/21/2024	8:23 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Living Room/Dining Room	Room	Wall	Drywall	B	
5212005	20406	0	Negative	FALSE	FALSE	5/21/2024	8:24 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Living Room/Dining Room	Room	Ceiling	Plaster		
5212005	20407	0	Negative	FALSE	FALSE	5/21/2024	8:25 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Kitchen	Room	Ceiling	Drywall		
5212005	20408	-0.1	Negative	FALSE	FALSE	5/21/2024	8:26 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Kitchen	Room	Wall	Drywall	A	
5212005	20409	-0.1	Negative	FALSE	FALSE	5/21/2024	8:27 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Kitchen	Room	Wall	Drywall	D	
5212005	20410	-0.1	Negative	FALSE	FALSE	5/21/2024	8:27 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Kitchen	Room	Wall	Drywall	C	
5212005	20411	-0.1	Negative	FALSE	FALSE	5/21/2024	8:27 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Kitchen	Room	Wall	Drywall	B	
5212005	20412	-0.2	Negative	FALSE	TRUE	5/21/2024	8:28 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Kitchen	Door		Metal	B	1
5212005	20413	0	Negative	FALSE	FALSE	5/21/2024	8:28 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Kitchen	Door	Casing	Wood	B	1
5212005	20414	-0.4	Negative	FALSE	TRUE	5/21/2024	8:29 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Kitchen	Door	Jamb	Wood	B	1
5212005	20415	-0.3	Negative	FALSE	TRUE	5/21/2024	8:29 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Kitchen	Door	Jamb	Wood	B	2
5212005	20416	-0.6	Negative	FALSE	TRUE	5/21/2024	8:30 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Kitchen	Door	Casing	Wood	B	2
5212005	20417	-0.8	Negative	FALSE	TRUE	5/21/2024	8:30 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Kitchen	Door		Wood	B	2
5212005	20418	-0.4	Negative	FALSE	TRUE	5/21/2024	8:31 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		1/2 Bathroom	Door	Casing	Wood	D	
5212005	20419	-0.7	Negative	FALSE	TRUE	5/21/2024	8:31 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		1/2 Bathroom	Door	Jamb	Wood	D	
5212005	20420	-0.8	Negative	FALSE	TRUE	5/21/2024	8:34 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		1/2 Bathroom	Door	Jamb	Wood	D	
5212005	20421	-0.7	Negative	FALSE	TRUE	5/21/2024	8:34 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		1/2 Bathroom	Door	---	Wood	D	
5212005	20422	-0.1	Negative	FALSE	FALSE	5/21/2024	8:35 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		1/2 Bathroom	Room	Wall	Drywall	C	
5212005	20423	-0.6	Negative	FALSE	TRUE	5/21/2024	8:35 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		1/2 Bathroom	Room	Wall	Drywall	B	

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
5212005	20424	-0.3	Negative	FALSE	TRUE	5/21/2024	8:36 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		1/2 Bathroom	Room	Wall	Drywall	D	
5212005	20425	0	Negative	FALSE	FALSE	5/21/2024	8:36 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		1/2 Bathroom	Room	Wall	Drywall	A	
5212005	20426	0	Negative	FALSE	FALSE	5/21/2024	8:37 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		1/2 Bathroom	Room	Ceiling	Plaster		
5212005	20427	-0.9	Negative	FALSE	TRUE	5/21/2024	8:37 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Kitchen	Door		Wood	A	
5212005	20428	-0.6	Negative	FALSE	TRUE	5/21/2024	8:38 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Kitchen	Door	Casing	Wood	A	
5212005	20429	-0.8	Negative	FALSE	TRUE	5/21/2024	8:38 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Kitchen	Door	Jamb	Wood	A	
5212005	20430	-0.6	Negative	FALSE	TRUE	5/21/2024	8:39 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Kitchen	Room	Baseboard	Wood	A	
5212005	20431	-0.4	Negative	FALSE	TRUE	5/21/2024	8:40 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		2nd Floor Hallway	Stair	Newel Post	Wood		
5212005	20432	1.8	Positive	FALSE	FALSE	5/21/2024	8:41 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		2nd Floor Hallway	Stair	Balusters	Wood		
5212005	20433	0.6	Negative	FALSE	FALSE	5/21/2024	8:42 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		2nd Floor Hallway	Stair	Gate	Wood		
5212005	20434	-0.7	Negative	FALSE	TRUE	5/21/2024	8:42 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		2nd Floor Hallway	Stair	Support column	Wood		
5212005	20435	-0.5	Negative	FALSE	TRUE	5/21/2024	8:43 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		2nd Floor Hallway	Room	Baseboard	Wood	B	
5212005	20436	-0.8	Negative	FALSE	TRUE	5/21/2024	8:44 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		2nd Floor Hallway	Window	Casing	Wood	D	
5212005	20437	-0.7	Negative	FALSE	TRUE	5/21/2024	8:44 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		2nd Floor Hallway	Window	Sill	Wood	D	
5212005	20438	-0.7	Negative	FALSE	TRUE	5/21/2024	8:45 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		2nd Floor Hallway	Door	Casing	Wood	C	
5212005	20439	-0.6	Negative	FALSE	TRUE	5/21/2024	8:45 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		2nd Floor Hallway	Door	Jamb	Wood	C	
5212005	20440	-0.1	Negative	FALSE	FALSE	5/21/2024	8:46 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		2nd Floor Hallway	Door	---	Wood	C	
5212005	20441	-1.1	Negative	FALSE	TRUE	5/21/2024	8:47 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		2nd Floor Hallway	Door	---	Wood	A	
5212005	20442	0	Negative	FALSE	FALSE	5/21/2024	8:47 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		2nd Floor Hallway	Room	Wall	Drywall	D	
5212005	20443	0	Negative	FALSE	FALSE	5/21/2024	8:48 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		2nd Floor Hallway	Room	Wall	Drywall	B	
5212005	20444	-0.6	Negative	FALSE	TRUE	5/21/2024	8:48 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		2nd Floor Hallway	Room	Wall	Drywall	C	
5212005	20445	-0.1	Negative	FALSE	FALSE	5/21/2024	8:49 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		2nd Floor Hallway	Room	Wall	Drywall	A	
5212005	20446	0	Negative	FALSE	FALSE	5/21/2024	8:51 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		2nd Floor Hallway	Room	Ceiling	Plaster		
5212005	20447	-0.6	Negative	FALSE	TRUE	5/21/2024	8:52 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bathroom	Window	Casing	Drywall	A	
5212005	20448	-0.7	Negative	FALSE	TRUE	5/21/2024	8:52 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bathroom	Window	Sill	Drywall	A	
5212005	20449	-0.3	Negative	FALSE	TRUE	5/21/2024	8:53 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bathroom	Room	Wall	Drywall	D	
5212005	20450	0.1	Negative	FALSE	FALSE	5/21/2024	8:54 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bathroom	Room	Wall	Drywall	C	
5212005	20451	-0.1	Negative	FALSE	FALSE	5/21/2024	8:54 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bathroom	Room	Wall	Drywall	B	
5212005	20452	-0.4	Negative	FALSE	TRUE	5/21/2024	8:54 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bathroom	Room	Wall	Drywall	A	
5212005	20453	0	Negative	FALSE	FALSE	5/21/2024	8:55 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bathroom	Room	Ceiling	Plaster		
5212005	20454	-0.8	Negative	FALSE	TRUE	5/21/2024	8:55 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bathroom	Door	Casing	Wood	C	
5212005	20455	-0.9	Negative	FALSE	TRUE	5/21/2024	8:56 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bathroom	Door	Jamb	Wood	C	
5212005	20456	-0.7	Negative	FALSE	TRUE	5/21/2024	8:56 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bathroom	Door	---	Wood	C	
5212005	20457	-0.8	Negative	FALSE	TRUE	5/21/2024	8:57 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bedroom 1	Door	---	Wood	D	
5212005	20458	-0.4	Negative	FALSE	TRUE	5/21/2024	8:58 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bedroom 1	Door	Casing	Wood	D	
5212005	20459	-0.8	Negative	FALSE	TRUE	5/21/2024	8:58 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bedroom 1	Door	Jamb	Wood	D	
5212005	20460	-0.5	Negative	FALSE	TRUE	5/21/2024	8:59 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bedroom 1	Window	Casing	Wood	A	1
5212005	20461	-0.7	Negative	FALSE	TRUE	5/21/2024	8:59 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bedroom 1	Window	Sill	Wood	A	1
5212005	20462	-0.7	Negative	FALSE	TRUE	5/21/2024	9:00 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bedroom 1	Room	Baseboard	Wood	A	
5212005	20463	-1	Negative	FALSE	TRUE	5/21/2024	9:00 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bedroom 1	Door	Jamb	Wood	C	
5212005	20464	-0.8	Negative	FALSE	TRUE	5/21/2024	9:01 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bedroom 1	Door	Casing	Wood	C	
5212005	20465	0	Negative	FALSE	FALSE	5/21/2024	9:02 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bedroom 1	Closet	Shelf Support	Wood	C	
5212005	20466	0	Negative	FALSE	FALSE	5/21/2024	9:02 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bedroom 1	Closet	Shelf	Wood	C	
5212005	20467	-0.1	Negative	FALSE	FALSE	5/21/2024	9:03 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bedroom 1	Room	Wall	Drywall	C	
5212005	20468	0	Negative	FALSE	FALSE	5/21/2024	9:03 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bedroom 1	Room	Wall	Drywall	B	
5212005	20469	0.2	Negative	FALSE	FALSE	5/21/2024	9:03 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bedroom 1	Room	Wall	Drywall	D	
5212005	20470	-0.1	Negative	FALSE	FALSE	5/21/2024	9:04 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bedroom 1	Room	Wall	Drywall	A	
5212005	20471	0.2	Negative	FALSE	FALSE	5/21/2024	9:04 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bedroom 1	Room	Wall	Drywall	B	
5212005	20472	0	Negative	FALSE	FALSE	5/21/2024	9:06 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bedroom 1	Room	Ceiling	Plaster		
5212005	20473	-0.1	Negative	FALSE	FALSE	5/21/2024	9:06 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bedroom 2	Room	Ceiling	Plaster		
5212005	20474	0.1	Negative	FALSE	FALSE	5/21/2024	9:07 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bedroom 2	Room	Wall	Drywall	C	
5212005	20475	0.2	Negative	FALSE	FALSE	5/21/2024	9:07 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bedroom 2	Room	Wall	Drywall	B	
5212005	20476	-0.1	Negative	FALSE	FALSE	5/21/2024	9:07 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bedroom 2	Room	Wall	Drywall	A	
5212005	20477	-0.1	Negative	FALSE	FALSE	5/21/2024	9:08 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bedroom 2	Room	Wall	Drywall	D	
5212005	20478	-0.8	Negative	FALSE	TRUE	5/21/2024	9:08 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bedroom 2	Window	Casing	Wood	B	
5212005	20479	-0.7	Negative	FALSE	TRUE	5/21/2024	9:09 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bedroom 2	Window	Sill	Wood	B	
5212005	20480	-0.6	Negative	FALSE	TRUE	5/21/2024	9:09 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		Bedroom 2	Room	Baseboard	Wood	A	

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 2128

Lead concentration units: mg/cm2

Total Readings: 112 Total Positives 1

Action Level 1

Mode Action Level

Analytic Mode Paint

Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
5212005	20432	1.8	Positive	FALSE	FALSE	5/21/2024	8:41 PM	Danny Feliciano	Paint	109 Joyce Kilmer	Unit		2nd Floor Hallway	Stair	Balusters	Wood		