

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 2128
 Lead concentration units: mg/cm2
 Total Readings: 73
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
5281550	21722	1.1		TRUE	FALSE	5/28/2024	3:50 PM	Danny Feliciano	Paint	237 N. Fullerton								
5281550	21723	1		TRUE	FALSE	5/28/2024	3:51 PM	Danny Feliciano	Paint	237 N. Fullerton								
5281550	21724	1		TRUE	FALSE	5/28/2024	3:51 PM	Danny Feliciano	Paint	237 N. Fullerton								
5281550	21725	0.1		TRUE	FALSE	5/28/2024	3:52 PM	Danny Feliciano	Paint	237 N. Fullerton								
5281550	21726	0.1		TRUE	FALSE	5/28/2024	3:52 PM	Danny Feliciano	Paint	237 N. Fullerton								
5281550	21727	0.1		TRUE	FALSE	5/28/2024	3:53 PM	Danny Feliciano	Paint	237 N. Fullerton								
5281550	21728	0	Negative	FALSE	FALSE	5/28/2024	4:48 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Foyer/Hall	Door	---	Metal	B	
5281550	21729	-0.7	Negative	FALSE	TRUE	5/28/2024	4:48 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Foyer/Hall	Door	Casing	Metal	B	
5281550	21730	-0.6	Negative	FALSE	TRUE	5/28/2024	4:49 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Foyer/Hall	Window	Casing	Wood	B	
5281550	21731	-0.1	Negative	FALSE	FALSE	5/28/2024	4:50 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Foyer/Hall	Stair	Railing	Wood	B	
5281550	21732	0	Negative	FALSE	FALSE	5/28/2024	4:50 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Foyer/Hall	Stair	Stringer	Wood	B	
5281550	21733	0	Negative	FALSE	FALSE	5/28/2024	4:51 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Foyer/Hall	Stair	Treads	Wood	B	
5281550	21734	-0.8	Negative	FALSE	TRUE	5/28/2024	4:51 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Foyer/Hall	Stair	Risers	Wood	B	
5281550	21735	0	Negative	FALSE	FALSE	5/28/2024	4:52 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Foyer/Hall	Room	Wall	Drywall	A	
5281550	21736	0.1	Negative	FALSE	FALSE	5/28/2024	4:52 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Foyer/Hall	Room	Wall	Drywall	C	
5281550	21737	0.2	Negative	FALSE	FALSE	5/28/2024	4:53 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Foyer/Hall	Room	Wall	Drywall	B	
5281550	21738	-0.6	Negative	FALSE	TRUE	5/28/2024	4:53 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Foyer/Hall	Room	Wall	Drywall	D	
5281550	21739	0.1	Negative	FALSE	FALSE	5/28/2024	4:54 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Foyer/Hall	Room	Ceiling	Drywall		
5281550	21740	-0.4	Negative	FALSE	TRUE	5/28/2024	4:55 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Foyer/Hall	Window	Casing	Wood		
5281550	21741	-0.7	Negative	FALSE	TRUE	5/28/2024	4:56 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Living Room/Dining Room	Room	Wall	Drywall	B	
5281550	21742	0	Negative	FALSE	FALSE	5/28/2024	4:57 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Living Room/Dining Room	Room	Wall	Drywall	C	
5281550	21743	0	Negative	FALSE	FALSE	5/28/2024	4:57 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Living Room/Dining Room	Room	Wall	Drywall	D	
5281550	21744	-0.5	Negative	FALSE	TRUE	5/28/2024	4:58 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Living Room/Dining Room	Room	Wall	Drywall	A	
5281550	21745	-0.1	Negative	FALSE	FALSE	5/28/2024	4:58 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Living Room/Dining Room	Room	Ceiling	Drywall		
5281550	21746	-0.8	Negative	FALSE	TRUE	5/28/2024	4:59 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Living Room/Dining Room	Door		Wood	D	
5281550	21747	-0.7	Negative	FALSE	TRUE	5/28/2024	4:59 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Living Room/Dining Room	Door	Jamb	Wood	D	
5281550	21748	-0.6	Negative	FALSE	TRUE	5/28/2024	5:00 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Living Room/Dining Room	Door	Casing	Wood	D	
5281550	21749	-0.6	Negative	FALSE	TRUE	5/28/2024	5:00 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Living Room/Dining Room	Room	Baseboard	Wood	D	
5281550	21750	-0.4	Negative	FALSE	TRUE	5/28/2024	5:01 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Living Room/Dining Room	Window	Casing	Wood	C	
5281550	21751	-0.6	Negative	FALSE	TRUE	5/28/2024	5:01 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Living Room/Dining Room	Stair	Treads	Wood		
5281550	21752	0	Negative	FALSE	FALSE	5/28/2024	5:02 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Living Room/Dining Room	Stair	Risers	Wood		
5281550	21753	-0.7	Negative	FALSE	TRUE	5/28/2024	5:02 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Kitchen	Window	Casing	Wood	C	
5281550	21754	-0.4	Negative	FALSE	TRUE	5/28/2024	5:03 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Kitchen	Room	Wall	Drywall	C	
5281550	21755	-0.9	Negative	FALSE	TRUE	5/28/2024	5:03 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Kitchen	Room	Wall	Drywall	D	
5281550	21756	0	Negative	FALSE	FALSE	5/28/2024	5:04 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Kitchen	Room	Wall	Drywall	B	
5281550	21757	0	Negative	FALSE	FALSE	5/28/2024	5:05 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Kitchen	Room	Wall	Drywall	A	
5281550	21758	-0.1	Negative	FALSE	FALSE	5/28/2024	5:05 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Kitchen	Room	Ceiling	Drywall		
5281550	21759	-0.1	Negative	FALSE	FALSE	5/28/2024	5:06 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Bedroom 1	Door		Wood	B	
5281550	21760	-0.5	Negative	FALSE	TRUE	5/28/2024	5:07 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Bedroom 1	Door	Jamb	Wood	B	
5281550	21761	-0.8	Negative	FALSE	TRUE	5/28/2024	5:07 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Bedroom 1	Door	Casing	Wood	B	
5281550	21762	-0.5	Negative	FALSE	TRUE	5/28/2024	5:07 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Bedroom 1	Room	Baseboard	Wood	B	
5281550	21763	-0.5	Negative	FALSE	TRUE	5/28/2024	5:08 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Bedroom 1	Window	Casing	Wood	D	
5281550	21764	0	Negative	FALSE	FALSE	5/28/2024	5:08 PM	Danny Feliciano	Paint	237 N. Fullerton	Unit	2	Bedroom 1	Room	Wall	Drywall	D	

Company LEW Corporation
XRF Make Heuresis
Model Pb200i
Serial Num. 2128
Lead concentration units: mg/cm2
Total Readings: 73 Total Positives 0
Action Level 1
Mode Action Level
Analytic Mode Paint

Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
No Actionables																		