

Company LEW Corporation  
 XRF Make Heuresis  
 Model Pb200i  
 Serial Num. 2128

Lead concentration units: mg/cm2  
 Total Readings: 205  
 Action Level 1  
 Mode Action Level  
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
5231531	21166	1		TRUE	FALSE	5/23/2024	3:32 PM	Danny Feliciano	Paint	170 Township Line Rd								
5231531	21167	1		TRUE	FALSE	5/23/2024	3:32 PM	Danny Feliciano	Paint	170 Township Line Rd								
5231531	21168	1		TRUE	FALSE	5/23/2024	3:33 PM	Danny Feliciano	Paint	170 Township Line Rd								
5231531	21169	0		TRUE	FALSE	5/23/2024	3:34 PM	Danny Feliciano	Paint	170 Township Line Rd								
5231531	21170	0.1		TRUE	FALSE	5/23/2024	3:34 PM	Danny Feliciano	Paint	170 Township Line Rd								
5231531	21171	0		TRUE	FALSE	5/23/2024	3:35 PM	Danny Feliciano	Paint	170 Township Line Rd								
5231531	21172	0.2	Negative	FALSE	FALSE	5/23/2024	3:35 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Door			Metal	A
5231531	21173	-0.9	Negative	FALSE	TRUE	5/23/2024	3:36 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Door	Casing	Wood	A	
5231531	21174	6.4	Positive	FALSE	FALSE	5/23/2024	3:36 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Door	Casing	Wood	B	
5231531	21175	5.4	Positive	FALSE	FALSE	5/23/2024	3:37 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Door	Jamb	Wood	B	
5231531	21176	1.9	Positive	FALSE	FALSE	5/23/2024	3:38 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Baseboard	Wood	B	
5231531	21177	5.9	Positive	FALSE	FALSE	5/23/2024	3:39 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Chair Rail	Wood	B	
5231531	21178	-0.8	Negative	FALSE	TRUE	5/23/2024	3:39 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Archway		Wood	C	
5231531	21179	0.3	Negative	FALSE	FALSE	5/23/2024	3:40 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Window	Casing	Wood	C	
5231531	21180	0.6	Negative	FALSE	FALSE	5/23/2024	3:40 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Window	Sill	Wood	C	
5231531	21181	-0.5	Negative	FALSE	TRUE	5/23/2024	3:41 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Floor	Wood		
5231531	21182	0	Negative	FALSE	FALSE	5/23/2024	3:44 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Wall	Plaster	D	
5231531	21183	0	Negative	FALSE	FALSE	5/23/2024	3:44 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Wall	Plaster	B	
5231531	21184	0.2	Negative	FALSE	FALSE	5/23/2024	3:45 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Wall	Plaster	A	
5231531	21185	-0.1	Negative	FALSE	FALSE	5/23/2024	3:45 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Wall	Plaster	C	
5231531	21186	0.1	Negative	FALSE	FALSE	5/23/2024	3:46 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Ceiling	Plaster		2
5231531	21187	-0.1	Negative	FALSE	FALSE	5/23/2024	3:46 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Ceiling	Drywall		1
5231531	21188	0	Negative	FALSE	FALSE	5/23/2024	3:47 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Crown Molding	Wood	D	
5231531	21189	3	Positive	FALSE	FALSE	5/23/2024	3:48 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Wall Trim	Wood	D	
5231531	21190	1.6	Positive	FALSE	FALSE	5/23/2024	3:48 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Door		Wood	A	2
5231531	21191	-0.6	Negative	FALSE	TRUE	5/23/2024	3:49 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Baseboard	Wood	D	2
5231531	21192	0.3	Negative	FALSE	FALSE	5/23/2024	3:50 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Door	Casing	Wood	A	2
5231531	21193	0.3	Negative	FALSE	FALSE	5/23/2024	3:52 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Wall	Concrete	D	2
5231531	21194	-0.5	Negative	FALSE	TRUE	5/23/2024	3:54 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Stair	Wall	Wood	A	
5231531	21195	0.5	Negative	FALSE	TRUE	5/23/2024	3:54 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Stair	Ceiling	Wood	A	
5231531	21196	-0.4	Negative	FALSE	TRUE	5/23/2024	3:56 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Stair	Wall	Wood	B	
5231531	21197	0	Negative	FALSE	FALSE	5/23/2024	3:56 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Stair	Wall	Plaster	D	
5231531	21198	6.7	Positive	FALSE	FALSE	5/23/2024	3:57 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Window	Casing	Wood	D	
5231531	21199	2.6	Positive	FALSE	FALSE	5/23/2024	3:58 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Window	Sill	Wood	D	
5231531	21200	7.8	Positive	FALSE	FALSE	5/23/2024	3:59 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Door	Casing	Wood	D	
5231531	21201	4	Positive	FALSE	FALSE	5/23/2024	3:59 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Door	Jamb	Wood	D	
5231531	21202	4.3	Positive	FALSE	FALSE	5/23/2024	3:59 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Room	Baseboard	Wood	D	
5231531	21203	9.6	Positive	FALSE	TRUE	5/23/2024	4:00 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Room	Chair Rail	Wood	D	
5231531	21204	20.5	Positive	FALSE	TRUE	5/23/2024	4:01 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Window	Casing	Wood	A	1
5231531	21205	17.4	Positive	FALSE	TRUE	5/23/2024	4:01 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Window	Sill	Wood	A	1
5231531	21206	0.2	Negative	FALSE	FALSE	5/23/2024	4:02 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Pipe	Vertical	Metal	A	1
5231531	21207	0.1	Negative	FALSE	FALSE	5/23/2024	4:03 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Radiator		Metal	A	
5231531	21208	-0.8	Negative	FALSE	TRUE	5/23/2024	4:03 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Closet	Door	Wood	B	
5231531	21209	-0.6	Negative	FALSE	TRUE	5/23/2024	4:04 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Closet	Door Casing	Wood	B	
5231531	21210	-0.3	Negative	FALSE	TRUE	5/23/2024	4:04 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Closet	Door Jamb	Wood	B	
5231531	21211	0.2	Negative	FALSE	FALSE	5/23/2024	4:05 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Closet	Wall	Wood	B	
5231531	21212	1.8	Positive	FALSE	TRUE	5/23/2024	4:05 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Fire Place	Mantle	Wood	B	

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
5231531	21213	0.7	Negative	FALSE	TRUE	5/23/2024	4:06 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Fire Place	Frame	Wood	B	
5231531	21214	0	Negative	FALSE	TRUE	5/23/2024	4:07 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Fire Place	Trim	Wood	B	
5231531	21215	0	Negative	FALSE	FALSE	5/23/2024	4:08 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Archway		Wood	C	
5231531	21216	7.3	Positive	FALSE	FALSE	5/23/2024	4:08 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Cabinets	Door	Wood	B	Upper
5231531	21217	7.1	Positive	FALSE	FALSE	5/23/2024	4:09 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Cabinets	Door	Wood	B	Lower
5231531	21218	-1	Negative	FALSE	TRUE	5/23/2024	4:10 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Cabinets	Shelf	Wood	B	Lower
5231531	21219	-0.5	Negative	FALSE	TRUE	5/23/2024	4:11 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Cabinets	Shelf Support	Wood	B	Lower
5231531	21220	0.2	Negative	FALSE	FALSE	5/23/2024	4:12 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Cabinets	Inside Wall	Plaster	B	Lower
5231531	21221	0	Negative	FALSE	FALSE	5/23/2024	4:13 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Cabinets	Inside Wall	Plaster	B	Lower
5231531	21222	0.5	Negative	FALSE	TRUE	5/23/2024	4:15 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Cabinets	Door	Wood	B	Lower
5231531	21223	0.1	Negative	FALSE	FALSE	5/23/2024	4:18 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Column		Wood	C	Lower
5231531	21224	0	Negative	FALSE	FALSE	5/23/2024	4:20 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Room	Wall	Plaster	D	
5231531	21225	0	Negative	FALSE	FALSE	5/23/2024	4:21 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Room	Wall	Plaster	C	
5231531	21226	0.2	Negative	FALSE	FALSE	5/23/2024	4:21 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Room	Wall	Concrete	B	
5231531	21227	0.3	Negative	FALSE	FALSE	5/23/2024	4:22 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Room	Wall	Drywall	A	
5231531	21228	0.2	Negative	FALSE	FALSE	5/23/2024	4:23 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Room	Wall	Plaster	A	2
5231531	21229	0	Negative	FALSE	FALSE	5/23/2024	4:24 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Room	Crown Molding	Wood	C	2
5231531	21230	-0.1	Negative	FALSE	FALSE	5/23/2024	4:25 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Room	Ceiling	Plaster		
5231531	21231	0	Negative	FALSE	FALSE	5/23/2024	4:26 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Room	Wall	Plaster	D	
5231531	21232	0.1	Negative	FALSE	FALSE	5/23/2024	4:26 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Room	Wall	Plaster	C	
5231531	21233	0.2	Negative	FALSE	FALSE	5/23/2024	4:27 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Room	Wall	Concrete	B	
5231531	21234	-0.1	Negative	FALSE	FALSE	5/23/2024	4:27 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Room	Wall	Plaster	A	
5231531	21235	0	Negative	FALSE	FALSE	5/23/2024	4:28 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Archway		Wood	A	
5231531	21236	0	Negative	FALSE	FALSE	5/23/2024	4:28 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Column		Wood	A	
5231531	21237	0.5	Negative	FALSE	FALSE	5/23/2024	4:29 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Fire Place	Mantle	Wood	B	
5231531	21238	7	Positive	FALSE	FALSE	5/23/2024	4:30 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Fire Place	Frame	Wood	B	
5231531	21239	4.2	Positive	FALSE	FALSE	5/23/2024	4:30 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Fire Place	Trim	Wood	B	
5231531	21240	2.8	Positive	FALSE	FALSE	5/23/2024	4:32 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Cabinets	Door	Wood	B	Upper
5231531	21241	1.7	Positive	FALSE	FALSE	5/23/2024	4:32 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Cabinets	Door	Wood	B	Lower
5231531	21242	-0.6	Negative	FALSE	TRUE	5/23/2024	4:34 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Closet	Door	Wood	B	
5231531	21243	-0.7	Negative	FALSE	TRUE	5/23/2024	4:35 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Closet	Door Casing	Wood	B	
5231531	21244	2.4	Positive	FALSE	FALSE	5/23/2024	4:36 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Window	Casing	Wood	C	1
5231531	21245	2.9	Positive	FALSE	TRUE	5/23/2024	4:36 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Window	Sill	Wood	C	1
5231531	21246	2.5	Positive	FALSE	FALSE	5/23/2024	4:37 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Room	Chair Rail	Wood	C	1
5231531	21247	0.6	Negative	FALSE	FALSE	5/23/2024	4:38 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Room	Baseboard	Wood	A	1
5231531	21248	2.6	Positive	FALSE	FALSE	5/23/2024	4:39 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Door	Casing	Wood	D	1
5231531	21249	7.1	Positive	FALSE	TRUE	5/23/2024	4:40 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Door	Jamb	Wood	D	1
5231531	21250	0	Negative	FALSE	FALSE	5/23/2024	4:41 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Room	Wall	Plaster	A	
5231531	21251	-0.1	Negative	FALSE	FALSE	5/23/2024	4:41 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Room	Wall	Plaster	D	
5231531	21252	0.2	Negative	FALSE	FALSE	5/23/2024	4:42 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Room	Wall	Plaster	C	
5231531	21253	0.3	Negative	FALSE	FALSE	5/23/2024	4:45 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Room	Wall	Plaster	C	
5231531	21254	0.3	Negative	FALSE	FALSE	5/23/2024	4:46 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Room	Wall	Plaster	B	
5231531	21255	0.2	Negative	FALSE	FALSE	5/23/2024	4:46 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Room	Wall	Plaster	A	
5231531	21256	0.2	Negative	FALSE	FALSE	5/23/2024	4:47 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Room	Wall	Plaster	D	
5231531	21257	1	Positive	FALSE	FALSE	5/23/2024	4:48 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Window	Casing	Wood	D	
5231531	21258	-0.1	Negative	FALSE	FALSE	5/23/2024	4:48 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Window	Sill	Wood	D	
5231531	21259	0	Negative	FALSE	FALSE	5/23/2024	4:49 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Room	Baseboard	Wood	D	
5231531	21260	0.7	Negative	FALSE	FALSE	5/23/2024	4:50 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Door	Casing	Wood	B	
5231531	21261	2	Positive	FALSE	FALSE	5/23/2024	4:51 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Door	---	Wood	B	
5231531	21262	5	Positive	FALSE	FALSE	5/23/2024	4:51 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Door	Jamb	Wood	B	
5231531	21263	1	Positive	FALSE	FALSE	5/23/2024	4:53 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Door	---	Wood	A	
5231531	21264	0.7	Negative	FALSE	FALSE	5/23/2024	4:53 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Door	Casing	Wood	A	
5231531	21265	1.3	Positive	FALSE	FALSE	5/23/2024	4:54 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Closet	Door Casing	Wood	A	
5231531	21266	-0.4	Negative	FALSE	TRUE	5/23/2024	4:55 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Closet	Door	Wood	A	
5231531	21267	0.6	Negative	FALSE	FALSE	5/23/2024	4:55 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Closet	Door	Wood		
5231531	21268	0.7	Negative	FALSE	FALSE	5/23/2024	4:56 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Closet	Door Jamb	Wood		
5231531	21269	0.6	Negative	FALSE	FALSE	5/23/2024	4:58 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Room	Floor	Wood		

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
5231531	21270	0.2	Negative	FALSE	FALSE	5/23/2024	4:59 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Room	Ceiling	Plaster		
5231531	21271	0.2	Negative	FALSE	FALSE	5/23/2024	5:03 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Room	Ceiling	Plaster		
5231531	21272	-0.8	Negative	FALSE	TRUE	5/23/2024	5:03 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Door	Casing	Wood	C	
5231531	21273	0.2	Negative	FALSE	FALSE	5/23/2024	5:04 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Room	Wall	Drywall	A	
5231531	21274	-0.1	Negative	FALSE	FALSE	5/23/2024	5:04 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Room	Wall	Drywall	D	
5231531	21275	0	Negative	FALSE	FALSE	5/23/2024	5:05 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Room	Wall	Drywall	C	
5231531	21276	-0.1	Negative	FALSE	FALSE	5/23/2024	5:05 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Room	Wall	Drywall	B	
5231531	21277	0.1	Negative	FALSE	FALSE	5/23/2024	5:06 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Room	Ceiling	Drywall		
5231531	21278	-0.6	Negative	FALSE	TRUE	5/23/2024	5:07 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Window	Casing	Wood	C	
5231531	21279	-0.7	Negative	FALSE	TRUE	5/23/2024	5:08 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Window	Sill	Wood	C	
5231531	21280	-0.8	Negative	FALSE	TRUE	5/23/2024	5:08 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Window	Casing	Wood	D	
5231531	21281	-0.8	Negative	FALSE	TRUE	5/23/2024	5:09 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Window	Sill	Wood	D	
5231531	21282	0.8	Negative	FALSE	FALSE	5/23/2024	5:09 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Window	Sash	Wood	D	
5231531	21283	-0.1	Negative	FALSE	FALSE	5/23/2024	5:10 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Room	Baseboard	Wood	C	
5231531	21284	-0.1	Negative	FALSE	FALSE	5/23/2024	5:10 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Door	Casing	Wood	C	
5231531	21285	-0.7	Negative	FALSE	TRUE	5/23/2024	5:11 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Kitchen	Door	Jamb	Wood	C	
5231531	21286	-0.2	Negative	FALSE	TRUE	5/23/2024	5:11 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Door	---	Metal	A	
5231531	21287	-0.7	Negative	FALSE	TRUE	5/23/2024	5:12 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Door	Casing	Wood	A	
5231531	21288	-0.4	Negative	FALSE	TRUE	5/23/2024	5:12 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Door	Outer Casing	Wood	A	
5231531	21289	-0.7	Negative	FALSE	TRUE	5/23/2024	5:13 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Door	Jamb	Wood	A	
5231531	21290	1	Positive	FALSE	FALSE	5/23/2024	5:13 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Door	Casing	Wood	C	
5231531	21291	0.4	Negative	FALSE	TRUE	5/23/2024	5:14 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Room	Wall	Wood	C	
5231531	21292	0.9	Positive	FALSE	TRUE	5/23/2024	5:15 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Room	Wall	Wood	D	
5231531	21293	0.9	Positive	FALSE	TRUE	5/23/2024	5:16 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Room	Wall	Wood	A	
5231531	21294	1.3	Positive	FALSE	TRUE	5/23/2024	5:17 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Room	Wall	Wood	B	
5231531	21295	0.7	Negative	FALSE	FALSE	5/23/2024	5:19 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Room	Ceiling	Wood		
5231531	21296	-0.1	Negative	FALSE	FALSE	5/23/2024	5:19 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Room	Ceiling	Wood		
5231531	21297	0.7	Negative	FALSE	FALSE	5/23/2024	5:20 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Window	Casing	Wood	B	
5231531	21298	1.9	Positive	FALSE	TRUE	5/23/2024	5:21 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Window	Sill	Wood	B	
5231531	21299	0.3	Negative	FALSE	TRUE	5/23/2024	5:22 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Window	Sill	Wood	D	
5231531	21300	0.8	Negative	FALSE	FALSE	5/23/2024	5:24 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Window	Sill	Wood	C	
5231531	21301	1.1	Positive	FALSE	FALSE	5/23/2024	5:25 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Window	Casing	Wood	C	
5231531	21302	1.2	Positive	FALSE	FALSE	5/23/2024	5:25 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Room	Baseboard	Wood	C	
5231531	21303	0.2	Negative	FALSE	FALSE	5/23/2024	5:26 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Room	Wall	Plaster	C	
5231531	21304	0.7	Negative	FALSE	FALSE	5/23/2024	5:27 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Room	Wall	Wood	B	
5231531	21305	0.8	Negative	FALSE	FALSE	5/23/2024	5:27 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Room	Wall	Wood	D	
5231531	21306	-0.1	Negative	FALSE	FALSE	5/23/2024	5:28 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Room	Wall	Plaster	A	
5231531	21307	2.4	Positive	FALSE	TRUE	5/23/2024	5:29 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Closet	Door	Wood	C	
5231531	21308	2.4	Positive	FALSE	TRUE	5/23/2024	5:29 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Closet	Door Casing	Wood	C	
5231531	21309	3.9	Positive	FALSE	FALSE	5/23/2024	5:30 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Door		Wood	B	1
5231531	21310	0.7	Negative	FALSE	FALSE	5/23/2024	5:30 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Door		Wood	B	2
5231531	21311	0.8	Negative	FALSE	FALSE	5/23/2024	5:31 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Door	Casing	Wood	B	2
5231531	21312	0.1	Negative	FALSE	FALSE	5/23/2024	5:33 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Door	---	Wood	A	
5231531	21313	0.8	Negative	FALSE	FALSE	5/23/2024	5:33 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Door	Casing	Wood	A	
5231531	21314	1.3	Positive	FALSE	FALSE	5/23/2024	5:34 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Access Panel	Door	Wood	D	
5231531	21315	0.8	Negative	FALSE	FALSE	5/23/2024	5:35 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Access Panel	Casing	Wood	D	
5231531	21316	0.8	Negative	FALSE	FALSE	5/23/2024	5:36 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bathroom	Door		Wood	C	
5231531	21317	-0.6	Negative	FALSE	TRUE	5/23/2024	5:37 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bathroom	Door	Casing	Wood	C	
5231531	21318	-0.4	Negative	FALSE	TRUE	5/23/2024	5:37 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bathroom	Room	Baseboard	Wood	C	
5231531	21319	-0.6	Negative	FALSE	TRUE	5/23/2024	5:37 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bathroom	Room	Chair Rail	Wood	C	
5231531	21320	0	Negative	FALSE	FALSE	5/23/2024	5:38 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bathroom	Room	Crown Molding	Wood	C	
5231531	21321	0.1	Negative	FALSE	FALSE	5/23/2024	5:39 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bathroom	Room	Ceiling	Drywall		
5231531	21322	-0.6	Negative	FALSE	TRUE	5/23/2024	5:39 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bathroom	Room	Wall	Drywall	A	
5231531	21323	-0.1	Negative	FALSE	FALSE	5/23/2024	5:40 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bathroom	Room	Wall	Drywall	D	
5231531	21324	-0.1	Negative	FALSE	FALSE	5/23/2024	5:40 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bathroom	Room	Wall	Drywall	C	
5231531	21325	-0.1	Negative	FALSE	FALSE	5/23/2024	5:40 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bathroom	Room	Wall	Drywall	B	
5231531	21326	1.1	Positive	FALSE	FALSE	5/23/2024	5:41 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bathroom	Window	Casing	Wood	A	



Company LEW Corporation  
 XRF Make Heuresis  
 Model Pb200i  
 Serial Num. 2128

Lead concentration units: mg/cm2

Total Readings: 205 Total Positives 48

Action Level 1

Mode Action Level

Analytic Mode Paint

**Actionables**

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
5231531	21174	6.4	Positive	FALSE	FALSE	5/23/2024	3:36 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Door	Casing	Wood	B	
5231531	21175	5.4	Positive	FALSE	FALSE	5/23/2024	3:37 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Door	Jamb	Wood	B	
5231531	21176	1.9	Positive	FALSE	FALSE	5/23/2024	3:38 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Baseboard	Wood	B	
5231531	21177	5.9	Positive	FALSE	FALSE	5/23/2024	3:39 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Chair Rail	Wood	B	
5231531	21189	3	Positive	FALSE	FALSE	5/23/2024	3:48 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Room	Wall Trim	Wood	D	
5231531	21190	1.6	Positive	FALSE	FALSE	5/23/2024	3:48 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Door		Wood	A	2
5231531	21198	6.7	Positive	FALSE	FALSE	5/23/2024	3:57 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Window	Casing	Wood	D	
5231531	21199	2.6	Positive	FALSE	FALSE	5/23/2024	3:58 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Foyer/Hall	Window	Sill	Wood	D	
5231531	21200	7.8	Positive	FALSE	FALSE	5/23/2024	3:59 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Door	Casing	Wood	D	
5231531	21201	4	Positive	FALSE	FALSE	5/23/2024	3:59 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Door	Jamb	Wood	D	
5231531	21202	4.3	Positive	FALSE	FALSE	5/23/2024	3:59 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Room	Baseboard	Wood	D	
5231531	21203	9.6	Positive	FALSE	TRUE	5/23/2024	4:00 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Room	Chair Rail	Wood	D	
5231531	21204	20.5	Positive	FALSE	TRUE	5/23/2024	4:01 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Window	Casing	Wood	A	1
5231531	21205	17.4	Positive	FALSE	TRUE	5/23/2024	4:01 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Window	Sill	Wood	A	1
5231531	21212	1.8	Positive	FALSE	TRUE	5/23/2024	4:05 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Fire Place	Mantle	Wood	B	
5231531	21216	7.3	Positive	FALSE	FALSE	5/23/2024	4:08 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Cabinets	Door	Wood	B	Upper
5231531	21217	7.1	Positive	FALSE	FALSE	5/23/2024	4:09 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Living Room	Cabinets	Door	Wood	B	Lower
5231531	21238	7	Positive	FALSE	FALSE	5/23/2024	4:30 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Fire Place	Frame	Wood	B	
5231531	21239	4.2	Positive	FALSE	FALSE	5/23/2024	4:30 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Fire Place	Trim	Wood	B	
5231531	21240	2.8	Positive	FALSE	FALSE	5/23/2024	4:32 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Cabinets	Door	Wood	B	Upper
5231531	21241	1.7	Positive	FALSE	FALSE	5/23/2024	4:32 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Cabinets	Door	Wood	B	Lower
5231531	21244	2.4	Positive	FALSE	FALSE	5/23/2024	4:36 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Window	Casing	Wood	C	1
5231531	21245	2.9	Positive	FALSE	TRUE	5/23/2024	4:36 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Window	Sill	Wood	C	1
5231531	21246	2.5	Positive	FALSE	FALSE	5/23/2024	4:37 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Room	Chair Rail	Wood	C	1
5231531	21248	2.6	Positive	FALSE	FALSE	5/23/2024	4:39 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Door	Casing	Wood	D	1
5231531	21249	7.1	Positive	FALSE	TRUE	5/23/2024	4:40 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Family Room	Door	Jamb	Wood	D	1
5231531	21257	1	Positive	FALSE	FALSE	5/23/2024	4:48 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Window	Casing	Wood	D	
5231531	21261	2	Positive	FALSE	FALSE	5/23/2024	4:51 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Door	---	Wood	B	
5231531	21262	5	Positive	FALSE	FALSE	5/23/2024	4:51 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Door	Jamb	Wood	B	
5231531	21263	1	Positive	FALSE	FALSE	5/23/2024	4:53 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Door	---	Wood	A	
5231531	21265	1.3	Positive	FALSE	FALSE	5/23/2024	4:54 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Dining Room	Closet	Door Casing	Wood	A	
5231531	21290	1	Positive	FALSE	FALSE	5/23/2024	5:13 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Door	Casing	Wood	C	
5231531	21292	0.9	Positive	FALSE	TRUE	5/23/2024	5:15 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Room	Wall	Wood	D	
5231531	21293	0.9	Positive	FALSE	TRUE	5/23/2024	5:16 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Room	Wall	Wood	A	
5231531	21294	1.3	Positive	FALSE	TRUE	5/23/2024	5:17 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Room	Wall	Wood	B	
5231531	21298	1.9	Positive	FALSE	TRUE	5/23/2024	5:21 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Rear Entry	Window	Sill	Wood	B	
5231531	21301	1.1	Positive	FALSE	FALSE	5/23/2024	5:25 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Window	Casing	Wood	C	
5231531	21302	1.2	Positive	FALSE	FALSE	5/23/2024	5:25 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Room	Baseboard	Wood	C	
5231531	21307	2.4	Positive	FALSE	TRUE	5/23/2024	5:29 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Closet	Door	Wood	C	
5231531	21308	2.4	Positive	FALSE	TRUE	5/23/2024	5:29 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Closet	Door Casing	Wood	C	
5231531	21309	3.9	Positive	FALSE	FALSE	5/23/2024	5:30 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Door		Wood	B	1
5231531	21314	1.3	Positive	FALSE	FALSE	5/23/2024	5:34 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		2nd Floor Hallway	Access Panel	Door	Wood	D	
5231531	21326	1.1	Positive	FALSE	FALSE	5/23/2024	5:41 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bathroom	Window	Casing	Wood	A	
5231531	21334	1.6	Positive	FALSE	TRUE	5/23/2024	5:45 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bedroom 1	Door		Wood	B	
5231531	21336	1.2	Positive	FALSE	FALSE	5/23/2024	5:46 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bedroom 1	Door	Threshold	Wood	D	
5231531	21351	2.3	Positive	FALSE	FALSE	5/23/2024	5:54 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bedroom 2	Door		Wood	D	
5231531	21354	1.2	Positive	FALSE	FALSE	5/23/2024	5:56 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Bedroom 2	Window	Casing	Wood	C	2

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
5231531	21362	1.3	Positive	FALSE	FALSE	5/23/2024	6:02 PM	Danny Feliciano	Paint	170 Township Line Rd	Unit		Basement room 1	Door	---	Wood	C	