

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 2822
 Lead concentration units: mg/cm2
 Total Readings: 103
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
5231047	18935	1		TRUE	FALSE	5/23/2024	10:47 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ								
5231047	18936	1		TRUE	FALSE	5/23/2024	10:47 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ								
5231047	18937	0.9		TRUE	FALSE	5/23/2024	10:48 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ								
5231047	18938	0		TRUE	FALSE	5/23/2024	10:48 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ								
5231047	18939	0.1		TRUE	FALSE	5/23/2024	10:48 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ								
5231047	18940	0		TRUE	FALSE	5/23/2024	10:48 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ								
5231047	18941	1.7	Positive	FALSE	FALSE	5/23/2024	10:48 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Window	Casing	Wood	D	1
5231047	18942	0.2	Negative	FALSE	FALSE	5/23/2024	10:49 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Window	Sill	Wood	D	1
5231047	18943	4.2	Positive	FALSE	FALSE	5/23/2024	10:49 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Window	Apron	Wood	D	1
5231047	18944	0.3	Negative	FALSE	FALSE	5/23/2024	10:50 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Window	Sash	Metal	D	1
5231047	18945	0.3	Negative	FALSE	FALSE	5/23/2024	10:50 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Window	Frame	Metal	D	1
5231047	18946	0	Negative	FALSE	FALSE	5/23/2024	10:50 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Room	Wall	Plaster	D	1
5231047	18947	14.8	Positive	FALSE	FALSE	5/23/2024	10:51 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Room	Baseboard	Wood	D	1
5231047	18948	0	Negative	FALSE	FALSE	5/23/2024	10:51 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Room	Wall	Plaster	A	1
5231047	18949	0.3	Negative	FALSE	FALSE	5/23/2024	10:51 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Room	Wall	Plaster	B	1
5231047	18950	0.2	Negative	FALSE	FALSE	5/23/2024	10:52 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Room	Wall	Plaster	C	1
5231047	18951	8.5	Positive	FALSE	FALSE	5/23/2024	10:52 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Door	---	Wood	B	1
5231047	18952	1.1	Positive	FALSE	FALSE	5/23/2024	10:52 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Door	Jamb	Wood	B	1
5231047	18953	1.8	Positive	FALSE	FALSE	5/23/2024	10:53 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Door	Casing	Wood	B	1
5231047	18954	0.2	Negative	FALSE	FALSE	5/23/2024	11:06 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Radiator	---	Metal	D	1
5231047	18955	0.1	Negative	FALSE	FALSE	5/23/2024	11:06 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Cabinets	Door	Wood	A	1
5231047	18956	0	Negative	FALSE	FALSE	5/23/2024	11:06 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Cabinets	Frame	Wood	A	1
5231047	18957	0.1	Negative	FALSE	FALSE	5/23/2024	11:07 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Door	---	Metal	A	1
5231047	18958	0.2	Negative	FALSE	FALSE	5/23/2024	11:07 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Door	Buck	Metal	A	1
5231047	18959	0	Negative	FALSE	FALSE	5/23/2024	11:07 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Door	Casing	Wood	A	1
5231047	18960	-0.2	Negative	FALSE	FALSE	5/23/2024	11:08 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bathroom	Door	Casing	Wood	A	1
5231047	18961	3	Positive	FALSE	FALSE	5/23/2024	11:08 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bathroom	Door	Jamb	Wood	A	1
5231047	18962	9	Positive	FALSE	FALSE	5/23/2024	11:08 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bathroom	Door	Stop	Wood	A	1
5231047	18963	-0.1	Negative	FALSE	FALSE	5/23/2024	11:09 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bathroom	Door	---	Wood	A	1
5231047	18964	2.7	Positive	FALSE	FALSE	5/23/2024	11:09 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bathroom	Door	Jamb	Wood	A	1
5231047	18965	1.7	Positive	FALSE	FALSE	5/23/2024	11:10 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bathroom	Window	Sash	Wood	D	1
5231047	18966	3.6	Positive	FALSE	FALSE	5/23/2024	11:10 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bathroom	Window	Jamb	Wood	D	1
5231047	18967	3.9	Positive	FALSE	FALSE	5/23/2024	11:10 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bathroom	Window	Casing	Wood	D	1
5231047	18968	0	Negative	FALSE	FALSE	5/23/2024	11:10 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bathroom	Window	Sill	Wood	D	1
5231047	18969	0.1	Negative	FALSE	FALSE	5/23/2024	11:11 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bathroom	Window	Apron	Wood	D	1
5231047	18970	0.1	Negative	FALSE	FALSE	5/23/2024	11:11 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bathroom	Radiator	Cover	Wood	A	1
5231047	18971	1.6	Positive	FALSE	FALSE	5/23/2024	11:11 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bathroom	Room	Wall	Plaster	A	1
5231047	18972	2.6	Positive	FALSE	FALSE	5/23/2024	11:12 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bathroom	Room	Wall	Plaster	D	1
5231047	18973	0.2	Negative	FALSE	FALSE	5/23/2024	11:12 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bathroom	Room	Wall	Plaster	C	1
5231047	18974	0.2	Negative	FALSE	FALSE	5/23/2024	11:12 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bathroom	Room	Wall	Plaster	B	1
5231047	18975	0.5	Negative	FALSE	FALSE	5/23/2024	11:12 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bathroom	Room	Ceiling	Plaster	B	1
5231047	18976	13.1	Positive	FALSE	FALSE	5/23/2024	11:13 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Door	Jamb	Wood	C	1
5231047	18977	17.2	Positive	FALSE	FALSE	5/23/2024	11:13 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Door	Casing	Wood	C	1
5231047	18978	20.6	Positive	FALSE	FALSE	5/23/2024	11:14 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Room	Baseboard	Wood	C	1
5231047	18979	-0.3	Negative	FALSE	FALSE	5/23/2024	11:15 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Room	Wall	Plaster	C	1
5231047	18980	0.2	Negative	FALSE	FALSE	5/23/2024	11:15 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Room	Wall	Plaster	D	1

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
5231047	18981	0.1	Negative	FALSE	FALSE	5/23/2024	11:15 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Room	Wall	Plaster	C	2
5231047	18982	0.2	Negative	FALSE	FALSE	5/23/2024	11:15 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Room	Wall	Plaster	B	1
5231047	18983	23.4	Positive	FALSE	FALSE	5/23/2024	11:16 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Fire Place	Mantle	Wood	B	1
5231047	18984	15.1	Positive	FALSE	FALSE	5/23/2024	11:16 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Fire Place	Trim	Wood	B	1
5231047	18985	-0.3	Negative	FALSE	FALSE	5/23/2024	11:17 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Bookcase	Frame	Wood	B	1
5231047	18986	0.2	Negative	FALSE	FALSE	5/23/2024	11:17 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Bookcase	Shelf	Wood	B	1
5231047	18987	0.4	Negative	FALSE	FALSE	5/23/2024	11:18 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Window	Sash	Metal	A	1
5231047	18988	0.3	Negative	FALSE	FALSE	5/23/2024	11:19 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Window	Frame	Metal	A	1
5231047	18989	6.5	Positive	FALSE	FALSE	5/23/2024	11:19 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Window	Casing	Wood	A	1
5231047	18990	5.6	Positive	FALSE	FALSE	5/23/2024	11:20 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Window	Sill	Wood	A	1
5231047	18991	3.1	Positive	FALSE	FALSE	5/23/2024	11:20 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Window	Apron	Wood	A	1
5231047	18992	-0.1	Negative	FALSE	FALSE	5/23/2024	11:21 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Room	Wall	Plaster	A	1
5231047	18993	11.2	Positive	FALSE	FALSE	5/23/2024	11:21 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Closet	Door	Wood	D	1
5231047	18994	15	Positive	FALSE	FALSE	5/23/2024	11:21 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Closet	Door Casing	Wood	D	1
5231047	18995	9.5	Positive	FALSE	FALSE	5/23/2024	11:22 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Closet	Door Jamb	Wood	D	1
5231047	18996	3.3	Positive	FALSE	FALSE	5/23/2024	11:22 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Closet	Baseboard	Wood	D	1
5231047	18997	0.1	Negative	FALSE	FALSE	5/23/2024	11:22 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Closet	Wall	Plaster	D	1
5231047	18998	10.3	Positive	FALSE	FALSE	5/23/2024	11:23 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Walk-in Closet	Closet	Door Jamb	Wood	B	1
5231047	18999	9.7	Positive	FALSE	FALSE	5/23/2024	11:23 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Walk-in Closet	Closet	Door Buck	Wood	B	1
5231047	19000	0.6	Negative	FALSE	FALSE	5/23/2024	11:24 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Walk-in Closet	Closet	Wall	Plaster	B	1
5231047	19001	0.2	Negative	FALSE	FALSE	5/23/2024	11:24 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Walk-in Closet	Closet	Wall	Plaster	C	1
5231047	19002	0.2	Negative	FALSE	FALSE	5/23/2024	11:24 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Walk-in Closet	Closet	Wall	Plaster	D	1
5231047	19003	0.1	Negative	FALSE	FALSE	5/23/2024	11:24 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Walk-in Closet	Closet	Wall	Plaster	A	1
5231047	19004	13.7	Positive	FALSE	FALSE	5/23/2024	11:25 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Walk-in Closet	Closet	Baseboard	Wood	A	1
5231047	19005	2.2	Positive	FALSE	FALSE	5/23/2024	11:25 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Walk-in Closet	Window	Casing	Wood	A	1
5231047	19006	0.5	Negative	FALSE	FALSE	5/23/2024	11:25 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Walk-in Closet	Window	Sill	Wood	A	1
5231047	19007	1.2	Positive	FALSE	FALSE	5/23/2024	11:25 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Walk-in Closet	Window	Apron	Wood	A	1
5231047	19008	0.2	Negative	FALSE	FALSE	5/23/2024	11:27 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Walk-in Closet	Radiator	---	Metal	A	1
5231047	19009	0.1	Negative	FALSE	FALSE	5/23/2024	11:28 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 2	Radiator	---	Metal	B	1
5231047	19010	0.1	Negative	FALSE	FALSE	5/23/2024	11:29 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 2	Window	Casing	Wood	B	1
5231047	19011	0.3	Negative	FALSE	FALSE	5/23/2024	11:29 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 2	Window	Sill	Wood	B	1
5231047	19012	0.6	Negative	FALSE	FALSE	5/23/2024	11:29 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 2	Window	Apron	Wood	B	1
5231047	19013	6.7	Positive	FALSE	FALSE	5/23/2024	11:30 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 2	Room	Baseboard	Wood	B	1
5231047	19014	0.1	Negative	FALSE	FALSE	5/23/2024	11:30 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 2	Room	Wall	Plaster	B	1
5231047	19015	-0.2	Negative	FALSE	FALSE	5/23/2024	11:30 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 2	Room	Wall	Plaster	A	1
5231047	19016	-0.1	Negative	FALSE	FALSE	5/23/2024	11:31 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 2	Room	Wall	Plaster	C	1
5231047	19017	0	Negative	FALSE	FALSE	5/23/2024	11:31 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 2	Room	Wall	Plaster	D	1
5231047	19018	5.7	Positive	FALSE	FALSE	5/23/2024	11:31 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 2	Door	---	Wood	D	1
5231047	19019	1.6	Positive	FALSE	FALSE	5/23/2024	11:32 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 2	Door	Jamb	Wood	D	1
5231047	19020	15.7	Positive	FALSE	FALSE	5/23/2024	11:32 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 2	Door	Casing	Wood	D	1
5231047	19021	0.1	Negative	FALSE	FALSE	5/23/2024	11:33 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 2	Closet	Door	Wood	A	1
5231047	19022	2.9	Positive	FALSE	FALSE	5/23/2024	11:34 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 2	Closet	Door Jamb	Wood	A	1
5231047	19023	3.5	Positive	FALSE	FALSE	5/23/2024	11:34 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 2	Closet	Door Casing	Wood	A	1
5231047	19024	3.8	Positive	FALSE	FALSE	5/23/2024	11:34 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 2	Closet	Shelf Support	Wood	A	1
5231047	19025	0.9	Negative	FALSE	FALSE	5/23/2024	11:34 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 2	Closet	Wall	Plaster	A	1
5231047	19026	7.3	Positive	FALSE	FALSE	5/23/2024	11:35 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 3	Door	---	Wood	D	1
5231047	19027	5.9	Positive	FALSE	FALSE	5/23/2024	11:36 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 3	Door	Jamb	Wood	D	1
5231047	19028	12.3	Positive	FALSE	FALSE	5/23/2024	11:36 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 3	Door	Casing	Wood	D	1
5231047	19029	2.9	Positive	FALSE	FALSE	5/23/2024	11:36 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 3	Window	Casing	Wood	C	1
5231047	19030	0.1	Negative	FALSE	FALSE	5/23/2024	11:37 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 3	Window	Sill	Wood	C	1
5231047	19031	4	Positive	FALSE	FALSE	5/23/2024	11:37 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 3	Window	Apron	Wood	C	1
5231047	19032	0.5	Negative	FALSE	FALSE	5/23/2024	11:37 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 3	Window	Sash	Wood	C	1
5231047	19033	2.8	Positive	FALSE	FALSE	5/23/2024	11:38 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 3	Room	Baseboard	Wood	C	1
5231047	19034	0.1	Negative	FALSE	FALSE	5/23/2024	11:38 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 3	Room	Wall	Plaster	C	1
5231047	19035	0.1	Negative	FALSE	FALSE	5/23/2024	11:38 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 3	Room	Wall	Plaster	B	1
5231047	19036	-0.2	Negative	FALSE	FALSE	5/23/2024	11:38 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 3	Room	Wall	Plaster	A	1
5231047	19037	0.3	Negative	FALSE	FALSE	5/23/2024	11:39 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 3	Room	Wall	Plaster	D	1

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 2822
 Lead concentration units: mg/cm2
 Total Readings: 103 Total Positives 45
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
5231047	18941	1.7	Positive	FALSE	FALSE	5/23/2024	10:48 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Window	Casing	Wood	D	1
5231047	18943	4.2	Positive	FALSE	FALSE	5/23/2024	10:49 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Window	Apron	Wood	D	1
5231047	18947	14.8	Positive	FALSE	FALSE	5/23/2024	10:51 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Room	Baseboard	Wood	D	1
5231047	18951	8.5	Positive	FALSE	FALSE	5/23/2024	10:52 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Door	---	Wood	B	1
5231047	18952	1.1	Positive	FALSE	FALSE	5/23/2024	10:52 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Door	Jamb	Wood	B	1
5231047	18953	1.8	Positive	FALSE	FALSE	5/23/2024	10:53 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Kitchen	Door	Casing	Wood	B	1
5231047	18961	3	Positive	FALSE	FALSE	5/23/2024	11:08 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bathroom	Door	Jamb	Wood	A	1
5231047	18962	9	Positive	FALSE	FALSE	5/23/2024	11:08 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bathroom	Door	Stop	Wood	A	1
5231047	18964	2.7	Positive	FALSE	FALSE	5/23/2024	11:09 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bathroom	Door	Jamb	Wood	A	1
5231047	18965	1.7	Positive	FALSE	FALSE	5/23/2024	11:10 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bathroom	Window	Sash	Wood	D	1
5231047	18966	3.6	Positive	FALSE	FALSE	5/23/2024	11:10 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bathroom	Window	Jamb	Wood	D	1
5231047	18967	3.9	Positive	FALSE	FALSE	5/23/2024	11:10 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bathroom	Window	Casing	Wood	D	1
5231047	18971	1.6	Positive	FALSE	FALSE	5/23/2024	11:11 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bathroom	Room	Wall	Plaster	A	1
5231047	18972	2.6	Positive	FALSE	FALSE	5/23/2024	11:12 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bathroom	Room	Wall	Plaster	D	1
5231047	18976	13.1	Positive	FALSE	FALSE	5/23/2024	11:13 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Door	Jamb	Wood	C	1
5231047	18977	17.2	Positive	FALSE	FALSE	5/23/2024	11:13 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Door	Casing	Wood	C	1
5231047	18978	20.6	Positive	FALSE	FALSE	5/23/2024	11:14 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Room	Baseboard	Wood	C	1
5231047	18983	23.4	Positive	FALSE	FALSE	5/23/2024	11:16 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Fire Place	Mantle	Wood	B	1
5231047	18984	15.1	Positive	FALSE	FALSE	5/23/2024	11:16 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Fire Place	Trim	Wood	B	1
5231047	18989	6.5	Positive	FALSE	FALSE	5/23/2024	11:19 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Window	Casing	Wood	A	1
5231047	18990	5.6	Positive	FALSE	FALSE	5/23/2024	11:20 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Window	Sill	Wood	A	1
5231047	18991	3.1	Positive	FALSE	FALSE	5/23/2024	11:20 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Window	Apron	Wood	A	1
5231047	18993	11.2	Positive	FALSE	FALSE	5/23/2024	11:21 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Closet	Door	Wood	D	1
5231047	18994	15	Positive	FALSE	FALSE	5/23/2024	11:21 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Closet	Door Casing	Wood	D	1
5231047	18995	9.5	Positive	FALSE	FALSE	5/23/2024	11:22 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Closet	Door Jamb	Wood	D	1
5231047	18996	3.3	Positive	FALSE	FALSE	5/23/2024	11:22 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Closet	Baseboard	Wood	D	1
5231047	18998	10.3	Positive	FALSE	FALSE	5/23/2024	11:23 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Walk-in Closet	Closet	Door Jamb	Wood	B	1
5231047	18999	9.7	Positive	FALSE	FALSE	5/23/2024	11:23 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Walk-in Closet	Closet	Door Buck	Wood	B	1
5231047	19004	13.7	Positive	FALSE	FALSE	5/23/2024	11:25 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Walk-in Closet	Closet	Baseboard	Wood	A	1
5231047	19005	2.2	Positive	FALSE	FALSE	5/23/2024	11:25 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Walk-in Closet	Window	Casing	Wood	A	1
5231047	19007	1.2	Positive	FALSE	FALSE	5/23/2024	11:25 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Walk-in Closet	Window	Apron	Wood	A	1
5231047	19013	6.7	Positive	FALSE	FALSE	5/23/2024	11:30 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 2	Room	Baseboard	Wood	B	1
5231047	19018	5.7	Positive	FALSE	FALSE	5/23/2024	11:31 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 2	Door	---	Wood	D	1
5231047	19019	1.6	Positive	FALSE	FALSE	5/23/2024	11:32 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 2	Door	Jamb	Wood	D	1
5231047	19020	15.7	Positive	FALSE	FALSE	5/23/2024	11:32 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 2	Door	Casing	Wood	D	1
5231047	19022	2.9	Positive	FALSE	FALSE	5/23/2024	11:34 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 2	Closet	Door Jamb	Wood	A	1
5231047	19023	3.5	Positive	FALSE	FALSE	5/23/2024	11:34 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 2	Closet	Door Casing	Wood	A	1
5231047	19024	3.8	Positive	FALSE	FALSE	5/23/2024	11:34 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 2	Closet	Shelf Support	Wood	A	1
5231047	19026	7.3	Positive	FALSE	FALSE	5/23/2024	11:35 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 3	Door	---	Wood	D	1
5231047	19027	5.9	Positive	FALSE	FALSE	5/23/2024	11:36 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 3	Door	Jamb	Wood	D	1
5231047	19028	12.3	Positive	FALSE	FALSE	5/23/2024	11:36 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 3	Door	Casing	Wood	D	1
5231047	19029	2.9	Positive	FALSE	FALSE	5/23/2024	11:36 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 3	Window	Casing	Wood	C	1
5231047	19031	4	Positive	FALSE	FALSE	5/23/2024	11:37 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 3	Window	Apron	Wood	C	1
5231047	19033	2.8	Positive	FALSE	FALSE	5/23/2024	11:38 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Bedroom 3	Room	Baseboard	Wood	C	1
5231047	19043	12.1	Positive	FALSE	FALSE	5/23/2024	11:41 AM	Alex Salvador	Paint	47 High Street New Brunswick NJ	Unit	2	Living Room	Room	Baseboard	Wood	C	1