

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 2822
 Lead concentration units: mg/cm2
 Total Readings: 104
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
5230956	18819	1		TRUE	FALSE	5/23/2024	9:56 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ								
5230956	18820	1		TRUE	FALSE	5/23/2024	9:57 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ								
5230956	18821	1		TRUE	FALSE	5/23/2024	9:57 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ								
5230956	18822	0		TRUE	FALSE	5/23/2024	9:57 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ								
5230956	18823	0		TRUE	FALSE	5/23/2024	9:57 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ								
5230956	18824	0.1		TRUE	FALSE	5/23/2024	9:57 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ								
5230956	18825	-0.2	Negative	FALSE	FALSE	5/23/2024	9:58 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Living Room/Kitchen	Door	---	Wood	A	1
5230956	18826	-0.2	Negative	FALSE	FALSE	5/23/2024	9:58 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Living Room/Kitchen	Door	Jamb	Wood	A	1
5230956	18827	-0.2	Negative	FALSE	FALSE	5/23/2024	9:59 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Living Room/Kitchen	Door	Casing	Wood	A	1
5230956	18828	0.2	Negative	FALSE	FALSE	5/23/2024	9:59 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Living Room/Kitchen	Electric Panel	Door	Metal	A	1
5230956	18829	0.1	Negative	FALSE	FALSE	5/23/2024	9:59 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Living Room/Kitchen	Electric Panel	Frame	Metal	A	1
5230956	18830	0.1	Negative	FALSE	FALSE	5/23/2024	10:00 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Living Room/Kitchen	Door	---	Wood	B	1
5230956	18831	0	Negative	FALSE	FALSE	5/23/2024	10:00 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Living Room/Kitchen	Door	Jamb	Wood	B	1
5230956	18832	-0.4	Negative	FALSE	FALSE	5/23/2024	10:00 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Living Room/Kitchen	Door	Casing	Wood	B	1
5230956	18833	0.1	Negative	FALSE	FALSE	5/23/2024	10:00 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Living Room/Kitchen	Room	Wall	Drywall	A	1
5230956	18834	0.1	Negative	FALSE	FALSE	5/23/2024	10:01 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Living Room/Kitchen	Room	Wall	Drywall	B	1
5230956	18835	0.1	Negative	FALSE	FALSE	5/23/2024	10:01 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Living Room/Kitchen	Room	Wall	Drywall	C	1
5230956	18836	0.4	Negative	FALSE	FALSE	5/23/2024	10:01 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Living Room/Kitchen	Window	Sash	Metal	C	1
5230956	18837	0.1	Negative	FALSE	FALSE	5/23/2024	10:02 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Living Room/Kitchen	Window	Frame	Metal	C	1
5230956	18838	-0.1	Negative	FALSE	FALSE	5/23/2024	10:02 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Living Room/Kitchen	Window	Sill	Wood	C	1
5230956	18839	0	Negative	FALSE	FALSE	5/23/2024	10:02 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Living Room/Kitchen	Room	Wall	Drywall	A	2
5230956	18840	0.2	Negative	FALSE	FALSE	5/23/2024	10:03 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Living Room/Kitchen	Room	Wall	Drywall	D	1
5230956	18841	0.1	Negative	FALSE	FALSE	5/23/2024	10:03 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Living Room/Kitchen	Room	Baseboard	Wood	D	1
5230956	18842	0	Negative	FALSE	FALSE	5/23/2024	10:03 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Living Room/Kitchen	Cabinets	Door	Wood	C	1
5230956	18843	0	Negative	FALSE	FALSE	5/23/2024	10:03 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Living Room/Kitchen	Cabinets	Frame	Wood	C	1
5230956	18844	-0.1	Negative	FALSE	FALSE	5/23/2024	10:04 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Bathroom 1	Door	---	Wood	C	1
5230956	18845	0	Negative	FALSE	FALSE	5/23/2024	10:04 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Bathroom 1	Door	Jamb	Wood	C	1
5230956	18846	-0.1	Negative	FALSE	FALSE	5/23/2024	10:05 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Bathroom 1	Door	Casing	Wood	C	1
5230956	18847	0.1	Negative	FALSE	FALSE	5/23/2024	10:05 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Bathroom 1	Cabinets	Door	Wood	A	1
5230956	18848	-0.1	Negative	FALSE	FALSE	5/23/2024	10:05 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Bathroom 1	Cabinets	Frame	Wood	A	1
5230956	18849	0	Negative	FALSE	FALSE	5/23/2024	10:06 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Bathroom 2	Cabinets	Frame	Wood	A	1
5230956	18850	0	Negative	FALSE	FALSE	5/23/2024	10:06 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Bathroom 2	Cabinets	Door	Wood	A	1
5230956	18851	0.1	Negative	FALSE	FALSE	5/23/2024	10:06 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Bathroom 2	Door	---	Wood	C	1
5230956	18852	-0.4	Negative	FALSE	FALSE	5/23/2024	10:06 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Bathroom 2	Door	Jamb	Wood	C	1
5230956	18853	-0.3	Negative	FALSE	FALSE	5/23/2024	10:07 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Bathroom 2	Door	Casing	Wood	C	1
5230956	18854	0.1	Negative	FALSE	FALSE	5/23/2024	10:07 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Bathroom 2	Radiator	---	Metal	B	1
5230956	18855	0.2	Negative	FALSE	FALSE	5/23/2024	10:07 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Bathroom 1	Radiator	---	Metal	D	1
5230956	18856	0.1	Negative	FALSE	FALSE	5/23/2024	10:08 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Living Room/Kitchen	Radiator	---	Metal	C	1
5230956	18857	0.2	Negative	FALSE	FALSE	5/23/2024	10:08 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Bedroom 1	Radiator	---	Metal	B	1
5230956	18858	0.1	Negative	FALSE	FALSE	5/23/2024	10:09 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Bedroom 1	Window	Sill	Wood	B	1
5230956	18859	0.4	Negative	FALSE	FALSE	5/23/2024	10:09 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Bedroom 1	Window	Frame	Metal	B	1
5230956	18860	0.3	Negative	FALSE	FALSE	5/23/2024	10:09 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Bedroom 1	Window	Sash	Metal	B	1
5230956	18861	-0.1	Negative	FALSE	FALSE	5/23/2024	10:10 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Bedroom 1	Room	Wall	Drywall	B	1
5230956	18862	0	Negative	FALSE	FALSE	5/23/2024	10:10 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Bedroom 1	Room	Wall	Drywall	C	1
5230956	18863	0.1	Negative	FALSE	FALSE	5/23/2024	10:10 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Bedroom 1	Room	Wall	Drywall	D	1
5230956	18864	0.2	Negative	FALSE	FALSE	5/23/2024	10:10 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Bedroom 1	Room	Wall	Drywall	A	1
5230956	18865	0.1	Negative	FALSE	FALSE	5/23/2024	10:11 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Bedroom 1	Closet	Door	Wood	D	1
5230956	18866	0	Negative	FALSE	FALSE	5/23/2024	10:11 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Bedroom 1	Closet	Door Jamb	Wood	D	1
5230956	18867	-0.3	Negative	FALSE	FALSE	5/23/2024	10:11 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Bedroom 1	Closet	Door Casing	Wood	D	1
5230956	18868	0.2	Negative	FALSE	FALSE	5/23/2024	10:11 AM	Alex Salvador	Paint	210 Hamilton Street New Brunswick NJ	Interior	unit 2	Bedroom 1	Closet	Wall	Drywall	D	1

Company LEW Corporation
XRF Make Heuresis
Model Pb200i
Serial Num. 2822

Lead concentration units: mg/cm2

Total Readings: 104 Total Positives 0

Action Level 1

Mode Action Level

Analytic Mode Paint

Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
No Actionables																		