



7469 Whitepine Rd  
 North Chesterfield, VA 23237  
 Telephone: 800.347.4010

# Lead Dust Wipe Analysis Report

**Report Number:** 24-05-04572

**Client:** LEW Corp  
 181 US Hwy 46  
 Mine Hill, NJ 07803

**Received Date:** 05/29/2024  
**Analyzed Date:** 05/31/2024  
**Reported Date:** 05/31/2024

**Project/Test Address:** 33964; Cesar and Maria Garcia; 47 Belmont Ave; Dover, NJ

**Collection Date:** 05/24/2024

**Client Number:**  
 201327

## Laboratory Results

**Fax Number:**  
 Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft <sup>2</sup> )	Concentration (ug/ft <sup>2</sup> )	Narrative ID
24-05-04572-001	47-1	LR AB	FL	<5.00	1.00	<5.00	
24-05-04572-002	47-2	KT BCC	FL	<5.00	1.00	<5.00	
24-05-04572-003	47-3	BR 1 CC	FL	<5.00	1.00	<5.00	
24-05-04572-004	47-4	AH AB	FL	<5.00	1.00	<5.00	
24-05-04572-005	47-5	SUNROOM AD	FL	<5.00	1.00	<5.00	
24-05-04572-006	47-6	LR A2	SL	10.9	0.700	15.6	
24-05-04572-007	47-7	KT B2	SL	<5.00	0.700	<7.15	
24-05-04572-008	47-8	BR 1 B	SL	<5.00	0.768	<6.52	
24-05-04572-009	47-9	AH C	SL	36.1	0.656	55.0	

# Environmental Hazards Services, L.L.C

**Client Number:** 201327

**Report Number:** 24-05-04572

**Project/Test Address:** 33964; Cesar and Maria Garcia; 47 Belmont Ave;  
Dover, NJ

---

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft <sup>2</sup> )	Concentration (ug/ft <sup>2</sup> )	Narrative ID
-------------------	----------------------	---------------------	---------	---------------	------------------------------	-------------------------------------	--------------

---

**Method:** ASTM E-1979-17/EPA SW846 7000B

**Accreditation #:**

Reviewed By Authorized Signatory:



*Amanda Lowery*

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft<sup>2</sup> are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accreditation through AIHA LAP, LLC (100420), NY ELAP #11714.

---

Legend	ug = microgram	ug/ft <sup>2</sup> = micrograms per square foot	Pb = lead
	mL = milliliter	ft <sup>2</sup> = square foot	

---



# ENVIRONMENTAL SERVICES

A Mainline Company

LEW Environmental Services P: (800) 783-0567 F: (908) 654-8069

## Lead

### Chain-of-Custody

24-05-04572



Due Date: 06/03/2024 (Monday) AE

\* All wipes

51

Project Name: Cesar & Maria Garcia  
Address: 47 Belmont Ave  
City, State: Dover, NJ  
Project Number: 33964

**Sample Type**

Dust wipe  
 Paint chip  
 Soil  
 TCLP

**Turn Around Time (TAT)**

Same Day  
 1 Day  
 1 Week  
 3 Day  
 Weekend  
 2 Weeks

**Sampler Information**  
Name: Gloria Washington  
Signature: [Signature]

Sample #	Date Collected	Sample Location (Ex: Fl, Kitchen, AC)	Area (inches)	Paint Chip Analysis		
				mg/cm <sup>2</sup>	PPM	% wt
47-1	5-24-2024	LRFLAB	12 X 12			
2		KFLBCC	12 X 12			
3		BRIFLCC	12 X 12			
4		AHFLAB	12 X 12			
5		Sunroom FLAD	12 X 12			
6		LRWSA-2	31 X 3 1/4			
7		KWSBA	31 X 3 1/4			
8		BR1WSB	29 1/2 X 3 3/4			
9		AHWSL	27 X 3 1/2			

Relinquished by: Gloria Washington Signature: [Signature] Date/Time: 5/24/24 - 10pm

Received by: [Signature] Signature: [Signature] Date/Time: 5/29/24 12:17pm