

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 2128
 Lead concentration units: mg/cm2
 Total Readings: 68
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
6051700	22317	1		TRUE	FALSE	6/5/2024	5:01 PM	Danny Feliciano	Paint	32 Polk Ave								
6051700	22318	1		TRUE	FALSE	6/5/2024	5:01 PM	Danny Feliciano	Paint	32 Polk Ave								
6051700	22319	1		TRUE	FALSE	6/5/2024	5:02 PM	Danny Feliciano	Paint	32 Polk Ave								
6051700	22320	0.1		TRUE	FALSE	6/5/2024	5:02 PM	Danny Feliciano	Paint	32 Polk Ave								
6051700	22321	0		TRUE	FALSE	6/5/2024	5:03 PM	Danny Feliciano	Paint	32 Polk Ave								
6051700	22322	0		TRUE	FALSE	6/5/2024	5:04 PM	Danny Feliciano	Paint	32 Polk Ave								
6051700	22323	-0.1	Negative	FALSE	FALSE	6/5/2024	5:05 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Living Room	Room	Wall	Drywall	C	
6051700	22324	-0.1	Negative	FALSE	FALSE	6/5/2024	5:05 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Living Room	Room	Wall	Drywall	B	
6051700	22325	-0.1	Negative	FALSE	FALSE	6/5/2024	5:06 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Living Room	Room	Wall	Drywall	A	
6051700	22326	0	Negative	FALSE	FALSE	6/5/2024	5:06 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Living Room	Room	Wall	Drywall	D	
6051700	22327	-0.4	Negative	FALSE	TRUE	6/5/2024	5:07 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Living Room	Door	Casing	Wood	C	
6051700	22328	0.2	Negative	FALSE	FALSE	6/5/2024	5:07 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Living Room	Door	Jamb	Wood	C	
6051700	22329	-0.4	Negative	FALSE	TRUE	6/5/2024	5:08 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Living Room	Door	Casing	Wood	B	
6051700	22330	-0.6	Negative	FALSE	TRUE	6/5/2024	5:09 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Living Room	Room	Baseboard	Wood	B	
6051700	22331	-0.6	Negative	FALSE	TRUE	6/5/2024	5:09 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Living Room	Window	Casing	Wood	A	
6051700	22332	0.1	Negative	FALSE	FALSE	6/5/2024	5:10 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Living Room	Window	Sill	Wood	A	
6051700	22333	-0.1	Negative	FALSE	FALSE	6/5/2024	5:11 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Living Room	Closet	Bi-Fold Door	Wood	B	
6051700	22334	-0.6	Negative	FALSE	TRUE	6/5/2024	5:11 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Living Room	Closet	Door Casing	Wood	B	
6051700	22335	0.5	Negative	FALSE	FALSE	6/5/2024	5:12 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Living Room	Closet	Door Jamb	Wood	B	
6051700	22336	0	Negative	FALSE	FALSE	6/5/2024	5:15 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Living Room	Room	Ceiling	Drywall		
6051700	22337	0.2	Negative	FALSE	FALSE	6/5/2024	5:15 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Kitchen	Room	Ceiling	Drywall		
6051700	22338	-0.7	Negative	FALSE	TRUE	6/5/2024	5:16 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Kitchen	Room	Wall	Drywall	C	
6051700	22339	-0.6	Negative	FALSE	TRUE	6/5/2024	5:17 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Kitchen	Room	Wall	Drywall	B	
6051700	22340	-0.5	Negative	FALSE	TRUE	6/5/2024	5:17 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Kitchen	Room	Wall	Drywall	A	
6051700	22341	-0.9	Negative	FALSE	TRUE	6/5/2024	5:17 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Kitchen	Room	Wall	Drywall	D	
6051700	22342	-0.7	Negative	FALSE	TRUE	6/5/2024	5:18 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Kitchen	Window	Casing	Wood	B	
6051700	22343	-0.5	Negative	FALSE	TRUE	6/5/2024	5:19 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Kitchen	Room	Baseboard	Wood	B	
6051700	22344	0.2	Negative	FALSE	FALSE	6/5/2024	5:20 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Foyer/Hall	Room	Wall	Drywall	A	
6051700	22345	0.2	Negative	FALSE	FALSE	6/5/2024	5:20 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Foyer/Hall	Room	Wall	Drywall	C	
6051700	22346	0.2	Negative	FALSE	FALSE	6/5/2024	5:21 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Foyer/Hall	Room	Wall	Drywall	B	
6051700	22347	0	Negative	FALSE	FALSE	6/5/2024	5:21 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Foyer/Hall	Room	Ceiling	Drywall		
6051700	22348	-0.6	Negative	FALSE	TRUE	6/5/2024	5:23 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Foyer/Hall	Closet	Door	Wood	A	1
6051700	22349	-0.7	Negative	FALSE	TRUE	6/5/2024	5:23 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Foyer/Hall	Closet	Door Casing	Wood	A	1
6051700	22350	-0.6	Negative	FALSE	TRUE	6/5/2024	5:23 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Foyer/Hall	Closet	Door Casing	Wood	A	2
6051700	22351	-0.9	Negative	FALSE	TRUE	6/5/2024	5:24 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Foyer/Hall	Closet	Door	Wood	A	2
6051700	22352	0.1	Negative	FALSE	FALSE	6/5/2024	5:25 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Foyer/Hall	Door		Wood	C	1
6051700	22353	-0.5	Negative	FALSE	TRUE	6/5/2024	5:25 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Foyer/Hall	Door	Casing	Wood	C	1
6051700	22354	-0.5	Negative	FALSE	TRUE	6/5/2024	5:26 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Foyer/Hall	Door	Jamb	Wood	C	1
6051700	22355	-0.1	Negative	FALSE	FALSE	6/5/2024	5:26 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Foyer/Hall	Room	Ceiling	Drywall		
6051700	22356	-0.1	Negative	FALSE	FALSE	6/5/2024	5:27 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Bathroom	Room	Ceiling	Drywall		
6051700	22357	-0.5	Negative	FALSE	TRUE	6/5/2024	5:27 PM	Danny Feliciano	Paint	32 Polk Ave	Unit		Bathroom	Window	Casing	Wood		

Company LEW Corporation
XRF Make Heuresis
Model Pb200i
Serial Num. 2128

Lead concentration units: mg/cm2

Total Readings: 68 Total Positives 0

Action Level 1

Mode Action Level

Analytic Mode Paint

Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
No Actionables																		