

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 2128
 Lead concentration units: mg/cm2
 Total Readings: 80
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
5241436	21383	0.9		TRUE	FALSE	5/24/2024	2:38 PM	Danny Feliciano	Paint	7 Alpine Dr								
5241436	21384	0.8		TRUE	FALSE	5/24/2024	2:38 PM	Danny Feliciano	Paint	7 Alpine Dr								
5241436	21385	1		TRUE	FALSE	5/24/2024	2:39 PM	Danny Feliciano	Paint	7 Alpine Dr								
5241436	21386	0		TRUE	FALSE	5/24/2024	2:39 PM	Danny Feliciano	Paint	7 Alpine Dr								
5241436	21387	0		TRUE	FALSE	5/24/2024	2:40 PM	Danny Feliciano	Paint	7 Alpine Dr								
5241436	21388	0		TRUE	FALSE	5/24/2024	2:40 PM	Danny Feliciano	Paint	7 Alpine Dr								
5241436	21389	-0.8	Negative	FALSE	TRUE	5/24/2024	2:41 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Living Room/Dining Room	Door	---	Wood	A	
5241436	21390	-0.1	Negative	FALSE	FALSE	5/24/2024	2:42 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Living Room/Dining Room	Door	Casing	Wood	A	
5241436	21391	-0.6	Negative	FALSE	TRUE	5/24/2024	2:42 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Living Room/Dining Room	Door	Jamb	Wood	A	
5241436	21392	0	Negative	FALSE	FALSE	5/24/2024	2:42 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Living Room/Dining Room	Stair	Stringer	Wood	D	
5241436	21393	-0.7	Negative	FALSE	TRUE	5/24/2024	2:43 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Living Room/Dining Room	Stair	Baseboard	Wood	D	
5241436	21394	-0.7	Negative	FALSE	TRUE	5/24/2024	2:44 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Living Room/Dining Room	Stair	Wall	Wood	D	
5241436	21395	-0.8	Negative	FALSE	TRUE	5/24/2024	2:44 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Living Room/Dining Room	Stair	Wall	Wood	B	
5241436	21396	-0.5	Negative	FALSE	TRUE	5/24/2024	2:45 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Living Room/Dining Room	Stair	Wall	Wood	A	
5241436	21397	0.1	Negative	FALSE	FALSE	5/24/2024	2:45 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Living Room/Dining Room	Stair	Wall	Wood	C	
5241436	21398	0.1	Negative	FALSE	FALSE	5/24/2024	2:46 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Living Room/Dining Room	Room	Wall	Drywall	D	
5241436	21399	0.1	Negative	FALSE	FALSE	5/24/2024	2:46 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Living Room/Dining Room	Room	Wall	Drywall	C	
5241436	21400	0	Negative	FALSE	FALSE	5/24/2024	2:47 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Living Room/Dining Room	Room	Wall	Drywall	B	
5241436	21401	0	Negative	FALSE	FALSE	5/24/2024	2:47 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Living Room/Dining Room	Room	Wall	Plaster	A	
5241436	21402	-0.6	Negative	FALSE	TRUE	5/24/2024	2:48 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Living Room/Dining Room	Window	Casing	Wood	A	
5241436	21403	-0.5	Negative	FALSE	TRUE	5/24/2024	2:48 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Living Room/Dining Room	Window	Jamb	Wood	A	
5241436	21404	-0.5	Negative	FALSE	TRUE	5/24/2024	2:49 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Living Room/Dining Room	Window	Sill	Wood	A	
5241436	21405	-0.6	Negative	FALSE	TRUE	5/24/2024	2:49 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Living Room/Dining Room	Room	Baseboard	Wood	B	
5241436	21406	-1	Negative	FALSE	TRUE	5/24/2024	2:50 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Living Room/Dining Room	Closet	Door	Wood	C	
5241436	21407	0	Negative	FALSE	FALSE	5/24/2024	2:50 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Living Room/Dining Room	Closet	Door Casing	Wood	C	
5241436	21408	-0.1	Negative	FALSE	FALSE	5/24/2024	2:51 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Living Room/Dining Room	Closet	Door Jamb	Wood	C	
5241436	21409	-0.8	Negative	FALSE	TRUE	5/24/2024	2:51 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Living Room/Dining Room	Closet	Shelf	Wood	C	
5241436	21410	-0.3	Negative	FALSE	TRUE	5/24/2024	2:52 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Living Room/Dining Room	Closet	Shelf Support	Wood	C	
5241436	21411	0.1	Negative	FALSE	FALSE	5/24/2024	2:54 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Kitchen	Room	Wall	Drywall	C	
5241436	21412	0.3	Negative	FALSE	FALSE	5/24/2024	2:55 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Kitchen	Room	Wall	Drywall	D	
5241436	21413	0.2	Negative	FALSE	FALSE	5/24/2024	2:55 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Kitchen	Room	Wall	Drywall	B	
5241436	21414	-0.5	Negative	FALSE	TRUE	5/24/2024	2:56 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Kitchen	Room	Baseboard	Wood	C	
5241436	21415	0	Negative	FALSE	FALSE	5/24/2024	2:56 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Kitchen	Room	Ceiling	Drywall		
5241436	21416	0.1	Negative	FALSE	FALSE	5/24/2024	2:57 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Living Room/Dining Room	Room	Ceiling	Plaster		
5241436	21417	0.1	Negative	FALSE	FALSE	5/24/2024	2:58 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Bathroom	Room	Ceiling	Drywall		
5241436	21418	0	Negative	FALSE	FALSE	5/24/2024	2:58 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Bathroom	Room	Wall	Drywall	D	
5241436	21419	-0.1	Negative	FALSE	FALSE	5/24/2024	2:59 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Bathroom	Room	Wall	Drywall	A	
5241436	21420	0.1	Negative	FALSE	FALSE	5/24/2024	2:59 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Bathroom	Room	Wall	Drywall	B	
5241436	21421	0	Negative	FALSE	FALSE	5/24/2024	3:00 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Bathroom	Room	Wall	Drywall	C	
5241436	21422	-0.4	Negative	FALSE	TRUE	5/24/2024	3:01 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Bathroom	Room	Baseboard	Wood	C	
5241436	21423	-0.8	Negative	FALSE	TRUE	5/24/2024	3:01 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Bathroom	Door	---	Wood	C	
5241436	21424	-0.6	Negative	FALSE	TRUE	5/24/2024	3:02 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Bathroom	Door	Casing	Wood	C	
5241436	21425	-0.5	Negative	FALSE	TRUE	5/24/2024	3:02 PM	Danny Feliciano	Paint	7 Alpine Dr	Unit	4	Bathroom	Door	Jamb	Wood	C	

Company LEW Corporation
XRF Make Heuresis
Model Pb200i
Serial Num. 2128

Lead concentration units: mg/cm2

Total Readings: 80 Total Positives 0

Action Level 1

Mode Action Level

Analytic Mode Paint

Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
No Actionables																		