



7469 Whitepine Rd
 North Chesterfield, VA 23237
 Telephone: 800.347.4010

Lead Dust Wipe Analysis Report

Report Number: 24-06-00822

Client: LEW Corp
 181 US Hwy 46
 Mine Hill, NJ 07803

Received Date: 06/06/2024
Analyzed Date: 06/10/2024
Reported Date: 06/11/2024

Project/Test Address: 35060; Jose Martinez; 12 Lincoln Ave; Dover, NJ

Collection Date: 06/04/2024

Client Number:
 201327

Laboratory Results

Fax Number:
 Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
24-06-00822-001	12-1	LR CC	FL	<5.00	1.00	<5.00	
24-06-00822-002	12-2	K CC	FL	<5.00	1.00	<5.00	
24-06-00822-003	12-3	B BC	FL	<5.00	1.00	<5.00	
24-06-00822-004	12-4	BR AD	FL	<5.00	1.00	<5.00	
24-06-00822-005	12-5	SUNROOM AC	FL	<5.00	1.00	<5.00	
24-06-00822-006	12-6	LR D	SL	<5.00	0.729	<6.86	
24-06-00822-007	12-7	K C	SL	<5.00	0.677	<7.39	
24-06-00822-008	12-8	B B	SL	26.3	0.679	38.7	
24-06-00822-009	12-9	BR A	SL	<5.00	0.677	<7.39	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 24-06-00822

Project/Test Address: 35060; Jose Martinez; 12 Lincoln Ave; Dover, NJ

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
-------------------	----------------------	---------------------	---------	---------------	------------------------------	-------------------------------------	--------------

Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode

QA/QC Clerk

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft² are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accreditation through AIHA LAP, LLC (100420), NY ELAP #11714.

Legend	ug = microgram	ug/ft ² = micrograms per square foot	Pb = lead
	mL = milliliter	ft ² = square foot	



ENVIRONMENTAL SERVICES

A Mainline Company


LEW Environmental Services P: (800) 783-0567

F: (908) 654-8069

Lead

Chain-of-Custody

24-06-00822



Due Date:

06/11/2024

(Tuesday)

AE

* All Wipes

AP

Project Name: Jose Mecheez
 Address: 12 Lincoln Ave
 City, State: Dover, NJ
 Project Number: 35060

Sample Type
 Dust wipe
 Paint chip
 Soil
 TCLP

Turn Around Time (TAT)
 Same Day
 1 Day
 1 Week
 3 Day
 Weekend
 2 Weeks

Sampler Information
 Name: Danny Feliciano
 Signature: [Signature]

Sample #	Date Collected	Sample Location (Ex: Fl, Kitchen, AC)	Area (inches)	Paint Chip Analysis		
				mg/cm ²	PPM	% wt
12-1	6/4/24	LR Fl, CC	12 x 12			
2		K Fl, CC	12 x 12			
3		B Fl, BC	12 x 12			
4		BR Fl, AD	12 x 12			
5		Sunroom Fl, AC	12 x 12			
6		LR WS, D	30 x 3 1/2			
7		K WS, C	30 x 3 1/4			
8		B WS, B	23 x 4 1/4			
9		BR WS, A	30 x 3 1/4			

See 6/6/24

Relinquished by: Danny Feliciano Signature: [Signature] Date/Time: 6/4/24 5:00pm

Received by: CHRISTINA Signature: [Signature] Date/Time: 6/6/24 14:30pm