

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 2128
 Lead concentration units: mg/cm2
 Total Readings: 162
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
6051135	21952	1		TRUE	FALSE	6/5/2024	11:36 AM	Danny Feliciano	Paint	55 Central Ave								
6051135	21953	1		TRUE	FALSE	6/5/2024	11:36 AM	Danny Feliciano	Paint	55 Central Ave								
6051135	21954	1		TRUE	FALSE	6/5/2024	11:37 AM	Danny Feliciano	Paint	55 Central Ave								
6051135	21955	0		TRUE	FALSE	6/5/2024	11:37 AM	Danny Feliciano	Paint	55 Central Ave								
6051135	21956	0		TRUE	FALSE	6/5/2024	11:38 AM	Danny Feliciano	Paint	55 Central Ave								
6051135	21957	0		TRUE	FALSE	6/5/2024	11:38 AM	Danny Feliciano	Paint	55 Central Ave								
6051135	21958	-0.1	Negative	FALSE	FALSE	6/5/2024	11:39 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Foyer/Hall	Door	---	Wood	A	
6051135	21959	-0.5	Negative	FALSE	TRUE	6/5/2024	11:39 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Foyer/Hall	Door	Casing	Wood	A	
6051135	21960	-0.3	Negative	FALSE	TRUE	6/5/2024	11:40 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Foyer/Hall	Room	Baseboard	Wood	D	
6051135	21961	0.1	Negative	FALSE	FALSE	6/5/2024	11:40 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Foyer/Hall	Door	Casing	Wood	D	
6051135	21962	-0.3	Negative	FALSE	TRUE	6/5/2024	11:40 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Foyer/Hall	Door	Jamb	Wood	D	
6051135	21963	-0.3	Negative	FALSE	TRUE	6/5/2024	11:41 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Foyer/Hall	Stair	Newel Post	Wood		
6051135	21964	0	Negative	FALSE	FALSE	6/5/2024	11:41 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Foyer/Hall	Stair	Railing	Wood		
6051135	21965	-0.1	Negative	FALSE	FALSE	6/5/2024	11:42 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Foyer/Hall	Stair	Balusters	Wood		
6051135	21966	-0.7	Negative	FALSE	TRUE	6/5/2024	11:42 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Foyer/Hall	Stair	Base	Wood		
6051135	21967	0.1	Negative	FALSE	FALSE	6/5/2024	11:43 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Foyer/Hall	Stair	Trim	Wood	D	
6051135	21968	-0.3	Negative	FALSE	TRUE	6/5/2024	11:44 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Foyer/Hall	Stair	Stringer	Wood	D	
6051135	21969	0.1	Negative	FALSE	FALSE	6/5/2024	11:45 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Foyer/Hall	Stair	Crown	Wood		
6051135	21970	0	Negative	FALSE	FALSE	6/5/2024	11:45 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Foyer/Hall	Room	Wall	Drywall	D	
6051135	21971	0.1	Negative	FALSE	FALSE	6/5/2024	11:46 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Foyer/Hall	Room	Wall	Drywall	B	
6051135	21972	0.1	Negative	FALSE	FALSE	6/5/2024	11:46 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Foyer/Hall	Room	Wall	Drywall	A	
6051135	21973	0	Negative	FALSE	FALSE	6/5/2024	11:47 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Foyer/Hall	Room	Ceiling	Drywall		
6051135	21974	0.1	Negative	FALSE	FALSE	6/5/2024	11:47 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Living Room/Dining Room	Room	Ceiling	Drywall		
6051135	21975	0	Negative	FALSE	FALSE	6/5/2024	11:48 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Living Room/Dining Room	Room	Ceiling	Drywall		
6051135	21976	0	Negative	FALSE	FALSE	6/5/2024	11:48 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Living Room/Dining Room	Room	Wall	Drywall	A	
6051135	21977	0.2	Negative	FALSE	FALSE	6/5/2024	11:49 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Living Room/Dining Room	Room	Wall	Drywall	D	
6051135	21978	0	Negative	FALSE	FALSE	6/5/2024	11:53 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Living Room/Dining Room	Room	Wall	Drywall	B	
6051135	21979	0	Negative	FALSE	FALSE	6/5/2024	11:54 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Living Room/Dining Room	Room	Baseboard	Wood	C	
6051135	21980	-0.6	Negative	FALSE	TRUE	6/5/2024	11:54 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Living Room/Dining Room	Archway		Wood	C	
6051135	21981	-0.1	Negative	FALSE	TRUE	6/5/2024	11:54 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Living Room/Dining Room	Archway		Wood	A	
6051135	21982	0	Negative	FALSE	TRUE	6/5/2024	11:55 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Living Room/Dining Room	Door	Casing	Wood	B	
6051135	21983	-0.6	Negative	FALSE	TRUE	6/5/2024	11:55 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Living Room/Dining Room	Door	Jamb	Wood	B	
6051135	21984	0	Negative	FALSE	FALSE	6/5/2024	11:56 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Living Room/Dining Room	Door	Jamb	Wood	C	
6051135	21985	-0.3	Negative	FALSE	TRUE	6/5/2024	11:57 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Living Room/Dining Room	Door	Jamb	Wood	C	2
6051135	21986	0.1	Negative	FALSE	FALSE	6/5/2024	11:57 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Living Room/Dining Room	Window	Casing	Wood	A	
6051135	21987	-0.4	Negative	FALSE	TRUE	6/5/2024	11:58 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Living Room/Dining Room	Window	Sill	Wood	A	
6051135	21988	-0.3	Negative	FALSE	TRUE	6/5/2024	11:59 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Living Room/Dining Room	Window	Sill	Wood	D	1
6051135	21989	-0.5	Negative	FALSE	TRUE	6/5/2024	11:59 AM	Danny Feliciano	Paint	55 Central Ave	Unit		Living Room/Dining Room	Window	Casing	Wood	D	1
6051135	21990	-0.4	Negative	FALSE	TRUE	6/5/2024	12:00 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Kitchen	Window	Casing	Wood	D	
6051135	21991	-0.8	Negative	FALSE	TRUE	6/5/2024	12:00 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Kitchen	Window	Sill	Wood	D	
6051135	21992	-0.7	Negative	FALSE	TRUE	6/5/2024	12:01 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Kitchen	Archway		Wood	A	
6051135	21993	-0.6	Negative	FALSE	TRUE	6/5/2024	12:01 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Kitchen	Closet	Door Casing	Wood	B	
6051135	21994	-0.6	Negative	FALSE	TRUE	6/5/2024	12:01 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Kitchen	Closet	Door Jamb	Wood	B	
6051135	21995	-0.6	Negative	FALSE	TRUE	6/5/2024	12:03 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Kitchen	Door	Casing	Wood	A	
6051135	21996	0	Negative	FALSE	FALSE	6/5/2024	12:03 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Kitchen	Door	---	Wood	A	

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
6051135	21997	-0.1	Negative	FALSE	TRUE	6/5/2024	12:04 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Kitchen	Door	Jamb	Wood	A	
6051135	21998	-0.8	Negative	FALSE	TRUE	6/5/2024	12:04 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Kitchen	Door	Jamb	Wood	C	
6051135	21999	-0.7	Negative	FALSE	TRUE	6/5/2024	12:05 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Kitchen	Door	Casing	Wood	C	
6051135	22000	-0.1	Negative	FALSE	FALSE	6/5/2024	12:05 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Kitchen	Door	---	Wood	C	
6051135	22001	-0.1	Negative	FALSE	FALSE	6/5/2024	12:06 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Kitchen	Room	Wall	Drywall	C	
6051135	22002	-0.8	Negative	FALSE	TRUE	6/5/2024	12:06 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Kitchen	Room	Wall	Drywall	D	
6051135	22003	-0.1	Negative	FALSE	FALSE	6/5/2024	12:07 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Kitchen	Room	Wall	Drywall	B	
6051135	22004	-0.5	Negative	FALSE	TRUE	6/5/2024	12:07 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Kitchen	Room	Wall	Drywall	A	
6051135	22005	0	Negative	FALSE	FALSE	6/5/2024	12:08 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Kitchen	Room	Ceiling	Drywall		
6051135	22006	5.7	Positive	FALSE	FALSE	6/5/2024	12:09 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Rear Entry	Room	Ceiling	Wood		
6051135	22007	26.7	Positive	FALSE	TRUE	6/5/2024	12:09 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Rear Entry	Room	Wall	Wood	A	
6051135	22008	-0.7	Negative	FALSE	TRUE	6/5/2024	12:10 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Rear Entry	Room	Wall	Drywall	D	
6051135	22009	-0.6	Negative	FALSE	TRUE	6/5/2024	12:10 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Rear Entry	Room	Wall	Drywall	C	
6051135	22010	-0.9	Negative	FALSE	TRUE	6/5/2024	12:11 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Rear Entry	Room	Wall	Drywall	B	
6051135	22011	4.7	Positive	FALSE	TRUE	6/5/2024	12:12 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Rear Entry	Window	mullion	Drywall	B	
6051135	22012	29	Positive	FALSE	TRUE	6/5/2024	12:13 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Rear Entry	Room	Crown Molding	Wood	D	
6051135	22013	27.4	Positive	FALSE	TRUE	6/5/2024	12:14 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Rear Entry	Room	Wall	Wood	D	Upper
6051135	22014	2.1	Positive	FALSE	TRUE	6/5/2024	12:14 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Rear Entry	Door		Wood	C	Upper
6051135	22015	2.7	Positive	FALSE	TRUE	6/5/2024	12:15 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Rear Entry	Door	Casing	Wood	C	Upper
6051135	22016	3.7	Positive	FALSE	TRUE	6/5/2024	12:16 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Rear Entry	Door	Upper Transom	Wood	C	Upper
6051135	22017	-0.4	Negative	FALSE	TRUE	6/5/2024	12:18 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Basement room 1	Door	---	Wood	C	
6051135	22018	-0.7	Negative	FALSE	TRUE	6/5/2024	12:18 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Basement room 1	Door	Casing	Wood	C	
6051135	22019	-0.6	Negative	FALSE	TRUE	6/5/2024	12:19 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Basement room 1	Stair	Hanger	Wood	B	
6051135	22020	-0.5	Negative	FALSE	TRUE	6/5/2024	12:20 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Basement room 1	Stair	Underside	Wood	A	
6051135	22021	0	Negative	FALSE	FALSE	6/5/2024	12:21 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Basement room 1	Stair	Threshold	Wood	A	
6051135	22022	0	Negative	FALSE	FALSE	6/5/2024	12:21 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Basement room 1	Stair	Threshold	Wood		2
6051135	22023	0	Negative	FALSE	FALSE	6/5/2024	12:22 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Basement room 1	Stair	Support column	Wood		
6051135	22024	-0.5	Negative	FALSE	TRUE	6/5/2024	12:22 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Basement room 1	Stair	Stringer	Wood		
6051135	22025	-0.6	Negative	FALSE	TRUE	6/5/2024	12:23 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Basement room 1	Stair	Risers	Wood		
6051135	22026	-0.7	Negative	FALSE	TRUE	6/5/2024	12:23 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Basement room 1	Stair	Railing	Wood		
6051135	22027	-0.2	Negative	FALSE	TRUE	6/5/2024	12:24 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Basement room 1	Door		Metal	C	2
6051135	22028	-0.3	Negative	FALSE	TRUE	6/5/2024	12:25 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Basement room 1	Door	Casing	Wood	C	2
6051135	22029	0.2	Negative	FALSE	FALSE	6/5/2024	12:26 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Basement room 1	Column		Metal		1
6051135	22030	0	Negative	FALSE	FALSE	6/5/2024	12:26 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Basement room 1	Column		Metal		2
6051135	22031	0.1	Negative	FALSE	FALSE	6/5/2024	12:27 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Basement room 1	Column		Metal		3
6051135	22032	0.1	Negative	FALSE	FALSE	6/5/2024	12:27 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Basement room 1	Room	Beam	Wood		
6051135	22033	-0.1	Negative	FALSE	FALSE	6/5/2024	12:28 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Basement room 1	Room	Stud	Wood		
6051135	22034	0.3	Negative	FALSE	FALSE	6/5/2024	12:29 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Basement room 1	Room	Wall	Concrete	C	
6051135	22035	0.5	Negative	FALSE	FALSE	6/5/2024	12:29 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Basement room 1	Room	Wall	Concrete	D	
6051135	22036	-0.4	Negative	FALSE	FALSE	6/5/2024	12:30 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Basement room 1	Room	Wall	Concrete	A	
6051135	22037	-0.4	Negative	FALSE	TRUE	6/5/2024	12:30 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Basement room 1	Room	Wall	Concrete	B	
6051135	22038	-0.5	Negative	FALSE	TRUE	6/5/2024	12:31 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Basement room 1	Window	Sash	Wood	D	1
6051135	22039	0	Negative	FALSE	FALSE	6/5/2024	12:35 PM	Danny Feliciano	Paint	55 Central Ave	Unit		2nd Floor Hallway	Stair	Support column	Wood		1
6051135	22040	-0.6	Negative	FALSE	TRUE	6/5/2024	12:35 PM	Danny Feliciano	Paint	55 Central Ave	Unit		2nd Floor Hallway	Stair	Newel Post	Wood		1
6051135	22041	0	Negative	FALSE	FALSE	6/5/2024	12:36 PM	Danny Feliciano	Paint	55 Central Ave	Unit		2nd Floor Hallway	Stair	Railing	Wood		1
6051135	22042	-0.7	Negative	FALSE	TRUE	6/5/2024	12:36 PM	Danny Feliciano	Paint	55 Central Ave	Unit		2nd Floor Hallway	Stair	Balusters	Wood		1
6051135	22043	0	Negative	FALSE	FALSE	6/5/2024	12:37 PM	Danny Feliciano	Paint	55 Central Ave	Unit		2nd Floor Hallway	Stair	Baseboard	Wood		
6051135	22044	0	Negative	FALSE	FALSE	6/5/2024	12:37 PM	Danny Feliciano	Paint	55 Central Ave	Unit		2nd Floor Hallway	Door	Casing	Wood	C	
6051135	22045	-0.2	Negative	FALSE	TRUE	6/5/2024	12:38 PM	Danny Feliciano	Paint	55 Central Ave	Unit		2nd Floor Hallway	Door	Jamb	Wood	C	
6051135	22046	0	Negative	FALSE	FALSE	6/5/2024	12:38 PM	Danny Feliciano	Paint	55 Central Ave	Unit		2nd Floor Hallway	Door	---	Wood	C	
6051135	22047	-0.4	Negative	FALSE	TRUE	6/5/2024	12:39 PM	Danny Feliciano	Paint	55 Central Ave	Unit		2nd Floor Hallway	Window	Casing	Wood	A	
6051135	22048	-0.2	Negative	FALSE	TRUE	6/5/2024	12:39 PM	Danny Feliciano	Paint	55 Central Ave	Unit		2nd Floor Hallway	Window	Sill	Wood	A	
6051135	22049	-0.4	Negative	FALSE	TRUE	6/5/2024	12:40 PM	Danny Feliciano	Paint	55 Central Ave	Unit		2nd Floor Hallway	Door		Wood	C	
6051135	22050	0	Negative	FALSE	FALSE	6/5/2024	12:40 PM	Danny Feliciano	Paint	55 Central Ave	Unit		2nd Floor Hallway	Room	Wall	Drywall	A	
6051135	22051	-0.1	Negative	FALSE	FALSE	6/5/2024	12:41 PM	Danny Feliciano	Paint	55 Central Ave	Unit		2nd Floor Hallway	Room	Wall	Drywall	B	

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
6051135	22052	-0.1	Negative	FALSE	FALSE	6/5/2024	12:41 PM	Danny Feliciano	Paint	55 Central Ave	Unit		2nd Floor Hallway	Room	Wall	Drywall	D	
6051135	22053	-0.1	Negative	FALSE	FALSE	6/5/2024	12:41 PM	Danny Feliciano	Paint	55 Central Ave	Unit		2nd Floor Hallway	Room	Wall	Drywall	C	
6051135	22054	0.1	Negative	FALSE	FALSE	6/5/2024	12:42 PM	Danny Feliciano	Paint	55 Central Ave	Unit		2nd Floor Hallway	Room	Ceiling	Drywall		
6051135	22055	-0.1	Negative	FALSE	FALSE	6/5/2024	12:43 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bathroom	Room	Wall	Drywall	B	
6051135	22056	-0.1	Negative	FALSE	FALSE	6/5/2024	12:44 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bathroom	Room	Wall	Drywall	C	
6051135	22057	-0.1	Negative	FALSE	FALSE	6/5/2024	12:44 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bathroom	Room	Wall	Drywall	D	
6051135	22058	0	Negative	FALSE	FALSE	6/5/2024	12:44 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bathroom	Room	Wall	Drywall	A	
6051135	22059	0	Negative	FALSE	FALSE	6/5/2024	12:45 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bathroom	Room	Ceiling	Drywall		
6051135	22060	-0.7	Negative	FALSE	TRUE	6/5/2024	12:45 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bathroom	Window	Casing	Wood	C	
6051135	22061	-0.5	Negative	FALSE	TRUE	6/5/2024	12:46 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bathroom	Door		Wood	A	
6051135	22062	-0.7	Negative	FALSE	TRUE	6/5/2024	12:46 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bathroom	Door	Casing	Wood	A	
6051135	22063	-0.3	Negative	FALSE	TRUE	6/5/2024	12:47 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bathroom	Door	Jamb	Wood	A	
6051135	22064	-0.6	Negative	FALSE	TRUE	6/5/2024	12:47 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 1	Door	Jamb	Wood	B	
6051135	22065	-0.4	Negative	FALSE	TRUE	6/5/2024	12:48 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 1	Door	Casing	Wood	B	
6051135	22066	-0.1	Negative	FALSE	FALSE	6/5/2024	12:48 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 1	Door	---	Wood	B	
6051135	22067	-0.4	Negative	FALSE	TRUE	6/5/2024	12:49 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 1	Closet	Door	Wood	A	
6051135	22068	-0.5	Negative	FALSE	TRUE	6/5/2024	12:49 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 1	Closet	Door Casing	Wood	A	
6051135	22069	-0.6	Negative	FALSE	TRUE	6/5/2024	12:49 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 1	Closet	Door Jamb	Wood	A	
6051135	22070	0	Negative	FALSE	FALSE	6/5/2024	12:50 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 1	Closet	Shelf Support	Wood	A	
6051135	22071	-0.1	Negative	FALSE	FALSE	6/5/2024	12:50 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 1	Closet	Shelf	Wood	A	
6051135	22072	0.2	Negative	FALSE	FALSE	6/5/2024	12:51 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 1	Closet	Wall	Wood	A	
6051135	22073	0	Negative	FALSE	FALSE	6/5/2024	12:51 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 1	Room	Baseboard	Wood	A	
6051135	22074	0	Negative	FALSE	FALSE	6/5/2024	12:52 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 1	Window	Casing	Wood	C	
6051135	22075	0	Negative	FALSE	FALSE	6/5/2024	12:52 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 1	Window	Sill	Wood	C	
6051135	22076	0.3	Negative	FALSE	FALSE	6/5/2024	12:53 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 1	Room	Wall	Drywall	C	
6051135	22077	0.4	Negative	FALSE	FALSE	6/5/2024	12:53 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 1	Room	Wall	Drywall	B	
6051135	22078	0.6	Negative	FALSE	FALSE	6/5/2024	12:54 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 1	Room	Wall	Drywall	D	
6051135	22079	0	Negative	FALSE	FALSE	6/5/2024	12:54 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 1	Room	Wall	Drywall	A	
6051135	22080	0.7	Negative	FALSE	FALSE	6/5/2024	12:55 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 1	Room	Ceiling	Drywall		
6051135	22081	0.1	Negative	FALSE	FALSE	6/5/2024	1:00 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 2	Room	Ceiling	Drywall		
6051135	22082	0.3	Negative	FALSE	FALSE	6/5/2024	1:00 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 2	Room	Wall	Drywall	B	
6051135	22083	0.5	Negative	FALSE	FALSE	6/5/2024	1:01 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 2	Room	Wall	Drywall	A	
6051135	22084	0.4	Negative	FALSE	FALSE	6/5/2024	1:01 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 2	Room	Wall	Drywall	D	
6051135	22085	0.2	Negative	FALSE	FALSE	6/5/2024	1:02 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 2	Room	Wall	Drywall	C	
6051135	22086	-0.5	Negative	FALSE	TRUE	6/5/2024	1:02 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 2	Closet	Door	Wood	C	
6051135	22087	-0.5	Negative	FALSE	TRUE	6/5/2024	1:03 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 2	Closet	Door Casing	Wood	C	
6051135	22088	-0.3	Negative	FALSE	TRUE	6/5/2024	1:03 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 2	Closet	Door Jamb	Wood	C	
6051135	22089	0.1	Negative	FALSE	FALSE	6/5/2024	1:03 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 2	Closet	Shelf Support	Wood	C	
6051135	22090	-0.4	Negative	FALSE	TRUE	6/5/2024	1:04 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 2	Window	Casing	Wood	D	1
6051135	22091	-0.2	Negative	FALSE	TRUE	6/5/2024	1:04 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 2	Window	Sill	Wood	D	1
6051135	22092	-0.1	Negative	FALSE	FALSE	6/5/2024	1:05 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 2	Door		Wood	B	
6051135	22093	-0.3	Negative	FALSE	TRUE	6/5/2024	1:05 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 2	Door	Casing	Wood	B	
6051135	22094	-0.5	Negative	FALSE	TRUE	6/5/2024	1:06 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 2	Door	Jamb	Wood	B	
6051135	22095	-0.6	Negative	FALSE	TRUE	6/5/2024	1:06 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 3	Door	Jamb	Wood	B	
6051135	22096	-0.6	Negative	FALSE	TRUE	6/5/2024	1:07 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 3	Door	Casing	Wood	B	
6051135	22097	0	Negative	FALSE	FALSE	6/5/2024	1:07 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 3	Door	---	Wood	B	
6051135	22098	-0.5	Negative	FALSE	TRUE	6/5/2024	1:08 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 3	Closet	Door	Wood	C	
6051135	22099	-0.6	Negative	FALSE	TRUE	6/5/2024	1:08 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 3	Closet	Door Casing	Wood	C	
6051135	22100	0.1	Negative	FALSE	FALSE	6/5/2024	1:09 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 3	Closet	Door Jamb	Wood	C	
6051135	22101	-0.5	Negative	FALSE	TRUE	6/5/2024	1:09 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 3	Window	Casing	Wood	D	
6051135	22102	-0.6	Negative	FALSE	TRUE	6/5/2024	1:10 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 3	Window	Sill	Wood	D	
6051135	22103	-0.3	Negative	FALSE	TRUE	6/5/2024	1:10 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 3	Room	Baseboard	Wood	C	
6051135	22104	-0.3	Negative	FALSE	TRUE	6/5/2024	1:11 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 2	Room	Baseboard	Wood	C	
6051135	22105	0	Negative	FALSE	FALSE	6/5/2024	1:11 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 3	Room	Wall	Drywall	C	
6051135	22106	0	Negative	FALSE	FALSE	6/5/2024	1:12 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Bedroom 3	Room	Wall	Drywall	B	

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 2128

Lead concentration units: mg/cm2

Total Readings: 162 Total Positives 8

Action Level 1

Mode Action Level

Analytic Mode Paint

Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
6051135	22006	5.7	Positive	FALSE	FALSE	6/5/2024	12:09 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Rear Entry	Room	Ceiling	Wood		
6051135	22007	26.7	Positive	FALSE	TRUE	6/5/2024	12:09 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Rear Entry	Room	Wall	Wood	A	
6051135	22011	4.7	Positive	FALSE	TRUE	6/5/2024	12:12 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Rear Entry	Window	mullion	Drywall	B	
6051135	22012	29	Positive	FALSE	TRUE	6/5/2024	12:13 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Rear Entry	Room	Crown Molding	Wood	D	
6051135	22013	27.4	Positive	FALSE	TRUE	6/5/2024	12:14 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Rear Entry	Room	Wall	Wood	D	Upper
6051135	22014	2.1	Positive	FALSE	TRUE	6/5/2024	12:14 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Rear Entry	Door		Wood	C	Upper
6051135	22015	2.7	Positive	FALSE	TRUE	6/5/2024	12:15 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Rear Entry	Door	Casing	Wood	C	Upper
6051135	22016	3.7	Positive	FALSE	TRUE	6/5/2024	12:16 PM	Danny Feliciano	Paint	55 Central Ave	Unit		Rear Entry	Door	Upper Transom	Wood	C	Upper