

Company LEW Corporation  
 XRF Make Heuresis  
 Model Pb200i  
 Serial Num. 1834  
 Lead concentration units: mg/cm2  
 Total Readings: 95  
 Action Level 1  
 Mode Action Level  
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
6111104	39699	1		TRUE	FALSE	6/11/2024	11:05 AM	Paint	419 Victory Ave								
6111104	39700	0.9		TRUE	FALSE	6/11/2024	11:06 AM	Paint	419 Victory Ave								
6111104	39701	1		TRUE	FALSE	6/11/2024	11:06 AM	Paint	419 Victory Ave								
6111104	39702	-0.1		TRUE	FALSE	6/11/2024	11:07 AM	Paint	419 Victory Ave								
6111104	39703	0		TRUE	FALSE	6/11/2024	11:07 AM	Paint	419 Victory Ave								
6111104	39704	0		TRUE	FALSE	6/11/2024	11:08 AM	Paint	419 Victory Ave								
6111104	39705	0.2	Negative	FALSE	FALSE	6/11/2024	11:10 AM	Paint	419 Victory Ave	Unit		Living Room	Door	---	Metal	A	1
6111104	39706	0	Negative	FALSE	FALSE	6/11/2024	11:10 AM	Paint	419 Victory Ave	Unit		Living Room	Door	Casing	Wood	A	1
6111104	39707	-0.1	Negative	FALSE	FALSE	6/11/2024	11:10 AM	Paint	419 Victory Ave	Unit		Living Room	Closet	Door	Wood	A	1
6111104	39708	0	Negative	FALSE	FALSE	6/11/2024	11:11 AM	Paint	419 Victory Ave	Unit		Living Room	Closet	Door Jamb	Wood	A	1
6111104	39709	0	Negative	FALSE	FALSE	6/11/2024	11:11 AM	Paint	419 Victory Ave	Unit		Living Room	Closet	Door Casing	Wood	A	1
6111104	39710	-0.1	Negative	FALSE	FALSE	6/11/2024	11:12 AM	Paint	419 Victory Ave	Unit		Living Room	Stair	Stringer	Wood	D	1
6111104	39711	-0.2	Negative	FALSE	FALSE	6/11/2024	11:12 AM	Paint	419 Victory Ave	Unit		Living Room	Stair	Railing	Wood	D	1
6111104	39712	-0.2	Negative	FALSE	FALSE	6/11/2024	11:13 AM	Paint	419 Victory Ave	Unit		Living Room	Stair	Balusters	Wood	D	1
6111104	39713	-0.1	Negative	FALSE	FALSE	6/11/2024	11:13 AM	Paint	419 Victory Ave	Unit		Living Room	Stair	Newel Post	Wood	D	1
6111104	39714	-0.1	Negative	FALSE	FALSE	6/11/2024	11:14 AM	Paint	419 Victory Ave	Unit		Living Room	Window	Jamb	Wood	B	1
6111104	39715	-0.1	Negative	FALSE	FALSE	6/11/2024	11:15 AM	Paint	419 Victory Ave	Unit		Living Room	Window	Casing	Wood	B	1
6111104	39716	-0.2	Negative	FALSE	FALSE	6/11/2024	11:15 AM	Paint	419 Victory Ave	Unit		Living Room	Window	Sill	Wood	B	1
6111104	39717	-0.2	Negative	FALSE	FALSE	6/11/2024	11:16 AM	Paint	419 Victory Ave	Unit		Living Room	Room	Baseboard	Wood	A	1
6111104	39718	0	Negative	FALSE	FALSE	6/11/2024	11:16 AM	Paint	419 Victory Ave	Unit		Living Room	Room	Wall	Drywall	A	1
6111104	39719	-0.1	Negative	FALSE	FALSE	6/11/2024	11:17 AM	Paint	419 Victory Ave	Unit		Living Room	Room	Wall	Drywall	B	1
6111104	39720	-0.1	Negative	FALSE	FALSE	6/11/2024	11:17 AM	Paint	419 Victory Ave	Unit		Living Room	Room	Wall	Drywall	C	1
6111104	39721	0.1	Negative	FALSE	FALSE	6/11/2024	11:18 AM	Paint	419 Victory Ave	Unit		Living Room	Room	Wall	Drywall	D	1
6111104	39722	0	Negative	FALSE	FALSE	6/11/2024	11:18 AM	Paint	419 Victory Ave	Unit		Living Room	Room	Ceiling	Drywall	D	1
6111104	39723	0	Negative	FALSE	FALSE	6/11/2024	11:19 AM	Paint	419 Victory Ave	Unit		Hall	Room	Ceiling	Drywall	A	1
6111104	39724	0	Negative	FALSE	FALSE	6/11/2024	11:19 AM	Paint	419 Victory Ave	Unit		Hall	Room	Wall	Drywall	A	1
6111104	39725	-0.1	Negative	FALSE	FALSE	6/11/2024	11:20 AM	Paint	419 Victory Ave	Unit		Hall	Room	Wall	Drywall	B	1
6111104	39726	0	Negative	FALSE	FALSE	6/11/2024	11:20 AM	Paint	419 Victory Ave	Unit		Hall	Room	Wall	Drywall	C	1
6111104	39727	0.1	Negative	FALSE	FALSE	6/11/2024	11:21 AM	Paint	419 Victory Ave	Unit		Hall	Room	Wall	Drywall	D	1
6111104	39728	-0.1	Negative	FALSE	FALSE	6/11/2024	11:21 AM	Paint	419 Victory Ave	Unit		Hall	Room	Baseboard	Wood	D	1
6111104	39729	0	Negative	FALSE	FALSE	6/11/2024	11:22 AM	Paint	419 Victory Ave	Unit		Hall	Closet	Door	Wood	A	1
6111104	39730	-0.1	Negative	FALSE	FALSE	6/11/2024	11:22 AM	Paint	419 Victory Ave	Unit		Hall	Closet	Door Jamb	Wood	A	1
6111104	39731	-0.2	Negative	FALSE	FALSE	6/11/2024	11:23 AM	Paint	419 Victory Ave	Unit		Hall	Closet	Door Casing	Wood	A	1
6111104	39732	-0.5	Negative	FALSE	FALSE	6/11/2024	11:23 AM	Paint	419 Victory Ave	Unit		Hall	Door	---	Wood	C	1
6111104	39733	0	Negative	FALSE	FALSE	6/11/2024	11:24 AM	Paint	419 Victory Ave	Unit		Hall	Door	Jamb	Wood	C	1
6111104	39734	0	Negative	FALSE	FALSE	6/11/2024	11:24 AM	Paint	419 Victory Ave	Unit		Hall	Door	Casing	Wood	C	1
6111104	39735	-0.2	Negative	FALSE	FALSE	6/11/2024	11:24 AM	Paint	419 Victory Ave	Unit		Bedroom 1	Door	Casing	Wood	D	1
6111104	39736	-0.1	Negative	FALSE	FALSE	6/11/2024	11:25 AM	Paint	419 Victory Ave	Unit		Bedroom 1	Door	Jamb	Wood	D	1
6111104	39737	-0.1	Negative	FALSE	FALSE	6/11/2024	11:25 AM	Paint	419 Victory Ave	Unit		Bedroom 1	Door	---	Wood	D	1

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
6111104	39738	0.1	Negative	FALSE	FALSE	6/11/2024	11:26 AM	Paint	419 Victory Ave	Unit		Bedroom 1	Closet	Door	Wood	D	1
6111104	39739	-0.2	Negative	FALSE	FALSE	6/11/2024	11:26 AM	Paint	419 Victory Ave	Unit		Bedroom 1	Closet	Door Casing	Wood	D	1
6111104	39740	-0.1	Negative	FALSE	FALSE	6/11/2024	11:27 AM	Paint	419 Victory Ave	Unit		Bedroom 1	Closet	Door Jamb	Wood	D	1
6111104	39741	-0.2	Negative	FALSE	FALSE	6/11/2024	11:27 AM	Paint	419 Victory Ave	Unit		Bedroom 1	Window	Jamb	Wood	C	1
6111104	39742	-0.4	Negative	FALSE	FALSE	6/11/2024	11:28 AM	Paint	419 Victory Ave	Unit		Bedroom 1	Window	Casing	Wood	C	1
6111104	39743	-0.1	Negative	FALSE	FALSE	6/11/2024	11:28 AM	Paint	419 Victory Ave	Unit		Bedroom 1	Window	Sill	Wood	C	1
6111104	39744	-0.1	Negative	FALSE	FALSE	6/11/2024	11:29 AM	Paint	419 Victory Ave	Unit		Bedroom 1	Room	Baseboard	Wood	C	1
6111104	39745	0	Negative	FALSE	FALSE	6/11/2024	11:29 AM	Paint	419 Victory Ave	Unit		Bedroom 1	Room	Wall	Drywall	D	1
6111104	39746	0	Negative	FALSE	FALSE	6/11/2024	11:30 AM	Paint	419 Victory Ave	Unit		Bedroom 1	Room	Wall	Drywall	C	1
6111104	39747	-0.1	Negative	FALSE	FALSE	6/11/2024	11:30 AM	Paint	419 Victory Ave	Unit		Bedroom 1	Room	Wall	Drywall	B	1
6111104	39748	-0.1	Negative	FALSE	FALSE	6/11/2024	11:30 AM	Paint	419 Victory Ave	Unit		Bedroom 1	Room	Wall	Drywall	A	1
6111104	39749	-0.2	Negative	FALSE	FALSE	6/11/2024	11:31 AM	Paint	419 Victory Ave	Unit		Bedroom 1	Room	Ceiling	Drywall	A	1
6111104	39750	0.1	Negative	FALSE	FALSE	6/11/2024	11:32 AM	Paint	419 Victory Ave	Unit		Bathroom 1	Room	Ceiling	Drywall	A	1
6111104	39751	-0.1	Negative	FALSE	FALSE	6/11/2024	11:32 AM	Paint	419 Victory Ave	Unit		Bathroom 1	Room	Wall	Drywall	A	1
6111104	39752	0	Negative	FALSE	FALSE	6/11/2024	11:33 AM	Paint	419 Victory Ave	Unit		Bathroom 1	Room	Wall	Drywall	B	1
6111104	39753	-0.1	Negative	FALSE	FALSE	6/11/2024	11:33 AM	Paint	419 Victory Ave	Unit		Bathroom 1	Room	Wall	Drywall	C	1
6111104	39754	0	Negative	FALSE	FALSE	6/11/2024	11:34 AM	Paint	419 Victory Ave	Unit		Bathroom 1	Room	Wall	Drywall	D	1
6111104	39755	-0.1	Negative	FALSE	FALSE	6/11/2024	11:34 AM	Paint	419 Victory Ave	Unit		Bathroom 1	Room	Baseboard	Wood	C	1
6111104	39756	-0.2	Negative	FALSE	FALSE	6/11/2024	11:35 AM	Paint	419 Victory Ave	Unit		Bathroom 1	Window	Jamb	Wood	C	1
6111104	39757	-0.2	Negative	FALSE	FALSE	6/11/2024	11:35 AM	Paint	419 Victory Ave	Unit		Bathroom 1	Window	Casing	Wood	C	1
6111104	39758	-0.1	Negative	FALSE	FALSE	6/11/2024	11:36 AM	Paint	419 Victory Ave	Unit		Bathroom 1	Window	Sill	Wood	C	1
6111104	39759	-0.1	Negative	FALSE	FALSE	6/11/2024	11:36 AM	Paint	419 Victory Ave	Unit		Bathroom 1	Cabinets	Door	Wood	B	1
6111104	39760	0.1	Negative	FALSE	FALSE	6/11/2024	11:37 AM	Paint	419 Victory Ave	Unit		Bathroom 1	Cabinets	Frame	Wood	B	1
6111104	39761	-0.1	Negative	FALSE	FALSE	6/11/2024	11:38 AM	Paint	419 Victory Ave	Unit		Bathroom 1	Door	---	Wood	A	1
6111104	39762	-0.2	Negative	FALSE	FALSE	6/11/2024	11:38 AM	Paint	419 Victory Ave	Unit		Bathroom 1	Door	Casing	Wood	A	1
6111104	39763	-0.1	Negative	FALSE	FALSE	6/11/2024	11:39 AM	Paint	419 Victory Ave	Unit		Bathroom 1	Door	Jamb	Wood	A	1
6111104	39764	0	Negative	FALSE	FALSE	6/11/2024	11:39 AM	Paint	419 Victory Ave	Unit		Kitchen	Door	Casing	Wood	D	1
6111104	39765	-0.2	Negative	FALSE	FALSE	6/11/2024	11:40 AM	Paint	419 Victory Ave	Unit		Kitchen	Door	---	Wood	D	1
6111104	39766	0	Negative	FALSE	FALSE	6/11/2024	11:40 AM	Paint	419 Victory Ave	Unit		Kitchen	Cabinets	Door	Wood	D	1
6111104	39767	0.1	Negative	FALSE	FALSE	6/11/2024	11:41 AM	Paint	419 Victory Ave	Unit		Kitchen	Cabinets	Frame	Wood	D	1
6111104	39768	-0.3	Negative	FALSE	FALSE	6/11/2024	11:41 AM	Paint	419 Victory Ave	Unit		Kitchen	Window	Jamb	Wood	D	1
6111104	39769	-0.1	Negative	FALSE	FALSE	6/11/2024	11:42 AM	Paint	419 Victory Ave	Unit		Kitchen	Window	Casing	Wood	D	1
6111104	39770	-0.2	Negative	FALSE	FALSE	6/11/2024	11:42 AM	Paint	419 Victory Ave	Unit		Kitchen	Window	Sill	Wood	D	1
6111104	39771	-0.3	Negative	FALSE	FALSE	6/11/2024	11:43 AM	Paint	419 Victory Ave	Unit		Kitchen	Room	Baseboard	Wood	D	1
6111104	39772	-0.1	Negative	FALSE	FALSE	6/11/2024	11:44 AM	Paint	419 Victory Ave	Unit		Kitchen	Room	Wall	Drywall	D	1
6111104	39773	-0.1	Negative	FALSE	FALSE	6/11/2024	11:44 AM	Paint	419 Victory Ave	Unit		Kitchen	Room	Wall	Drywall	C	1
6111104	39774	0.1	Negative	FALSE	FALSE	6/11/2024	11:44 AM	Paint	419 Victory Ave	Unit		Kitchen	Room	Wall	Drywall	B	1
6111104	39775	0.1	Negative	FALSE	FALSE	6/11/2024	11:45 AM	Paint	419 Victory Ave	Unit		Kitchen	Room	Wall	Drywall	A	1
6111104	39776	-0.1	Negative	FALSE	FALSE	6/11/2024	11:46 AM	Paint	419 Victory Ave	Unit		Kitchen	Door	---	Wood	B	1
6111104	39777	-0.1	Negative	FALSE	FALSE	6/11/2024	11:46 AM	Paint	419 Victory Ave	Unit		Kitchen	Door	Casing	Wood	B	1
6111104	39778	-0.2	Negative	FALSE	FALSE	6/11/2024	11:47 AM	Paint	419 Victory Ave	Unit		Kitchen	Door	Jamb	Wood	B	1
6111104	39779	-0.1	Negative	FALSE	FALSE	6/11/2024	11:47 AM	Paint	419 Victory Ave	Unit		Dining Room	Door	Jamb	Wood	B	1
6111104	39780	-0.1	Negative	FALSE	FALSE	6/11/2024	11:48 AM	Paint	419 Victory Ave	Unit		Dining Room	Door	Casing	Wood	B	1
6111104	39781	-0.1	Negative	FALSE	FALSE	6/11/2024	11:49 AM	Paint	419 Victory Ave	Unit		Dining Room	Window	Jamb	Wood	A	1
6111104	39782	-0.2	Negative	FALSE	FALSE	6/11/2024	11:49 AM	Paint	419 Victory Ave	Unit		Dining Room	Window	Casing	Wood	A	1
6111104	39783	-0.3	Negative	FALSE	FALSE	6/11/2024	11:49 AM	Paint	419 Victory Ave	Unit		Dining Room	Window	Sill	Wood	A	1
6111104	39784	-0.2	Negative	FALSE	FALSE	6/11/2024	11:50 AM	Paint	419 Victory Ave	Unit		Dining Room	Room	Baseboard	Wood	A	1
6111104	39785	0	Negative	FALSE	FALSE	6/11/2024	11:50 AM	Paint	419 Victory Ave	Unit		Dining Room	Room	Wall	Drywall	A	1
6111104	39786	-0.1	Negative	FALSE	FALSE	6/11/2024	11:51 AM	Paint	419 Victory Ave	Unit		Dining Room	Room	Wall	Drywall	B	1
6111104	39787	0	Negative	FALSE	FALSE	6/11/2024	11:51 AM	Paint	419 Victory Ave	Unit		Dining Room	Room	Wall	Drywall	C	1



Company LEW Corporation  
XRF Make Heuresis  
Model Pb200i  
Serial Num. 1834  
Lead concentration units: mg/cm2  
Total Readings: 95 Total Positives 0  
Action Level 1  
Mode Action Level  
Analytic Mode Paint

**Actionables**

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
No Actionables																	