



7469 Whitepine Rd
 North Chesterfield, VA 23237
 Telephone: 800.347.4010

Lead Dust Wipe Analysis Report

Report Number: 24-05-04640

Client: LEW Corp
 181 US Hwy 46
 Mine Hill, NJ 07803

Received Date: 05/29/2024
Analyzed Date: 05/31/2024
Reported Date: 05/31/2024

Project/Test Address: 36360; 55 Guilden St; New Brunswick, NJ

Collection Date: 05/24/2024

Client Number:
 201327

Laboratory Results

Fax Number:
 Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
24-05-04640-001	01	BED 1	FL	<5.00	1.00	<5.00	
24-05-04640-002	02	BED 1	SL	29.1	0.646	45.0	
24-05-04640-003	03	BED 2	FL	<5.00	1.00	<5.00	
24-05-04640-004	04	BED 2	SL	29.4	0.323	91.1	
24-05-04640-005	05	BED 4	FL	5.84	1.00	5.84	
24-05-04640-006	06	BED 4	SL	<5.00	0.646	<7.74	
24-05-04640-007	07	BED 6	FL	<5.00	1.00	<5.00	
24-05-04640-008	08	BED 6	SL	<5.00	0.306	<16.4	
24-05-04640-009	09	SUNROOM	FL	<5.00	1.00	<5.00	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 24-05-04640

Project/Test Address: 36360; 55 Guilden St; New Brunswick, NJ

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
-------------------	----------------------	---------------------	---------	---------------	------------------------------	-------------------------------------	--------------

Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode

QA/QC Clerk

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft² are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accreditation through AIHA LAP, LLC (100420), NY ELAP #11714.

Legend	ug = microgram	ug/ft ² = micrograms per square foot	Pb = lead
	mL = milliliter	ft ² = square foot	



ENVIRONMENTAL SERVICES

A Mainline Company


LEW Environmental Services P: (800) 783-0567

F: (908) 654-8069

Lead

Chain-of-Custody

24-05-04640



Due Date:

06/03/2024

(Monday)

AE

* All wipe... its.

Project Name: 55 Gildan - 36360
 Address: 55 Gildan St
 City, State: New Brunswick, NJ
 Project Number: 36360

Sample Type: Dust wipe Paint chip Soil TCP

Turn Around Time (TAT): Same Day 3 Day 1 Day 2 Weeks 1 Week

Sampler Information: Name: Nicole Grant Signature: Nicole Grant

Sample #	Date Collected	Sample Location (Ex: Fl, Kitchen, AC)	Area (inches)	Paint Chip Analysis		
				mg/cm ²	PPM	% wt
01	5/24/24	Bed 1 Fl	12 x 12			
02	5/24/24	Bed 1 ws	3 x 31			
03	5/24/24	Bed 2 Fl	12 x 12			
04	5/24/24	Bed 2 ws	1 1/2 x 31			
05	5/24/24	Bed 4 Fl	12 x 12			
06	5/24/24	Bed 4 ws	3 x 31			
07	5/24/24	Bed 6 Fl	12 x 12			
08	5/24/24	Bed 6 ws	2 x 22			
09	5/24/24	Sun room Fl	12 x 12			

Relinquished by: Nicole Grant Signature: Nicole Grant Date/Time: 5/26/24

Received by: DBrown Signature: DBrown Date/Time: 5/29/24 3:14pm