

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 2822
 Lead concentration units: mg/cm2
 Total Readings: 225
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location	Condition	Cause
5211414	18579	0.9		TRUE	FALSE	5/21/2024	2:15 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ										
5211414	18580	1		TRUE	FALSE	5/21/2024	2:15 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ										
5211414	18581	1		TRUE	FALSE	5/21/2024	2:15 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ										
5211414	18582	0.1		TRUE	FALSE	5/21/2024	2:15 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ										
5211414	18583	0.1		TRUE	FALSE	5/21/2024	2:16 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ										
5211414	18584	0.2		TRUE	FALSE	5/21/2024	2:16 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ										
5211414	18585	0.4	Negative	FALSE	FALSE	5/21/2024	2:17 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Door	---	Wood	A	1	Deteriorated	Preparation
5211414	18586	0.7	Negative	FALSE	FALSE	5/21/2024	2:17 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Door	Jamb	Wood	A	1	Deteriorated	Preparation
5211414	18587	0.3	Negative	FALSE	FALSE	5/21/2024	2:17 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Door	Casing	Wood	A	1	Deteriorated	Preparation
5211414	18588	0.2	Negative	FALSE	FALSE	5/21/2024	2:18 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Door	Casing	Wood	B	1	Deteriorated	Preparation
5211414	18589	0.2	Negative	FALSE	FALSE	5/21/2024	2:18 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Door	---	Wood	B	1	Deteriorated	Preparation
5211414	18590	0.2	Negative	FALSE	FALSE	5/21/2024	2:19 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Closet	Door	Wood	B	1	Intact	
5211414	18591	0.3	Negative	FALSE	FALSE	5/21/2024	2:19 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Closet	Door Jamb	Wood	B	1	Intact	
5211414	18592	0.4	Negative	FALSE	FALSE	5/21/2024	2:19 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Closet	Door Casing	Wood	B	1	Intact	
5211414	18593	0.2	Negative	FALSE	FALSE	5/21/2024	2:19 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Closet	Shelf Support	Wood	B	1	Intact	
5211414	18594	0.1	Negative	FALSE	FALSE	5/21/2024	2:19 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Closet	Shelf	Wood	B	1	Intact	
5211414	18595	0.2	Negative	FALSE	FALSE	5/21/2024	2:20 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Closet	Wall	Plaster	B	1	Intact	
5211414	18596	0.2	Negative	FALSE	FALSE	5/21/2024	2:20 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Closet	Baseboard	Wood	B	1	Intact	
5211414	18597	-0.3	Negative	FALSE	FALSE	5/21/2024	2:21 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Room	Wall	Plaster	A	1	Intact	
5211414	18598	0	Negative	FALSE	FALSE	5/21/2024	2:21 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Room	Wall	Plaster	D	1	Intact	
5211414	18599	0.1	Negative	FALSE	FALSE	5/21/2024	2:22 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Room	Wall	Plaster	C	1	Intact	
5211414	18600	0.1	Negative	FALSE	FALSE	5/21/2024	2:22 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Room	Wall	Plaster	B	1	Intact	
5211414	18601	0.4	Negative	FALSE	FALSE	5/21/2024	2:22 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Room	Baseboard	Wood	B	1	Intact	
5211414	18602	0.4	Negative	FALSE	FALSE	5/21/2024	2:23 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Radiator	---	Metal	A	1	Intact	
5211414	18603	0.2	Negative	FALSE	FALSE	5/21/2024	2:23 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Window	Sill	Wood	A	1	Intact	
5211414	18604	0.3	Negative	FALSE	FALSE	5/21/2024	2:23 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Window	Jamb	Wood	A	1	Intact	
5211414	18605	0.2	Negative	FALSE	FALSE	5/21/2024	2:23 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Window	Casing	Wood	A	1	Intact	
5211414	18606	0.3	Negative	FALSE	FALSE	5/21/2024	2:24 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Shelf	---	Wood	A	1	Intact	
5211414	18607	0.3	Negative	FALSE	FALSE	5/21/2024	2:24 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Shelf Support	---	Wood	A	1	Intact	
5211414	18608	0.3	Negative	FALSE	FALSE	5/21/2024	2:25 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Fire Place	Wall	Brick	A	1	Intact	
5211414	18609	0.2	Negative	FALSE	FALSE	5/21/2024	2:25 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Fire Place	Mantle	Wood	A	1	Intact	
5211414	18610	-0.1	Negative	FALSE	FALSE	5/21/2024	2:25 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Room	Floor	Wood	B	1	Intact	
5211414	18611	8.6	Positive	FALSE	FALSE	5/21/2024	2:26 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Sun Room	Door	---	Wood	D	1	Deteriorated	Impact
5211414	18612	4.6	Positive	FALSE	FALSE	5/21/2024	2:26 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Sun Room	Door	Jamb	Wood	D	1	Deteriorated	Impact
5211414	18613	-0.4	Negative	FALSE	FALSE	5/21/2024	2:27 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Sun Room	Window	Jamb	Wood	B	1	Intact	
5211414	18614	-0.1	Negative	FALSE	FALSE	5/21/2024	2:27 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Sun Room	Window	Casing	Wood	B	1	Intact	
5211414	18615	0.8	Negative	FALSE	FALSE	5/21/2024	2:27 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Sun Room	Room	Wall	Plaster	A	1	Intact	
5211414	18616	0	Negative	FALSE	FALSE	5/21/2024	2:28 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Sun Room	Room	Wall	Plaster	B	1	Intact	
5211414	18617	1.6	Positive	FALSE	FALSE	5/21/2024	2:28 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Sun Room	Room	Wall	Plaster	D	1	Intact	
5211414	18618	0.8	Negative	FALSE	FALSE	5/21/2024	2:28 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Sun Room	Room	Wall	Plaster	C	1	Intact	
5211414	18619	0.3	Negative	FALSE	FALSE	5/21/2024	2:29 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Sun Room	Room	Baseboard	Wood	D	1	Intact	
5211414	18620	0.9	Negative	FALSE	FALSE	5/21/2024	2:29 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Sun Room	Window	Jamb	Wood	D	1	Intact	
5211414	18621	0.4	Negative	FALSE	FALSE	5/21/2024	2:29 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Sun Room	Window	Casing	Wood	D	1	Intact	
5211414	18622	0.2	Negative	FALSE	FALSE	5/21/2024	2:30 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Sun Room	Window	Sill	Wood	D	1	Intact	
5211414	18623	0.5	Negative	FALSE	FALSE	5/21/2024	2:31 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Door	---	Wood	B	1	Intact	
5211414	18624	0.4	Negative	FALSE	FALSE	5/21/2024	2:31 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Door	Casing	Wood	B	1	Intact	
5211414	18625	0.3	Negative	FALSE	FALSE	5/21/2024	2:32 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Stair	Risers	Wood	C	1	Intact	
5211414	18626	0	Negative	FALSE	FALSE	5/21/2024	2:32 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Stair	Treads	Wood	C	1	Intact	
5211414	18627	-0.1	Negative	FALSE	FALSE	5/21/2024	2:32 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Stair	Newel Post	Wood	C	1	Intact	
5211414	18628	0.1	Negative	FALSE	FALSE	5/21/2024	2:33 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Stair	Balusters	Wood	C	1	Intact	
5211414	18629	0.6	Negative	FALSE	FALSE	5/21/2024	2:34 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Living Room	Radiator	Cover	Wood	D	1	Intact	
5211414	18630	0.1	Negative	FALSE	FALSE	5/21/2024	2:34 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	1/2 Bathroom	Door	---	Wood	B	1	Intact	
5211414	18631	0.3	Negative	FALSE	FALSE	5/21/2024	2:34 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	1/2 Bathroom	Door	Jamb	Wood	B	1	Intact	
5211414	18632	0.1	Negative	FALSE	FALSE	5/21/2024	2:35 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	1/2 Bathroom	Door	Casing	Wood	B	1	Intact	
5211414	18633	0.3	Negative	FALSE	FALSE	5/21/2024	2:35 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	1/2 Bathroom	Radiator	---	Metal	A	1	Intact	

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 2822

Lead concentration units: mg/cm2

Total Readings: 225 Total Positives 19

Action Level 1

Mode Action Level

Analytic Mode Paint

Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location	Condition	Cause
5211414	18611	8.6	Positive	FALSE	FALSE	5/21/2024	2:26 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Sun Room	Door	---	Wood	D	1	Deteriorated	Impact
5211414	18612	4.6	Positive	FALSE	FALSE	5/21/2024	2:26 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Sun Room	Door	Jamb	Wood	D	1	Deteriorated	Impact
5211414	18617	1.6	Positive	FALSE	FALSE	5/21/2024	2:28 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Sun Room	Room	Wall	Plaster	D	1	Intact	
5211414	18668	4.2	Positive	FALSE	FALSE	5/21/2024	2:50 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Kitchen	Window	Sill	Wood	D	1	Intact	
5211414	18677	2.3	Positive	FALSE	FALSE	5/21/2024	2:53 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Side Entry	Room	Wall	Plaster	A	1	Intact	
5211414	18678	3	Positive	FALSE	FALSE	5/21/2024	2:53 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Side Entry	Room	Wall	Plaster	B	1	Intact	
5211414	18679	2.5	Positive	FALSE	FALSE	5/21/2024	2:54 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Side Entry	Room	Wall	Plaster	C	1	Intact	
5211414	18680	3.5	Positive	FALSE	FALSE	5/21/2024	2:54 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Side Entry	Room	Wall	Plaster	D	1	Intact	
5211414	18681	2.9	Positive	FALSE	FALSE	5/21/2024	2:54 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Side Entry	Room	Ceiling	Plaster	D	1	Intact	
5211414	18684	2	Positive	FALSE	FALSE	5/21/2024	2:55 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Side Entry	Room	Wall Trim	Wood	C	1	Intact	
5211414	18690	3.1	Positive	FALSE	FALSE	5/21/2024	2:59 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Side Entry	Room	Ceiling	Plaster	C	1	Intact	
5211414	18694	1.6	Positive	FALSE	FALSE	5/21/2024	3:02 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Sun Room	Room	Ceiling	Plaster	C	1	Intact	
5211414	18709	1.5	Positive	FALSE	FALSE	5/21/2024	3:07 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Bedroom 1	Radiator	Cover	Wood	A	1	Intact	
5211414	18727	2.1	Positive	FALSE	FALSE	5/21/2024	3:13 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Bedroom 2	Radiator	Cover	Wood	C	1	Intact	
5211414	18765	2.2	Positive	FALSE	FALSE	5/21/2024	3:25 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Bedroom 3	Radiator	Cover	Wood	D	1	Intact	
5211414	18806	13.2	Positive	FALSE	FALSE	5/21/2024	3:43 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Exterior	house	House (Exterior)	Door	Jamb	Wood	A	1	Deteriorated	Impact
5211414	18807	11.4	Positive	FALSE	FALSE	5/21/2024	3:43 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Exterior	house	House (Exterior)	Door	---	Wood	A	1	Deteriorated	Impact
5211414	18808	2.2	Positive	FALSE	FALSE	5/21/2024	3:45 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Exterior	house	House (Exterior)	Door	---	Wood	D	1	Deteriorated	Impact
5211414	18809	17.3	Positive	FALSE	FALSE	5/21/2024	3:46 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Exterior	house	House (Exterior)	Door	Jamb	Wood	D	1	Deteriorated	Impact

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 2822

Lead concentration units: mg/cm2

Total Readings: 225 Total Hazards 6

Action Level 1

Mode Action Level

Analytic Mode Paint

Hazards

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location	Condition	Cause
5211414	18611	8.6	Positive	FALSE	FALSE	5/21/2024	2:26 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Sun Room	Door	---	Wood	D	1	Deteriorated	Impact
5211414	18612	4.6	Positive	FALSE	FALSE	5/21/2024	2:26 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Interior	house	Sun Room	Door	Jamb	Wood	D	1	Deteriorated	Impact
5211414	18806	13.2	Positive	FALSE	FALSE	5/21/2024	3:43 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Exterior	house	House (Exterior)	Door	Jamb	Wood	A	1	Deteriorated	Impact
5211414	18807	11.4	Positive	FALSE	FALSE	5/21/2024	3:43 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Exterior	house	House (Exterior)	Door	---	Wood	A	1	Deteriorated	Impact
5211414	18808	2.2	Positive	FALSE	FALSE	5/21/2024	3:45 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Exterior	house	House (Exterior)	Door	---	Wood	D	1	Deteriorated	Impact
5211414	18809	17.3	Positive	FALSE	FALSE	5/21/2024	3:46 PM	Alex Salvador	Paint	37 Brinkerhoff Avenue Freehold NJ	Exterior	house	House (Exterior)	Door	Jamb	Wood	D	1	Deteriorated	Impact