

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 1830
 Lead concentration units: mg/cm2
 Total Readings: 59
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
24A Roosevelt	18548	1.3		TRUE	FALSE	6/6/2024	1:52 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ								
24A Roosevelt	18549	1.3		TRUE	FALSE	6/6/2024	1:53 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ								
24A Roosevelt	18550	1.3		TRUE	FALSE	6/6/2024	1:54 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ								
24A Roosevelt	18551	0		TRUE	FALSE	6/6/2024	1:55 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ								
24A Roosevelt	18552	0		TRUE	FALSE	6/6/2024	1:56 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ								
24A Roosevelt	18553	0		TRUE	FALSE	6/6/2024	1:56 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ								
24A Roosevelt	18554	1.5	Positive	FALSE	FALSE	6/6/2024	1:58 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Foyer	Window	Casing	Wood	D		1
24A Roosevelt	18555	1.6	Positive	FALSE	FALSE	6/6/2024	1:59 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Foyer	Window	Sill	Wood	D		1
24A Roosevelt	18556	1.8	Positive	FALSE	FALSE	6/6/2024	2:00 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Foyer	Window	Sash	Wood	D		1
24A Roosevelt	18557	1.5	Positive	FALSE	FALSE	6/6/2024	2:01 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Foyer	Window	Sill	Wood	A		1
24A Roosevelt	18558	1.6	Positive	FALSE	FALSE	6/6/2024	2:01 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Foyer	Window	Casing	Wood	A		1
24A Roosevelt	18559	0	Negative	FALSE	FALSE	6/6/2024	2:02 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Foyer	Door		Wood	D		1
24A Roosevelt	18560	2.8	Positive	FALSE	FALSE	6/6/2024	2:03 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Foyer	Door	Casing	Wood	D		1
24A Roosevelt	18561	0	Negative	FALSE	FALSE	6/6/2024	2:04 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Foyer	Room	Wall	Drywall	D		1
24A Roosevelt	18562	0.3	Negative	FALSE	FALSE	6/6/2024	2:05 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Foyer	Room	Wall	Drywall	C		1
24A Roosevelt	18563	0.3	Negative	FALSE	FALSE	6/6/2024	2:06 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Foyer	Room	Wall	Drywall	C		1
24A Roosevelt	18564	2	Positive	FALSE	FALSE	6/6/2024	2:07 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Foyer	Room	Baseboard	Wood	C		1
24A Roosevelt	18565	1.6	Positive	FALSE	FALSE	6/6/2024	2:08 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Foyer	Room	Baseboard	Wood	A		1
24A Roosevelt	18566	0.1	Negative	FALSE	FALSE	6/6/2024	2:09 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Foyer	Radiator		Metal	A		1
24A Roosevelt	18567	1.8	Positive	FALSE	FALSE	6/6/2024	2:09 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Foyer	Archway		Wood	C		1
24A Roosevelt	18568	3.5	Positive	FALSE	FALSE	6/6/2024	2:11 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Living Room	Window	Sill	Wood	B		1
24A Roosevelt	18569	3.4	Positive	FALSE	FALSE	6/6/2024	2:11 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Living Room	Window	Casing	Wood	B		1
24A Roosevelt	18570	2.9	Positive	FALSE	FALSE	6/6/2024	2:12 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Living Room	Room	Baseboard	Wood	C		1
24A Roosevelt	18571	-0.3	Negative	FALSE	FALSE	6/6/2024	2:13 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Living Room	Room	Wall	Drywall	C		1
24A Roosevelt	18572	0.1	Negative	FALSE	FALSE	6/6/2024	2:14 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Living Room	Room	Wall	Drywall	A		1
24A Roosevelt	18573	-0.2	Negative	FALSE	FALSE	6/6/2024	2:15 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Living Room	Room	Wall	Drywall	B		1
24A Roosevelt	18574	-0.3	Negative	FALSE	FALSE	6/6/2024	2:15 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Living Room	Room	Wall	Drywall	D		1
24A Roosevelt	18575	0.3	Negative	FALSE	FALSE	6/6/2024	2:16 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Living Room	Radiator		Metal	C		1
24A Roosevelt	18576	3.5	Positive	FALSE	FALSE	6/6/2024	2:17 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Living Room	Door	Casing	Wood	C		1
24A Roosevelt	18577	5.2	Positive	FALSE	FALSE	6/6/2024	2:18 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Living Room	Door	Jamb	Wood	C		1
24A Roosevelt	18578	-0.1	Negative	FALSE	FALSE	6/6/2024	2:20 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Dining Room/Kitchen	Door	Casing	Wood	C		1
24A Roosevelt	18579	0.9	Negative	FALSE	FALSE	6/6/2024	2:20 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Dining Room/Kitchen	Door	---	Wood	C		1
24A Roosevelt	18580	0	Negative	FALSE	FALSE	6/6/2024	2:22 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Dining Room/Kitchen	Archway		Wood	A		1
24A Roosevelt	18581	0.1	Negative	FALSE	FALSE	6/6/2024	2:23 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Dining Room/Kitchen	Window	Sill	Wood	B		1
24A Roosevelt	18582	1.1	Positive	FALSE	FALSE	6/6/2024	2:24 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Dining Room/Kitchen	Window	Casing	Wood	B		1
24A Roosevelt	18583	0	Negative	FALSE	FALSE	6/6/2024	2:25 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Dining Room/Kitchen	Window	Casing	Wood	B		3
24A Roosevelt	18584	0.3	Negative	FALSE	FALSE	6/6/2024	2:30 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Dining Room/Kitchen	Window	Sill	Wood	B		3
24A Roosevelt	18585	1.4	Positive	FALSE	FALSE	6/6/2024	2:31 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Dining Room/Kitchen	Room	Baseboard	Wood	B		3
24A Roosevelt	18586	0.4	Negative	FALSE	FALSE	6/6/2024	2:33 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Dining Room/Kitchen	Room	Wall	Drywall	B		3
24A Roosevelt	18587	0.1	Negative	FALSE	FALSE	6/6/2024	2:34 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Dining Room/Kitchen	Room	Wall	Drywall	C		3
24A Roosevelt	18588	0.1	Negative	FALSE	FALSE	6/6/2024	2:36 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Dining Room/Kitchen	Room	Wall	Drywall	A		3
24A Roosevelt	18589	1.5	Positive	FALSE	FALSE	6/6/2024	2:36 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Dining Room/Kitchen	Door	Casing	Wood	D		3
24A Roosevelt	18590	1.8	Positive	FALSE	FALSE	6/6/2024	2:38 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Dining Room/Kitchen	Door	Jamb	Wood	D		3
24A Roosevelt	18591	1.6	Positive	FALSE	FALSE	6/6/2024	2:40 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Bedroom 1	Door	Casing	Wood	A		3
24A Roosevelt	18592	-0.2	Negative	FALSE	FALSE	6/6/2024	2:41 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Bedroom 1	Door	---	Wood	A		3
24A Roosevelt	18593	1.6	Positive	FALSE	FALSE	6/6/2024	2:42 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Bedroom 1	Window	Sill	Wood	C		3
24A Roosevelt	18594	2	Positive	FALSE	FALSE	6/6/2024	2:43 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Bedroom 1	Window	Casing	Wood	C		3
24A Roosevelt	18595	0.1	Negative	FALSE	FALSE	6/6/2024	2:44 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Bedroom 1	Closet	Door	Wood	A		3
24A Roosevelt	18596	1.6	Positive	FALSE	FALSE	6/6/2024	2:45 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Bedroom 1	Closet	Door Casing	Wood	A		3
24A Roosevelt	18597	1.8	Positive	FALSE	FALSE	6/6/2024	2:49 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit	Bedroom 1	Closet	Shelf Support	Wood	A		3

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
24A Roosevelt	18598	0.2	Negative	FALSE	FALSE	6/6/2024	2:50 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bedroom 1	Closet	Wall	Drywall	A	3
24A Roosevelt	18599	-0.2	Negative	FALSE	FALSE	6/6/2024	2:51 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bedroom 1	Room	Wall	Drywall	A	3
24A Roosevelt	18600	-0.2	Negative	FALSE	FALSE	6/6/2024	2:52 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bedroom 1	Room	Wall	Drywall	A	3
24A Roosevelt	18601	-0.1	Negative	FALSE	FALSE	6/6/2024	2:52 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bedroom 1	Room	Wall	Drywall	A	3
24A Roosevelt	18602	-0.4	Negative	FALSE	FALSE	6/6/2024	2:53 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bedroom 1	Room	Wall	Drywall	A	3
24A Roosevelt	18603	0.2	Negative	FALSE	FALSE	6/6/2024	2:54 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bedroom 1	Radiator		Drywall	A	3
24A Roosevelt	18604	1.1	Positive	FALSE	FALSE	6/6/2024	2:55 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bathroom	Door	Casing	Drywall	A	3
24A Roosevelt	18605	1	Positive	FALSE	FALSE	6/6/2024	2:57 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bathroom	Door	Jamb	Drywall	A	3
24A Roosevelt	18606	1.1	Positive	FALSE	FALSE	6/6/2024	3:00 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bathroom	Door	---	Drywall	B	3
24A Roosevelt	18607	0.1	Negative	FALSE	FALSE	6/6/2024	3:02 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bathroom	Room	Wall	Drywall	B	3
24A Roosevelt	18608	0.1	Negative	FALSE	FALSE	6/6/2024	3:02 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bathroom	Room	Wall	Drywall	B	3
24A Roosevelt	18609	1.2	Positive	FALSE	FALSE	6/6/2024	3:04 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bathroom	Closet	Door	Drywall	B	3
24A Roosevelt	18610	0	Negative	FALSE	FALSE	6/6/2024	3:05 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bathroom	Closet	Door Casing	Wood	C	3
24A Roosevelt	18611	1.7	Positive	FALSE	FALSE	6/6/2024	3:06 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bathroom	Closet	Shelf Support	Wood	C	3
24A Roosevelt	18612	-0.1	Negative	FALSE	FALSE	6/6/2024	3:07 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bathroom	Closet	Door Jamb	Wood	C	3

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 1830

Lead concentration units: mg/cm2

Total Readings: 59 Total Positives 28

Action Level 1

Mode Action Level

Analytic Mode Paint

Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
24A Roosevelt	18554	1.5	Positive	FALSE	FALSE	6/6/2024	1:58 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Foyer	Window	Casing	Wood	D	1
24A Roosevelt	18555	1.6	Positive	FALSE	FALSE	6/6/2024	1:59 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Foyer	Window	Sill	Wood	D	1
24A Roosevelt	18556	1.8	Positive	FALSE	FALSE	6/6/2024	2:00 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Foyer	Window	Sash	Wood	D	1
24A Roosevelt	18557	1.5	Positive	FALSE	FALSE	6/6/2024	2:01 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Foyer	Window	Sill	Wood	A	1
24A Roosevelt	18558	1.6	Positive	FALSE	FALSE	6/6/2024	2:01 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Foyer	Window	Casing	Wood	A	1
24A Roosevelt	18560	2.8	Positive	FALSE	FALSE	6/6/2024	2:03 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Foyer	Door	Casing	Wood	D	1
24A Roosevelt	18564	2	Positive	FALSE	FALSE	6/6/2024	2:07 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Foyer	Room	Baseboard	Wood	C	1
24A Roosevelt	18565	1.6	Positive	FALSE	FALSE	6/6/2024	2:08 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Foyer	Room	Baseboard	Wood	A	1
24A Roosevelt	18567	1.8	Positive	FALSE	FALSE	6/6/2024	2:09 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Foyer	Archway		Wood	C	1
24A Roosevelt	18568	3.5	Positive	FALSE	FALSE	6/6/2024	2:11 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Living Room	Window	Sill	Wood	B	1
24A Roosevelt	18569	3.4	Positive	FALSE	FALSE	6/6/2024	2:11 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Living Room	Window	Casing	Wood	B	1
24A Roosevelt	18570	2.9	Positive	FALSE	FALSE	6/6/2024	2:12 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Living Room	Room	Baseboard	Wood	C	1
24A Roosevelt	18576	3.5	Positive	FALSE	FALSE	6/6/2024	2:17 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Living Room	Door	Casing	Wood	C	1
24A Roosevelt	18577	5.2	Positive	FALSE	FALSE	6/6/2024	2:18 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Living Room	Door	Jamb	Wood	C	1
24A Roosevelt	18582	1.1	Positive	FALSE	FALSE	6/6/2024	2:24 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Dining Room/Kitchen	Window	Casing	Wood	B	1
24A Roosevelt	18585	1.4	Positive	FALSE	FALSE	6/6/2024	2:31 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Dining Room/Kitchen	Room	Baseboard	Wood	B	3
24A Roosevelt	18589	1.5	Positive	FALSE	FALSE	6/6/2024	2:36 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Dining Room/Kitchen	Door	Casing	Wood	D	3
24A Roosevelt	18590	1.8	Positive	FALSE	FALSE	6/6/2024	2:38 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Dining Room/Kitchen	Door	Jamb	Wood	D	3
24A Roosevelt	18591	1.6	Positive	FALSE	FALSE	6/6/2024	2:40 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bedroom 1	Door	Casing	Wood	A	3
24A Roosevelt	18593	1.6	Positive	FALSE	FALSE	6/6/2024	2:42 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bedroom 1	Window	Sill	Wood	C	3
24A Roosevelt	18594	2	Positive	FALSE	FALSE	6/6/2024	2:43 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bedroom 1	Window	Casing	Wood	C	3
24A Roosevelt	18596	1.6	Positive	FALSE	FALSE	6/6/2024	2:45 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bedroom 1	Closet	Door Casing	Wood	A	3
24A Roosevelt	18597	1.8	Positive	FALSE	FALSE	6/6/2024	2:49 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bedroom 1	Closet	Shelf Support	Wood	A	3
24A Roosevelt	18604	1.1	Positive	FALSE	FALSE	6/6/2024	2:55 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bathroom	Door	Casing	Drywall	A	3
24A Roosevelt	18605	1	Positive	FALSE	FALSE	6/6/2024	2:57 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bathroom	Door	Jamb	Drywall	A	3
24A Roosevelt	18606	1.1	Positive	FALSE	FALSE	6/6/2024	3:00 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bathroom	Door	---	Drywall	B	3
24A Roosevelt	18609	1.2	Positive	FALSE	FALSE	6/6/2024	3:04 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bathroom	Closet	Door	Drywall	B	3
24A Roosevelt	18611	1.7	Positive	FALSE	FALSE	6/6/2024	3:06 PM	Nyire Edmonds-Grant	Paint	24A Roosevelt Ave, Northfield, NJ	Unit		Bathroom	Closet	Shelf Support	Wood	C	3