

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 1830
 Lead concentration units: mg/cm2
 Total Readings: 92
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
Genoa 5976	19578	1.3		TRUE	FALSE	6/24/2024	10:45 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ								
Genoa 5976	19579	1.2		TRUE	FALSE	6/24/2024	10:46 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ								
Genoa 5976	19580	1.2		TRUE	FALSE	6/24/2024	10:48 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ								
Genoa 5976	19581	0		TRUE	FALSE	6/24/2024	10:48 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ								
Genoa 5976	19582	0		TRUE	FALSE	6/24/2024	10:49 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ								
Genoa 5976	19583	0		TRUE	FALSE	6/24/2024	10:50 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ								
Genoa 5976	19584	0	Negative	FALSE	FALSE	6/24/2024	10:53 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 1	Door	Casing	Wood	D	1
Genoa 5976	19585	0	Negative	FALSE	FALSE	6/24/2024	10:54 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 1	Door	Jamb	Wood	D	1
Genoa 5976	19586	-0.1	Negative	FALSE	FALSE	6/24/2024	10:54 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 1	Window	Sill	Wood	C	1
Genoa 5976	19587	-0.1	Negative	FALSE	FALSE	6/24/2024	10:55 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 1	Window	Casing	Wood	C	1
Genoa 5976	19588	1.4	Positive	FALSE	FALSE	6/24/2024	10:56 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 1	Window	Sash	Wood	C	1
Genoa 5976	19589	0.6	Negative	FALSE	FALSE	6/24/2024	10:58 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 1	Window	Jamb	Wood	C	1
Genoa 5976	19590	0.1	Negative	FALSE	FALSE	6/24/2024	11:00 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 1	Room	Wall	Drywall	C	1
Genoa 5976	19591	0.1	Negative	FALSE	FALSE	6/24/2024	11:01 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 1	Room	Wall	Drywall	D	1
Genoa 5976	19592	0.1	Negative	FALSE	FALSE	6/24/2024	11:01 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 1	Room	Wall	Drywall	A	1
Genoa 5976	19593	0.1	Negative	FALSE	FALSE	6/24/2024	11:02 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 1	Room	Wall	Drywall	B	1
Genoa 5976	19594	0	Negative	FALSE	FALSE	6/24/2024	11:03 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 1	Room	Ceiling	Wood		1
Genoa 5976	19595	-0.1	Negative	FALSE	FALSE	6/24/2024	11:04 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 1	Room	Baseboard	Wood		1
Genoa 5976	19596	0.1	Negative	FALSE	FALSE	6/24/2024	11:06 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Walk-in Closet	Room	Wall	Drywall	A	1
Genoa 5976	19597	-0.1	Negative	FALSE	FALSE	6/24/2024	11:06 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Walk-in Closet	Room	Wall	Drywall	B	1
Genoa 5976	19598	0.1	Negative	FALSE	FALSE	6/24/2024	11:07 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Walk-in Closet	Room	Wall	Drywall	C	1
Genoa 5976	19599	0.1	Negative	FALSE	FALSE	6/24/2024	11:08 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Walk-in Closet	Room	Wall	Wood	D	1
Genoa 5976	19600	0	Negative	FALSE	FALSE	6/24/2024	11:09 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Walk-in Closet	Room	Ceiling	Wood	D	1
Genoa 5976	19601	2.4	Positive	FALSE	FALSE	6/24/2024	11:10 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Walk-in Closet	Window	Sash	Wood	D	1
Genoa 5976	19602	1.4	Positive	FALSE	FALSE	6/24/2024	11:11 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Walk-in Closet	Window	Sill	Wood	A	1
Genoa 5976	19603	0	Negative	FALSE	FALSE	6/24/2024	11:13 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Walk-in Closet	Window	Casing	Wood	A	1
Genoa 5976	19604	-0.3	Negative	FALSE	FALSE	6/24/2024	11:15 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Walk-in Closet	Door	Casing	Wood	C	1
Genoa 5976	19605	0	Negative	FALSE	FALSE	6/24/2024	11:16 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Walk-in Closet	Door	Jamb	Wood	C	1
Genoa 5976	19606	0.1	Negative	FALSE	FALSE	6/24/2024	11:17 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Hall	Room	Wall	Drywall	C	1
Genoa 5976	19607	0.1	Negative	FALSE	FALSE	6/24/2024	11:18 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Hall	Room	Wall	Drywall	B	1
Genoa 5976	19608	0	Negative	FALSE	FALSE	6/24/2024	11:19 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Hall	Room	Wall	Drywall	D	1
Genoa 5976	19609	0.1	Negative	FALSE	FALSE	6/24/2024	11:19 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Hall	Room	Wall	Drywall	A	1
Genoa 5976	19610	-0.2	Negative	FALSE	FALSE	6/24/2024	11:20 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Hall	Closet	Door Casing	Wood	A	1
Genoa 5976	19611	-0.1	Negative	FALSE	FALSE	6/24/2024	11:21 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Hall	Closet	Door Jamb	Wood	A	1
Genoa 5976	19612	-0.1	Negative	FALSE	FALSE	6/24/2024	11:22 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Hall	Closet	Shelf Support	Wood	A	1
Genoa 5976	19613	0	Negative	FALSE	FALSE	6/24/2024	11:23 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Hall	Room	Ceiling	Wood	A	1
Genoa 5976	19614	0	Negative	FALSE	FALSE	6/24/2024	11:25 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 2	Room	Ceiling	Wood	A	1
Genoa 5976	19615	-0.2	Negative	FALSE	FALSE	6/24/2024	11:26 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 2	Room	Baseboard	Wood	B	1
Genoa 5976	19616	0.1	Negative	FALSE	FALSE	6/24/2024	11:27 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 2	Room	Wall	Drywall	B	1
Genoa 5976	19617	0.2	Negative	FALSE	FALSE	6/24/2024	11:27 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 2	Room	Wall	Drywall	A	1
Genoa 5976	19618	0	Negative	FALSE	FALSE	6/24/2024	11:29 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 2	Room	Wall	Drywall	D	1
Genoa 5976	19619	0	Negative	FALSE	FALSE	6/24/2024	11:29 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 2	Room	Wall	Drywall	C	1
Genoa 5976	19620	0.8	Negative	FALSE	FALSE	6/24/2024	11:31 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 2	Window	Sill	Wood	A	1
Genoa 5976	19621	-0.2	Negative	FALSE	FALSE	6/24/2024	11:33 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 2	Window	Casing	Wood	A	1
Genoa 5976	19622	3	Positive	FALSE	FALSE	6/24/2024	11:34 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 2	Window	Sash	Wood	A	1
Genoa 5976	19623	1.6	Positive	FALSE	FALSE	6/24/2024	11:35 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 2	Door	---	Wood	C	1
Genoa 5976	19624	-0.1	Negative	FALSE	FALSE	6/24/2024	11:36 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 2	Door	Jamb	Wood	C	1
Genoa 5976	19625	0.9	Negative	FALSE	FALSE	6/24/2024	11:38 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Hall	Window	Sill	Wood	D	1
Genoa 5976	19626	0	Negative	FALSE	FALSE	6/24/2024	11:39 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Hall	Window	Casing	Wood	D	1
Genoa 5976	19627	1	Positive	FALSE	FALSE	6/24/2024	11:40 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Hall	Window	Sash	Wood	D	1

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 1830

Lead concentration units: mg/cm2

Total Readings: 92 Total Positives 8

Action Level 1

Mode Action Level

Analytic Mode Paint

Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
Genoa 5976	19588	1.4	Positive	FALSE	FALSE	6/24/2024	10:56 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 1	Window	Sash	Wood	C	1
Genoa 5976	19601	2.4	Positive	FALSE	FALSE	6/24/2024	11:10 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Walk-in Closet	Window	Sash	Wood	D	1
Genoa 5976	19602	1.4	Positive	FALSE	FALSE	6/24/2024	11:11 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Walk-in Closet	Window	Sill	Wood	A	1
Genoa 5976	19622	3	Positive	FALSE	FALSE	6/24/2024	11:34 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 2	Window	Sash	Wood	A	1
Genoa 5976	19623	1.6	Positive	FALSE	FALSE	6/24/2024	11:35 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Bedroom 2	Door	---	Wood	C	1
Genoa 5976	19627	1	Positive	FALSE	FALSE	6/24/2024	11:40 AM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Hall	Window	Sash	Wood	D	1
Genoa 5976	19656	1.1	Positive	FALSE	FALSE	6/24/2024	12:11 PM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		Living Room/Kitchen	Room	Wall	Drywall	C	1
Genoa 5976	19666	2.6	Positive	FALSE	FALSE	6/24/2024	12:20 PM	Nyire Edmonds-Grant	Paint	5976 Genoa Ave, Buena Vista, NJ	Unit		office	Window	Sash	Wood	D	1